

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Drakeholes Road (2207428)

Street: Drakeholes Road (2207428)

Locality: Wiseton, Nottinghamshire

Area: Bassetlaw

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Bassetlaw	
Batch: 20274336 - Inspection Batch				Route: Bassetlaw Area 1 Mar Saf CW				Date: 23/03/2018
3572400	14No potholes	23/03/2018	as markedmon site	CW Repairs-Bituminous	Internal		Committed	2675407
3572399	7No potholes	23/03/2018	as marked on site with a 1	CW Repairs-Bituminous	Internal		Committed	2675406
Batch: 20270651 - Inspection Batch				Route: Bassetlaw Area 1 Feb Enh CW				Date: 02/03/2018
	No actionable defects found							
Batch: 20264841 - Inspection Batch				Route: Bassetlaw Area 1 Jan Saf CW				Date: 25/01/2018
3565583	13No potholes	25/01/2018	as marked on site	CW Repairs-Bituminous	Internal		Committed	2668518
Batch: 20262108 - Inspection Batch				Route: Adhoc Inspection				Date: 09/01/2018
3563482	14No potholes	09/01/2018	as marked on site	CW Repairs-Bituminous	Internal		Committed	2666378
Batch: 20262107 - Inspection Batch				Route: Adhoc Inspection				Date: 09/01/2018
3563481	3No potholes	09/01/2018	as marked on site	CW Repairs-Bituminous	Internal		Committed	2666377
Batch: 20259033 - Inspection Batch				Route: Bassetlaw Area 1 Dec Saf CW				Date: 13/12/2017
	No actionable defects found							
Batch: 20254738 - Inspection Batch				Route: Bassetlaw Area 1 Nov Saf CW				Date: 13/11/2017
3559590	7No potholes	13/11/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2662352
Batch: 20250248 - Inspection Batch				Route: Bassetlaw Area 1 Oct Saf CW				Date: 17/10/2017
	No actionable defects found							
Batch: 20248869 - Inspection Batch				Route: Review Outcome-Mark Campbell				Date: 05/10/2017
	No actionable defects found							
Batch: 20246006 - Inspection Batch				Route: Bassetlaw Area 1 Sep Saf CW				Date: 15/09/2017
3555296	8No potholes	15/09/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2657808
Batch: 20241945 - Inspection Batch				Route: Bassetlaw Area 1 Aug Saf CW				Date: 16/08/2017
	No actionable defects found							
Batch: 20239064 - Inspection Batch				Route: Bassetlaw Area 1 Jul Saf CW				Date: 24/07/2017
3552327	12No potholes	24/07/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2654608
3552326	1No pothole marked with a 1 to denote 24hr pothole	24/07/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2654607
Batch: 20233874 - Inspection Batch				Route: Bassetlaw Area 1 Jun Saf CW				Date: 13/06/2017
	No actionable defects found							
Batch: 20228006 - Inspection Batch				Route: Bassetlaw Area 1 May Saf CW				Date: 03/05/2017
	No actionable defects found							
Batch: 20224125 - Inspection Batch				Route: Bassetlaw Area 1 Apr Saf CW				Date: 05/04/2017
	No actionable defects found							

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Drakeholes Road (2207428)

Customer Services

Enquiry No.: 6075576

Logged by: External to Confirm

on: 09/01/2018 09:33

Service: Carriageway/Footway

Subject: Carriageway Pothole

Classification: Report or Observation

Enquiry Ref: FS-CASE-65358907

Desc.: Road Pothole - There are a number of potholes on the road from Drakeholes to the first turning (on the left) to Wiseton. . Online report

Location: See map coordinates and description details

Contact:

Plot Number: 2,000.00

Feature Id - Location:

Feature Type: Street Section

Job Number: 2666377

Defect Number: 3563481

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Bassetlaw	
2654607	1No pothole marked with a 1 to denote 24hr pothole (CW Repairs-Bituminous)	as marked on site	Category 1	Job Completed	24/07/2017	25/07/2017	Act. BAS-AS/5102271
2654608	12No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	24/07/2017	25/07/2017	Act. BAS-AS/5102273
2657808	8No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	15/09/2017	18/09/2017	Act. BAS-AS/5102530
2662352	7No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	13/11/2017	14/11/2017	Act. BAS-AS/5102835
2666377	3No potholes (CW Repairs-Bituminous)	as marked on site	Category 1	Job Completed	09/01/2018	10/01/2018	Act. BAS-AS/5103109
2666378	14No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (High)	Job Completed	09/01/2018	15/01/2018	Act. BAS-AS/5103127
2668518	13No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (High)	Job Completed	25/01/2018	09/02/2018	Act. BAS-AS/5103297
2675406	7No potholes (CW Repairs-Bituminous)	as marked on site with a 1	Category 1	Job Completed	23/03/2018	26/03/2018	Act. BAS-AS/5103840
2675407	14No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (High)	Works Order Printed	23/03/2018	30/03/2018	Est. BASS/3901568