

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Wiseton Road (2207427)

Street: Wiseton Road (2207427)

Locality: Drakeholes, Nottinghamshire

Area: Bassetlaw

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: Worksop			Feature Type: Street Section			Area: Bassetlaw	
Batch: 20273488 - Inspection Batch				Route: Bassetlaw Area 1 Mar Saf CW				Date: 21/03/2018
3571891	4No potholes	21/03/2018	as marked at kerbed section on r/hand side of road if heading towards Wiseton	CW Repairs-Bituminous	Internal		Committed	2674896
Batch: 20269311 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Feb Enh CW				Date: 21/02/2018
Batch: 20264842 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jan Saf CW				Date: 25/01/2018
Batch: 20259034 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Dec Saf CW				Date: 13/12/2017
Batch: 20254740 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Nov Saf CW				Date: 13/11/2017
Batch: 20250250 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Oct Saf CW				Date: 17/10/2017
Batch: 20248865 - Inspection Batch	No actionable defects found			Route: Review Outcome-Mark Campbell				Date: 05/10/2017
Batch: 20246007 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Sep Saf CW				Date: 15/09/2017
Batch: 20241946 - Inspection Batch				Route: Bassetlaw Area 1 Aug Saf CW				Date: 16/08/2017
3553532	2No potholes at same location	16/08/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2655971
Batch: 20238056 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jul Saf CW				Date: 14/07/2017
Batch: 20233873 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jun Saf CW				Date: 13/06/2017
Batch: 20228008 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 May Saf CW				Date: 03/05/2017
Batch: 20224124 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Apr Saf CW				Date: 05/04/2017
Feat No.: 2,020.00	Feature Id - Locn.:			Feature Type: Layby - Integrated			Area: Bassetlaw	
Batch: 20273476 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Mar Saf CW				Date: 21/03/2018
Batch: 20268781 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Feb Enh CW				Date: 19/02/2018
Batch: 20261446 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jan Saf CW				Date: 04/01/2018
Batch: 20259024 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Dec Saf CW				Date: 13/12/2017

Effective: 01/04/2017 to 31/03/2018

Display Action Officer: No

Feature No.: 2000.00 to 2020.00

Street: Wiseton Road (2207427)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,020.00	Feature Id - Locn.:			Feature Type: Layby - Integrated			Area: Bassetlaw	
Batch: 20254717 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Nov Saf CW				Date: 13/11/2017
Batch: 20250243 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Oct Saf CW				Date: 17/10/2017
Batch: 20245811 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Sep Saf CW				Date: 13/09/2017
Batch: 20241708 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Aug Saf CW				Date: 15/08/2017
Batch: 20238076 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jul Saf CW				Date: 14/07/2017
Batch: 20233877 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Jun Saf CW				Date: 13/06/2017
Batch: 20228010 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 May Saf CW				Date: 03/05/2017
Batch: 20224123 - Inspection Batch	No actionable defects found			Route: Bassetlaw Area 1 Apr Saf CW				Date: 05/04/2017

Customer Services

Enquiry No.: 6050988

Logged by: External to Confirm

on: 25/04/2017 12:08

Service: Road Works

Subject: Road Works Report

Classification: Report or Observation

Enquiry Ref: FS-CASE-51377298

Desc.: Road work issue - Customer is concerned that the diversion for the roadworks is diverting HGV over the bridge that has a 3 ton max weight. concern that it will cause an accident. . Submitted by Advisor: Jane Howlett

Location: See map coordinates and description details

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: Worksop			Feature Type: Street Section		Area: Bassetlaw	
2647498 CW Repairs-Bituminous	on bend photo attached		Category 1	Job Completed	31/03/2017	03/04/2017	Act. BAS-AS/5101772
2655971 2No potholes at same location (CW Repairs-Bituminous)	as marked on site		Category 1	Job Completed	16/08/2017	17/08/2017	Act. BAS-AS/5102405
2674896 4No potholes (CW Repairs-Bituminous)	as marked at kerbed section on r/hand side of road if heading towards Wiseton		Category 2 (High)	Works Order Printed	21/03/2018	28/03/2018	Est. BASS/3901517