

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Wiseton Road (2203408)

Street: Wiseton Road (2203408)

Locality: Clayworth, Nottinghamshire

Area: Bassetlaw

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b>	C10 - Worksop	<b>Feature Type:</b>	Street Section		<b>Area:</b> Bassetlaw	
<b>Batch:</b>	20274335 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Mar Saf CW			<b>Date:</b> 23/03/2018
	No actionable defects found							
<b>Batch:</b>	20271488 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Feb Enh CW/F'			<b>Date:</b> 07/03/2018
3570107	1No pothole repaired by Paul TPD on the 7-3-18 at approx 9:50	07/03/2018	at gully near springs lane	CW Repairs-Bituminous	Internal		Uncommitt	2673090
3570113	3No potholes marked with a 1	07/03/2018	junction Springs Lane, at severn trent pump station	CW Repairs-Bituminous	Internal		Committed	2673096
3570115	2No potholes	07/03/2018	at severn trent pump station, at pull off area near canal bridge	CW Repairs-Bituminous	Internal		Committed	2673098
3570116	seal patch	07/03/2018	at severn trent pump station	CW Repairs-Bituminous	Internal		Committed	2673099
<b>Batch:</b>	20264843 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Jan Saf CW			<b>Date:</b> 25/01/2018
	No actionable defects found							
<b>Batch:</b>	20259037 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Dec Saf CW			<b>Date:</b> 13/12/2017
	No actionable defects found							
<b>Batch:</b>	20254743 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Nov Saf CW			<b>Date:</b> 13/11/2017
	No actionable defects found							
<b>Batch:</b>	20250252 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Oct Saf CW			<b>Date:</b> 17/10/2017
3557508	3No potholes	17/10/2017	at 30mph signs	CW Repairs-Bituminous	Internal		Committed	2660145
<b>Batch:</b>	20248883 - Inspection Batch			<b>Route:</b>	Review Outcome-Mark TPD			<b>Date:</b> 05/10/2017
	No actionable defects found							
<b>Batch:</b>	20246009 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Sep Saf CW			<b>Date:</b> 15/09/2017
	No actionable defects found							
<b>Batch:</b>	20241953 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Aug Saf CW			<b>Date:</b> 16/08/2017
	No actionable defects found							
<b>Batch:</b>	20239093 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Jul Saf CW			<b>Date:</b> 24/07/2017
3552336	seal patch	24/07/2017	at severn trent pump station	CW Repairs-Bituminous	Internal		Committed	2654617
3552335	1No pothole	24/07/2017	at gully near streetlight 41	CW Repairs-Bituminous	Internal		Committed	2654616
<b>Batch:</b>	20233871 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Jun Saf CW			<b>Date:</b> 13/06/2017
	No actionable defects found							
<b>Batch:</b>	20228002 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 May Saf CW			<b>Date:</b> 03/05/2017
	No actionable defects found							
<b>Batch:</b>	20224855 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 1 Apr Saf CW			<b>Date:</b> 11/04/2017
	No actionable defects found							

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Wiseton Road (2203408)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: C10 - Worksop	Feature Type: Street Section		Area: Bassetlaw		
2654616	1No pothole (CW Repairs-Bituminous)	at gully near streetlight 41	Category 1	Job Completed	24/07/2017	25/07/2017	Act. BAS-AS/5102275
2654617	seal patch (CW Repairs-Bituminous)	at severn trent pump station	Category 2 (Low)	Job Completed	24/07/2017	30/08/2017	Act. BASS/3900542
2660145	3No potholes (CW Repairs-Bituminous)	at 30mph signs	Category 2 (Low)	Job Completed	17/10/2017	03/11/2017	Act. BASS/3900814
2673090	1No pothole repaired by Paul TPD on the 7-3-18 at approx 9:50 (CW Repairs-Bituminous)	at gully near springs lane	Filled when found (Cat 1)	Job Completed	07/03/2018	07/03/2018	Act.
2673096	3No potholes marked with a 1 (CW Repairs-Bituminous)	junct Springs Lane, at severn trent pump station	Category 1	Job Completed	07/03/2018	08/03/2018	Act. BAS-AS/5103642
2673098	2No potholes (CW Repairs-Bituminous)	at severn trent pump station, at pull off area near canal bridge	Category 2 (High)	Job Completed	07/03/2018	14/03/2018	Act. BASS/3901402
2673099	seal patch (CW Repairs-Bituminous)	at severn trent pump station	Category 2 (High)	Job Completed	07/03/2018	14/03/2018	Act. BASS/3901396