

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Clayworth Road (2207426)

Street: Clayworth Road (2207426)

Locality: Wiseton, Nottinghamshire

Area: Bassetlaw

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> 10 - Workshops			<b>Feature Type:</b> Street Section			<b>Area:</b> Bassetlaw	
<b>Batch:</b> 20274337 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Mar Saf CW				<b>Date:</b> 23/03/2018
3572402	3No potholes	23/03/2018	as marked on site	CW Repairs-Bituminous	Internal		Committed	2675409
3572401	5No potholes marked with a 1	23/03/2018	at wiseton turn nearest one to Drakeholes, top of hill, as marked on site	CW Repairs-Bituminous	Internal		Committed	2675408
<b>Batch:</b> 20270655 - Inspection Batch	No actionable defects found			<b>Route:</b> Bassetlaw Area 1 Feb Enh CW/F'				<b>Date:</b> 02/03/2018
<b>Batch:</b> 20267647 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 09/02/2018
3567478	1No pothole	09/02/2018	near Dairy Cottage	CW Repairs-Bituminous	Internal		Uncommitt	2670434
<b>Batch:</b> 20265858 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 01/02/2018
3566341	3No potholes repaired by Paul TPD on the 1-2-18 at approx 10:30	01/02/2018	just after springs lane turn if heading towards Drakeholes	CW Repairs-Bituminous	Internal		Uncommitt	2669288
<b>Batch:</b> 20265819 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Jan Saf CW				<b>Date:</b> 31/01/2018
3566307	4No potholes repaired by Paul TPD on the 31-1-18	31/01/2018	near turn onto springs lane	CW Repairs-Bituminous	Internal		Uncommitt	2669254
<b>Batch:</b> 20262110 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 09/01/2018
3563483	1No pothole	09/01/2018	nr junct with Springs Lane	Drainage	Internal		Committed	2666379
<b>Batch:</b> 20259035 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Dec Saf CW				<b>Date:</b> 13/12/2017
3561767	5No potholes marked out when road was wet	13/12/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2664629
<b>Batch:</b> 20254741 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Nov Saf CW				<b>Date:</b> 13/11/2017
3559591	2No potholes	13/11/2017	at top of hill opp property	CW Repairs-Bituminous	Internal		Committed	2662353
<b>Batch:</b> 20250251 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Oct Saf CW				<b>Date:</b> 17/10/2017
3557507	6No potholes	17/10/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2660144
<b>Batch:</b> 20248868 - Inspection Batch	No actionable defects found			<b>Route:</b> Review Outcome-Mark Campbell				<b>Date:</b> 05/10/2017
<b>Batch:</b> 20246008 - Inspection Batch	No actionable defects found			<b>Route:</b> Bassetlaw Area 1 Sep Saf CW				<b>Date:</b> 15/09/2017
<b>Batch:</b> 20241947 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Aug Saf CW				<b>Date:</b> 16/08/2017
3553537	seal patch	16/08/2017	near Dairy Cottage which is on brow of hill	CW Repairs-Bituminous	Internal		Committed	2655976
3553533	1No pothole	16/08/2017	near Dairy Cottage which is on brow of hill	CW Repairs-Bituminous	Internal		Committed	2655972
<b>Batch:</b> 20239065 - Inspection Batch				<b>Route:</b> Bassetlaw Area 1 Jul Saf CW				<b>Date:</b> 24/07/2017
3552329	3No pothole	24/07/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2654610
3552328	1No pothole marked with a 1 to denote 24hr pothole	24/07/2017	as marked on site	CW Repairs-Bituminous	Internal		Committed	2654609
<b>Batch:</b> 20233872 - Inspection Batch	No actionable defects found			<b>Route:</b> Bassetlaw Area 1 Jun Saf CW				<b>Date:</b> 13/06/2017

Effective: 01/04/2017 to 31/03/2018

Display Action Officer: No

Feature No.: 2000.00 to 2020.00

Street: Clayworth Road (2207426)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> 10 - Worksop			<b>Feature Type:</b> Street Section			<b>Area:</b> Bassetlaw	
<b>Batch:</b> 20228003 - Inspection Batch	No actionable defects found			<b>Route:</b> Bassetlaw Area 1 May Saf CW				<b>Date:</b> 03/05/2017
<b>Batch:</b> 20224126 - Inspection Batch	No actionable defects found			<b>Route:</b> Bassetlaw Area 1 Apr Saf CW				<b>Date:</b> 05/04/2017

**Customer Services**

**Enquiry No.:** 6079612 **Logged by:** External to Confirm **on:** 31/01/2018 19:44  
**Service:** Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-67050168  
**Desc.:** Road Pothole - large hole appearing if you try to avoid it you are on the wrong side of the road and risk oncoming traffic. If oncoming traffic is unavoidable and you hit the hole you risk damage to vehicles & accident; particularly if on pushbike or motorcycle. . Online report  
**Location:** Driving from Clayworth towards Drakeholes just after junction on right to Wiston on the left hand bend. **Contact:**

**Plot Number:** 2,000.00 **Feature Id - Location:** 10 - Worksop **Feature Type:** Street Section  
**Job Number:** 2669288 **Defect Number:** 3566341

**Enquiry No.:** 6079448 **Logged by:** External to Confirm **on:** 31/01/2018 11:30  
**Service:** Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66996460  
**Desc.:** Road Pothole - There iare a number of potholes in a small area. This area is filling with water and is very dangerous when icy.

Please note that at present a large amount of mud has also been spread over the road, presumably during hedge cutting. This has also made the area very slippery. . Online report  
**Location:** On Wiseton Road from the turn off out of the village towards Drakeholes **Contact:**

**Plot Number:** 2,000.00 **Feature Id - Location:** 10 - Worksop **Feature Type:** Street Section  
**Job Number:** 2670434 **Defect Number:** 3567478

**Enquiry No.:** 6079138 **Logged by:** External to Confirm **on:** 30/01/2018 09:42  
**Service:** Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66891761  
**Desc.:** Overhanging trees - There are 4 large trees in a row, which are overhanging the carriageway which need to be cut back.

**TPD** drivers experience this issue, and have to drive down the centre of the road to avoid the branches, which is dangerous for them, and for other drivers.

Also, opposite the trees, there is a hedgerow which has grown right out into the carriageway, which makes this issue even worse as there is less room to get past. If it was cut back a metre, it would make it less problematic.

Can we get someone out to have a look at these issues please? . Submitted by Advisor: Jason **TPD**

**Location:** On Wiseton Road, on the right hand side, going from Clayworth towards Drakeholes, **Contact:** just past the turning for Wiseton (near the woodlands).

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> 10 - Worksop			<b>Feature Type:</b> Street Section		<b>Area:</b> Bassetlaw	
2654609	1No pothole marked with a 1 to denote 24hr pothole (CW Repairs-Bituminous)	as marked on site	Category 1	Job Completed	24/07/2017	25/07/2017	Act. BAS-AS/5102270

Effective: 01/04/2017 to 31/03/2018

Feature No.: 2000.00 to 2020.00

Display Action Officer: No

Street: Clayworth Road (2207426)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> 10 - Workshops		<b>Feature Type:</b> Street Section		<b>Area:</b> Bassettlaw	
2654610	3No pothole (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	24/07/2017	25/07/2017	Act. BAS-AS/5102272
2655972	1No pothole (CW Repairs-Bituminous)	near Dairy Cottage which is on brow of hill	Category 2 (Low)	Job Completed	16/08/2017	30/08/2017	Act. BASS/3900599
2655976	seal patch (CW Repairs-Bituminous)	near Dairy Cottage which is on brow of hill	Category 2 (Low)	Job Completed	16/08/2017	30/08/2017	Act. BASS/3900599
2660144	6No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	17/10/2017	10/11/2017	Act. BASS/3900814
2662353	2No potholes (CW Repairs-Bituminous)	at top of hill opp property	Category 2 (Low)	Job Completed	13/11/2017	14/11/2017	Act. BAS-AS/5102836
2664629	5No potholes marked out when road was wet (CW Repairs-Bituminous)	as marked on site	Category 2 (Low)	Job Completed	13/12/2017	21/12/2017	Act. BAS-AS/5102980
2666379	1No pothole (Drainage)	nr junct with Springs Lane	Category 1	Job Completed	09/01/2018	10/01/2018	Act. BAS-AS/5103109
2669254	4No potholes repaired by Paul Boscolo on the 31-1-18 (CW Repairs-Bituminous)	near turn onto springs lane	Filled when found (Cat 1)	Job Completed	31/01/2018	31/01/2018	Act.
2669288	3No potholes repaired by Paul Boscolo on the 1-2-18 at approx 10:30 (CW Repairs-Bituminous)	just after springs lane turn if heading towards Drakeholes	Filled when found (Cat 1)	Job Completed	01/02/2018	01/02/2018	Act.
2670434	1No pothole (CW Repairs-Bituminous)	near Dairy Cottage	Filled when found (Cat 1)	Job Completed	09/02/2018	09/02/2018	Act.
2675408	5No potholes marked with a 1 (CW Repairs-Bituminous)	at wiseton turn nearest one to Drakeholes, top of hill, as marked on site	Category 1	Job Completed	23/03/2018	26/03/2018	Act. BAS-AS/5103841
2675409	3No potholes (CW Repairs-Bituminous)	as marked on site	Category 2 (High)	Works Order Printed	23/03/2018	30/03/2018	Est. BASS/3901569

**Street Works Notices****Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 2655972**Version:** 3**Work Desc:** potholes & Patching**Notice Type:** Works Stop**Start:** 30/08/2017 00:00:00**Work Status:** Works Stopped**Issued:** 31/08/2017 08:23:23**Work Type:** EToN 4: Minor**Est. End:** 30/08/2017**Completion:** 30/08/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside Dairy Cottage	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	30/08/2017			30/08/2017