

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Street: Besthorpe Road (26822192)

Locality: Collingham, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu			Feature Type: Street Section			Area: Newark	
Batch: 20265543 - Inspection Batch				Route: Adhoc Inspection				Date: 30/01/2018
3566106	pothole	30/01/2018	opposite besthorpe quarry edge of carriageway marked	CW Repairs-Bituminous	Internal		Committed	2669048
3566107	potholes x 3 cat 1 high repaid	30/01/2018	opposite water works besthorpe quarry .	CW Repairs-Bituminous	Internal		Uncommitt	2669047
Batch: 20263876 - Inspection Batch				Route: Adhoc Inspection				Date: 22/01/2018
3564926	potholes	22/01/2018	800 yrd from one stop shop	CW Repairs-Bituminous	Internal		Uncommitt	2667847
Batch: 20263874 - Inspection Batch				Route: Adhoc Inspection				Date: 22/01/2018
3564925	cat 1 repairs x 2 . 400 x 400 x 80 mm and 950 x 400 x 80 mm , repaired highway /insp.. john TPD	22/01/2018	800yrds before collingham one stop shop coming from besthorpe	CW Repairs-Bituminous	Internal		Uncommitt	2667846
Batch: 20261561 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jan Saf CW				Date: 05/01/2018
Batch: 20258589 - Inspection Batch				Route: Newark Area 1 Dec Saf CW				Date: 08/12/2017
3561606	pothole repair around gully cat 2 high	08/12/2017	opposite grey horse pub	CW Repairs-Bituminous	Internal		Uncommitt	2664452
Batch: 20253627 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Nov Saf CW				Date: 07/11/2017
Batch: 20251066 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Oct Saf CW				Date: 20/10/2017
Batch: 20245125 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Sep Saf CW				Date: 08/09/2017
Batch: 20240428 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Aug Saf CW				Date: 03/08/2017
Batch: 20237146 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jul Enh CW/FW				Date: 06/07/2017
Batch: 20233620 - Inspection Batch				Route: Adhoc Inspection				Date: 12/06/2017
3550055	pothole	12/06/2017	as mapped , filled during inspections cat 1 high .	CW Repairs-Bituminous	Internal		Uncommitt	2652105
Batch: 20232587 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jun Saf CW				Date: 06/06/2017
Batch: 20227531 - Inspection Batch	No actionable defects found			Route: Newark Area 1 May Saf CW				Date: 02/05/2017
Batch: 20223604 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Apr Saf CW				Date: 04/04/2017
Batch: 20220933 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Mar Saf CW				Date: 14/03/2017
Batch: 20215373 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Feb Saf CW				Date: 06/02/2017

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A1133 - Woodhill Road Junction To Point 25M South-East Of Ql			Feature Type: Street Section			Area: Newark	
Batch: 20215279 - Inspection Batch				Route: Adhoc Inspection				Date: 06/02/2017
3541681	manhole cover. please replace frame and cover	06/02/2017	outside number 6 the cottage	CW Ironwork	Internal		Committed	2643384
Batch: 20215120 - Inspection Batch				Route: Adhoc Inspection				Date: 03/02/2017
3541616	please renew cover and frame , road has been made safe and cones and signage is in place .	03/02/2017	outside number 6 The Cottage , opposite the Grey Horse public house	CW Ironwork	Internal		Committed	2643315
Batch: 20211833 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jan Saf CW				Date: 10/01/2017
Batch: 20208724 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Dec Saf CW				Date: 12/12/2016
Batch: 20204180 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Nov Saf CW				Date: 07/11/2016
Batch: 20199479 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Oct Saf CW				Date: 05/10/2016
Batch: 20196378 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Sep Saf CW				Date: 09/09/2016
Batch: 20192680 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Aug Saf CW				Date: 09/08/2016
Batch: 20189310 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jul Enh CW/FW				Date: 15/07/2016
Batch: 20182749 - Inspection Batch				Route: Newark Area 3 Jun Saf CW				Date: 01/06/2016
3530072	6 x pot holes	01/06/2016	marked on road	CW Repairs-Bituminous	Internal		Uncommitt	2631078
Batch: 20177999 - Inspection Batch	No actionable defects found			Route: Newark Area 3 May Saf CW				Date: 03/05/2016
Batch: 20173880 - Inspection Batch				Route: Newark Area 3 Apr Saf CW				Date: 04/04/2016
3526483	2 x pot holes	04/04/2016	Marked on road	HW CW Pothole Z1	Internal		Uncommitt	2627439
Batch: 20169862 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Mar Saf CW				Date: 03/03/2016
Batch: 20164364 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Feb Saf CW				Date: 01/02/2016
Batch: 20160396 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Jan Saf CW				Date: 06/01/2016

Effective: 01/01/2016 to 30/01/2018
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Besthorpe Road (26822192)

Customer Services

Enquiry No.: 6079009 Logged by: External to Confirm on: 29/01/2018 15:54
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-66855996
 Desc.: Road Pothole - TPD
 TPD
 TPD
 Please use the web link below to update the status of this hazard in the
 Fill That Hole.org.uk database directly: <http://www.fillthathole.org.uk/hazard/146180?key=/d28df/d7c> OUR REFERENCE: #146180 The hazard is lo-cated at: ----- OS GRID
 REFERENCE: SK 83103 62862 DISTRICT: Newark and Sherwood WARD: Collingham and Meering PARISH: Collingham LOCATION DESCRIPTION: south bound carriageway - several large
 holes LOCATION MAP: <http://www.fillthathole.org.uk/hazard/146180/map> Hazard information: ----- HAZARD TYPE: Pothole APPROX. SIZE: 20.0 cm APPROX. DEPTH: 14.0 cm
 APPROX. DISTANCE FROM KERB: 100.0 cm DATE ENCOUNTERED: 2018-01-26 DEFECT DESCRIPTION: large holes FURTHER INFORMATION: <http://www.fillthathole.org.uk/hazard/146180>
 Change History: ----- -- 26 Jan 2018, 5:32pm -- . Submitted by Advisor: Dawn TPD
 Location: A1133 reference SK 83103 62862 Contact:

Plot Number: 2,000.00 Feature Id - Location: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu Feature Type: Street Section
Job Number: 2669047 Defect Number: 3566107

Enquiry No.: 6077199 Logged by: External to Confirm on: 22/01/2018 09:49
 Service: TPD Subject: Highway Insurance TPD Classification: Report or Observation Enquiry Ref: FS66323963
 Desc.: TPD defect reference: 6077183
 Date/Time: 22/01/2018 07:05:00
 Direction of travel: From gainsborough to collingham
 TPD
 Location: See map coordinates and description details Contact:

Enquiry No.: 6077183 Logged by: External to Confirm on: 22/01/2018 08:24
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-66323963
 Desc.: TPD - coming from Gainsborough on the A1133 coming into to collingham quarter of a mile from One stop Store
 TPD
 TPD
 . Submitted by Advisor: Anne TPD
 Location: See map coordinates and description details Contact:

Plot Number: 2,000.00 Feature Id - Location: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu Feature Type: Street Section
Job Number: 2667846 Defect Number: 3564925

Enquiry No.: 6041137 Logged by: External to Confirm on: 02/02/2017 09:10
 Service: Carriageway/Footway Subject: Manholes/Gullies Classification: Report or Observation Enquiry Ref: FS-CASE-12445171
 Desc.: Missing manhole/drain covers - Damaged manhole cover near the grey horse pub on the A1133 - it has risen around 6 inches and could easily cause an RTC. Needs looking at as soon as possible.
 . Submitted by Advisor: Kelly TPD
 Location: See map coordinates and description details Contact:

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Customer Services

Enquiry No.: 3203781

Logged by: John TPD

on: 03/02/2017 11:45

Service: Other

Subject: Other Request (Highways)

Classification: Service Request

Desc.: renew manhole cover .

Location: outside number 6 The Cottage . as mapped

Contact:

Plot Number: 2,000.00

Feature Id - Location: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu

Feature Type: Street Section

Job Number: 2643315

Defect Number: 3541616

Enquiry No.: 61797

Logged by: Pauline TPD

on: 03/04/2017 10:19

Service: Carriageway/Footway

Subject: Carriageway Damage

Classification: Report or Observation

Desc.: Grate sinking & tarmac breaking up around it. Also request for cones left from previous work on opposite of road, at junction Woodhill Rd, be removed please.

Location: by Grey Horse PH

Contact:

Plot Number: 2,000.00

Feature Id - Location: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu

Feature Type: Street Section

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: A1133 - Woodhill Road Junction To Point 25M South-East Of Qu		Feature Type: Street Section		Area: Newark	
2627439	2 x pot holes (HW CW Pothole Z1)	Marked on road	Filled when found (Cat 2H)	Job Completed	04/04/2016	04/04/2016	Act.
2631078	6 x pot holes (CW Repairs-Bituminous)	marked on road	Filled when found (Cat 2L)	Job Completed	01/06/2016	01/06/2016	Act.
2643315	please renew cover and frame , road has been made safe and cones and signage is in place . (CW Ironwork)	outside number 6 The Cottage , opposite the Grey Horse public house	Category 2 (High)	Job Completed	03/02/2017	07/02/2017	Act. NEW/3604452
2643384	manhole cover. please replace frame and cover (CW Ironwork)	outside number 6 the cottage	Category 2 (High)	Job Completed	06/02/2017	07/02/2017	Act. NEW/3604449
2652105	pothole (CW Repairs-Bituminous)	as mapped , filled during inspections cat 1 high .	Filled when found (Cat 1)	Job Completed	12/06/2017	12/06/2017	Act.
2664452	pothole repair around gully cat 2 high (CW Repairs-Bituminous)	opposite grey horse pub	Filled when found (Cat 2H)	Job Completed	08/12/2017	08/12/2017	Act.
2667846	cat 1 repairs x 2 . 400 x 400 x 80 mm and 950 x 400 x 80 mm , repaired highway /insp.. john english (CW Repairs-Bituminous)	800yds before collingham one stop shop coming from besthorpe	Filled when found (Cat 1)	Job Completed	22/01/2018	22/01/2018	Act.
2667847	potholes (CW Repairs-Bituminous)	800 yrd from one stop shop	Filled when found (Cat 2H)	Job Completed	22/01/2018	22/01/2018	Act.
2669047	potholes x 3 cat 1 high repaired (CW Repairs-Bituminous)	opposite water works besthorpe quarry .	Filled when found (Cat 1)	Job Completed	30/01/2018	30/01/2018	Act.
2669048	pothole (CW Repairs-Bituminous)	opposite besthorpe quarry edge of carriageway marked	Category 1	Job Completed	30/01/2018	01/02/2018	Act. NEW-AS/5504776

Effective: 01/01/2016 to 30/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Besthorpe Road (26822192)

Street Works Inspections

Organisation: Anglian Water - ClancyMetering& Dev Services (9100029)

Works Ref: 000053292534

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 06/06/2017 14:24:33
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: TPD	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: near turning for sewage works
Defect Notes:			Position: Footway
			Site Post Code:

Organisation: WPD - 6115 Lincoln West (7011615)

Works Ref: M61150384661

Group No: 1	Site No: 2	Street Authority: Nottinghamshire	Inspected: 05/01/2018 13:14:15
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: TPD	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: OUTSIDE 1 THE BUNGALOW
Defect Notes:			Position: Footway
			Site Post Code:

Works Ref: M61150385746

Group No: 1	Site No: 3	Street Authority: Nottinghamshire	Inspected: 10/11/2016 13:28:49
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: TPD	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: next to the grey horse pub
Defect Notes:			Position: Footway
			Site Post Code:

Street Works Notices

Organisation: Anglian Water - ClancyMetering& Dev Services (9100029)

Works Ref: 000053292534

Version: 6

Work Desc: Disconnection on Cust Req

Notice Type: Registration of Reinstatement - Full

Start: 19/01/2017 00:00:00

Work Status: Works Stopped

Issued: 24/01/2017 10:30:15

Work Type: EToN 4: Minor

Est. End: 23/01/2017

Completion: 23/01/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	near turning for sewage works	Footway	Up to 1.5 Metres of Cover	0.90	0.90	A Permanent Reinstatement	23/01/2017		23/01/2017	23/01/2017

Organisation: NCC - NEWARK (3055004)

Works Ref: 2464

Version: 1

Work Desc: Replacing Speed/Village Sign

Notice Type: 3 Day Initial Notice

Start: 23/06/2016 00:00:00

Work Status: Proposed Works

Issued: 16/06/2016 16:57:01

Work Type: EToN 4: Minor

Est. End: 23/06/2016

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Entry to Collingham Village from Besthorpe	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	23/06/2016			23/06/2016

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Street Works Notices**Organisation:** NCC - NEWARK (3055004)**Works Ref:** 30603044**Version:** 3**Work Desc:** Side Up Footway**Notice Type:** Cancellation**Start:** 04/01/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 12/01/2016 15:57:47**Work Type:** EToN 4: Standard**Est. End:** 19/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	04/01/2016			12/01/2016

Works Ref: 30603134**Version:** 1**Work Desc:** Verge Works**Notice Type:** 10 Day Initial Notice**Start:** 04/03/2016 00:00:00**Work Status:** Proposed Works**Issued:** 31/03/2016 10:01:56**Work Type:** EToN 4: Standard**Est. End:** 08/03/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Collingham and Besthorpe	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	04/03/2016			08/03/2016

Works Ref: 30603330**Version:** 4**Work Desc:** Planing and Patching Work**Notice Type:** Works Stop**Start:** 03/10/2016 00:00:00**Work Status:** Works Stopped**Issued:** 31/10/2016 11:10:25**Work Type:** EToN 4: Major**Est. End:** 21/10/2016**Completion:** 21/10/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A1133 through Collingham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	21/10/2016			21/10/2016

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** /A1133COLLINGHAM/03**Version:** 5**Work Desc:** Surface Dressing**Notice Type:** Works Stop**Start:** 26/04/2017 00:00:00**Work Status:** Works Stopped**Issued:** 04/05/2017 13:18:16**Work Type:** EToN 4: Major**Est. End:** 26/04/2017**Completion:** 26/04/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Besthorpe Road Collingham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	26/04/2017			26/04/2017

Works Ref: /BESTCOLLGULLYS**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 27/09/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 02/10/2017 08:14:56**Work Type:** EToN 4: Minor**Est. End:** 29/09/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A1133 Besthorpe and Collingham areas.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	27/09/2017			29/09/2017

Works Ref: 40806281**Version:** 2**Work Desc:** Surface Dressing**Notice Type:** Revised Duration Estimate**Start:** 09/05/2017 00:00:00**Work Status:** Proposed Works**Issued:** 04/05/2017 13:18:30**Work Type:** EToN 4: Major**Est. End:** 10/05/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Besthorpe Road Collingham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	09/05/2017			09/05/2017

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 40806446**Version:** 1**Work Desc:** Surface Dressing**Notice Type:** 3 Month Initial Notice**Start:** 21/05/2017 00:00:00**Work Status:** Proposed Works**Issued:** 08/05/2017 15:18:44**Work Type:** EToN 4: Major**Est. End:** 21/05/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Besthorpe Road Collingham - road closed between 08:00hrs & 18:30hrs	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	21/05/2017			21/05/2017

Works Ref: 40806447**Version:** 1**Work Desc:** Surface Dressing**Notice Type:** 3 Month Initial Notice**Start:** 22/05/2017 00:00:00**Work Status:** Proposed Works**Issued:** 08/05/2017 15:20:06**Work Type:** EToN 4: Major**Est. End:** 22/05/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Besthorpe Road Collingham - road closed between 09:30hrs & 20:00hrs	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	22/05/2017			22/05/2017

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000011608867**Version:** 4**Work Desc:** Hydrant Reset lid Job in Carriageway (Hot Rolled Asphalt)**Notice Type:** Registration of Reinstatement - Full**Start:** 18/05/2017 00:00:00**Work Status:** Works Stopped**Issued:** 18/05/2017 13:51:05**Work Type:** EToN 4: Minor**Est. End:** 22/05/2017**Completion:** 18/05/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opp grey horse	Carriageway	Up to 1.5 Metres of Cover	1.00	0.85	A Permanent Reinstatement	18/05/2017		18/05/2017	19/05/2017

Organisation: WPD - 6115 Lincoln West (7011615)**Works Ref:** M61150384543**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 27/04/2016 08:00:00**Work Status:** Works Stopped**Issued:** 06/05/2016 08:38:17**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 04/05/2016**Completion:** 30/04/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outsdie hollybrooke house	Verge	Up to 1.5 Metres of Cover	0.90	0.77	A Permanent Reinstatement	28/04/2016		28/04/2016	04/05/2016
2	outside hollybrooke house	Footway	Up to 1.5 Metres of Cover	3.20	0.40	A Permanent Reinstatement	29/04/2016		29/04/2016	
3	outside hollybrooke house	Footway	Up to 1.5 Metres of Cover	1.50	1.30	A Permanent Reinstatement	29/04/2016		29/04/2016	
4	outside hollybrooke house	Footway	Up to 1.5 Metres of Cover	2.30	1.30	A Permanent Reinstatement	29/04/2016		29/04/2016	

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Besthorpe Road (26822192)

Street Works Notices**Organisation:** WPD - 6115 Lincoln West (7011615)**Works Ref:** M61150384661**Version:** 5**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 04/01/2016 12:30:00**Work Status:** Works Stopped**Issued:** 12/01/2016 10:39:42**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 08/01/2016**Completion:** 07/01/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 1 THE BUNGALOW	Footway	Up to 1.5 Metres of Cover	1.80	0.50 A Permanent Reinstatement	07/01/2016		07/01/2016	08/01/2016
2	OUTSIDE 1 THE BUNGALOW	Footway	Up to 1.5 Metres of Cover	2.60	0.70 A Permanent Reinstatement	07/01/2016		07/01/2016	
3	OUTSIDE 1 THE BUNGALOW	Footway	Up to 1.5 Metres of Cover	2.50	1.10 A Permanent Reinstatement	07/01/2016		07/01/2016	
4	OUTSIDE 1 THE BUNGALOW	Verge	Up to 1.5 Metres of Cover	20.00	1.10 A Permanent Reinstatement	07/01/2016		07/01/2016	
5	OUTSIDE 1 THE BUNGALOW	Verge	Up to 1.5 Metres of Cover	1.10	1.00 A Permanent Reinstatement	07/01/2016		07/01/2016	

Works Ref: M61150385746**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair HV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 09/05/2016 18:00:00**Work Status:** Works Stopped**Issued:** 18/05/2016 08:52:59**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 13/05/2016**Completion:** 13/05/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	next to the grey horse pub	Verge	Up to 1.5 Metres of Cover	3.00	0.50 A Permanent Reinstatement	12/05/2016		12/05/2016	13/05/2016
2	next to the grey horse pub	Verge	Up to 1.5 Metres of Cover	2.00	1.20 A Permanent Reinstatement	12/05/2016		12/05/2016	
3	next to the grey horse pub	Footway	Up to 1.5 Metres of Cover	1.70	0.45 A Permanent Reinstatement	12/05/2016		12/05/2016	
4	next to the grey horse pub	Footway	Up to 1.5 Metres of Cover	5.10	1.20 A Permanent Reinstatement	12/05/2016		12/05/2016	
5	next to the grey horse pub	Footway	Up to 1.5 Metres of Cover	3.50	0.90 A Permanent Reinstatement	12/05/2016		12/05/2016	

Works Ref: M61152006967D**Version:** 5**Work Desc:** 1 joint hole in tarmac footway for reinforcement scheme - works in conjunction with DY615M61152006967A, B, C and D**Notice Type:** Registration of Reinstatement - Full**Start:** 21/08/2017 00:00:00**Work Status:** Works Stopped**Issued:** 01/09/2017 10:52:52**Work Type:** EToN 4: Standard**Est. End:** 25/08/2017**Completion:** 24/08/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 1	Footway	Up to 1.5 Metres of Cover	8.00	1.89 A Permanent Reinstatement	24/08/2017		24/08/2017	25/08/2017