

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Collingham Road (26822229)

Street: Collingham Road (26822229)

Locality: Besthorpe, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feature No.: 2,000.00	Feature Id - Locn.: A1133 - Point 25M South-East Of Quarry Access Road Junction			Feature Type: Street Section			Area: Newark	
Batch: 20265562 - Inspection Batch				Route: Adhoc Inspection				Date: 30/01/2018
3566126	potholes	30/01/2018	0.7 miles from one stop shop collingham heading north to besthorpe , just before bend blackand white chevrons , near tractor turning sign	CW Repairs-Bituminous	Internal		Committed	2669069
Batch: 20261562 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jan Saf CW				Date: 05/01/2018
Batch: 20261062 - Inspection Batch	No actionable defects found			Route: Review Outcome-Wayne Prince				Date: 03/01/2018
Batch: 20258584 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Dec Saf CW				Date: 08/12/2017
Batch: 20253628 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Nov Saf CW				Date: 07/11/2017
Batch: 20251067 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Oct Saf CW				Date: 20/10/2017
Batch: 20245126 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Sep Saf CW				Date: 08/09/2017
Batch: 20240433 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Aug Saf CW				Date: 03/08/2017
Batch: 20237149 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jul Enh CW/FW				Date: 06/07/2017
Batch: 20232588 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jun Saf CW				Date: 06/06/2017
Batch: 20227663 - Inspection Batch				Route: Newark Area 1 May Saf CW				Date: 02/05/2017
3547498	filled during inspections with assistants cat 2 high repaired	02/05/2017	as mapped	CW Repairs-Bituminous	Internal		Uncommitt	2649386
3547497	filled during inspections cat 2 high	02/05/2017	as mapped	CW Repairs-Bituminous	Internal		Uncommitt	2649388
3547496	filled during inspections .. cat 2 high	02/05/2017	as mapped	CW Repairs-Bituminous	Internal		Uncommitt	2649387
Batch: 20223605 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Apr Saf CW				Date: 04/04/2017
Batch: 20220937 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Mar Saf CW				Date: 14/03/2017
Batch: 20215374 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Feb Saf CW				Date: 06/02/2017
Batch: 20211832 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jan Saf CW				Date: 10/01/2017

Effective: 01/01/2016 to 30/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Collingham Road (26822229)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A1133 - Point 25M South-East Of Quarry Access Road Junction			Feature Type: Street Section			Area: Newark	
Batch: 20208723 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Dec Saf CW				Date: 12/12/2016
Batch: 20204181 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Nov Saf CW				Date: 07/11/2016
Batch: 20201325 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Oct Saf CW				Date: 19/10/2016
Batch: 20196380 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Sep Saf CW				Date: 09/09/2016
Batch: 20192682 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Aug Saf CW				Date: 09/08/2016
Batch: 20189311 - Inspection Batch	No actionable defects found			Route: Newark Area 1 Jul Enh CW/FW				Date: 15/07/2016
Batch: 20182960 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Jun Saf CW				Date: 01/06/2016
Batch: 20178005 - Inspection Batch	No actionable defects found			Route: Newark Area 3 May Saf CW				Date: 03/05/2016
Batch: 20173900 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Apr Saf CW				Date: 04/04/2016
Batch: 20170743 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Mar Saf CW				Date: 07/03/2016
Batch: 20164366 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Feb Saf CW				Date: 01/02/2016
Batch: 20160402 - Inspection Batch	No actionable defects found			Route: Newark Area 3 Jan Saf CW				Date: 06/01/2016

Customer Services**Enquiry No.:** 6064218**Logged by:** External to Confirm**on:** 14/09/2017 18:40**Service:** Carriageway/Footway**Subject:** Carriageway Obstruction**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-58743881**Desc.:** Road obstructions - Notts police reporting branches on the North Bound carriageway of Besthorpe road, A1133, half way between Collingham and Besthorpe.

Branches said to be large, spread over 100 metres. Looks like they have come off a lorry.

customer Called from TPD - called - but went to answer phone. No size details.

TPD

Incident number - 67914092017 . Submitted by Advisor: Robert TPD

Location: See map coordinates and description details**Contact:****Enquiry No.:** 2504915**Logged by:** Mike TPD**on:** 28/06/2017 14:44**Service:** Trees/Verges**Subject:** Weeds**Classification:** Report or Observation**Desc.:** Weeds in drainage gutter and kerblin**Location:** footway from Collingham to Besthorpe**Contact:**

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Collingham Road (26822229)

Street Works Notices**Organisation:** NCC - NEWARK (3055004)**Works Ref:** 30603045**Version:** 3**Work Desc:** Side Up Footway**Notice Type:** Cancellation**Start:** 04/01/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 12/01/2016 15:58:19**Work Type:** EToN 4: Standard**Est. End:** 19/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	04/01/2016			12/01/2016

Works Ref: 30603065**Version:** 1**Work Desc:** Tree Cutting**Notice Type:** 3 Day Initial Notice**Start:** 29/01/2016 00:00:00**Work Status:** Proposed Works**Issued:** 13/01/2016 15:59:34**Work Type:** EToN 4: Minor**Est. End:** 29/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Near West View Farm	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	29/01/2016			29/01/2016

Works Ref: 30603084**Version:** 1**Work Desc:** Siding up footway**Notice Type:** 10 Day Initial Notice**Start:** 08/02/2016 00:00:00**Work Status:** Proposed Works**Issued:** 29/01/2016 10:36:34**Work Type:** EToN 4: Standard**Est. End:** 12/02/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Collingham and Besthorpe	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	08/02/2016			12/02/2016

Works Ref: 30603135**Version:** 1**Work Desc:** Verge Works**Notice Type:** 10 Day Initial Notice**Start:** 04/03/2016 00:00:00**Work Status:** Proposed Works**Issued:** 31/03/2016 10:04:24**Work Type:** EToN 4: Standard**Est. End:** 08/03/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Collingham and Besthorpe	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	04/03/2016			08/03/2016

Organisation: NRSWA - BT (0030005)**Works Ref:** WP00100500212337300**Version:** 2**Work Desc:** Replace 1 jointbox frame and cover(s) (915mm x 445mm) in Footway**Notice Type:** Cancellation**Start:** 25/05/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 24/05/2016 14:21:04**Work Type:** EToN 4: Minor**Est. End:** 27/05/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	IN VERGE, APPROX 20 METRES NORTH OF OPPOSITE BRICKYARD COTTAGE, COLLINGHAM ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	25/05/2016			27/05/2016

Effective: 01/01/2016 to 30/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Collingham Road (26822229)

Street Works Notices

Organisation: NRSWA - BT (0030005)

Works Ref: WP00100500212337301

Version: 3

Work Desc: Replace 1 jointbox frame and cover(s) (915mm x 445mm) in Footway

Notice Type: Registration of Reinstatement - Full

Start: 27/05/2016 14:08:00

Work Status: Works Stopped

Issued: 02/06/2016 10:16:44

Work Type: EToN 4: Immediate - Urgent

Est. End: 27/05/2016

Completion: 27/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN VERGE, APPROX 20 METRES NORTH OF OPPOSITE BRICKYARD COTTAGE, COLLINGHAM ROAD	Verge	Up to 1.5 Metres of Cover	1.60	0.90	A Permanent Reinstatement	27/05/2016		27/05/2016	27/05/2016

Works Ref: WP00100500212619500

Version: 4

Work Desc: Excavate 1 location (s) to expose/ repair existing ducts in Footway

Notice Type: Registration of Reinstatement - Full

Start: 24/05/2016 12:30:00

Work Status: Works Stopped

Issued: 14/06/2016 15:24:07

Work Type: EToN 4: Immediate - Urgent

Est. End: 26/05/2016

Completion: 26/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP NORTH CNR ENT TO BRICKYARD COTTAGE, COLLINGHAM ROAD	Verge	Up to 1.5 Metres of Cover	1.10	0.70	A Permanent Reinstatement	26/05/2016		26/05/2016	26/05/2016