

Effective: 12/01/2018 to 13/03/2018

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Netherfield Lane (24621959)

Street: Netherfield Lane (24621959)

Locality: Meden Vale, Nottinghamshire

Area: Mansfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,002.00	Feature Id - Locn.: From Elkesley Road to Boundary			Feature Type: Street Section			Area: Mansfield	
Batch: 20269474 - Inspection Batch				Route: Mansfield East Feb Saf CW				Date: 22/02/2018
3569048	11 number infill areas	22/02/2018	lamp 61 (4),lamp 60 (5),lamp 62 (2)	CW Repairs-Bituminous	Internal		Committed	2672011
Batch: 20268830 - Inspection Batch				Route: Adhoc Inspection				Date: 19/02/2018
3568380	3 number infill areas	19/02/2018	severn trent pumping station on boundary (3)	CW Repairs-Bituminous	Internal		Committed	2671337
Batch: 20264138 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2018
3565119	Manholes/Gullies - Missing manhole/drain covers - There is a missinggully lid laid on verge put back on by inspectors made safe with cone provide new grate stats required	23/01/2018	prior gleabthorpe farm	CW Ironwork	Internal		Committed	2668041
Batch: 20264136 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2018
3565118	Manholes/Gullies - Missing manhole/drain covers - There is a missinggully lid laid on grass verge put back in frame and made safe with cone on driven inspection	23/01/2018	prior gleabthorpe farm	CW Ironwork	Internal		Uncommitt	2668040
Batch: 20264080 - Inspection Batch				Route: Mansfield East Jan Saf CW				Date: 23/01/2018
3565066	11 number infill areas passed to operations gang	23/01/2018	opp side S T W A entrance (3),200m prior boundary (3),top side last cottage (2),lamp 70 (2),lamp 69 (1)	CW Repairs-Bituminous	Internal		Committed	2667988

Customer Services

Enquiry No.: 6085574 **Logged by:** External to Confirm **on:** 12/03/2018 18:50
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-70132148
Desc.: Road Pothole - See above! . Online report
Location: Heading towards Church Warsop on road identified before a set of houses which are on the right of you as you drive in the 30 mile per hour area. **Contact:**

Plot Number: 2,002.00 **Feature Id - Location:** From Elkesley Road to Boundary **Feature Type:** Street Section
Job Number: 2673893 **Defect Number:** 3570905

Enquiry No.: 6082042 **Logged by:** External to Confirm **on:** 16/02/2018 14:51
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68255880
Desc.: Road Pothole - deepening long pothole . Online report
Location: Netherfield Lane, between Meden Vale and Budby on a `S` bend at cycle route crossing point. **Contact:**

Plot Number: 2,002.00 **Feature Id - Location:** From Elkesley Road to Boundary **Feature Type:** Street Section
Job Number: 2671337 **Defect Number:** 3568380

Effective: 12/01/2018 to 13/03/2018
 Display Action Officer: No

Feature No.: 2002.00 to 2002.00
 Street: Netherfield Lane (24621959)

Customer Services

Enquiry No.: 6079315 **Logged by:** External to Confirm **on:** 30/01/2018 17:00
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66951275
Desc.: Other enquiry - Customer is calling due to the fact that there have been a series of crashes on this road in the last few months. They have twice now had someone crash through their garden wall and this has led to a fatality. Customer believes that the road speed limit needs to be enforced all the way along the road to ensure people are not speeding. Could someone please come out and take a look at this and also if you could please call the customer just to let them know that something is being looked at as they're yet to receive a response. . Submitted by Advisor: Shane Sims -
 - -
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6077720 **Logged by:** External to Confirm **on:** 23/01/2018 10:13
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66433529
Desc.: Missing manhole/drain covers - There is a missing drain cover on Netherfield road. Caller described the location as being between the Budby pumping station and the railway bridge. As you go under the bridge there is a house on the left and it is on the opposite side of the road. If you get to the pumping station you have gone too far. The cover for the drain is actually propped up at the side. . Submitted by Advisor: Abi Gee
Location: See map coordinates and description details **Contact:**

Plot Number: 2,002.00 **Feature Id - Location:** From Elkesley Road to Boundary **Feature Type:** Street Section
Job Number: 2668040 **Defect Number:** 3565118

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,002.00	Feature Id - Locn.: From Elkesley Road to Boundary		Feature Type: Street Section		Area: Mansfield	
2667988	11 number infill areas passed to operations gang (CW Repairs-Bituminous)	opp side S T W A entrance (3),200m prior boundary (3),top side last cottage (2),lamp 70 (2),lamp 69 (1)	Category 1	Job Completed	23/01/2018	23/01/2018	Act. MAN/3504305
2668040	Manholes/Gullies - Missing manhole/drain covers - There is a missinggully lid laid on grass verge put back in frame and made safe with cone on driven inspection (CW Ironwork)	prior gleabthorpe farm	SELECT PRIORITY	Job Cancelled	23/01/2018	23/01/2018	Est.
2668041	Manholes/Gullies - Missing manhole/drain covers - There is a missinggully lid laid on verge put back on by inspectors made safe with cone provide new grate stats required (CW Ironwork)	prior gleabthorpe farm: STATS 458835 - 369992	Category 2 (High)	Job Completed	23/01/2018	28/01/2018	Act. MAN/3504309
2671337	3 number infill areas (CW Repairs-Bituminous)	severn trent pumping station on boundary (3)	Category 2 (High)	Job Completed	19/02/2018	22/02/2018	Act. MAN-AS/5404432
2672011	11 number infill areas (CW Repairs-Bituminous)	lamp 61 (4),lamp 60 (5),lamp 62 (2)	Category 2 (High)	Job Completed	22/02/2018	05/03/2018	Act. MAN-AS/5404471

Effective: 12/01/2018 to 13/03/2018

Display Action Officer: No

Feature No.: 2002.00 to 2002.00

Street: Netherfield Lane (24621959)

Street Works Inspections

Organisation: NRSWA Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000680034

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 12/01/2018 09:48:59
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: 07557895771	Site Location: IN FOOTPATH OS 6
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 40808956

Version: 1

Work Desc: Replace broken Gullylid

Notice Type: 3 Day Initial Notice

Start: 28/01/2018 00:00:00

Work Status: Proposed Works

Issued: 24/01/2018 13:15:52

Work Type: EToN 4: Minor

Est. End: 28/01/2018

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Netherfield Lane Meden Vale, near to Gleadthopre Cottage	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	28/01/2018			28/01/2018

Organisation: NRSWA - BT (0030005)

Works Ref: PP25W00001623842132

Version: 8

Work Desc: Remove Kiosk and Reinstate

Notice Type: Registration of Reinstatement - Full

Start: 13/03/2018 00:00:00

Work Status: Works Stopped

Issued: 23/03/2018 16:34:14

Work Type: EToN 4: Minor

Est. End: 15/03/2018

Completion: 14/03/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	NETHERFIELD LANE, ON JUNCTION TO EGMANTON ROAD, NG20 9PF	Verge	Up to 1.5 Metres of Cover	1.40	1.40 A Permanent Reinstatement	14/03/2018		14/03/2018	14/03/2018

Organisation: NRSWA Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000680034

Version: 3

Work Desc: Trace, then excavate to repair gas escape and reinstate where possible

Notice Type: Registration of Reinstatement - Full

Start: 10/01/2018 12:48:00

Work Status: Works Stopped

Issued: 12/01/2018 11:55:24

Work Type: EToN 4: Immediate - Emergency

Est. End: 16/01/2018

Completion: 12/01/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	IN FOOTPATH OS 6	Footway	Up to 1.5 Metres of Cover	1.00	0.70 A Permanent Reinstatement	11/01/2018		11/01/2018	16/01/2018