


Request for Information: Ref NCC-031146-18 Inspections undertaken on carriageways

Thank you for your request for information relating to inspections undertaken on carriageways I can now let you have the following information in response to the questions you raised.

**Street Sections addressed** 



а	Station Road	26822223
b	Southwell Road	26808597
С	Lower Kirklington Road	26822708
d	Lower Kirklington Road	26805177
e	Station Road	26805195
f	Harlow Field House to Goldhill Cott	26808598

1) Station Road, Edingley from its junction with Southwell Road to its junction with Lower Kirklington Road. (Shown incorrectly on the NCC website of 'Road Publicly Maintained Status' as Station Road, Kirklington.)

Section a on plan: Station Road 26822223

•	The hierarchy classification			
	Net.Priority	4b - Local Access Road		

• The intended frequency of safety inspections

Carriageway Inspection Frequen	Annual (once a year)	
Footway Inspection Frequency	Annual (once a year)	

 The Dates of all safety inspections undertaken on the carriageway between 1 Jan 2016 and 30 April 2018.
 Contained in the attached Street History report

 Details of all carriageway defects identified during the safety inspections and at any other time during the period at 2 above.

Contained in the attached Street History report

The dates and detail of remedial action taken, if any, in relation to the identified defects. Contained in the attached Street History report

2) Southwell Road, Edingley from its junction with Station Road to its junction with Lower Kirklington Road. (Shown incorrectly on the NCC website of 'Road Publicly Maintained Status' as Station Road, Kirklington.)

Section **b** on plan: Station Road 26822223

•	The hierarchy classification		
	Net.Priority	3b - Secondary Distributor	

The intended frequency of safety inspections

Camageway Inspection Frequen	Monthly
Footway Inspection Frequency	Annual (once a year)

• The Dates of all safety inspections undertaken on the carriageway between 1 Jan 2016 and 30 April 2018.

Contained in the attached Street History report

 Details of all carriageway defects identified during the safety inspections and at any other time during the period at 2 above.

Contained in the attached Street History report

The dates and detail of remedial action taken, if any, in relation to the identified defects. Contained in the attached Street History report

3) Lower Kirklington Road, Edingley from the parish boundary to the east to its junction with Station Road, Edingley. (Shown correctly on the NCC website of 'Road Publicly Maintained Status' as extending from the parish boundary to the east but incorrectly as ending at its junction with Southwell Road. This entry appears to show that the part of the road between the junctions of Southwell Road and Station Road is neither named or maintained by Notts CC, which is clearly incorrect)

Section c and d on plan: Lower Kirlington Road, Edingley and Lower Kirklinton Road, Halam respectively

Note: Section c and d were combined up to 27/02/2017 (as Lower Kirklington Road, Halam 26805177) when section c was split/created. Both Street history reports attached.

The hierarchy classification			
Section c Net.Priority		Publicly Maintainable	
Section d	Net.Priority	3b - Secondary Distributor	

		Carriageway Inspection Frequen	Annual (once a year)	
	Continuo	Footway Inspection Frequency	Annual (once a year)	
	Section c		r <u>-</u>	_
		Carriageway Inspection Frequen	Monthly	
	Section d	Footway Inspection Frequency	Annual (once a year)	
	Section a			_
•	The Dates of all safety inspections undertaken on the carriageway between 1 Jan 2016 and 30 April 2018.  Contained in the attached Street History report			en 1 Jan 2016
•	Details of all carriageway defects identified during the safety inspections and at any other time during the period at 2 above.  Contained in the attached Street History report			and at any
	The dates and detail of remedial action taken, if any, in relation to the identified defects. Contained in the attached Street History report			ntified defects.
4)	Station Road, Edwith Lower Kirkl	lingley from the village itsoington Road.	elf in an easterly direction	to its junction
	Section e	and f on plan: Station Road	and Harlow Field House to	Goldhill Cott
		·		
•		rarchy classification	! ^ D!	
	Section e and f	Net.Priority 4b - Lo	cal Access Road	
•	The intended freq	uency of safety inspections		
		Camageway Inspection F		
	Section e and f	Footway Inspection Frequency	Jency Annual (once a year)	
•	The Dates of all safety inspections undertaken on the carriageway between 1 Jan 2016 and 30 April 2018.  Contained in the attached Street History report			
•	<ul> <li>Details of all carriageway defects identified during the safety inspections and at any other time during the period at 2 above.</li> <li>Contained in the attached Street History report</li> </ul>			
		etail of remedial action taken attached Street History repo		ntified defects.

The intended frequency of safety inspections

We hope this now satisfies your request, and should you have any further enquiries please do not hesitate to contact me directly using the contact details below. In addition and for future reference Nottinghamshire County Council regularly publish previous Freedom of Information Requests and answers on our website, under Disclosure logs, available at the following link:

http://site.nottinghamshire.gov.uk/thecouncil/democracy/freedom-of-information/disclosure-log/

Complaints & Information Team, Nottinghamshire County Council, County Hall, Loughborough Rd, West Bridgford, Nottingham, NG2 7QP

If you are unhappy with the service you have received in relation to your request and wish to make a complaint or request a review of our decision, you should write to the Team Manager, Complaints and Information Team, County Hall, West Bridgford, Nottingham, NG2 7QP or email complaints@nottscc.gov.uk.

Yours sincerely

Name Jilly Walden Position Complaints information and Mediation Officer Nottinghamshire County Council