

Effective: 01/01/2016 to 30/04/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Lower Kirklington Road (26822708)

Street: Lower Kirklington Road (26822708)

Locality: EDINGLEY, NEWARK, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	From junction with Station Road to Lower Kirklington Road, Hale	Feature Type:	Street Section		Area: Newark	
Batch:	20262763 - Inspection Batch			Route:	Newark Area 2 Jan Enh CW/FW		Date:	15/01/2018
No actionable defects found								