

Effective: 01/01/2016 to 30/04/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26808597)

Street: Southwell Road (26808597)

Locality: Kirklington, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C25 - A617 Junction, Kirklington To Lower Kirklington Road - Kir			Feature Type: Street Section			Area: Newark	
Batch: 20277470 - Inspection Batch			Route: Newark Area 2 Apr Saf CW				Date: 13/04/2018	
No actionable defects found								
Batch: 20273651 - Inspection Batch			Route: Newark Area 2 Mar Saf CW				Date: 21/03/2018	
3572065	potholes	21/03/2018	near osmanthorpe manor marked	CW Repairs-Bituminous	Internal		Committed	2675071
Batch: 20269178 - Inspection Batch			Route: Adhoc Inspection				Date: 20/02/2018	
3568758	potholes	20/02/2018	near the green private rd marked	CW Repairs-Bituminous	Internal		Committed	2671719
Batch: 20269176 - Inspection Batch			Route: Adhoc Inspection				Date: 20/02/2018	
3568756	potholes	20/02/2018	near edingley turn off	CW Repairs-Bituminous	Internal		Committed	2671717
Batch: 20267297 - Inspection Batch			Route: Newark Area 2 Feb Saf CW				Date: 07/02/2018	
No actionable defects found								
Batch: 20262761 - Inspection Batch			Route: Newark Area 2 Jan Enh CW/FW				Date: 15/01/2018	
No actionable defects found								
Batch: 20260066 - Inspection Batch			Route: Newark Area 2 Dec Saf CW				Date: 20/12/2017	
No actionable defects found								
Batch: 20254142 - Inspection Batch			Route: Newark Area 2 Nov Saf CW				Date: 09/11/2017	
No actionable defects found								
Batch: 20248820 - Inspection Batch			Route: Newark Area 2 Oct Saf CW				Date: 05/10/2017	
No actionable defects found								
Batch: 20246648 - Inspection Batch			Route: Newark Area 2 Sep Saf CW				Date: 20/09/2017	
3555624	pothole	20/09/2017	50m from junction of lower kirklington rd marked	CW Repairs-Bituminous	Internal		Committed	2658140
Batch: 20243586 - Inspection Batch			Route: Newark Area 2 Aug Saf CW				Date: 30/08/2017	
No actionable defects found								
Batch: 20239381 - Inspection Batch			Route: Newark Area 2 Jul Saf CW				Date: 25/07/2017	
No actionable defects found								
Batch: 20233807 - Inspection Batch			Route: Newark Area 2 Jun Saf CW				Date: 13/06/2017	
No actionable defects found								
Batch: 20229459 - Inspection Batch			Route: Newark Area 2 May Saf CW				Date: 10/05/2017	
No actionable defects found								
Batch: 20226424 - Inspection Batch			Route: Newark Area 2 Apr Saf CW				Date: 24/04/2017	
No actionable defects found								
Batch: 20220085 - Inspection Batch			Route: Newark Area 2 Mar Saf CW				Date: 07/03/2017	
No actionable defects found								
Batch: 20219026 - Inspection Batch			Route: Adhoc Inspection				Date: 28/02/2017	
3543497	Carriageway Pothole	28/02/2017	next to junc with the green, marked	CW Repairs-Bituminous	Internal		Committed	2645227

Effective: 01/01/2016 to 30/04/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26808597)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C25 - A617 Junction, Kirklington To Lower Kirklington Road - Kir			Feature Type: Street Section			Area: Newark	
Batch: 20216078 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Feb Saf CW				Date: 09/02/2017
Batch: 20212819 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jan Enh CW/FW				Date: 17/01/2017
Batch: 20209431 - Inspection Batch				Route: Newark Area 2 Dec Saf CW				Date: 19/12/2016
3539340 pothole		19/12/2016	nr osmanthorpe manor	CW Repairs-Bituminous	Internal		Uncommitt	2640973
Batch: 20204994 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Nov Saf CW				Date: 14/11/2016
Batch: 20200611 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Oct Saf CW				Date: 13/10/2016
Batch: 20195666 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Sep Saf CW				Date: 06/09/2016
Batch: 20192657 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 09/08/2016
3533306 pothole		09/08/2016	outside the mill house marked	CW Repairs-Bituminous	Internal		Committed	2634471
Batch: 20190267 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jul Saf CW				Date: 25/07/2016
Batch: 20184099 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jun Saf CW				Date: 07/06/2016
Batch: 20180925 - Inspection Batch	No actionable defects found			Route: Newark Area 2 May Saf CW				Date: 19/05/2016
Batch: 20174482 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Apr Saf CW				Date: 06/04/2016
Batch: 20170764 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Mar Saf CW				Date: 07/03/2016
Batch: 20164771 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Feb Saf CW				Date: 02/02/2016
Batch: 20161860 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jan Enh CW/FW				Date: 14/01/2016

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: C25 - A617 Junction, Kirklington To Lower Kirklington Road - Kir			Feature Type: Street Section		Area: Newark	
2634471 pothole (CW Repairs-Bituminous)	outside the mill house marked		Category 2 (High)	Job Completed	09/08/2016	10/08/2016	Act. NEW-AS/5501613
2640973 pothole (CW Repairs-Bituminous)	nr osmanthorpe manor		Filled when found (Cat 1)	Job Completed	19/12/2016	19/12/2016	Act.
2645227 Carriageway Pothole (CW Repairs-Bituminous)	next to junc with the green, marked		Category 2 (High)	Job Completed	28/02/2017	01/03/2017	Act. NEW-AS/5502525

Effective: 01/01/2016 to 30/04/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26808597)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C25 - A617 Junction, Kirklington To Lower Kirklington Road - Kir		Feature Type: Street Section		Area: Newark	
2658140	pothole (CW Repairs-Bituminous)	50m from junction of lower kirklington rd marked	Category 2 (Low)	Job Completed	20/09/2017	21/09/2017	Act. NEW-AS/5503855
2671717	potholes (CW Repairs-Bituminous)	near edingley turn off	Category 2 (Low)	Job Completed	20/02/2018	12/04/2018	Act. NEW/3608174
2671719	potholes (CW Repairs-Bituminous)	near the green private rd marked	Category 2 (High)	Job Completed	20/02/2018	05/03/2018	Act. NEW/3608189
2675071	potholes (CW Repairs-Bituminous)	near osmanthorpe manor marked	Category 2 (Low)	Job Completed	21/03/2018	16/05/2018	Act. NEW/3608784