

Effective: 01/01/2016 to 30/04/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Station Road (26805195)

Street: Station Road (26805195)

Locality: Edingley, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> Main Street, Edingley To Station Road, Kirklington - Edingley			<b>Feature Type:</b> Street Section		<b>Area:</b> Newark		
<b>Batch:</b> 20262766 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Enh CW/FW				<b>Date:</b> 15/01/2018
No actionable defects found								
<b>Batch:</b> 20213081 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Enh CW/FW				<b>Date:</b> 18/01/2017
No actionable defects found								
<b>Batch:</b> 20183748 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 06/06/2016
3530297	in stall new glasdots	06/06/2016	from lc7 through bends away from village marked	Bollard Repairs	Internal		Committed	2631312
<b>Batch:</b> 20162641 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Enh CW/FW				<b>Date:</b> 20/01/2016
No actionable defects found								

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> Main Street, Edingley To Station Road, Kirklington - Edingley			<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2631312	in stall new glasdots (Bollard Repairs)	from lc7 through bends away from village marked	Category 2 (Low)	Job Completed	06/06/2016	02/08/2016	Act. NEW/3603786