

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Street: Stamford Road (33001446)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: From Trevor Road to Rufford Way			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20227287 - Inspection Batch				Route: Adhoc Inspection				Date: 27/04/2017
3547336	Defect made safe	27/04/2017	Opposite property number 105	CW Repairs-Bituminous	Internal		Uncommitt	2649219
Batch: 20223880 - Inspection Batch				Route: Adhoc Inspection				Date: 05/04/2017
3545939	Defect made safe.	05/04/2017	Outside house number 121	CW Repairs-Bituminous	Internal		Uncommitt	2647752
Batch: 20219359 - Inspection Batch				Route: Adhoc Inspection				Date: 02/03/2017
3543668	Defect made safe	02/03/2017	Outside house number 103	CW Repairs-Bituminous	Internal		Uncommitt	2645409
Batch: 20215389 - Inspection Batch				Route: Adhoc Inspection				Date: 06/02/2017
3541739	Total of 9 obsolete slabs are protruding from uplift by Highway tree and home owner illegally riding over the footpath which notice has been served to him . Slabs require removing and replacing with Bitmac - defects are marked up.	06/02/2017	Outside house number 119	FW Repairs-Bituminous	Internal		Committed	2643449
Batch: 20214933 - Inspection Batch				Route: Rush Area 2 Feb Enh CW/FW				Date: 08/02/2017
3541505	Defect made safe during inspection	02/02/2017	Outside house number 39	CW Repairs-Bituminous	Internal		Uncommitt	2643187
Batch: 20213212 - Inspection Batch				Route: Adhoc Inspection				Date: 19/01/2017
3540773	Defect made safe	19/01/2017	Outside house number 121	CW Repairs-Bituminous	Internal		Uncommitt	2642434
Batch: 20211032 - Inspection Batch				Route: Adhoc Inspection				Date: 05/01/2017
3539874	Overlay - Various sized wearing course erosion (total of 13) along street section requires making safe . Defects also include a old reinstatement which is slightly sunken adjacent to L / C 18 , defects are marked up .	05/01/2017	In between the junctions of Alford road & Rodney road	CW Repairs-Bituminous	Internal		Committed	2641519
Batch: 20206245 - Inspection Batch				Route: Rush Area 2 Nov Saf CW				Date: 25/11/2016
	No actionable defects found							
Batch: 20204077 - Inspection Batch				Route: Adhoc Inspection				Date: 07/11/2016
3537251	Defect made safe.	07/11/2016	Outside house number 93	CW Repairs-Bituminous	Internal		Uncommitt	2638732
Batch: 20195076 - Inspection Batch				Route: Adhoc Inspection				Date: 01/09/2016
3534051	cw sink hole, reconstruct and 2 course patch approx 5 sqm , barriers are at site and made safe.	01/09/2016	outside 52	CW Repairs-Bituminous	Internal		Committed	2635321
Batch: 20192289 - Inspection Batch				Route: Rush Area 2 Aug Saf CW				Date: 08/08/2016
3533177	Defect made safe	08/08/2016	outside house number 103	CW Repairs-Bituminous	Internal		Uncommitt	2634340
Batch: 20187274 - Inspection Batch				Route: Adhoc Inspection				Date: 04/07/2016
3531484	Defects have been made safe during time of inspection	04/07/2016	Outside house numbers 73 & 75	CW Repairs-Bituminous	Internal		Uncommitt	2632570

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: From Trevor Road to Rufford Way			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20183794 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 06/06/2016
Batch: 20183776 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 06/06/2016
Batch: 20176698 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 21/04/2016
Batch: 20174424 - Inspection Batch				Route: Adhoc Inspection				Date: 06/04/2016
3526667	Wearing course erosion & pot holes along stated location requires patching - 7 day response for marked up defects please .	06/04/2016	Outside house numbers 53 / 59 / 61 / 63 / 66	HW CW Pothole Z1	Internal		Committed	2627621
Batch: 20172105 - Inspection Batch				Route: Adhoc Inspection				Date: 16/03/2016
3525697	Slabs x 2 and hydrant marker post have been damaged . Please reset defect which has cones adjacent to it , 7 day response please .	16/03/2016	Outside house number 44 near to Rodney Road turn off .	HW FW Uneven slab Z2	Internal		Committed	2626645
Batch: 20171525 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 14/03/2016
Batch: 20164859 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Enh CW/FW				Date: 03/02/2016
Batch: 20162527 - Inspection Batch				Route: Rush Area 2 Jan Saf CW				Date: 20/01/2016
3521730	Defect made safe at time of inspection	20/01/2016	Outside house number 77	HW CW Pothole Z1	Internal		Uncommitt	2622597
Batch: 20157854 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW				Date: 10/12/2015
Batch: 20157394 - Inspection Batch				Route: Adhoc Inspection				Date: 08/12/2015
3519759	Defect made safe at time of inspection	08/12/2015	Outside house number 91	HW CW Pothole Z1	Internal		Uncommitt	2620569
Batch: 20155912 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW				Date: 27/11/2015
Batch: 20152931 - Inspection Batch				Route: Adhoc Inspection				Date: 06/11/2015
3518071	Footpath slabs rocking / uneven which require relaying . Defects marked up at time of inspection . 7 day response please .	06/11/2015	Outside house number 63 - opposite Glenmore Rd	HW FW Uneven slab Z2	Internal		Committed	2618807
Batch: 20149844 - Inspection Batch				Route: Rush Area 2 Oct Saf CW				Date: 19/10/2015
3517095	Defect made safe at time of inspection	19/10/2015	Outside house number 66	HW CW Pothole Z1	Internal		Uncommitt	2617799
Batch: 20146413 - Inspection Batch				Route: Rush Area 2 Sep Saf CW				Date: 26/09/2015
3516001	Defect made safe at time of inspection - 25 / 9 / 15	25/09/2015	Outside house number 61	HW CW Pothole Z1	Internal		Uncommitt	2616676
Batch: 20142005 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 24/08/2015

Effective: 01/04/2015 to 30/04/2017

Display Action Officer: No

Feature No.: 2001.00 to 2001.00

Street: Stamford Road (33001446)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: From Trevor Road to Rufford Way			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20136521	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 13/07/2015
Batch: 20134515	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jun Saf CW				Date: 27/06/2015
Batch: 20128640	- Inspection Batch No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 20/05/2015
Batch: 20125025	- Inspection Batch No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 28/04/2015

Customer Services

Enquiry No.: 6051202	Logged by: External to Confirm	on: 27/04/2017 10:50	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-51469877
Desc.: Road Pothole - Customer states car damaged due to several potholes on burly road and gordon road. Stamford road is where incident happened outside number 71. Customer states they have had to have car tyres repaired 3 times in 1 year due to terr ble conditions of roads in area. Alloy wheels that are damaged - which makes tyres loose pressure. This involves lots of repairs at multiple garages. . Submitted by Advisor: Personal Information			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6049857	Logged by: External to Confirm	on: 11/04/2017 12:54	
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-50914181
Desc.: Road work issue - A customer on Stamford road has called to report some problems with the road works on Stamford road currently taking place. On the junction of Alford Road and Stamford Road. There are temporary traffic lights in place on this junction and down Stamford Road for 3-way traffic control on all points of the t-junction. It seems that none of the workers seem to ever tend to the sight reports the customer. This is causing some problems because people living between the lights have trouble leaving there own driveways. This is frustrating as the works have been going on for 2 weeks and this problem persists. Customer reports that in those 2 weeks to his knowledge only a day or possibly 2 days at most of work have been committed. Customer did not want to provide personal details. . Submitted by Advisor: Personal Information			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6048288	Logged by: External to Confirm	on: 27/03/2017 13:58	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-50368157
Desc.: Overgrown hedges and vegetation - Digital team have forwarded the attached image from a customer on twitter, asking for the hedges to be cut back as on this occasion with the parked car as well, his partner has had to walk out on to the main road with their wheelchair bound son to proceed on their journey. Having used google maps it appears the location is near to the entrance of the West Bridgford Sports Club . Submitted by Advisor: Personal Information			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6048109	Logged by: External to Confirm	on: 24/03/2017 16:43	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-50320731
Desc.: Road Pothole - Holes and damage at the junction of Stamford Road and Melton Road . Online report			
Location: See map coordinates and description details	Contact:		

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 6041576	Logged by: External to Confirm	on: 06/02/2017 11:55	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS12609909
Desc.: Insurance claim - related to Confirm defect reference: 6041575			
Date/Time: 03/02/2017 21:30:00			
Direction of travel: Travelling down Stamford Road, on the odd number sides of the road.			
Account of what happened: Customer was waking down Stamford road and has tripped over some raised slabs and has injured his face badly and also his hand.. Personal Information			
Location: In-between No. 117 - 119		Contact:	
Enquiry No.: 6041575	Logged by: External to Confirm	on: 06/02/2017 11:55	
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-12609909
Desc.: Pavement Damage - Customer has called regarding raised paving slabs on Stamford road, outside property number 117-119. Customer fell over the slabs, while walking and has injured his hand and face. . Submitted by Advisor: Personal Information			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,001.00	Feature Id - Location: From Trevor Road to Rufford Way	Feature Type: Street Section	
Job Number: 2643449	Defect Number: 3541739		
Enquiry No.: 6041193	Logged by: External to Confirm	on: 02/02/2017 14:40	
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-12449723
Desc.: Pavement obstructions - High Wall over 5ft belonging to a property on the corner of Melton Road and Stamford Road in West Bridgford is in bad repair and pieces are falling out on to the pavement customer worried about large cracks in the wall . Submitted by Advisor: Personal Information			
Location: O/S No 151 Stamford Road		Contact:	
Enquiry No.: 6038158	Logged by: External to Confirm	on: 04/01/2017 17:51	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-11245088
Desc.: Road Pothole - Potholes along centre of carriage way on Stamford road between Rodney road and Alford road . Online report			
Location: The pin has been placed near 40 Stamford Road, Nottingham, United Kingdom, NG2 6GE		Contact:	
Enquiry No.: 6030981	Logged by: External to Confirm	on: 18/10/2016 11:57	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-8922632
Desc.: Road Damage - very uneven and holed surface, as a cyclist this caused me to swerve into oncoming traffic . , , , . Online report			
Location: The pin has been placed near 111 Stamford Road, Nottingham, United Kingdom, NG2 6GG		Contact:	
Enquiry No.: 6027014	Logged by: External to Confirm	on: 09/09/2016 20:03	
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS6260757
Desc.: Vehicle dropped kerb request - Hi i would like to put a droppee curb outside my property at Personal Inform . Per , Stamford Road, WEST BRIDGFORD, West Bridgford Personal Information . Online report			
Location: The pin has been placed near 1 Stamford Road, Nottingham, United Kingdom, NG2 6GA		Contact:	
Enquiry No.: 6025898	Logged by: External to Confirm	on: 31/08/2016 16:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS5831560
Desc.: Road Pothole - Adjacent to number 52 Stamford Road, a large hole has appeared on the side of the road. As this is a busy road with buses, cars and cycles using it regularly and frequently it could well cause an accident. . 52, Stamford Road, West Bridgford, Nottingham, NG2 6GG. Online report			
Location: The pin has been placed near 50-56 Stamford Road, Nottingham, United Kingdom, NG2 6GE		Contact:	
Plot Number: 2,001.00	Feature Id - Location: From Trevor Road to Rufford Way	Feature Type: Street Section	
Job Number: 2635321	Defect Number: 3534051		

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 6023236	Logged by: External to Confirm	on: 30/07/2016 08:13	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS4826864
Desc.: Overhanging trees - *Received Via Email*			
On the path between the end of Stamford Road and the footpath to Gamston between the Rugby club and the Willow Tree/Allotments, the vegetation on the right hand side is overhanging on the road. Can this be cut back say 1-2m away from the road.			
https://www.fixmystreet.com/report/865178 [Personal Information] Dorset Gardens, WEST BRIDGFORD, West Bridgford, [Personal Information]. Submitted by Advisor: [Personal Information]			
Location: The pin has been placed near 131 Stamford Road, Nottingham, United Kingdom, NG2 6GG		Contact:	
Enquiry No.: 6011655	Logged by: External to Confirm	on: 06/04/2016 10:51	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103888941
Desc.: Pothole on Stamford road between Glenmore road and Alford road , looks like it has been repaired, but has collapsed.			
Location: Near Glenmore Road		Contact:	
Plot Number: 2,001.00	Feature Id - Location: From Trevor Road to Rufford Way	Feature Type: Street Section	
Job Number: 2627621	Defect Number: 3526667		
Enquiry No.: 6010328	Logged by: External to Confirm	on: 23/03/2016 09:05	
Service: Traffic Management	Subject: Traffic Issues	Classification: Report or Observation	Enquiry Ref: 103886536
Desc.: There have been 3 accidents in this area this year. Customer sdays that people are ignoring the give way - customer thinks that it will be beneficial to have a stop sign or something more substantial on this crossroads. There was an accident yesterday.			
Logged by CSC operator: [Personal Information]			
** Customer Requested Auto Updates **			
Location:		Contact:	
Enquiry No.: 6010272	Logged by: External to Confirm	on: 22/03/2016 15:28	
Service: Traffic Management	Subject: Speed Limits/Issues	Classification: Report or Observation	Enquiry Ref: 103886447
Desc.: Potential speed issue along Stamford Road. There have been a number of a accidents down this road in recent months which may have been speed related. Can we look at this issue and see what can be done to improve speed in the area.			
Logged by CSC operator: [Personal Information]			
Location: Near Stamford Road		Contact:	
Enquiry No.: 3198913	Logged by: External to Confirm	on: 29/12/2015 14:48	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: 103827727
Desc.: Officer states that they've had an RTC and there's oil, tree branches and vehicle debris on the road. Thanks			
Logged by CSC operator: [Personal Information]			
Passed to [Personal Information] the emergency action officer. 29/12/15.			
Location: Near Stamford Road		Contact:	
Enquiry No.: 3196243	Logged by: External to Confirm	on: 03/12/2015 11:49	
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: 103805827
Desc.: Customer wishes to know for certain that a problem tree that was taken down 02.12.15 WILL be replaced.			
Logged by CSC operator: [Personal Information]			
Location: Right next to Stamford Road		Contact:	
Enquiry No.: 3192174	Logged by: External to Confirm	on: 05/11/2015 17:59	
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: 103775219
Desc.: Pavement outside 63 Stamford Road. Dangerous loose slabs. Already caused filthy water to come over shoes and trousers. Accident waiting to happen.			
Location: Right next to Stamford Road		Contact:	
Plot Number: 2,001.00	Feature Id - Location: From Trevor Road to Rufford Way	Feature Type: Street Section	
Job Number: 2618807	Defect Number: 3518071		

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 3189957	Logged by: External to Confirm	on: 21/10/2015 16:15	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: 103757635
Desc.: Customer has today witnessed an accident happening on this corner today. Customer has been saying for years that one day an accident will happen here, due to the way people drive. Customer would like to know if we can put speed bumps on Rufford way and Stamford road, or maybe also a pedestrian crossing in order to slow the traffic down. There is also a school nearby so customer is thinking of the childrens safety.			
Logged by CSC operator: Personal Information			
Location: 36 meters from Stamford Road	Contact:		
Enquiry No.: 3189764	Logged by: External to Confirm	on: 20/10/2015 15:04	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: 103755853
Desc.: At rodney road and stamford rpad tree has been hit rtc here. This happened at 14.26pm. 2 vehicles here, one vehicle is in the tree here. Tree may not be safe. 456 20/10/2015.			
Logged by CSC operator: Personal Information			
Location: Near Stamford Road	Contact:		
Enquiry No.: 3179705	Logged by: External to Confirm	on: 28/07/2015 13:42	
Service: Trees/Verges	Subject: Weeds	Classification: Report or Observation	Enquiry Ref: 103656699
Desc.: Weeds need clearing			
Logged by CSC operator: Personal Information			
Location: Right next to Stamford Road	Contact:		
Enquiry No.: 3167340	Logged by: External to Confirm	on: 07/04/2015 10:59	
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: 103527989
Desc.: Update in notes. Needs either the mixer moved off the footway, proper ped barriers around it or the footway closing off on that side KJH 8/4/15			
Personal I is wanting to inform the highways of people completing block paving outside number 8 stamford road, he states that there are around 2,000 bricks on the pavement a cement mixer alot of plywood and other tools just in the road, he says you have to struggle to get past it and its obstructing. he had to walk in the middle of the road to get around it. he would like to be contacted once someone has been out. Personal Information			
Logged by CSC operator: Joshua Thacker			
Location: Near 8 Stamford Road	Contact:		
Enquiry No.: 1303846	Logged by: Personal Information	on: 19/08/2015 09:34	
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	
Desc.: Recent overshoot accident - please renew all worn advance give way & giive way markings including central hatching on both approaches to this junction to reduce the likelihood of further accidents. photo attached			
Location: Stamford Road/Rodney Road	Contact:		
Enquiry No.: 58312	Logged by: Personal Information	on: 03/01/2017 15:17	
Service: Carriageway/Footway	Subject: Emergency Service Request	Classification: Report or Observation	
Desc.: RTC Debris			
Location: Stamford Road West bridford	Contact:		
Enquiry No.: 53982	Logged by: Personal Information	on: 13/09/2016 10:31	
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	
Desc.: From: Personal Information			
Sent: 12 September 2016 13:53			
To: Personal Information			
Subject: [Sent to NCC. Inform the Sender]Illegal Access			
Hi Personal In , spotted this kerb damage during routine inspections and more than likely been damaged by the home owner riding over the footpath . Can you inform the home owner of house number Pers Stamford road to reframe from this or request a dropped kerb to stop any further damage ,photos attached thanks Personal			
Location: O/S No Pers	Contact:		

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 53067 **Logged by:** Personal Information **on:** 19/08/2016 10:01
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8m x 3.4m 22/08/2016 to 18/09/2016
Location: 56 STAMFORD ROAD **Contact:**
 WEST BRIDGFORD
 NG2 6GF

Enquiry No.: 47103 **Logged by:** Personal Information **on:** 24/03/2016 15:02
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8 x 3.4m skip
 29/03/16 - 25/04/16
Location: 119 **Contact:**

Enquiry No.: 46190 **Logged by:** Personal Information **on:** 03/03/2016 12:26
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request
Desc.:
Location: **Contact:**

Enquiry No.: 45844 **Logged by:** Personal Information **on:** 25/02/2016 15:25
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8 x 3.4m skip
 01/03/16 - 28/03/16
Location: 119 **Contact:**

Enquiry No.: 45239 **Logged by:** Personal Information **on:** 11/02/2016 10:35
Service: Traffic Management **Subject:** Traffic Calming **Classification:** Report or Observation
Desc.: From: Personal Information
 Sent: 08 February 2016 17:11
 To: Personal Information
 Subject: Car crashes at the junction of Rodney and Stamford Roads NG2

Good Afternoon,

Unfortunately today there has been another incident at the above junction. This is the 2 nd in as many months. On both occasions the police have attended.

I felt compelled to write to yourselves as I am concerned it is only a matter of time before someone sustains a serious injury. The junction is very busy at school times due to the proximity of both Abbey Road Primary and Edmund Campion schools. Cars appear to drive rapidly on Stamford Road and often break the 30 mph limit.

Would the council consider some traffic calming measures on Stamford Road, or some measures to make the junction clearer.

There is a 20mph limit on the lower part of Rodney Road just by the schools but could this be extended?

I look forward to hearing your response.

Thank you

Yours sincerely,

Personal Information

Location: Junction Rodney Road

Contact:

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 45237 Logged by: Personal Information on: 11/02/2016 10:30
 Service: Traffic Management Subject: Traffic Calming Classification: Report or Observation
 Desc.: From: Personal Information
 Sent: 09 February 2016 11:45
 To: Personal Information
 Subject: Incident on Stamford Road

Hi there,

A neighbour passed me this email address in order to write and express my concern about the speed of cars and number of accidents on our road, Stamford Road West Bridgford. Just yesterday a collision occurred on the corner of Rodney road and Stamford Road causing a car to crash through our front hedge and into the front garden. The police incident number is 290-08022016.

My main concern is that there are many children crossing this road on their way to Abbey Road school, Edmund Champion School and also Rushcliffe School Personal Information

I really hope something can be done to calm traffic and help children cross safely to put all our minds at rest.

Best wishes,

Personal Information

Location: Junction Rodney Road

Contact:

Enquiry No.: 45186 Logged by: Personal Information on: 10/02/2016 09:25
 Service: Carriageway/Footway Subject: Dropped Kerb (Vehicle) Request Classification: Service Request
 Desc.: Personal Information is wanting to carry out the works at Personal Information Stamford Road, West Bridgford
 Location: Contact:

Enquiry No.: 44789 Logged by: Personal Information on: 29/01/2016 15:26
 Service: Licenses/Permits Subject: Skip License Request Classification: Service Request
 Desc.: 1.8 x 3.4m
 02/02/16 - 29/02/16
 Location: 119 Contact:

Enquiry No.: 44525 Logged by: Personal Information on: 25/01/2016 09:28
 Service: Licenses/Permits Subject: Skip License Request Classification: Service Request
 Desc.: 1.8 x 3.4m skip
 27/01/16 - 23/02/16
 Location: 11 Contact:

Enquiry No.: 43784 Logged by: Personal Information on: 04/01/2016 12:50
 Service: Trees/Verges Subject: Tree Enquiry Classification: Report or Observation
 Desc.: We have twice last year requested the pollarding of a tree opposite our property using your web site form. to date nothing has been done despite most of the trees in the neighbouring streets being dealt with. PLEASE EXPLAIN WHETHER THERE IS ANY POINT IN YOUR WEB SITE ENQUIRY SYSTEMS.
 We expect the tree to be reduced in height immediately as it affects nearby properties.
 Location: Opposite No 38 Contact:

Enquiry No.: 42865 Logged by: Personal Information on: 26/11/2015 12:02
 Service: Traffic Management Subject: Parking General Classification: Report or Observation
 Desc.: Bus Stop Clearway Consultation Nov/Dec 2015
 Location: East of Covert Rd jcn on south side Contact:

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 38798

Logged by: Personal Information

on: 21/08/2015 09:14

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Desc.: I have received the following request to prune some Sycamore tree, I have checked our maps and the land appears to be adopted highway. Can you take a look and advise the customer about what can be done.

please can someone go out to lop the sycamore trees next to this customers house as they are blocking light into her garden and getting very large, can someone call the customer if this is not possible. Thanks

Personal Information

Location: 131

Contact:

Enquiry No.: 37320

Logged by: Personal Information

on: 07/07/2015 17:39

Service: Traffic Management

Subject: Traffic Survey

Classification: Report or Observation

Desc.: Request for traffic surveys to support area wide Prohibition of Driving between A52/A606/A6011 Radcliffe Rd and also to support/not support future planning applications

Location: Residential area between A52, A606 and A6011 Radcliffe Rd

Contact:

Enquiry No.: 36262

Logged by: Personal Information

on: 04/06/2015 10:58

Service: Carriageway/Footway

Subject: Emergency Service Request

Classification: Report or Observation

Desc.: RWO

Location:

Contact:

Enquiry No.: 35698

Logged by: Personal Information

on: 19/05/2015 12:06

Service: Trees/Verges

Subject: Overhanging Vegetation/Trees

Classification: Report or Observation

Desc.: Hi Personal In

One for you, when trying to get out of Stamford Road onto Melton Road you cannot see the approaching traffic let alone walk on the footpath. Certainly well encroaching within your guidelines and an accident waiting to happen. The branches are also affecting the road and catching tall vehicles.

Kind Regards

Personal Information

Location: When trying to get out of Stamford Road onto Melton Road

Contact:

Effective: 01/04/2015 to 30/04/2017
 Display Action Officer: No

Feature No.: 2001.00 to 2001.00
 Street: Stamford Road (33001446)

Customer Services

Enquiry No.: 35062
 Service: Trees/Verges
 Desc.: Hi

Logged by: [Personal Information]
 Subject: Tree Enquiry

on: 27/04/2015 13:09
 Classification: Report or Observation

The following information was reported on our website. Unfortunately no contact information was provided, but I thought I should make you aware of the issue.

Regards

[Personal Information]

Location of the problem: the large tree outside no 41 / 43 Stamford road has not been pollarded, many others have but this tree is a nuisance, it is too large, too close to properties and blocks out sun from properties, Stamford Road, West Bridgford

Where exactly is the tree located (the more information you give the more quickly we can locate the tree)? Street name and house number

What is the problem with the tree? Loss of light or other nuisance

Other details: other trees in the area that are not as large have been pollarded, this was brought to your attention a month ago and still nothing

Location: Outside no 41 / 43 Stamford road

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: From Trevor Road to Rufford Way		Feature Type: Street Section		Area: Rushcliffe	
2606935	Pothole made safe at time of inspection . (HW CW Pothole Z1)	Outside house number 59	Category 2 (High)	Job Completed	11/03/2015	11/03/2015	Act. RUSH/3700881
2607802	H W I A - 7 Days Please, not marked out. (HW CW Pothole Z1)	Outside 40 and 42.	Category 2 (High)	Job Completed	26/03/2015	02/04/2015	Act. RUSH/3700949
2616676	Defect made safe at time of inspection - 25 / 9 / 15 (HW CW Pothole Z1)	Outside house number 61	Filled when found (Cat 2H)	Job Completed	26/09/2015	25/09/2015	Act.
2617799	Defect made safe at time of inspection (HW CW Pothole Z1)	Outside house number 66	Filled when found (Cat 2H)	Job Completed	19/10/2015	19/10/2015	Act.
2618807	Footpath slabs rocking / uneven which require relaying . Defects marked up at time of inspection . 7 day response please . (HW FW Uneven slab Z2)	Outside house number 63 - opposite Glenmore Rd	Category 2 (High)	Job Completed	06/11/2015	12/11/2015	Act. RUSH/3701373
2620569	Defect made safe at time of inspection (HW CW Pothole Z1)	Outside house number 91	Filled when found (Cat 2H)	Job Completed	08/12/2015	08/12/2015	Act.
2622597	Defect made safe at time of inspection (HW CW Pothole Z1)	Outside house number 77	Filled when found (Cat 2H)	Job Completed	20/01/2016	20/01/2016	Act.

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Trevor Road to Rufford Way	Feature Type:	Street Section	Area:	Rushcliffe
2626645	Slabs x 2 and hydrant marker post have been damaged . Please reset defect which has cones adjacent to it , 7 day response please . (HW FW Uneven slab Z2)	Outside house number 44 near to Rodney Road turn off .	Category 2 (High)	Job Completed	16/03/2016	20/04/2016	Act. RUS-AS/5600258
2627621	Wearing course erosion & pot holes along stated location requires patching - 7 day response for marked up defects please . (HW CW Pothole Z1)	Outside house numbers 53 / 59 / 61 / 63 / 66	Category 2 (High)	Job Completed	06/04/2016	11/04/2016	Act. RUSH/3701679
2632570	Defects have been made safe during time of inspection (CW Repairs-Bituminous)	Outside house numbers 73 & 75	Filled when found (Cat 2H)	Job Completed	04/07/2016	04/07/2016	Act.
2634340	Defect made safe (CW Repairs-Bituminous)	outside house number 103	Filled when found (Cat 2H)	Job Completed	08/08/2016	08/08/2016	Act.
2635321	cw sink hole, reconstruct and 2 course patch approx 5 sqm , barriers are at site and made safe. (CW Repairs-Bituminous)	outside 52	Category 2 (High)	Job Completed	01/09/2016	09/09/2016	Act. RUSH/3701917
2638732	Defect made safe. (CW Repairs-Bituminous)	Outside house number 93	Filled when found (Cat 2H)	Job Completed	07/11/2016	07/11/2016	Act.
2641519	Overlay - Various sized wearing course erosion (total of 13) along street section requires making safe . Defects also include a old reinstatement which is slightly sunken adjacent to L / C 18 , defects are marked up . (CW Repairs-Bituminous)	In between the junctions of Alford road & Rodney road	Category 2 (High)	Job Completed	05/01/2017	06/01/2017	Act. RUSH/3702097
2642434	Defect made safe (CW Repairs-Bituminous)	Outside house number 121	Filled when found (Cat 2H)	Job Completed	19/01/2017	19/01/2017	Act.
2643187	Defect made safe during inspection (CW Repairs-Bituminous)	Outside house number 39	Filled when found (Cat 2H)	Job Completed	02/02/2017	02/02/2017	Act.
2643449	Total of 9 obsolete slabs are protruding from uplift by Highway tree and home owner illegally riding over the footpath which notice has been served to him . Slabs require removing and replacing with Bitmac - defects are marked up. (FW Repairs-Bituminous)	Outside house number Person	Category 2 (High)	Job Completed	06/02/2017	14/02/2017	Act. RUSH/3702152
2645409	Defect made safe (CW Repairs-Bituminous)	Outside house number 103	Filled when found (Cat 2H)	Job Completed	02/03/2017	02/03/2017	Act.

Effective: 01/04/2015 to 30/04/2017

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Stamford Road (33001446)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: From Trevor Road to Rufford Way		Feature Type: Street Section		Area: Rushcliffe	
2647752	Defect made safe. (CW Repairs-Bituminous)	Outside house number 121	Filled when found (Cat 2H)	Job Completed	05/04/2017	05/04/2017	Act.
2649219	Defect made safe (CW Repairs-Bituminous)	Opposite property number 105	Filled when found (Cat 2H)	Job Completed	27/04/2017	27/04/2017	Act.