

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Cotgrave Road (33022092)

Street: Cotgrave Road (33022092)

Locality: Tollerton, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From end of house, outside number 44 to junction with Cotgrave			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20274159 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 22/03/2018
Batch: 20269559 - Inspection Batch				Route: Adhoc Inspection				Date: 22/02/2018
3569170	Carriageway Pothole - Road Pothole - Pothole . Online report (Enquiry 6082863)	22/02/2018	Junction of Cotgrave Lane/Cotgrave Road as you turn left from Cotgrave Lane towards Cotgrave. pothole around ironwork.	CW Repairs-Bituminous	Internal		Committed	2672134
Batch: 20267024 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Enh CW/FW				Date: 06/02/2018
Batch: 20264326 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 24/01/2018
Batch: 20258482 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW				Date: 08/12/2017
Batch: 20255533 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW				Date: 20/11/2017
Batch: 20250815 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Oct Saf CW				Date: 19/10/2017
Batch: 20246579 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Sep Saf CW				Date: 20/09/2017
Batch: 20243112 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 25/08/2017
Batch: 20238152 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 17/07/2017
Batch: 20235653 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jun Saf CW				Date: 26/06/2017
Batch: 20234065 - Inspection Batch				Route: Adhoc Inspection				Date: 14/06/2017
3550278	Defect made safe	14/06/2017	On the T junction with Cotgrave Lane	CW Repairs-Bituminous	Internal		Uncommitt	2652344
Batch: 20230850 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 22/05/2017
Batch: 20225754 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 20/04/2017

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: From end of house, outside number 44 to junction with Cotgrave			Feature Type: Street Section			Area: Rushcliffe
2652344	Defect made safe (CW Repairs-Bituminous)	On the T junction with Cotgrave Lane	Filled when found (Cat 2H)	Job Completed	14/06/2017	14/06/2017	Act.

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Cotgrave Road (33022092)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From end of house, outside number 44 to junction with Cotgrave Lane/Cotgrave Road as you turn left from Cotgrave Lane towards Cotgrave. pothole around ironwork.		Feature Type: Street Section		Area: Rushcliffe	
2672134	Carriageway Pothole - Road Pothole - Pothole . Online report (Enquiry 6082863) (CW Repairs-Bituminous)	Junction of Cotgrave Lane/Cotgrave Road as you turn left from Cotgrave Lane towards Cotgrave. pothole around ironwork.	Category 2 (High)	Job Completed	22/02/2018	02/03/2018	Act. RUS-AS/5600955