

Effective: 01/04/2019 to 30/06/2019
 Display Action Officer: No
 Street: Nottingham Road (4911550)

Feature No.: 2000.00 to 2002.00
 Street: Nottingham Road (4911550)

Locality: Trowell, Nottinghamshire
 Area: Broxtowe

Condition Survey

Defect No: Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00 Feature Id - Locn.: Ilkeston Road To Smithfield Ave			Feature Type: Street Section			Area: Broxtowe	
Batch: 20343453 - Inspection Batch No actionable defects found			Route: Broxtowe North Jun Saf CW				Date: 25/06/2019
Batch: 20338453 - Inspection Batch No actionable defects found			Route: Broxtowe North May Saf CW				Date: 29/05/2019
Batch: 20334159 - Inspection Batch			Route: Adhoc Inspection				Date: 30/04/2019
3608603 Reset metal bollard I have made safe with cones	30/04/2019	Outside number 18	Bollard Repairs	Internal		Committed	2712258
Batch: 20333460 - Inspection Batch No actionable defects found			Route: Broxtowe North Apr Saf CW				Date: 25/04/2019
Feat No.: 2,002.00 Feature Id - Locn.: Smithfield Ave To Waterloo Lane			Feature Type: Street Section			Area: Broxtowe	
Batch: 20343581 - Inspection Batch No actionable defects found			Route: Broxtowe North Jun Saf CW				Date: 25/06/2019
Batch: 20338202 - Inspection Batch			Route: Broxtowe North May Saf CW				Date: 28/05/2019
3611295 Cway potholes	28/05/2019	Lamp columns 43, 45, 50, 51, 52, 54, 64 & 65	CW Repairs-Bituminous	Internal		Committed	2714957
Batch: 20333474 - Inspection Batch No actionable defects found			Route: Broxtowe North Apr Saf CW				Date: 25/04/2019

Customer Services

Enquiry No.: 6131936	Logged by: External to Confirm	on: 27/06/2019 14:18	Enquiry Ref: FS127275998
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	
Desc.: Insurance claim - related to Confirm defect reference: 6131933	Date/Time: 24/06/2019 18:30:00	Direction of travel: Was travelling towards Ilkeston	
	Account of what happened: Passenger front side wheel hit the pothole and popped the tyre, buckled the wheel and damaged the tracking on it.	Contact:	
Location: A609 Nottingham Road, opposite Cossall Road junction		on: 27/06/2019 14:14	Enquiry Ref: FS-CASE-127275998
Enquiry No.: 6131933	Logged by: External to Confirm	Classification: Report or Observation	Customer title is [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Submitted by Advisor:	
Desc.: Insurance claim form requested - Road Pothole - Large pothole approx width 23cm x depth 9cm .	Location: A609 Nottingham Road, opposite Cossall Road junction	Contact:	
Enquiry No.: 6131851	Logged by: External to Confirm	on: 26/06/2019 17:38	Enquiry Ref: FS-CASE-127093980
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: Road Pothole - Near the Festival Inn in the side of the road there is a pothole that [REDACTED] drove over which has caused damage to the vehicle. It is near the bus stop near the Walkers of Trowell. It is about 3 inches deep, can someone go out to inspect this as soon as possible. [REDACTED] will call on Friday to request a claim form. . Submitted by Advisor: [REDACTED]	Location: On Nottingham Road in Trowell.	Contact:	

Effective: 01/04/2019 to 30/06/2019
Display Action Officer: No
Feature No.: 2000.00 to 2002.00
Street: Nottingham Road (4911550)

Customer Services

Enquiry No.: 6128891
Service: Trees/Verges
Desc.: Overgrown grass and verges - The grass/ vegetation at this junction has not been cut back this year and now it is very difficult to see traffic coming down the road when you want to pull onto Nottingham Road. Can you please arrange to get this cut back . . . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]
Location: The junction of Smithfield Ave and Nottingham Road trowell
Logged by: External to Confirm
Subject: Grass Cutting
Classification: Report or Observation
on: 30/05/2019 12:54
Enquiry Ref: FS-CASE-121679116

Enquiry No.: 6127721
Service: Road Works
Desc.: Other requests - VolkerLaser limited working on behalf of highways England will be carrying out planned maintenance works to the bridge abutments and beams which carry the M1 motorway over the A609 Ilkeston road (see drawing attached). Our works are programmed to commence on 15th July 2019 for a period of 9 weeks, during our works we request the disconnection of the 4 Lamp standards on the south side of the bridge and the 2 lamps fitted to the north abutment.
Location: [REDACTED]
Logged by: External to Confirm
Subject: Road Works Report
Classification: Report or Observation
on: 14/05/2019 15:12
Enquiry Ref: FS-CASE-118814911

Should you require any further information please do not hesitate to contact the undersigned.
Submitted by Advisor: [REDACTED] Customer title is [REDACTED] Will contact the person direct.
Location: A609 where it goes under the M1.
Contact: [REDACTED]

Enquiry No.: 6127394
Service: Carriageway/Footway
Desc.: Spillage/debris in road - A bus from Trent Barton has been dripping diesel on the road from Ilkeston to Nottingham City. When it has stopped at the bus stops it has left a puddle of diesel. The Bus came down Ilkeston Road then into trowell then onto Nottingham Road to Wollaton. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]
Location: Diesel spillage in the road dripping out of a bus going from Ilkeston to Nottingham
Logged by: External to Confirm
Subject: Spillage/Debris on Carriageway
Classification: Report or Observation
on: 10/05/2019 12:26
Enquiry Ref: FS-CASE-118176015

Enquiry No.: 6125380
Service: Carriageway/Footway
Desc.: Fencing damage - A number of black bollards, one of which is leaning into the road . . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]
Location: On trowell road/nottingham road between woolaton and trowell, by turnings to hill
Logged by: External to Confirm
Subject: Fencing Damage (Other)
Classification: Report or Observation
on: 11/04/2019 11:34
Enquiry Ref: FS-CASE-113558451

Enquiry No.: 3207812
Service: Carriageway/Footway
Desc.: Replace existing ACO rodding access with a chamber near Col 5 & install a chamber at the end of the run to allow access to clean the system
Location: LAMP col 52 & 53
Logged by: [REDACTED]
Subject: Flooding
Classification: Report or Observation
on: 15/04/2019 08:37

Plot Number: 2,002.00
Job Number: 2710698
Feature Id - Location: Smithfield Ave To Waterloo Lane
Feature Type: Street Section

Enquiry No.: 80595
Service: Trees/Verges
Desc.: Customer claims grass and the highway trees are obstructing the visibility splay. I have arranged for Broxtowe to cut the grass.
Location: Either side of the junction with Smithfield Avenue
Logged by: [REDACTED]
Subject: Tree Enquiry
Classification: Report or Observation
on: 17/06/2019 13:08

Street History Report

19/08/2019

Effective: 01/04/2019 to 30/06/2019
Display Action Officer: No
Feature No.: 2000.00 to 2002.00
Street: Nottingham Road (4911550)

Customer Services

Enquiry No.: 79898
Service: Other
Desc.: Dear [Redacted]
Logged by [Redacted] on: 14/05/2019 09:10
Subject: Other Enquiry (Highways)
Classification: Report or Observation

Picking your brains here - how can I find out the total number of street lighting columns on Nottingham Road, Stapleford Road & Ilkeston Road in Trowell please? We a looking at how many lamp post poppies to purchase for these main routes in the village.

Many thanks for your help as always.
[Redacted]
[Redacted]

[Redacted]
Location: Nottingham Road, Stapleford Road & Ilkeston Road in Trowell
Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
2712258	Reset metal bollard I have made safe with cones (Bollard Repairs)	Feature Id - Locn.: Ilkeston Road To Smithfield Ave Outside number 18	Category 2	Job Completed	30/04/2019	12/05/2019	Act. BROX/3305893
2703442	Replace existing ACO rodding access with a chamber near lamp column 52 & install a chamber at the end of the run lamp column 53 to allow access to clean the system. (Drainage)	Feature Id - Locn.: Smithfield Ave To Waterloo Lane Lamp column 53 and 52	Category 3	Job Cancelled	30/01/2019	30/04/2019	Est. BROX/3305639
2710698	Flooding - Replace existing ACO rodding access with a chamber near Col 5 & install a chamber at the end of the run to allow access to clean the system (Enquiry 3207812)	LAMP COL 52 & 53 - STATS 448766 - 340060	Category 3	Job Completed	15/04/2019	08/05/2019	Act. BROX/3305850
2714957	Cway potholes (CW Repairs-Bituminous)	Lamp columns 43, 45, 50, 51, 52, 54, 64 & 65	Category 2	Job Completed	28/05/2019	06/06/2019	Act. BRO-AS/5204958

Effective: 01/04/2019 to 30/06/2019
 Display Action Officer: No

Feature No.: 2000.00 to 2002.00
 Street: Nottingham Road (4911550)

Street Works Notices

Organisation: MUS NORTH EAST UNMETERED SOLE USE CONNECTION (7011321)

Works Ref: /156639
 Notice Type: Actual Start Date
 Work Status: Proposed Works
 Work Type: Not Applicable
 Version: -1
 Start: 03/05/2011 00:00:00
 Issued: 03/05/2011 09:37:21
 Est. End: 01/01/4000
 Work Desc: Unknown

Completion:

Site No. Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1 FEEDER PILLAR, NEAR DAYDAWN (HOUSE)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Works	03/05/2011		04/05/2011	05/05/2011

Organisation: New Maintenance District (0010014) (Street Works Admin Team NG Gas)

Works Ref: EIM2319
 Notice Type: Registration of Reinstatement - Full
 Work Status: Works Stopped
 Work Type: EToN 4: Minor
 Version: 4
 Start: 22/05/2019 00:00:00
 Issued: 23/05/2019 08:34:01
 Est. End: 24/05/2019
 Work Desc: Replacement of anti-corrosion materials and street furniture on gas pipeline.

Completion:

Site No. Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1 Grass Verges - approx 65 metres from Cossall Road.	Verge	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	22/05/2019		22/05/2019	24/05/2019

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /NOTTINGHAM250419
 Notice Type: 10 Day Initial Notice
 Work Status: Proposed Works
 Work Type: EToN 4: Standard
 Version: 1
 Start: 07/05/2019 00:00:00
 Issued: 25/04/2019 14:15:25
 Est. End: 10/05/2019
 Work Desc: Gully Cleansing

Completion:

Site No. Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1 Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Works	07/05/2019			10/05/2019

Works Ref: 2705020

Notice Type: Actual Start Date
 Work Status: Proposed Works
 Work Type: Not Applicable
 Version: -1
 Start: 03/03/2019 00:00:00
 Issued: 01/03/2019 08:17:17
 Est. End: 01/01/4000
 Work Desc: Unknown

Completion:

Site No. Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1 20 Nottingham Road Trowell	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Works	03/03/2019		03/03/2019	03/03/2019

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000010712229
 Notice Type: Actual Start Date
 Work Status: Proposed Works
 Work Type: Not Applicable
 Version: -1
 Start: 08/10/2013 00:00:00
 Issued: 08/10/2013 09:31:58
 Est. End: 01/01/4000
 Work Desc: Unknown

Completion:

Site No. Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1 24	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Works	08/10/2013		08/10/2013	10/10/2013

Effective: 01/04/2019 to 30/06/2019
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Nottingham Road (4922005)

Street Works Notices

Organisation: COLT - UDP (7075005)

Works Ref: 010419/NOTT/01

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 4

Start: 05/04/2019 00:00:00

Issued: 25/04/2019 13:28:12

Est. End: 09/04/2019

Work Desc: Excavate in Carriageway to repair damaged frame and cover

Completion: 09/04/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
3	At Column 97	Carriageway	Up to 1.5 Metres of Cover	1.40	0.80 A Permanent Reinstatement	09/04/2019		09/04/2019	09/04/2019

Works Ref: 040419/NOTT/02

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 09/04/2019 00:00:00

Issued: 08/04/2019 10:07:54

Est. End: 11/04/2019

Work Desc: Renew Frame and cover in Carriageway for Fibre optic Network

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Opposite Lamp Column 83	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	09/04/2019			11/04/2019

Works Ref: 040419/NOTT/03

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 09/04/2019 00:00:00

Issued: 08/04/2019 10:08:17

Est. End: 11/04/2019

Work Desc: Renew Frame and cover in Carriageway

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	At Lamp Column 97	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	09/04/2019			11/04/2019

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /NOTTINGHAM/250419A

Notice Type: 10 Day Initial Notice

Work Status: Proposed Works

Work Type: EToN 4: Standard

Version: 1

Start: 07/05/2019 00:00:00

Issued: 25/04/2019 14:34:06

Est. End: 10/05/2019

Work Desc: Gully Cleansing

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	07/05/2019			10/05/2019

Street History Report

19/08/2019

Effective: 01/04/2019 to 30/06/2019
 Display Action Officer: No
 Feature No.: 2,000.00 to 2000.00
 Street: Nottingham Road (4922005)
 Locality: Trowell Moor, Trowell, Nottinghamshire
 Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section			Area: Broxtowe	Date: 25/06/2019
Batch:	20343580 - Inspection Batch			Route: Broxtowe North Jun Saf CW				
	No actionable defects found							
Batch:	20340878 - Inspection Batch			Route: Adhoc Inspection	Internal		Committed	2716359
3612688	Reset loose gully cover	12/06/2019	Opposite lamp column 92	CW Ironwork				
Batch:	20340877 - Inspection Batch			Route: Adhoc Inspection			Uncommitted	2716358
3612687	Cway pothole filled when found	12/06/2019	LC 92	CW Repairs-Bituminous	Internal			
Batch:	20338200 - Inspection Batch			Route: Broxtowe North May Saf CW			Uncommitted	2716359
3611292	Cway potholes	28/05/2019	Lamp columns 83, 92, 97, 110 & 112	CW Repairs-Bituminous	Internal		Committed	2714955
3611293	Cway pothole filled when found	28/05/2019	LC95	CW Repairs-Bituminous	Internal		Uncommitted	2714954
Batch:	20333863 - Inspection Batch			Route: Adhoc Inspection			Uncommitted	2712034
3608382	Cway potholes filled when found	29/04/2019	Lamp column 110	CW Repairs-Bituminous	Internal			
Batch:	20333473 - Inspection Batch			Route: Broxtowe North Apr Saf CW			Uncommitted	2712034
	No actionable defects found							
Batch:	20332290 - Inspection Batch			Route: Adhoc Inspection			Committed	2711278
3607630	Excavate area and re patch	18/04/2019	Opposite lamp column 61 adjacent to the bus stop (city side of the crossroads)	CW Repairs-Bituminous	Internal			
	Pat, This is the one with the metal below the surface I have attached some photos							
Batch:	20332024 - Inspection Batch			Route: Adhoc Inspection			Uncommitted	2711030
3607382	Carriageway Pothole filled when found	17/04/2019	opposite 342 Trowell Road Nottingham at the cross boundary point on county council side	CW Repairs-Bituminous	Internal			
Batch:	20330114 - Inspection Batch			Route: Adhoc Inspection			Uncommitted	2709624
3605991	Cway pothole filled whenfound	04/04/2019	LC 89	CW Repairs-Bituminous	Internal			

Customer Services

Enquiry No.: 6126001
 Logged by: External to Confirm on: 23/04/2019 10:48
 Service: Carriageway/Footway Subject: Line Marking/Stud Renewal Classification: Report or Observation Enquiry Ref: FS-CASE-115145051
 Desc.: Road marking renewal - Wild Deer Herd are crossing at least twice per day, they run along the fields and then cross the road through the hedge rows. Please put a warning sign up urgently before there is an accident . Online report Customer title [REDACTED]
 Location: Trowell Moor. A609 between Waterloo Lane and Coventry Lane traffic Lights Contact:

Effective: 01/04/2019 to 30/06/2019
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Nottingham Road (4922005)

Customer Services

Enquiry No.: 6125752
Service: Carriageway/Footway
Desc.: Road Pothole - email report -

Logged by: External to Confirm
Subject: Carriageway Pothole

on: 17/04/2019 08:48
Classification: Report or Observation
Enquiry Ref: FS-CASE-114392322

o: "Customer Service Centre" enquiries@nottscc.gov.ukcc: "Noreply.Enquiries@nottscc.gov.uk"
Noreply.Enquiries@nottscc.gov.ukRe: Potholes, roads and pavement damage - Nottinghamshire CountyCouncil. Enquiry reference: FS114294591

342 Trowell Road Nottingham at the cross boundary point on county council side.

[Redacted]

Get Outlook for Android

From: Customer Service Centre <enquiries@nottscc.gov.uk>

Sent: Tuesday, April 16, 2019 2:33:13 PM

To: [Redacted]

Subject: Potholes, roads and pavement damage - Nottinghamshire County Council. Enquiry reference: FS114294591

Dear [Redacted]

Thank you for your e-mail.

To respond to your enquiry fully, we require some additional information listed below and would be grateful if you could supply us with these details at your earliest convenience.

Are these two potholes on 342 Trowell Road, Stapleford or Nottingham?

We hope you find this helpful but if you have any further queries, please email us at: enquiries@nottscc.gov.uk.

For further information and advice on all County Council services please visit our website at <http://www.nottinghamshire.gov.uk>

Yours sincerely,

Customer Services

Nottinghamshire County Council

Street History Report

Effective: 01/04/2019 to 30/06/2019 Feature No.: 2000.00 to 2000.00
Display Action Officer: No Street: Nottingham Road (4922005)

Customer Services

Original email:
potholes opp 342 trowell road
Hi
Just to let you know there is 2 potholes on Trowell Road opp 342.



Highway Inspector

Highway Maintenance | Energy Services Directorate | Commercial and Operations | Nottingham City Council | Eastcroft | London Road |

NOTTINGHAM | NG2 3AH . Submitted by Advisor: [Redacted] Customer title is [Redacted]
Location: opposite 342 Trowell Road Nottingham at the cross boundary point on county council side Contact:

Plot Number: 2,000.00 Feature Id - Location: Street Section
Job Number: 2711030 Defect Number: 3607382

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	Category 2	Job Cancelled	01/12/2015	29/12/2015	Area: Broxtowe Est. BROX/3302403
2620076	The gullies along the footpath side of the carriageway require cleaning out (approximately 15No.) (HW DR Blocked Gully Z3)	From the junction of Waterloo road to Coventry lane junction along the footpath side					
2709624	Cway pothole filled whenfound (CW Repairs-Bituminous)	LC 89	Filled when found (Cat 2)	Job Completed	04/04/2019	04/04/2019	Act.

Effective: 01/04/2019 to 30/06/2019
 Display Action Officer: No
 Feature No.: 2000.00 to 2000.00
 Street: Nottingham Road (4922005)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
2711030	Carriageway Pothole filled when found (CW Repairs-Bituminous)	opposite 342 Trowell Road Nottingham at the cross boundary point on county council side	Filled when found (Cat 2)	Job Completed	17/04/2019	17/04/2019	Area: Broxtowe Act.
2711278	Excavate area and re patch Pat, This is the one with the metal below the surface I have attached some photos (CW Repairs-Bituminous)	Opposite lamp column 51 adjacent to the bus stop (city side of the crossroads): SUNDAY Work advised: STATS 450833 - 340001	Category 3	Job Completed	18/04/2019	02/06/2019	Act. BROX/3305873
2712034	Cway potholes filled when found (CW Repairs-Bituminous)	Lamp column 110	Filled when found (Cat 2)	Job Completed	29/04/2019	29/04/2019	Act.
2714954	Cway pothole filled when found (CW Repairs-Bituminous)	LC95	Filled when found (Cat 1)	Job Completed	28/05/2019	28/05/2019	Act.
2714955	Cway potholes (CW Repairs-Bituminous)	Lamp columns 83, 92, 97, 110 & 112	Category 2	Job Completed	28/05/2019	06/06/2019	Act. BRO-AS/5204957
2716358	Cway pothole filled when found (CW Repairs-Bituminous)	LC 92	Filled when found (Cat 1)	Job Completed	12/06/2019	12/06/2019	Act.
2716359	Reset loose gully cover (CW Ironwork)	Opposite lamp column 92	Category 2	Job Completed	12/06/2019	08/08/2019	Act. BROX/3306059

Street Works Notices

Organisation: Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)
 Works Ref: 1000841364
 Notice Type: Registration of Reinstatement - Full
 Work Status: Works Stopped
 Work Type: EToN 4: Standard
 Version: 4
 Start: 20/06/2019 00:00:00
 Issued: 26/06/2019 14:55:17
 Est. End: 26/06/2019
 Completion: 25/06/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	junction of coventry road in the verge	Verge	Up to 1.5 Metres of Cover	1.50	1.00 A Permanent Reinstatement	25/06/2019		25/06/2019	26/06/2019
2	junction of coventry road in the verge	Verge	Up to 1.5 Metres of Cover	1.00	1.00 A Permanent Reinstatement	25/06/2019		25/06/2019	25/06/2019
3	junction of coventry road in the verge	Verge	Up to 1.5 Metres of Cover	1.50	1.00 A Permanent Reinstatement	25/06/2019		25/06/2019	25/06/2019

Organisation: COLT - UDP (7075005)
 Works Ref: 010419/NOTT/01
 Notice Type: Registration of Reinstatement - Full
 Work Status: Works Stopped
 Work Type: EToN 4: Minor
 Version: 4
 Start: 05/04/2019 00:00:00
 Issued: 25/04/2019 13:28:12
 Est. End: 09/04/2019
 Completion: 09/04/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	10m from Lamp Column 69	Carriageway	Up to 1.5 Metres of Cover	1.40	0.80 A Permanent Reinstatement	09/04/2019		09/04/2019	09/04/2019
2	At Column 83	Carriageway	Up to 1.5 Metres of Cover	1.40	0.80 A Permanent Reinstatement	09/04/2019		09/04/2019	09/04/2019

Effective: 01/04/2019 to 30/06/2019
Display Action Officer: No

Feature No.: 2000.00 to 2002.00
Street: Nottingham Road (4911550)