

Effective: 26/11/2014 to 13/12/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Swingate (4911695)

Street: Swingate (4911695)

Locality: Kimberley, Nottinghamshire

Area: Broxtowe

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: High St To Knowle Ln		Feature Type: Street Section		Area: Broxtowe	
2608126	Cw pothole repaired by [REDACTED] (HW CW Pothole Z1)	68	Category 1	Job Completed	02/04/2015	02/04/2015	Act. BROX/3301116
2610037	Marked on site (HW CW Crazing Z1)	o/s 44 2 patches,	Category 2	Job Completed	07/05/2015	11/05/2015	Act. BROX/3301426
2610038	Marked on site (HW FW Crazing Side of Colly Gate, Z1)		Category 2	Job Completed	07/05/2015	11/05/2015	Act. BROX/3301427
2610039	PASS TO ASSISTANTS, marked on site (HW CW Pothole Z1)	o/s 44 on centre line,	Category 2	Job Completed	07/05/2015	11/05/2015	Act. BROX/3301428
2616964	Gully lid needs raising back to road level (HW DR Misalignment of cov Z4)	Gulley level and its surrounds - Opposite No 42 Swingate: STATS 450107 - 344112	Category 2	Job Completed	02/10/2015	05/01/2016	Act. BROX/3302168
2618492	Cway pothole filled when found (HW CW Pothole Z1)	At junction with knowle lane	Filled when found (Cat 1)	Job Completed	03/11/2015	03/11/2015	Act.
2621936	Cway pothole filled when found (HW CW Pothole Z1)	Outside numbers 68 and 17	Filled when found (Cat 1)	Job Completed	11/01/2016	11/01/2016	Act.
2622907	Cway pothole filled when found (HW CW Pothole Z1)	Outside number 68	Filled when found (Cat 1)	Job Completed	25/01/2016	25/01/2016	Act.
2623447	Cway pothole filled when found (HW CW Pothole Z1)	Outside number 19	Filled when found (Cat 1)	Job Completed	02/02/2016	02/02/2016	Act.
2624636	Cway pothole filled when found (HW CW Pothole Z1)	Outside number 68	Filled when found (Cat 1)	Job Completed	19/02/2016	19/02/2016	Act.
2624642	Cway patch (BC/WC) (may need to put no parking cones out prior to works as there are nearly always cars parked opposite) (HW CW Crazing Z1)	Outside number 68	Category 2	Job Completed	19/02/2016	11/10/2016	Act. BROX/3302622
2625997	Cway potholes filled when found (HW CW Pothole Z1)	Outside numbers 58,64 and 68	Filled when found (Cat 2)	Job Completed	08/03/2016	08/03/2016	Act.
2627135	Cway potholes (HW CW Pothole Z1)	Outside numbers 68,50 and 46	Category 2	Job Completed	30/03/2016	06/04/2016	Act. BRO-AS/5200835
2628732	Cway pothole (HW CW Pothole Z1)	Outside number 68	Category 2	Job Completed	22/04/2016	05/05/2016	Act. BRO-AS/5200929
2629481	Cway potholes filled when found (CW Repairs-Bituminous)	Outside number 68	Filled when found (Cat 1)	Job Completed	05/05/2016	05/05/2016	Act.
2633767	Cway potholes filled when found (CW Repairs-Bituminous)	outside numbers 68 and 46	Filled when found (Cat 2)	Job Completed	26/07/2016	26/07/2016	Act.
2634709	Cway pothole (CW Repairs-Bituminous)	outside 42	Category 2	Job Completed	15/08/2016	18/08/2016	Act. BRO-AS/5201162
2643817	Cway potholes (CW Repairs-Bituminous)	Lamp columns 27 & 31	Category 2	Job Completed	09/02/2017	10/02/2017	Act. BRO-AS/5201624
2646201	Carriageway Potholes (CW Repairs-Bituminous)	Outside 50 & 68	Category 1	Job Completed	13/03/2017	14/03/2017	Act. BRO-AS/5201781
2647313	Cway pothole filled when found (CW Repairs-Bituminous)	Outside 64	Filled when found (Cat 1)	Job Completed	29/03/2017	29/03/2017	Act.

Effective: 26/11/2014 to 13/12/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Swingate (4911695)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	High St To Knowle Ln	Feature Type:	Street Section	Area:	Broxtowe
2650211	Cway potholes (CW Repairs-Bituminous)	Outside 68	Category 2	Job Completed	11/05/2017	12/05/2017	Act. BRO-AS/5202010
2658508	Cway pothole filled when found (CW Repairs-Bituminous)	Lamp column 25	Filled when found (Cat 2)	Job Completed	25/09/2017	25/09/2017	Act.
2661593	Cway potholes (CW Repairs-Bituminous)	Lamp columns 22, 30 & 31	Category 2	Job Completed	06/11/2017	08/11/2017	Act. BRO-AS/5202553
2661594	Fway patches (FW Repairs-Bituminous)	Outside 22 & 52 and next to lamp column 28	Category 3	Job Completed	06/11/2017	09/11/2017	Act. BROX/3304294
2665366	Cway potholes filled when found (CW Repairs-Bituminous)	Outside the school	Filled when found (Cat 2)	Job Completed	28/12/2017	28/12/2017	Act.
2665942	Carriageway Pothole filled when found (CW Repairs-Bituminous)	Lamp column 29	Filled when found (Cat 1)	Job Completed	05/01/2018	05/01/2018	Act.
2667054	Carriageway Pothole filled when found (CW Repairs-Bituminous)	Outside 68	Filled when found (Cat 1)	Job Completed	16/01/2018	16/01/2018	Act.
2668755	Cway pothole filled when found (CW Repairs-Bituminous)	Opposite 58	Filled when found (Cat 1)	Job Completed	29/01/2018	29/01/2018	Act.
2669345	Cway potholes filled when found (CW Repairs-Bituminous)	LC 29	Filled when found (Cat 1)	Job Completed	01/02/2018	01/02/2018	Act.
2671088	Cway potholes (CW Repairs-Bituminous)	Between lamp columns 22 & 31	Category 2	Job Completed	15/02/2018	16/02/2018	Act. BRO-AS/5203122
2671089	Cway potholes filled when found (CW Repairs-Bituminous)	LC 31	Filled when found (Cat 1)	Job Completed	15/02/2018	15/02/2018	Act.
2674826	Carriageway Potholes filled when found (CW Repairs-Bituminous)	Outside 68 Swingate	Filled when found (Cat 1)	Job Completed	20/03/2018	20/03/2018	Act.
2677582	Carriageway potholes (CW Repairs-Bituminous)	Lamp column 25 to the bend	Category 2	Job Completed	12/04/2018	17/04/2018	Act. BRO-AS/5203505
2681331	Cway potholes (CW Repairs-Bituminous)	Lamp columns 22, 24, 28 & 30	Category 2	Job Completed	14/05/2018	17/05/2018	Act. BRO-AS/5203655
2681332	Reset loose bullnose kerb on the corner. (Kerbing/Edging)	At the junction with West st. STATS 450137 - 343990	Category 3	Job Completed	14/05/2018	31/05/2018	Act. BROX/3304857
2688947	Cway potholes (CW Repairs-Bituminous)	Around lamp column 29	Category 2	Job Completed	02/08/2018	02/08/2018	Act. BRO-AS/5203931
2688948	Cway patches (CW Repairs-Bituminous)	Outside 68 on the bend	Category 3	Job Completed	02/08/2018	07/08/2018	Act. BROX/3305076
2697807	Cway pothole filled when found (CW Repairs-Bituminous)	LC 25	Filled when found (Cat 2)	Job Completed	21/11/2018	21/11/2018	Act.
2699158	Cway potholes (CW Repairs-Bituminous)	Lamp columns 25, 27, 29 & 31	Category 2	Job Completed	07/12/2018	11/12/2018	Act. BRO-AS/5204290
2702257	Cway potholes (CW Repairs-Bituminous)	Lamp columns 22, 24, 25 & 31	Category 2	Job Completed	18/01/2019	22/01/2019	Act. BRO-AS/5204389
2706058	Cway potholes (CW Repairs-Bituminous)	Lamp columns 30 & 27	Category 2	Job Completed	26/02/2019	01/03/2019	Act. BRO-AS/5204555
2708644	Cway potholes (CW Repairs-Bituminous)	Around lamp column 29 and in the junction of North st	Category 2	Job Completed	22/03/2019	25/03/2019	Act. BRO-AS/5204661
2710661	Cway potholes (CW Repairs-Bituminous)	Lamp column 26	Category 2	Job Completed	12/04/2019	15/04/2019	Act. BRO-AS/5204748

Effective: 26/11/2014 to 13/12/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Swinggate (4911695)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: High St To Knowle Ln		Feature Type: Street Section		Area: Broxtowe	
2714081	Cway potholes (CW Repairs-Bituminous)	Lamp columns 22, 25, 27, 28 & 30	Category 2	Job Completed	17/05/2019	20/05/2019	Act. BRO-AS/5204892
2717525	Cway potholes (CW Repairs-Bituminous)	Lamp columns 25, 27, 29 & 30	Category 2	Job Completed	21/06/2019	28/06/2019	Act. BRO-AS/5205091
2721008	Replace 2x2m sections of sight gap pedestrian guard rail. This is at [REDACTED] request and not a safety defect. (Guardrail Repairs)	Swingate outside of Kimberley Primary School opposite West street junction	Category 3	Job Completed	05/08/2019	27/08/2019	Act. BROX/3306193
2726845	Cway potholes (CW Repairs-Bituminous)	Lamp columns 27 & 30	Category 2	Repair Completed	23/10/2019	29/10/2019	Act.
2726846	Fway patch (FW Repairs-Bituminous)	Outside number 46	Category 3	Job Completed	23/10/2019	26/11/2019	Act. BROX/3306473
2728858	Cway potholes (CW Repairs-Bituminous)	Lamp columns 22, 24, 25 & 29	Category 2	Repair Completed	20/11/2019	29/11/2019	Act.
2730016	Carriageway Pothole (CW Repairs-Bituminous)	Lamp column 29	Category 2	Repair Completed	02/12/2019	12/12/2019	Act.
2731038	Cway potholes (CW Repairs-Bituminous)	Lamp columns 25 & 27	Category 2	Job Sent to Operatives Device	11/12/2019	08/01/2020	Est.
Feat No.:	2,001.00	Feature Id - Locn.: Knowle Lane To End (Inc C-D-S)		Feature Type: Service Road		Area: Broxtowe	
2603175	PASS TO ASSISTANTS (HW CW Pothole Z1)	Outside 106	Category 1	Job Completed	19/01/2015	20/01/2015	Act. BROX/3300495
2606422	PASS TO ASSISTANTS, marked on site (HW CW Pothole Z1)	Opp White Lion 1no, outside 76 1no, outside 92 4no,	Category 2	Job Completed	04/03/2015	19/03/2015	Act. BROX/3300897
2608469	PASS TO ASSISTANTS, marked on site (HW CW Pothole Z1)	Outside 49	Category 2	Job Completed	09/04/2015	17/04/2015	Act. BROX/3301159
2610041	Marked on site (HW CW Crazying Z1)	o/s 65, junc Babbington Lane 2m2,	Category 2	Job Completed	07/05/2015	11/05/2015	Act. BROX/3301429
2610042	PASS TO ASSISTANTS, marked on site (HW CW Pothole Z1)	Opp 73	Category 2	Job Completed	07/05/2015	11/05/2015	Act. BROX/3301430
2610043	Fill all defects with 1 ton 6mm (HW CW Crazying Z1)	From outside 100a to Boundary	Category 2	Job Completed	07/05/2015	14/05/2015	Act. BROX/3301431
2620507	Cway pothole filled when found (HW CW Pothole Z1)	Outside number 78	Filled when found (Cat 1)	Job Completed	07/12/2015	07/12/2015	Act.
2623755	Cway potholes filled when found (HW CW Pothole Z1)	Outside numbers 100 and 55	Filled when found (Cat 1)	Job Completed	05/02/2016	05/02/2016	Act.
2634710	Cway potholes (CW Repairs-Bituminous)	Along the length	Category 2	Job Completed	15/08/2016	17/08/2016	Act. BRO-AS/5201163
2634711	Cway pothole filled when found (CW Repairs-Bituminous)	near lamp column 34	Filled when found (Cat 1)	Job Completed	15/08/2016	15/08/2016	Act.
2643819	Carriageway Potholes (CW Repairs-Bituminous)	between lamp column 33 & 34	Category 1	Job Completed	09/02/2017	10/02/2017	Act. BRO-AS/5201625
2649189	Carriageway potholes (CW Repairs-Bituminous)	Opposite 110	Category 1	Job Completed	27/04/2017	28/04/2017	Act. BRO-AS/5201943
2650150	Cway pothole (CW Repairs-Bituminous)	Outside 100	Category 1	Job Completed	10/05/2017	11/05/2017	Act. BRO-AS/5202005

Effective: 26/11/2014 to 13/12/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Swinggate (4911695)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Knowle Lane To End (Inc C-D-S)		Feature Type: Service Road		Area: Broxtowe	
2650209	Cway potholes (CW Repairs-Bituminous)	Between the White lion and 105	Category 2	Job Completed	11/05/2017	12/05/2017	Act. BRO-AS/5202009
2650210	Carriageway patch (CW Repairs-Bituminous)	outside No 73	Category 3	Job Cancelled	11/05/2017	08/06/2017	Est. BROX/3303889
2650457	Carriageway Damage - Carriageway patching and resetting of ironwork (Enquiry 3204206)	From 90 to 96 / Outside 98 / Junction of Babbington Lane / Outside 73	Category 3	Job Completed	16/05/2017	30/08/2017	Act. BROX/3303910
2650460	Carriageway Damage - Carriageway patching and reset gully (Enquiry 3204207)	Junction of Babbington Lane to 100A / Outside 102 - works to be undertaken in conjunction with WO 2650457	Category 3	Job Completed	16/05/2017	30/08/2017	Act. BROX/3303911
2654993	Carriageway Potholes (CW Repairs-Bituminous)	From Babbington lane to the end	Category 2	Job Completed	28/07/2017	02/08/2017	Act. BRO-AS/5202249
2655103	Cway potholes (CW Repairs-Bituminous)	Outside the white lion	Category 2	Job Completed	01/08/2017	02/08/2017	Act. BRO-AS/5202255
2655104	Fway pothole (FW Repairs-Bituminous)	Outside the white lion	Category 1	Job Completed	01/08/2017	02/08/2017	Act. BRO-AS/5202256
2671100	Carriageway Potholes filled when found (CW Repairs-Bituminous)	LC 38	Filled when found (Cat 1)	Job Completed	15/02/2018	15/02/2018	Act.
2671101	Carriageway Potholes (CW Repairs-Bituminous)	Lamp column 37 to 38	Category 2	Job Completed	15/02/2018	19/02/2018	Act. BRO-AS/5203134
2671102	Carriageway patch (CW Repairs-Bituminous)	On the bend near 102A	Category 3	Job Completed	15/02/2018	22/02/2018	Act. BROX/3304602
2674827	Cway potholes filled when found (CW Repairs-Bituminous)	LC 33	Filled when found (Cat 1)	Job Completed	20/03/2018	20/03/2018	Act.
2678179	Carriageway potholes (CW Repairs-Bituminous)	Outside 106 Swinggate property. At lamp column 38 near the boundary	Category 2	Job Completed	17/04/2018	20/04/2018	Act. BRO-AS/5203526
2681263	Carriageway patch also reset 3 stop valve covers and wash out lid to prevent water standing in the area. (CW Repairs-Bituminous)	outside 106 Swinggate on the boundary: STATS 450123 - 343760	Category 3	Job Completed	11/05/2018	28/06/2018	Act. BROX/3304853
2687634	Carriageway Potholes (CW Repairs-Bituminous)	From the pub to the boundary	Category 2	Job Completed	13/07/2018	17/07/2018	Act. BRO-AS/5203880
2687635	Carriageway Potholes filled when found (CW Repairs-Bituminous)	Towards the end of Swinggate at the tight bend opposite the semi detached red brick houses.	Filled when found (Cat 1)	Job Completed	13/07/2018	13/07/2018	Act.
2688951	Cway potholes (CW Repairs-Bituminous)	Lamp columns 33, 34, 35, 36 & 37 also in the dead end opposite 36	Category 2	Job Completed	02/08/2018	02/08/2018	Act. BRO-AS/5203934
2697808	Cway potholes filled when found (CW Repairs-Bituminous)	Along the length	Filled when found (Cat 2)	Job Completed	21/11/2018	21/11/2018	Act.
2699159	Cway potholes (CW Repairs-Bituminous)	Lamp columns 36 & 38	Category 2	Job Completed	07/12/2018	11/12/2018	Act. BRO-AS/5204291

Effective: 26/11/2014 to 13/12/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Swingate (4911695)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Knowle Lane To End (Inc C-D-S)		Feature Type: Service Road		Area: Broxtowe	
2702258	Cway potholes (CW Repairs-Bituminous)	Outside the white lion and next to lamp column 36	Category 2	Job Completed	18/01/2019	22/01/2019	Act. BRO-AS/5204390
2714078	Carriageway Potholes (CW Repairs-Bituminous)	Outside white lion pub	Category 2	Job Completed	17/05/2019	20/05/2019	Act. BRO-AS/5204891
2720958	Fway potholes filled when found (FW Repairs-Bituminous)	Outside the white lion pub	Filled when found (Cat 2)	Job Completed	05/08/2019	05/08/2019	Act.