

Effective: 26/11/2018 to 17/12/2019
 Display Action Officer: No

Feature No.: 2000.00 to 2000.00
 Street: Netherfield Lane (26808134)

Street: Netherfield Lane (26808134)

Locality: Perlethorpe cum Budby, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J			Feature Type: Street Section			Area: Newark	
Batch: 20367377 - Inspection Batch				Route: Newark Area 1 Dec Saf CW				Date: 09/12/2019
3626980	potholes marked	09/12/2019	50m from thoresby entrance	CW Repairs-Bituminous	Internal		Uncommitted	2730709
Batch: 20364473 - Inspection Batch				Route: Adhoc Inspection				Date: 25/11/2019
3625562	potholes mrked	25/11/2019	round bend from pink house westbound	CW Repairs-Bituminous	Internal		Uncommitted	2729287
Batch: 20364470 - Inspection Batch				Route: Adhoc Inspection				Date: 25/11/2019
3625560	potholes marked	25/11/2019	10m past bend/ice sign west bound	CW Repairs-Bituminous	Internal		Uncommitted	2729285
Batch: 20364468 - Inspection Batch				Route: Adhoc Inspection				Date: 25/11/2019
3625559	potholes marked	25/11/2019	50m before bend/ice sign westbound	CW Repairs-Bituminous	Internal		Uncommitted	2729284
Batch: 20364463 - Inspection Batch				Route: Adhoc Inspection				Date: 25/11/2019
3625557	pothole 500x450x70	25/11/2019	50m after layby travelling west	CW Repairs-Bituminous	Internal		Uncommitted	2729282
Batch: 20363322 - Inspection Batch				Route: Newark Area 1 Nov Saf CW				Date: 14/11/2019
No actionable defects found								
Batch: 20363102 - Inspection Batch				Route: Adhoc Inspection				Date: 13/11/2019
3624625		13/11/2019	100m before bend/ice sign	CW Repairs-Bituminous	Internal		Uncommitted	2728349
Batch: 20362640 - Inspection Batch				Route: Adhoc Inspection				Date: 11/11/2019
3624307	Carriageway Pothole - Road Pothole - 2 large potholes, within metres of eadh other. This report is about BOTH of these, which are very dangerous and need to be fixed asap!!!! Please check the remainder of the road as there are so many holes on this road, it is getting dangerous AND MAKE A PROPER JOB OF FIXING THEM SO THEY DONT DISINTEGRATE AND NEED FIXING AGAIN IN A MONTH!!!! . Online report Customer title [REDACTED] (Enquiry 6145245)	11/11/2019	Netherfield Lane, on the left as travelling from worksop towards perthorpe, before Thoresby hotel turning. NOTE There are 2 large potholes in fairly close proximity to each other, both before the Thoresby turning.	CW Repairs-Bituminous	Internal		Uncommitted	2728030
Batch: 20362638 - Inspection Batch				Route: Adhoc Inspection				Date: 11/11/2019
3624306	Carriageway Pothole - Insurance claim form requested - Road Pothole - Customer was travelling along the road and has struck a pot hole and damaged both wheels of the car, this has dented the inside of the rim . Submitted by Advisor: [REDACTED] (Enquiry 6145362)	11/11/2019	Netherfield Lane, Outside entrance to Thorseby Park, opposite side to the entrance	CW Repairs-Bituminous	Internal		Uncommitted	2728029

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	C6 - Point 1155M South-West Of A614 Roundabout To B6034 J	Feature Type:	Street Section		Area: Newark	
Batch: 20362208 - Inspection Batch		Route: Adhoc Inspection			Date: 06/11/2019			
3624065	Carriageway Pothole - Road Pothole - Please see the customer's email below: "There is a huge pothole coming from Thorsby Gall towards Worksop. It is very deep and in the line of tyres. This pothole is extremely deep and I have had to take my car to the garage to have a new tyre, tracking and paint work done on my car. This needs sorting ASAP, before it causes a serious accident!" Submitted by Advisor: [REDACTED] [REDACTED] Customer title is (Enquiry 6144448)	06/11/2019	From Thorsby Gall towards Worksop, Newark, NG22 9EW	CW Repairs-Bituminous	Internal		Uncommitted	2727788
Batch: 20361154 - Inspection Batch		Route: Adhoc Inspection			Date: 30/10/2019			
3623547	potholes	30/10/2019	near bend	CW Repairs-Bituminous	Internal		Uncommitted	2727267
Batch: 20361152 - Inspection Batch		Route: Adhoc Inspection			Date: 30/10/2019			
3623546	Carriageway Pothole - Road Pothole - Holes in road lucky they didn't cause accident to me and the car in front . Online report Customer title [REDACTED] (Enquiry 6143711)	30/10/2019	I cannot give exact location but it was on the road past Thoresby Park t Budby. I hit 2 potholes which subsequently gave me a puncture and I have to replace the tire. It also bent my alloy	CW Repairs-Bituminous	Internal		Uncommitted	2727266
Batch: 20358208 - Inspection Batch		Route: Adhoc Inspection			Date: 08/10/2019			
3621815	pothole marked	08/10/2019	Road from Budby to Thoresby.200m from junc Worksop Rd	CW Repairs-Bituminous	Internal		Uncommitted	2725523
Batch: 20357146 - Inspection Batch		Route: Newark Area 1 Oct Saf CW			Date: 03/10/2019			
3621383	potholes marked	03/10/2019	100m before chevrons	CW Repairs-Bituminous	Internal		Uncommitted	2725092
3621382		03/10/2019	between brows 100m from roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2725091
3621384		03/10/2019	between pink house and entrance	CW Repairs-Bituminous	Internal		Uncommitted	2725093
3621386	potholes marked	03/10/2019	around bend adj pink house	CW Repairs-Bituminous	Internal		Uncommitted	2725090
3621385	pothole marked	03/10/2019	50m before thoresby ent	CW Repairs-Bituminous	Internal		Uncommitted	2725094
Batch: 20352857 - Inspection Batch		Route: Newark Area 1 Sep Saf CW			Date: 03/09/2019			
No actionable defects found								
Batch: 20350019 - Inspection Batch		Route: Newark Area 1 Aug Saf CW			Date: 14/08/2019			
3617981	pothole	14/08/2019	near thoresby hall marked	CW Repairs-Bituminous	Internal		Committed	2721670
3617980	pothole	14/08/2019	near pink house marked	CW Repairs-Bituminous	Internal		Committed	2721669
3617982	pothole	14/08/2019	in dip mini roundabout end marked	CW Repairs-Bituminous	Internal		Committed	2721668
Batch: 20347131 - Inspection Batch		Route: Newark Area 1 Jul Saf CW			Date: 23/07/2019			
No actionable defects found								

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J			Feature Type: Street Section			Area: Newark	
Batch: 20342274 - Inspection Batch				Route: Newark Area 1 Jun Saf CW				Date: 20/06/2019
3613621	pothole	20/06/2019	either side of camillion pink cottage marked in white paint	CW Repairs-Bituminous	Internal		Uncommitted	2717291
3613620	pothole 120 mm x 400 mm x 95 mm	20/06/2019	200 m before camillion cottage left hand approach heading to budby	CW Repairs-Bituminous	Internal		Uncommitted	2717292
Batch: 20341822 - Inspection Batch				Route: Adhoc Inspection				Date: 18/06/2019
3613418	pothole 1 m x 1 m x	18/06/2019	approx 450 m from thoresby hall heading to A 614	CW Repairs-Bituminous	Internal		Uncommitted	2717088
Batch: 20341820 - Inspection Batch				Route: Adhoc Inspection				Date: 18/06/2019
3613414	pothole 940 x 500 x 90 mm	18/06/2019	approx 500 m from thoresby hall heading to budby	CW Repairs-Bituminous	Internal		Uncommitted	2717084
Batch: 20338356 - Inspection Batch				Route: Newark Area 1 May Saf CW				Date: 29/05/2019
3611357	pothole	29/05/2019	near big logs in layby marked	CW Repairs-Bituminous	Internal		Committed	2715019
Batch: 20337984 - Inspection Batch				Route: Adhoc Inspection				Date: 28/05/2019
3611230	potholes	28/05/2019	opposite camillion pink cottage marked near bend in both directions approx 100 m either way	CW Repairs-Bituminous	Internal		Committed	2714892
Batch: 20333752 - Inspection Batch				Route: Newark Area 1 Apr Enh CW/FW				Date: 29/04/2019
3608328	potholes	29/04/2019	after pink cottage and after road liable to icing sign heading to thoresby hall marked in white paint	CW Repairs-Bituminous	Internal		Committed	2711980
3608327	pothole L 890 x W 535 x D 50 mm	29/04/2019	after camillion pink cottage in center line	CW Repairs-Bituminous	Internal		Uncommitted	2711979
3608326	potholes	29/04/2019	before bend to pink cottage heading to thoresby hall marked in white paint	CW Repairs-Bituminous	Internal		Committed	2711978
3608330	potholes	29/04/2019	approx 800 m from budby roundabout heading to thoresby hall marked in white paint	CW Repairs-Bituminous	Internal		Committed	2711977
3608329	pothole	29/04/2019	far end approach to A614 roundabout marked in white paint	CW Repairs-Bituminous	Internal		Committed	2711981
Batch: 20325714 - Inspection Batch				Route: Newark Area 1 Mar Saf CW				Date: 05/03/2019
3603075	potholes filled during inspection	05/03/2019	outside camillion cottage	CW Repairs-Bituminous	Internal		Uncommitted	2706674
3603074	pothole filled during inspection with assistant	05/03/2019	outside thoresby hall	CW Repairs-Bituminous	Internal		Uncommitted	2706675
Batch: 20323350 - Inspection Batch				Route: Newark Area 1 Feb Saf CW				Date: 18/02/2019
3601636	pothole filled during inspection 450 x 450 x 80 mm	18/02/2019	as mapped 150 m past camillion cottage heading to A614	CW Repairs-Bituminous	Internal		Uncommitted	2705208
Batch: 20319188 - Inspection Batch				Route: Newark Area 1 Jan Saf CW				Date: 17/01/2019
3598716	potholes filled during inspection	17/01/2019	near camillion cottage	CW Repairs-Bituminous	Internal		Committed	2702225
3598718	potholes	17/01/2019	in center line on bend outside camillion cottage marked in yellow paint	CW Repairs-Bituminous	Internal		Committed	2702224

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J			Feature Type: Street Section			Area: Newark	
Batch: 20319188 - Inspection Batch				Route: Newark Area 1 Jan Saf CW				Date: 17/01/2019
3598717		17/01/2019	400 yds 600 yds and 800 yds from budby roundabout heading to thoresby marked on right hand side in yellow	CW Repairs-Bituminous	Internal		Committed	2702226
Batch: 20316444 - Inspection Batch				Route: Adhoc Inspection				Date: 24/12/2018
3596899	pothole filled when found cat 1 high 350 x 350 x 60 mm	24/12/2018	heading to A614 100 m before thoresby hall	CW Repairs-Bituminous	Internal		Uncommitted	2700361
Batch: 20316442 - Inspection Batch				Route: Adhoc Inspection				Date: 24/12/2018
3596897	filled when found	24/12/2018	400 m from camellion cottage heading to budby from thoresby hall	CW Repairs-Bituminous	Internal		Uncommitted	2700359
Batch: 20316440 - Inspection Batch				Route: Adhoc Inspection				Date: 24/12/2018
3596895	pothole filled when found 600 x 400 x 60 mm	24/12/2018	near road liable to icing sign and camellion cottage	CW Repairs-Bituminous	Internal		Uncommitted	2700357
Batch: 20316439 - Inspection Batch				Route: Adhoc Inspection				Date: 24/12/2018
3596894	potholes	24/12/2018	just past camellion cottage on bend heading back to budby	CW Repairs-Bituminous	Internal		Uncommitted	2700356
Batch: 20314064 - Inspection Batch				Route: Newark Area 1 Dec Saf CW				Date: 05/12/2018
3595428	pothole filled during inspection	05/12/2018	just before road liable to icing sign near camellion cottage	CW Repairs-Bituminous	Internal		Uncommitted	2698856
Batch: 20314037 - Inspection Batch				Route: Adhoc Inspection				Date: 05/12/2018
3595389	pothole filled during inspection 1.9 m x 0.6 x 0.070 mm	05/12/2018	near thoresby hall	CW Repairs-Bituminous	Internal		Uncommitted	2698817

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J			Feature Type: Street Section		Area: Newark	
2698817	pothole filled during inspection 1.9 m x 0.6 x 0.070 mm (CW Repairs-Bituminous)	near thoresby hall	Filled when found (Cat 1)	Job Completed	05/12/2018	05/12/2018	Act.
2698856	pothole filled during inspection (CW Repairs-Bituminous)	just before road liable to icing sign near camellion cottage	Filled when found (Cat 2)	Job Completed	05/12/2018	05/12/2018	Act.
2700356	potholes (CW Repairs-Bituminous)	just past camellion cottage on bend heading back to budby	Filled when found (Cat 2)	Job Completed	24/12/2018	24/12/2018	Act.
2700357	pothole filled when found 600 x 400 x 60 mm (CW Repairs-Bituminous)	near road liable to icing sign and camellion cottage	Filled when found (Cat 1)	Job Completed	24/12/2018	24/12/2018	Act.
2700359	filled when found (CW Repairs-Bituminous)	400 m from camellion cottage heading to budby from thoresby hall	Filled when found (Cat 2)	Job Completed	24/12/2018	24/12/2018	Act.
2700361	pothole filled when found cat 1 high 350 x 350 x 60 mm (CW Repairs-Bituminous)	heading to A614 100 m before thoresby hall	Filled when found (Cat 1)	Job Completed	24/12/2018	24/12/2018	Act.

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	C6 - Point 1155M South-West Of A614 Roundabout To B6034 J	Feature Type:	Street Section	Area:	Newark
2702224	potholes (CW Repairs-Bituminous)	in center line on bend outside camellion cottage marked in yellow paint	Category 3	Job Completed	17/01/2019	17/03/2019	Act. NEW/3612862
2702225	potholes filled during inspection (CW Repairs-Bituminous)	near camellion cottage	Filled when found (Cat 2)	Job Completed	17/01/2019	24/01/2019	Act. NEW/3612861
2702226	CW Repairs-Bituminous	400 yds 600 yds and 800 yds from budby roundabout heading to thoresby marked on right hand side in yellow	Category 3	Job Completed	17/01/2019	17/03/2019	Act. NEW/3612863
2705208	pothole filled during inspection 450 x 450 x 80 mm (CW Repairs-Bituminous)	as mapped 150 m past camellion cottage heading to A614	Filled when found (Cat 1)	Job Completed	18/02/2019	18/02/2019	Act.
2706674	potholes filled during inspection (CW Repairs-Bituminous)	outside camillion cottage	Filled when found (Cat 2)	Job Completed	05/03/2019	05/03/2019	Act.
2706675	pothole filled during inspection with assistant (CW Repairs-Bituminous)	outside thoresby hall	Filled when found (Cat 2)	Job Completed	05/03/2019	05/03/2019	Act.
2711977	potholes (CW Repairs-Bituminous)	approx 800 m from budby roundabout heading to thoresby hall marked in white paint	Category 2	Repair Completed	29/04/2019	08/05/2019	Act. NEW-AS/5508718
2711978	potholes (CW Repairs-Bituminous)	before bend to pink cottage heading to tjoresby hall marked in white paint	Category 2	Repair Completed	29/04/2019	08/05/2019	Act. NEW-AS/5508713
2711979	pothole L 890 x W 535 x D 50 mm (CW Repairs-Bituminous)	after camillion pink cottage in center line	Filled when found (Cat 1)	Job Completed	29/04/2019	29/04/2019	Act.
2711980	potholes (CW Repairs-Bituminous)	after pink cottage and after road liable to icing sign heading to thoresby hall marked in white paint	Category 2	Repair Completed	29/04/2019	08/05/2019	Act. NEW-AS/5508714
2711981	pothole (CW Repairs-Bituminous)	far end approach to A614 roundabout marked in white paint	Category 2	Repair Completed	29/04/2019	08/05/2019	Act. NEW-AS/5508715
2714892	potholes (CW Repairs-Bituminous)	opposite camellion pink cottage marked near bend in both directions approx 100 m either way	Category 2	Repair Completed	28/05/2019	29/05/2019	Act. NEW-AS/5509026
2715019	pothole (CW Repairs-Bituminous)	near big logs in layby marked	Category 2	Job Completed	29/05/2019	04/06/2019	Act. NEW/3614864
2717084	pothole 940 x 500 x 90 mm (CW Repairs-Bituminous)	approx 500 m from thoresby hall heading to budby	Filled when found (Cat 1)	Job Completed	18/06/2019	18/06/2019	Act.
2717088	pothole 1 m x 1 m x (CW Repairs-Bituminous)	approx 450 m from thoresby hall heading to A 614	Filled when found (Cat 1)	Job Completed	18/06/2019	18/06/2019	Act.
2717291	pothole (CW Repairs-Bituminous)	either side of camillion pink cottage marked in white paint	Filled when found (Cat 1)	Job Completed	20/06/2019	20/06/2019	Act.
2717292	pothole 120 mm x 400 mm x 95 mm (CW Repairs-Bituminous)	200 m before camillion cottage left hand approach heading to budby	Filled when found (Cat 1)	Job Completed	20/06/2019	20/06/2019	Act.

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J		Feature Type: Street Section		Area: Newark	
2721668	pothole (CW Repairs-Bituminous)	in dip mini roundabout end marked	Category 2	Repair Completed	14/08/2019	19/08/2019	Act. NEW-AS/5509603
2721669	pothole (CW Repairs-Bituminous)	near pink house marked	Category 2	Repair Completed	14/08/2019	19/08/2019	Act. NEW-AS/5509604
2721670	pothole (CW Repairs-Bituminous)	near thoresby hall marked	Category 2	Repair Completed	14/08/2019	19/08/2019	Act. NEW-AS/5509605
2725090	potholes marked (CW Repairs-Bituminous)	around bend adj pink house	Category 2	Repair Completed	03/10/2019	09/10/2019	Act. NEW-AS/5510056
2725091	CW Repairs-Bituminous	between brows 100m from roundabout	Category 2	Repair Completed	03/10/2019	09/10/2019	Act. NEW-AS/5510057
2725092	potholes marked (CW Repairs-Bituminous)	100m before chevrons	Category 2	Repair Completed	03/10/2019	09/10/2019	Act. NEW-AS/5510058
2725093	CW Repairs-Bituminous	between pink house and entrance	Category 2	Repair Completed	03/10/2019	09/10/2019	Act. NEW-AS/5510059
2725094	pothole marked (CW Repairs-Bituminous)	50m before thoresby ent	Category 2	Repair Completed	03/10/2019	09/10/2019	Act. NEW-AS/5510060
2725523	pothole marked (CW Repairs-Bituminous)	Road from Budby to Thoresby.200m from junc Worksoy Rd	Category 1	Repair Completed	08/10/2019	09/10/2019	Act. NEW-AS/5510145
2727266	Carriageway Pothole - Road Pothole - Holes in road lucky they didn't cause accident to me and the car in front. Online report Customer title [REDACTED]. (Enquiry 6143711) (CW Repairs-Bituminous)	I cannot give exact location but it was on the road past Thoresby Park t Budby. I hit 2 potholes which subsequently gave me a puncture and I have to replace the tire. It also bent my alloy	Filled when found (Cat 1)	Job Completed	30/10/2019	30/10/2019	Act.
2727267	potholes (CW Repairs-Bituminous)	near bend	Category 2	Repair Completed	30/10/2019	01/11/2019	Act.
2727788	Carriageway Pothole - Road Pothole - Please see the customer's email below: "There is a huge pothole coming from Thorsby Gall towards Worksoy. It is very deep and in the line of tyres. This pothole is extremely deep and I have had to take my car to the garage to have a new tyre, tracking and paint work done on my car. This needs sorting ASAP, before it causes a serious accident!" Submitted by Advisor: [REDACTED] Customer title is (Enquiry 6144448) (CW Repairs-Bituminous)	From Thorsby Gall towards Worksoy, Newark, NG22 9EW	Filled when found (Cat 1)	Job Completed	06/11/2019	07/11/2019	Act.

Effective: 26/11/2018 to 17/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Netherfield Lane (26808134)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C6 - Point 1155M South-West Of A614 Roundabout To B6034 J		Feature Type: Street Section		Area: Newark	
2728029	Carriageway Pothole - Insurance claim form requested - Road Pothole - Customer was travelling along the road and has struck a pot hole and damaged both wheels of the car, this has dented the inside of the rim. Submitted by Advisor: [REDACTED]. (Enquiry 6145362) (CW Repairs-Bituminous)	Netherfield Lane, Outside entrance to Thorseby Park, opposite side to the entrance	Filled when found (Cat 1)	Job Completed	11/11/2019	11/11/2019	Act.
2728030	Carriageway Pothole - Road Pothole - 2 large potholes, within metres of each other. This report is about BOTH of these, which are very dangerous and need to be fixed asap!!!! Please check the remainder of the road as there are so many holes on this road, it is getting dangerous AND MAKE A PROPER JOB OF FIXING THEM SO THEY DONT DISINTEGRATE AND NEED FIXING AGAIN IN A MONTH!!! . Online report Customer title [REDACTED] (Enquiry 6145245) (CW Repairs-Bituminous)	Netherfield Lane, on the left as travelling from worksop towards perthorpe, before Thoresby hotel turning. NOTE There are 2 large potholes in fairly close proximity to each other, both before the Thoresby turning.	Filled when found (Cat 1)	Job Completed	11/11/2019	11/11/2019	Act.
2728349	CW Repairs-Bituminous	100m before bend/ice sign	Filled when found (Cat 2)	Job Completed	13/11/2019	13/11/2019	Act.
2729282	pothole 500x450x70 (CW Repairs-Bituminous)	50m after layby travelling west	Filled when found (Cat 1)	Job Completed	25/11/2019	25/11/2019	Act.
2729284	potholes marked (CW Repairs-Bituminous)	50m before bend/ice sign westbound	Category 2	Repair Completed	25/11/2019	26/11/2019	Act.
2729285	potholes marked (CW Repairs-Bituminous)	10m past bend/ice sign west bound	Category 2	Repair Completed	25/11/2019	26/11/2019	Act.
2729287	potholes mrked (CW Repairs-Bituminous)	round bend from pink house westbound	Category 2	Repair Completed	25/11/2019	26/11/2019	Act.
2730709	potholes marked (CW Repairs-Bituminous)	50m from thoresby entrance	Category 2	Job Sent to Operatives Device	09/12/2019	06/01/2020	Est.