

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Way (15003246)

Display Action Officer: Yes

Street: Blidworth Way (15003246)

Locality: Ravenshead, Nottinghamshire

Area: Gedling

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	Ravenshead	Feature Type:	Street Section		Area: Gedling	
Batch:	20369762 - Inspection Batch			Route:	Gedling Area 1 Dec Saf CW	Officer:	(Ged Inspector)	Date: 20/12/2019
	No actionable defects found							
Batch:	20364558 - Inspection Batch			Route:	Gedling Area 1 Nov Saf CW	Officer:	(Ged Inspector)	Date: 25/11/2019
	No actionable defects found							
Batch:	20363566 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 18/11/2019
3624858	potholes as marked	18/11/2019	just as you turn on to Blidworth Way from mansfield road	CW Repairs-Bituminous	Internal		Uncommitted	2728582
Batch:	20363560 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 18/11/2019
3624854	PATCH AS MARKED OUT PHOTOS ADDED OF DEFECT	18/11/2019	Large pot hole of left hand side of lane travelling from Ravenshead to Papplewick. coned off to make safe just past ABBEY VIEW FARM	CW Repairs-Bituminous	Internal		Committed	2728578
Batch:	20362923 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 13/11/2019
3624530	Carriageway Pothole cat 1 repaired on site size 1mtr x 0.50 120ml depth	13/11/2019	almost at the junction with mansfield road	CW Repairs-Bituminous	Internal		Uncommitted	2728253
Batch:	20362916 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 13/11/2019
3624525	2 x seal patches as marked out	13/11/2019	opp side to abbey view as marked	CW Repairs-Bituminous	Internal		Committed	2728247
3624524	Carriageway pothole cat 1 size length 1mtr x 1mtr and depth of 120ml depth ... repaired on site with via fix	13/11/2019	just after where lay by is were building cat 1 repaired on site	CW Repairs-Bituminous	Internal		Uncommitted	2728248
Batch:	20360704 - Inspection Batch			Route:	Gedling Area 1 Oct Saf CW	Officer:	(Ged Inspector)	Date: 28/10/2019
3623372	potholes as marked	28/10/2019	just passed the GARTH gates and at the lay bye boundary	CW Repairs-Bituminous	Internal		Committed	2727092
Batch:	20356206 - Inspection Batch			Route:	Gedling Area 1 Sep Saf CW	Officer:	(Ged Inspector)	Date: 24/09/2019
	No actionable defects found							
Feat No.:	3,504.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 2 Posts		Area: Gedling	
Batch:	20702398 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,505.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702402 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,506.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702403 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,507.00	Feature Id - Locn.:	on col 1	Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702408 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003246)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	4,600.00	Feature Id - Locn.:	S1 - LHS from A60	Feature Type:	Lit Sign		Area: Gedling	
Batch:	20711010 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/12/2019
	No actionable defects found							
Batch:	20708918 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 25/11/2019
	No actionable defects found							
Batch:	20705335 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 14/10/2019
	No actionable defects found							
Batch:	20703343 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/09/2019
	No actionable defects found							
Batch:	20702399 - Inspection Batch			Route:	pAPPLEWICK LIT SIGNS	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	4,602.00	Feature Id - Locn.:	S3 - Give way - Junc With A60	Feature Type:	Lit Sign		Area: Gedling	
Batch:	20711010 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/12/2019
	No actionable defects found							
Batch:	20708918 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 25/11/2019
	No actionable defects found							
Batch:	20705335 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 14/10/2019
	No actionable defects found							
Batch:	20703343 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/09/2019
	No actionable defects found							
Batch:	20702401 - Inspection Batch			Route:	pAPPLEWICK LIT SIGNS	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	4,604.00	Feature Id - Locn.:	S2 - RHS from A60	Feature Type:	Lit Sign		Area: Gedling	
Batch:	20711010 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/12/2019
	No actionable defects found							
Batch:	20708918 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 25/11/2019
	No actionable defects found							
Batch:	20705335 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 14/10/2019
	No actionable defects found							
Batch:	20703343 - Inspection Batch			Route:	Gedling Patrol	Officer:	(SL Ged-Brox N)	Date: 23/09/2019
	No actionable defects found							
Batch:	20702400 - Inspection Batch			Route:	pAPPLEWICK LIT SIGNS	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003246)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6147337 **Logged by:** External to Confirm **on:** 22/11/2019 16:57 **Officer:** Risk & Insurance
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS158308798
Desc.: Insurance claim - related to Confirm defect reference: 6147336
Date/Time: 18/11/2019 07:45:00
Direction of travel: The caller was heading towards Papplewick on Blidworth Waye near the site entrance for a farm/building site.
Account of what happened: The caller was driving on the road in the morning when the front passenger side wheel hit the pothole, this has bent the alloy and it's not useable. The caller has had to replace the alloy and the tyre as it was slowly letting air out. [REDACTED].
Location: Blidworth waye **Contact:**

Enquiry No.: 6147336 **Logged by:** External to Confirm **on:** 22/11/2019 16:56 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Insurance claim form requested - Road Pothole - Large pothole within the road surface which has damaged the gentleman's alloy.
The caller was driving on the road in the morning when the front passenger side wheel hit the pothole, this has bent the alloy and it's not useable. The caller has had to replace the alloy and the tyre as it was slowly letting air out. HE is wanting to claim for this. . Submitted by Advisor: [REDACTED]
Location: Blidworth waye **Contact:**

Enquiry No.: 6147111 **Logged by:** External to Confirm **on:** 21/11/2019 10:36 **Officer:** [REDACTED]
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Insurance claim - related to Confirm defect reference: 6147110
Date/Time: 18/11/2019 07:50:00
Direction of travel: Towards Papplewick (South West)
Account of what happened: I hit a pothole at the edge of the road and consequently two of my tyres burst. Following the arrival of a breakdown patrol I had to go to a garage in order to have the tyres replaced and my wheels re-aligned. Several other cars also experienced an issue with the same pothole on that morning as it was not clearly marked on the road as a hazard.
Location: Blidworth Waye (B683), Papplewick, approximately opposite the sign for Abbey View Farm. **Contact:**

Enquiry No.: 6147110 **Logged by:** External to Confirm **on:** 21/11/2019 10:35 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Insurance claim form requested - Road Pothole - Pot hole on the edge of the South Bound carriage way. . Submitted by Advisor: [REDACTED]
Location: Blidworth Waye (B683), Papplewick, approximately opposite the sign for Abbey View Farm. **Contact:**

Enquiry No.: 6146650 **Logged by:** External to Confirm **on:** 18/11/2019 12:33 **Officer:** Risk & Insurance
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Insurance claim - related to Confirm defect reference: 6146494
Date/Time: 17/11/2019 19:00:00
Direction of travel: From Bolsover to Nottingham Road to Hucknall
Account of what happened: The customer rang regarding some potholes on the road which had an impact on the car's Tyre. The Tyre gone flat and had to wait for assistance which she got it 5 hours later because of the flood the customer had to wait so much [REDACTED].
Location: Left side from Ravenshead to Papplewick **Contact:**

Enquiry No.: 6146574 **Logged by:** External to Confirm **on:** 18/11/2019 08:45 **Officer:** [REDACTED] (Ged Inspector)
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - As above . Online report [REDACTED]
Location: Large pot hole of left hand side of lane travelling from Ravenshead to Papplewick. On straight just after the forest ends **Contact:**

Plot Number: 2,000.00
Job Number: 2728578

Feature Id - Location: Ravenshead
Defect Number: 3624854

Feature Type: Street Section

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003246)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6146494 **Logged by:** External to Confirm **on:** 16/11/2019 15:48 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - Large pothole at the side of the road . Online report [REDACTED].
Location: Left side from Ravenshead to Papplewick **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** Ravenshead **Feature Type:** Street Section
Job Number: 2728582

Enquiry No.: 6145900 **Logged by:** External to Confirm **on:** 13/11/2019 19:36 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - A large pothole which I couldn't avoid. I couldn't stop at the scene as there were cars behind me and there is no stopping place nearby. . Online report [REDACTED]
Previous Confirm Case: [REDACTED]
Location: At the top of Blidworth Waye. I was heading south on the A60 , and turned right into Blidworth Waye. There was a loud noise as I hit the pothole, just after turning right. There appeared to be no visible damage to my car, but it is going for an MOT and service on Monday, where I would think any non-visible damage will be detected.
Contact:

Time - 10.45.a.m on Tuesday 12 November 2019.

Enquiry No.: 6145636 **Logged by:** External to Confirm **on:** 12/11/2019 11:36 **Officer:** [REDACTED] (Ged Inspector)
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Damage - as above . Online report [REDACTED].
Location: on the left hand side going towards linby the new works being carried out is using large lorries which this road is not wide enough so the lorries are on the edge of the road this part has broke away and has left a considerable length of road damaged again full of water but the lorry i followed was pushing the water away with its tyres and exposing the damage allowing me to avoid damage to my car
Contact:

Plot Number: 2,000.00 **Feature Id - Location:** Ravenshead **Feature Type:** Street Section
Job Number: 2728247 **Defect Number:** 3624525

Enquiry No.: 6145635 **Logged by:** External to Confirm **on:** 12/11/2019 11:33 **Officer:** [REDACTED] (Ged Inspector)
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - 15 inches round hole full of water but feels deep with wheels . Online report [REDACTED]
Location: almost at the junction when turning in you have to avoid it by going towards incoming traffic
Contact:

Plot Number: 2,000.00 **Feature Id - Location:** Ravenshead **Feature Type:** Street Section
Job Number: 2728253 **Defect Number:** 3624530

Enquiry No.: 84197 **Logged by:** [REDACTED] **on:** 28/11/2019 12:43 **Officer:** [REDACTED]
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation
Desc.: Incident 18/11/19: Driving to work, hit the pot hole felt my car pulling to the left, tyre pressure light came on in car. (enquiry raised on receipt of claim form)
Location: B683 **Contact:**

Enquiry No.: 84087 **Logged by:** [REDACTED] **on:** 25/11/2019 10:35 **Officer:** Risk & Insurance
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation
Desc.: Incident date 18/11/2019 Car went into a pothole causing damage to tyre and wheel (on receipt of a claim form an insurance claim has been raised)
Location: Blidworth Waye **Contact:**

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003246)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: Ravenshead			Feature Type: Street Section		Area: Gedling	
2612501	Blocked gully (HW DR Blocked Gully Z3)	Outside bus stop/ enterence to Ravenshead lodge 100 m from A60		Category 2	Job Cancelled	17/06/2015	15/07/2015	Est. GED/3401827
2727092	potholes as marked (CW Repairs-Bituminous)	just passed the GARTH gates and at the lay bye boundary		Category 2	Repair Completed	28/10/2019	31/10/2019	Act. GED-AS/5306821
2728247	2 x seal patches as marked out (CW Repairs-Bituminous)	opp side to abbey view as marked		(Ged Insp Category 2	Job Completed	13/11/2019	19/11/2019	Act. GED/3408346
2728248	Carriageway pothole cat 1 size length 1mtr x 1mtr and depth of 120ml depth ... repaired on site with via fix (CW Repairs-Bituminous)	just after where lay by is were building cat 1 repaired on site		(Ged Insp Filled when found (Cat 1)	Job Completed	13/11/2019	13/11/2019	Act.
2728253	Carriageway Pothole cat 1 repaired on site size 1mtr x 0.50 120ml depth (CW Repairs-Bituminous)	almost at the junction with mansfield road		(Ged Insp Filled when found (Cat 1)	Job Completed	13/11/2019	13/11/2019	Act.
2728578	PATCH AS MARKED OUT PHOTOS ADDED OF DEFECT (CW Repairs-Bituminous)	Large pot hole of left hand side of lane travelling from Ravenshead to Papplewick. coned off to make safe just past ABBEY VIEW FARM		(Ged Insp Category 1	Job Completed	18/11/2019	19/11/2019	Act. GED/3408373
2728582	potholes as marked (CW Repairs-Bituminous)	just as you turn on to Blidworth Waye from mansfield road		Category 2	Repair Completed	18/11/2019	19/11/2019	Act.
Feat No.:	6,008.00	Feature Id - Locn.: GEDL-14861 - SIDE OF			Feature Type: Castanea sativa		Area: Gedling	
3001382	Tree Defect			Arbs - Cat 2 <90 Days	Job Raised	16/10/2018	14/01/2019	Est.
Feat No.:	6,014.00	Feature Id - Locn.: GEDL-14868 - SIDE OF			Feature Type: Acer pseudoplatanus (Sycamore)		Area: Gedling	
3001387	Tree Defect			Arbs - Cat 2 <90 Days	Job Raised	17/10/2018	15/01/2019	Est.
Feat No.:	6,019.00	Feature Id - Locn.: GEDL-14852 - SIDE OF			Feature Type: Crataegus monogyna (Common)		Area: Gedling	
3001383	Tree Defect			Arbs - Cat 2 <90 Days	Job Raised	16/10/2018	14/01/2019	Est.
Feat No.:	6,031.00	Feature Id - Locn.: GEDL-14862 - SIDE OF			Feature Type: Quercus robur (English Oak)		Area: Gedling	
3001381	Tree Defect			Arbs - Cat 2 <90 Days	Job Raised	16/10/2018	14/01/2019	Est.

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 2728247RL

Version: 3

Work Desc: carriageway repairs

Notice Type: Works Stop

Start: 19/11/2019 00:00:00

Work Status: Works Stopped

Issued: 22/11/2019 10:25:01

Work Type: EToN 4: Minor

Est. End: 21/11/2019

Completion: 21/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opposite side to abbey view as marked	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	21/11/2019			21/11/2019

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Way (15003246)

Display Action Officer: Yes