

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Way (15003117)

Display Action Officer: Yes

Street: Blidworth Way (15003117)

Locality: Papplewick, Nottinghamshire

Area: Gedling

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	Papplewick	Feature Type:	Street Section		Area: Gedling	
Batch:	20369761 - Inspection Batch			Route:	Gedling Area 1 Dec Saf CW	Officer:	(Ged Inspector)	Date: 20/12/2019
	No actionable defects found							
Batch:	20367381 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 09/12/2019
3626983	Carriageway Potholes as marked	09/12/2019	outside ravenhead lodge next to bus stop	CW Repairs-Bituminous	Internal		Uncommitted	2730712
Batch:	20364555 - Inspection Batch			Route:	Gedling Area 1 Nov Saf CW	Officer:	(Ged Inspector)	Date: 25/11/2019
	No actionable defects found							
Batch:	20362895 - Inspection Batch			Route:	Adhoc Inspection	Officer:	(Ged Inspector)	Date: 13/11/2019
3624510	Carriageway Potholes round gullies marked	13/11/2019	outside Avon Holm and The Hermitage ... name of houses all marked round gullies	CW Repairs-Bituminous	Internal		Uncommitted	2728233
Batch:	20360701 - Inspection Batch			Route:	Gedling Area 1 Oct Saf CW	Officer:	(Ged Inspector)	Date: 28/10/2019
3623370	potholes	28/10/2019	as marked just after boundary lay bye and the firs house	CW Repairs-Bituminous	Internal		Committed	2727090
Batch:	20356201 - Inspection Batch			Route:	Gedling Area 1 Sep Saf CW	Officer:	(Ged Inspector)	Date: 24/09/2019
	No actionable defects found							
Feat No.:	3,504.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702411 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,507.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20701679 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 06/09/2019
	No actionable defects found							
Feat No.:	3,509.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702410 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,510.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 1 Post		Area: Gedling	
Batch:	20702412 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,513.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 2 Posts		Area: Gedling	
Batch:	20702405 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							
Feat No.:	3,514.00	Feature Id - Locn.:		Feature Type:	Non-Illum Sign - 2 Posts		Area: Gedling	
Batch:	20702406 - Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	(SL Ged-Brox N)	Date: 11/09/2019
	No actionable defects found							

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003117)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 4,001.00	Feature Id - Locn.: 1 - On Bend O/S Top Farm			Feature Type: Column			Area: Gedling	
Batch: 20711010 - Inspection Batch	No actionable defects found			Route: Gedling Patrol	Officer:		SL Ged-Brox N)	Date: 23/12/2019
Batch: 20708918 - Inspection Batch	No actionable defects found			Route: Gedling Patrol	Officer:		SL Ged-Brox N)	Date: 25/11/2019
Batch: 20705335 - Inspection Batch	No actionable defects found			Route: Gedling Patrol	Officer:		SL Ged-Brox N)	Date: 14/10/2019
Batch: 20703343 - Inspection Batch	No actionable defects found			Route: Gedling Patrol	Officer:		SL Ged-Brox N)	Date: 23/09/2019
Batch: 20702404 - Inspection Batch	No actionable defects found			Route: PAPPLEWICK 5-6 COLUMNS	Officer:		SL Ged-Brox N)	Date: 11/09/2019

Customer Services

Enquiry No.: 6151073 **Logged by:** External to Confirm **on:** 20/12/2019 15:12 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Street flooding - Flooding from fields, Un- passerby on one side about 1foot deep and 5 meters in length going down the road.

Back county lane concerned with the lighting may cause more problems as it gets dark.

Ref - [REDACTED] Submitted by Advisor: [REDACTED]

Location: On bend towards cricket grounds on Blidworth waye, Papperwick

Contact:

Enquiry No.: 6149897 **Logged by:** External to Confirm **on:** 12/12/2019 17:51 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Street flooding - There is no streetlighting on the road. there is a pool of water that cannot be seen and caller thinks someone may go into the wall opposite.
coll - 7627
inc - 717. Submitted by Advisor: [REDACTED]

Location: Blidworth Waye Papplewick

Contact:

Enquiry No.: 6149334 **Logged by:** External to Confirm **on:** 09/12/2019 09:54 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - Small deep pot hole which can be easily repaired before it expands into a more serious problem. Also a larger area on at side of grass in the same vicinity . Online report Customer [REDACTED] r.
Location: Main Street, Papplewick (wrongly shown as Blidworth Way on your map) in the vicinity of the bus stop nearest to Blidworth Way

Contact:

Plot Number: 2,000.00
Job Number: 2730712

Feature Id - Location: Papplewick
Defect Number: 3626983

Feature Type: Street Section

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003117)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6147907	Logged by: External to Confirm	on: 27/11/2019 14:36	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: [REDACTED]
Desc.: Good morning, Your Reference: [REDACTED] Re: Flooding, Flood sign, Blidworth Waye (at the Hall Lane Bend near Top Farm), Papplewick, Nottingham One of our Councillors has contacted me to advise that the water is more than half way across the road and the 'flood' sign in the north side is too close to the hazard leaving no time for drivers to react. Please could you arrange for this to be rectified. Kind regards [REDACTED]			
Location: Blidworth Waye, Papplewick on the bend near Top Farm)		Contact:	
Enquiry No.: 6147331	Logged by: External to Confirm	on: 22/11/2019 16:27	Officer: Risk & Insurance
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: [REDACTED]
Desc.: Insurance claim - related to Confirm defect reference: 6146696 Date/Time: 17/11/2019 07:45:00 Direction of travel: The caller was heading towards Papplewick on Blidworth Waye near the site entrance for a farm/building site. Account of what happened: The caller was driving on the road in the morning when the front passenger side wheel hit the pothole, this has bent the alloy and it's not useable. The caller has had to replace the alloy and the tyre as it was slowly letting air out. [REDACTED]			
Location: Turning into Papplewick from ravens head there ar pot hole all down the side of the road getting worse as the day go by some small some are very big and deep		Contact:	
Enquiry No.: 6147094	Logged by: External to Confirm	on: 21/11/2019 09:42	Officer: Risk & Insurance
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: [REDACTED]
Desc.: Insurance claim - related to Confirm defect reference: 6147093 Date/Time: 18/11/2019 08:00:00 Direction of travel: Southbound on Blidworth Waye Account of what happened: > On Monday 18th November at approx 8am I was driving on Blidworth Waye between the A60 and Papplewick. The road was busy with commuters. A huge pothole was covering a large part of the road and the car in front drove through it as they had no option to avoid it as there were cars on the other side of the road. I also was unable to avoid it for the same reason and drove through it. There was water in the pothole. A vibration immediately became apparent in my car and the steering wheel was also vibrating. I pulled over further up the road to check my tyres, which seemed ok. [REDACTED] then returned to the road to photograph the pothole as it had become apparent that my car had sustained damage. Upon my return a man from the council was at the pothole and was putting cones around the hole. I have photographed the pothole to show the extent of the damage to the road. [REDACTED] [REDACTED]			
No telephone number given.			
Location: Blidworth Waye between A60 and Papplewick heading southbound, near the turning for Newstead Grange.		Contact:	

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003117)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6147093 **Logged by:** External to Confirm **on:** 21/11/2019 09:40 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Insurance claim form requested - Road Pothole - Advised by Highways South to repin for insurance claim.

On Monday 18th November at approx 8am I was driving on Blidworth Waye between the A60 and Papplewick. The road was busy with commuters. A huge pothole was covering a large part of the road and the car in front drove through it as they had no option to avoid it as there were cars on the other side of the road. I also was unable to avoid it for the same reason and drove through it. There was water in the pothole. A vibration immediately became apparent in my car and the steering wheel was also vibrating. I pulled over further up the road to check my tyres, which seemed ok [REDACTED] then returned to the road to photograph the pothole as it had become apparent that my car had sustained damage. Upon my return a man from the council was at the pothole and was putting cones around the hole. I have photographed the pothole to show the extent of the damage to the road. [REDACTED]
[REDACTED]

. Submitted by Advisor: [REDACTED] Customer title is

Location: Blidworth Waye between A60 and Papplewick heading southbound, near the turning for Newstead Grange. **Contact:**

Enquiry No.: 6147001 **Logged by:** External to Confirm **on:** 20/11/2019 13:27 **Officer:** [REDACTED]
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Traffic sign request - Permanent 'Road Liable to Flooding' Flood sign needed for traffic approaching the bend down Blidworth Waye from the A60 . Online report - [REDACTED]
Location: Before the bend on Blidworth Waye (Near Top Farm). Flood sign needed for traffic approaching the bend down Blidworth Waye from the A60 **Contact:**

Enquiry No.: 6146700 **Logged by:** External to Confirm **on:** 18/11/2019 14:27 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - Email from fixmystreet:

Recent erosion has caused a large pot hole and already several cars damaged and were blocking the road on the way into Papplewick. . Submitted by Advisor: [REDACTED]

Location: Blidworth Waye on the way into Papplewick. **Contact:**

Enquiry No.: 6146696 **Logged by:** External to Confirm **on:** 18/11/2019 14:21 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]
Desc.: Road Pothole - Turning into Papplewick from ravens head there ar pot hole all down the side of the road getting worse as the day go by some small some are very big and deep . Online report [REDACTED]
Location: Turning into Papplewick from ravens head there ar pot hole all down the side of the road getting worse as the day go by some small some are very big and deep **Contact:**

Effective: 01/09/2019 to 06/01/2020
Street: Blidworth Waye (15003117)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6146660 **Logged by:** External to Confirm **on:** 18/11/2019 12:48 **Officer:** Risk & Insurance
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]

Desc.: Insurance claim - related to Confirm defect reference: 6145637
Date/Time: 18/11/2019 08:03:00
Direction of travel: From ravens head to papplewick
Account of what happened: Damaged the front left allow, got a flat tyre, bent the alloy wheel from the impact
[REDACTED]

Has photos also

Location: on the road through the trees before the corver where there is a two lane flood the two gullies have dropped i watched a moter bike loose control over the first one that was unavoidable but managed to aviod the second but in the car its a big bounce in and out , i guess the new works and extra lorries are not helping you maintain this road

Contact:

Enquiry No.: 6146495 **Logged by:** External to Confirm **on:** 16/11/2019 15:51 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]

Desc.: Road Pothole - Large pothole . Online report [REDACTED]

Location: Opposite the bus stop

Contact:

Plot Number: 2,000.00

Feature Id - Location: Papplewick

Feature Type: Street Section

Job Number: 2728233

Enquiry No.: 6145637 **Logged by:** External to Confirm **on:** 12/11/2019 11:39 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** [REDACTED]

Desc.: Road Pothole - as above . Online report [REDACTED]

Location: on the road through the trees before the corver where there is a two lane flood the two gullies have dropped i watched a moter bike loose control over the first one that was unavoidable but managed to aviod the second but in the car its a big bounce in and out , i guess the new works and extra lorries are not helping you maintain this road

Contact:

Plot Number: 2,000.00

Feature Id - Location: Papplewick

Feature Type: Street Section

Job Number: 2728233

Defect Number: 3624510

Enquiry No.: 83858 **Logged by:** [REDACTED] **on:** 14/11/2019 16:41 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation

Desc.: REQUEST FLOOD BOARDS

Location: on bend into / out of village heading to / from A60

Contact:

Effective: 01/09/2019 to 06/01/2020
 Street: Blidworth Waye (15003117)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: Papplewick			Feature Type: Street Section		Area: Gedling	
239825	[standing water] Junction of hall lane there is a manhole cover which is a soak away within the verge. This is within a small triangle grassed area with a fence around and a bench within. Please clear . Also , please could x4 gullys be cleared from hall lane going up the hill going towards a60. Also, clear gully outside lamp column 15 which is near the first of the cottages in papplewick. for further information please call [REDACTED] (HW DR Blocked Gully Z3)	opposite junction of hall lane on bend.	[REDACTED]	DO NOT L Category 2	Job Cancelled	29/10/2013	26/11/2013	Est. GED/83667
242153	Please empty two blocked gully's. (HW DR Blocked Gully Z3)	Outside no 83 and adjacent to l/c no15.	[REDACTED]	(Rushcliffe Category 2	Job Cancelled	28/05/2014	25/06/2014	Est. GED/84976
2727090	potholes (CW Repairs-Bituminous)	as marked just after boundary lay bye and the firs house	[REDACTED]	Category 2	Repair Completed	28/10/2019	31/10/2019	Act. GED-AS/5306819
2728233	Carriageway Potholes round gullys marked (CW Repairs-Bituminous)	outside Avon Holm and The Hermitage ... name of houses all marked round gullys	[REDACTED]	Category 2	Repair Completed	13/11/2019	14/11/2019	Act.
2730712	Carriageway Potholes as marked (CW Repairs-Bituminous)	outside ravenshead lodge next to bus stop	[REDACTED]	Category 2	Repair Completed	09/12/2019	11/12/2019	Act.