

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Street: Woodhouse Way (4911713)

Locality: Nuthall, Nottinghamshire

Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: To Boundary Xba			Feature Type: Street Section			Area: Broxtowe	
Batch: 20385000 - Inspection Batch	No actionable defects found			Route: Broxtowe North Apr Saf CW	Officer:			Date: 30/03/2020
Batch: 20383298 - Inspection Batch	No actionable defects found			Route: Broxtowe North Mar Saf CW	Officer:			Date: 17/03/2020
Batch: 20381871 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 09/03/2020
3636029	Carriageway Potholes	09/03/2020	Lamp columns 34,35 & 55	CW Repairs-Bituminous	Inter		Uncommitted	2739779
Batch: 20378681 - Inspection Batch	No actionable defects found			Route: Broxtowe North Feb Saf CW	Officer:			Date: 20/02/2020
Batch: 20373872 - Inspection Batch				Route: Broxtowe North Jan Enh CW/FW	Officer:			Date: 23/01/2020
3631318	Cway potholes	23/01/2020	Lamp columns 8, 12, 31, 50, 51, 55 & 59	CW Repairs-Bituminous	Inter		Uncommitted	2735057
Batch: 20368484 - Inspection Batch	No actionable defects found			Route: Broxtowe North Dec Saf CW	Officer:			Date: 12/12/2019
Batch: 20366164 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 02/12/2019
3626287	Carriageway Potholes	02/12/2019	Lamp columns 32, 33, 51 & 55	CW Repairs-Bituminous	Inter		Uncommitted	2730013
Batch: 20364963 - Inspection Batch	No actionable defects found			Route: Broxtowe North Nov Saf CW	Officer:			Date: 26/11/2019
Batch: 20360760 - Inspection Batch	No actionable defects found			Route: Broxtowe North Oct Saf CW	Officer:			Date: 28/10/2019
Batch: 20355292 - Inspection Batch	No actionable defects found			Route: Broxtowe North Sep Saf CW	Officer:			Date: 18/09/2019
Batch: 20351875 - Inspection Batch	No actionable defects found			Route: Broxtowe North Aug Saf CW	Officer:			Date: 27/08/2019
Batch: 20348226 - Inspection Batch	No actionable defects found			Route: Broxtowe North Jul Saf CW	Officer:			Date: 29/07/2019
Batch: 20343577 - Inspection Batch	No actionable defects found			Route: Broxtowe North Jun Saf CW	Officer:			Date: 25/06/2019
Batch: 20338429 - Inspection Batch	No actionable defects found			Route: Broxtowe North May Saf CW	Officer:			Date: 29/05/2019
Batch: 20333480 - Inspection Batch	No actionable defects found			Route: Broxtowe North Apr Saf CW	Officer:			Date: 25/04/2019
Batch: 20328785 - Inspection Batch	No actionable defects found			Route: Broxtowe North Mar Saf CW	Officer:			Date: 25/03/2019
Batch: 20328402 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 22/03/2019
3604972	Carriageway Potholes	22/03/2019	Lamp columns 51, 55, 57 & 59	CW Repairs-Bituminous	Internal		Committed	2708594

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: To Boundary Xba			Feature Type: Street Sectio			Area: Broxtowe	
Batch: 20324061 - Inspection Batch	No actionable defects found			Route: Broxtowe North Feb Saf CW	Officer:			Date: 20/02/2019
Batch: 20321131 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 31/01/2019
3599975	Cway pothole	31/01/2019	Lamp column 51	CW Repairs-Bituminous	Inter		Committed	2703513
Batch: 20318411 - Inspection Batch				Route: Broxtowe North Jan Enh CW/FW	Officer:			Date: 14/01/2019
3598295	Replace missing gully cover	14/01/2019	Lamp column 26	CW Ironwork	Inter		Committed	2701793
3598294	Gully cover missing, I have made safe with cones and issued works for repair	14/01/2019	Lamp column 26	Other	Inter		Uncommitted	2701794
Batch: 20316596 - Inspection Batch	No actionable defects found			Route: Broxtowe North Dec Saf CW	Officer:			Date: 27/12/2018
Batch: 20312277 - Inspection Batch	No actionable defects found			Route: Broxtowe North Nov Saf CW	Officer:			Date: 22/11/2018
Batch: 20308264 - Inspection Batch	No actionable defects found			Route: Broxtowe North Oct Saf CW	Officer:			Date: 23/10/2018
Batch: 20303864 - Inspection Batch	No actionable defects found			Route: Broxtowe North Sep Saf CW	Officer:			Date: 25/09/2018
Batch: 20299825 - Inspection Batch	No actionable defects found			Route: Broxtowe North Aug Saf CW	Officer:			Date: 29/08/2018
Batch: 20294930 - Inspection Batch				Route: Broxtowe North Jul Saf CW/FW	Officer:			Date: 25/07/2018
3585234	Cway potholes filled when found	25/07/2018	LC 19, 55, 59 & in the junction with Mornington Crescent	CW Repairs-Bituminous	Inter		Uncommitted	2688476
Batch: 20291900 - Inspection Batch	No actionable defects found			Route: Broxtowe North Jun Saf CW	Officer:			Date: 03/07/2018
Batch: 20286971 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 04/06/2018
3580670	Cway pothole filled when found	04/06/2018	Lamp column 35	CW Repairs-Bituminous	Inter		Uncommitted	2683820
Batch: 20286264 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 30/05/2018
3580280	Carriageway Potholes filled when found	30/05/2018	Lamp column 46	CW Repairs-Bituminous	Inter		Uncommitted	2683428
Batch: 20286131 - Inspection Batch	No actionable defects found			Route: Broxtowe North May Saf CW	Officer:			Date: 30/05/2018
Batch: 20281541 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 03/05/2018
3577230	Carriageway Patches	03/05/2018	Lamp columns 46 & 50 at the traffic lights	CW Repairs-Bituminous	Inter		Committed	2680347
Batch: 20279895 - Inspection Batch	No actionable defects found			Route: Broxtowe North Apr Saf CW	Officer:			Date: 25/04/2018
Batch: 20276778 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 09/04/2018
3574065	Carriageway Potholes	09/04/2018	Lamp columns 37 & 39	CW Repairs-Bituminous	Inter		Committed	2677108
Batch: 20274950 - Inspection Batch				Route: Adhoc Inspection	Officer:			Date: 27/03/2018
3572768	Carriageway Potholes	27/03/2018	lamp column 8	CW Repairs-Bituminous	Internal		Committed	2675786

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	To Boundary Xba	Feature Type:	Street Section		Area: Broxtowe	
Batch:	20274664 - Inspection Batch			Route:	Broxtowe North Mar Saf CW	Officer:		Date: 26/03/2018
3572565	Cway potholes	26/03/2018	Lamp columns 46, 55, 59 & 60	CW Repairs-Bituminous	Internal		Committed	2675573

Customer Services

Enquiry No.: 6165175 **Logged by:** External to Confirm **on:** 23/03/2020 07:39 **Offic** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-186260034
Desc.: Road Damage - a previous repair has catastrophically failed. The repair can be seen failing on streetview dated march 2019. The hole includes one side and the corner of the drain grate. The hole is wider than a 205 tyre, longer and over 4cm deep. There is the remnants of yellow marker paint from the failed repair. . Online report Customer title is [REDACTED]
Location: A6002 Between the two mornington crescent entrances. between the two entrance **Contact:**
to the petrol station. Around the drain grate.

Plot Number: 2,000.00 **Feature Id - Location:** To Boundary Xba **Feature Type:** Street Section
Job Number: 2739779

Enquiry No.: 6165164 **Logged by:** External to Confirm **on:** 23/03/2020 07:39 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-186048667
Desc.: Road Pothole - Potholes around 2 rainwater drain grates. Potholes deep enough to cause damage to vehicles. . Online report Customer title is Mr.
Location: Wood house Way Nuthall .Outside petrol station near lamppost no. 36 **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** To Boundary Xba **Feature Type:** Street Section
Job Number: 2739779

Enquiry No.: 6164802 **Logged by:** External to Confirm **on:** 16/03/2020 18:39 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-184297541
Desc.: Road Damage - Multiple potholes . Online report Customer title is Mr.
Location: Multiple potholes along this carriage way. Nearby to the public house **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** To Boundary Xba **Feature Type:** Street Section
Job Number: 2739779

Enquiry No.: 6163366 **Logged by:** External to Confirm **on:** 06/03/2020 08:43 **Officer:** [REDACTED]
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-180891541
Desc.: Road Pothole - As above. Road is in appalling condition and has had no repairs. Potholes are continuous along the whole stretch. . Online report Customer title is [REDACTED]
Location: Series of large, deep holes northbound from Belfry roundabout. Causing traffic hazard due to drivers having to swerve. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** To Boundary Xba **Feature Type:** Street Section
Job Number: 2739779 **Defect Number:** 3636029

Enquiry No.: 6158686 **Logged by:** External to Confirm **on:** 13/02/2020 14:06 **Officer:** [REDACTED]
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174655662
Desc.: Other tree issues - Customer would like to know why a lot of the trees on Woodhouse Way have been felled. . Submitted by Advisor: Matthew Jackson2 Customer title is Mrs.
Location: Woodhouse Way, Nuthall near the Esso **Contact:**

Enquiry No.: 6156769 **Logged by:** External to Confirm **on:** 03/02/2020 10:15 **Officer:** [REDACTED]
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172009030
Desc.: Other tree issues - The customer wants more information as to why all the trees have been cut down to tree stumps. All the other trees have been vigorously thinned out too- Intrigued as to why - No signs for new development in the area either. . Submitted by Advisor: Saima Faisal Customer title is Mr.
Location: Opposite Old Moor Lodge - Coming off from the motorway, junction 26 going upto just before Belfry Hotel **Contact:**

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Customer Services

Enquiry No.: 6156154	Logged by: External to Confirm	on: 29/01/2020 10:36	Officer: [REDACTED]
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS170949580
Desc.: Insurance claim - related to Confirm defect reference: 6155262 Date/Time: 23/01/2020 12:00:00 Direction of travel: from Aldi in Nuthall going towards Sainsburys in Kimberley ON WOODHOUSE WAY, on the intersection of Mornington Crescent traffic lights...opposite the Family bar called old moor lodge. Account of what happened: I was driving from Aldi in Nuthall going towards Sainsburys in Kimberley. There was a car in front of me, so I did not see the road underneath and went through a few potholes(they are right in the middle of the road) as they are literally one after the other. There was a big piece of metal (photo attached) in one of the potholes that got lodged in the rear driver tyre. I had the window of my car opened and heard the damage straight away. Time of incident In the afternoon approx 12.00 noon. I called the AA and they said they will be with me by 2.15 pm.			
Location: Junction of Mornington Crescent and a6002 (near the oldmoor edge)		Contact:	
Enquiry No.: 6156070	Logged by: External to Confirm	on: 28/01/2020 16:45	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-170844444
Desc.: Road Pothole - Large line of holes on the downhill stretch towards Nuthall island. this is really part of the same problem I've just reported further up, but I'm not sure if you need additional reports for each group to action. . Online report Customer title is Mr.			
Location: Large line of holes on the downhill stretch towards Nuthall island. this is really part of the same problem I've just reported further up, but I'm not sure if you need additional reports for each group to action.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2735057			
Enquiry No.: 6156067	Logged by: External to Confirm	on: 28/01/2020 16:42	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-170842487
Desc.: Road Pothole - Long line of potholes of varying sizes on the downhill towards Nuthall island. Some of them have been previously repaired over the last couple of months but all the filler has come out. . Online report Customer title is [REDACTED]			
Location: Long line of potholes of varying sizes on the downhill towards Nuthall island. Some of them have been previously repaired over the last couple of months but all the filler has come out.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2735057			
Enquiry No.: 6155262	Logged by: External to Confirm	on: 22/01/2020 22:03	Office: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-169604294
Desc.: Road Pothole - A number of potholes and road damage running from the junction down 50 yards towards the right as you turn out of the junction . Online report Customer title is Mr.			
Location: Junction of Mornington Crescent and a6002 (near the oldmoor edge)		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2735057			
Enquiry No.: 6150716	Logged by: External to Confirm	on: 18/12/2019 12:27	Office: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS162921866
Desc.: Road Pothole - Please see the customer's email below: "Thanks for letting me know you have carried out some repairs, however, as explained in the original description "a collection of pot holes... in particular on Woodhouse Way just after the traffic lights heading towards Nuthall Island", the area just after the traffic lights towards Nuthall island still has issues." . Submitted by Advisor: Anda Stefania Suliteanu Customer title is - Previous Confirm Case: 6148442			
Location: Woodhouse Way,Nuthall		Contact:	

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Customer Services

Enquiry No.: 6149905	Logged by: External to Confirm	on: 12/12/2019 18:48	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-162054561
Desc.: Road Pothole - Pothole . Online report Customer title is Mrs.			
Location: Before the tuning into mornington estate heading towards the nuthall island.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2730013			
Enquiry No.: 6148442	Logged by: External to Confirm	on: 02/12/2019 08:32	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-160105184
Desc.: Road Pothole - Between Nottingham Business Park towards Nuthall island, starting opposite the Esso garage and carrying on for around 2-300 metres past the traffic lights are a serious of potholes getting steadily deeper. . Online report Customer title is Mr.			
Location: Between Nottingham Business Park towards Nuthall island, starting opposite the Esso garage and carrying on for around 2-300 metres past the traffic lights are a serious of potholes getting steadily deeper.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2730013			
Defect Number: 3626287			
Enquiry No.: 6134883	Logged by: External to Confirm	on: 30/07/2019 15:30	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Fencing Damage (Other)	Classification: Report or Observation	Enquiry Ref: FS-CASE-134226862
Desc.: Fencing damage - Hi I live on the Mornington crescent estate and have noticed people running across the busy road from the horse fair, this is kids and women! Someone will be knocked over and killed, a hole had been made in the hedge and fence broken so people can get through! . Submitted by Advisor: [REDACTED] customer title is Mr.			
Location: Woodhouse Way, A6002. Near the Horse fair.		Contact:	
Enquiry No.: 6123264	Logged by: External to Confirm	on: 20/03/2019 08:36	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-110183523
Desc.: Road Pothole - As you leave the Mornington estate to turn right towards Nuthall roundabout, there are numerous potholes within the first 50 meters or so. Some are quite deep and difficult to avoid. . Online report Customer title is Mr.			
Location: Woodhouse Way Northbound, adjacent to Odmoor Lodge		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2708594			
Defect Number: 3604972			
Enquiry No.: 6111714	Logged by: External to Confirm	on: 12/11/2018 10:48	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-95333030
Desc.: Traffic light fault - For at least 2 weeks the traffic lights have been faulty. The green facility for the minor road is activating for a maximum period even if no vehicles are waiting or if only 1 or 2 are, causing long unnecessary hold ups on the main road. . Online report Customer title is			
Location: Junction Woodhouse Way with Mornington Crescent, Nuthall		Contact:	
Enquiry No.: 6105601	Logged by: External to Confirm	on: 05/09/2018 11:24	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-87106282
Desc.: Overhanging trees - Overhanging trees blocking motorists view of road traffic signs that inform of correct lanes to approach the Island, this is causing drivers to change lanes once on the island and cutting up other motorists on this already busy roadway. As I use this island twice daily I have witnessed at least 10 of these incidences in the last seven days. . Online report Customer title is [REDACTED]			
Location: A6002 Woodhouse way, approaching nuthall island.		Contact:	

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Customer Services

Enquiry No.: 6096885	Logged by: External to Confirm	on: 31/05/2018 11:42	Officer: [REDACTED]
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS77142786
Desc.: Insurance claim - related to Confirm defect reference: 6096657 Date/Time: 27/05/2018 12:00:00 Direction of travel: Driving Towards Ikea- along Woodhouse Way- on the junction after the lights. Account of what happened: When driving along Woodhouse way- towards Ikea- the lights were on green- going about 30MPH straight at the lights- all of a sudden there was a loud bang and a scraping sound. It has blown the tire- bulge come out from the tire with a small breakage in tire.			
Location: on A6002 Woodhouse way		Contact:	
Enquiry No.: 6096657	Logged by: External to Confirm	on: 30/05/2018 11:13	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-77004369
Desc.: Insurance claim - Road Pothole - Large pothole- Roughly 5ft wide and deep in places- advised by Laura Truslous to Pu through secondary report as it is now an urgent. . Submitted by Advisor: Baily De Ville Customer title is Miss.			
Location: on A6002 Woodhouse way		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2683428	Defect Number: 3580280		
Enquiry No.: 6094733	Logged by: External to Confirm	on: 11/05/2018 06:59	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-75292264
Desc.: Road Pothole - Several potholes at the same location which are starting to merge into 1 large one - needs urgent attention, repair that was done is unacceptable and has not solved the issue. The location can't be missed and has already got yellow markings around it but it has been waiting for repairs for over a week and needs the road cutting out and doing a complete repatch rather than filling in the potholes. . Online report Customer title is Miss.			
Location: On A6002 Woodhouse Way, at the traffic light junction where you can enter the Morningson Crescent estate close to the Oldmoor Grill restaurant.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2680347			
Enquiry No.: 6093913	Logged by: External to Confirm	on: 02/05/2018 18:09	Office: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-74536430
Desc.: Road Pothole - Lots of potholes! . Online report Customer title is Mr.			
Location: In between the traffic lights heading down to Nuthall Island.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2680347	Defect Number: 3577230		
Enquiry No.: 6090690	Logged by: External to Confirm	on: 09/04/2018 16:50	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-72433518
Desc.: Road Damage - Top layer of asphalt is lifting in several places on this stretch of road. . Online report			
Location: A6002 - Opposite Oldmoor Lodge pub. North bound lane.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2675573			
Enquiry No.: 6090299	Logged by: External to Confirm	on: 06/04/2018 23:03	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-72269368
Desc.: Road Pothole - Pothole damage all across the road. . Online report			
Location: Opposite Esso garage past the traffic lights		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2675573			

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Customer Services

Enquiry No.: 6089404	Logged by: External to Confirm	on: 03/04/2018 20:30	Office
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Re
Desc.: Road Pothole - Several pot holes in the road so many you can't avoid them on this section of road. Some pot holes are already marked to be repaired & are getting larger. URGENT . Online report			
Location: Just after traffic lights with Mornington Crescent heading towards Nuthall island from Strelley		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2677108	Defect Number: 3574065		
Enquiry No.: 6089082	Logged by: External to Confirm	on: 02/04/2018 18:30	Office
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Re
Desc.: Road Pothole - Multiple potholes . Online report			
Location: Lots of potholes around the traffic light area heading towards nuthall island		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2675573			
Enquiry No.: 6088332	Logged by: External to Confirm	on: 27/03/2018 13:09	Office
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Re
Desc.: Road Pothole - road potholes 1 metre each . Submitted by Advisor: Eileen Clare			
Location: just before turning for Mornington Crescent in front of lamp column 8		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2675786	Defect Number:		
Enquiry No.: 3800679	Logged by: [REDACTED]	on: 26/02/2020 13:17	Office
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Recent maintenance works have exposed the properties to the traffic of the motorway. More noise and the works look like the area has been but additional screening?			
Location: Strelley bypass		Contact:	
Enquiry No.: 3207451	Logged by: [REDACTED]	on: 14/01/2019 15:09	Office
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	
Desc.: Missing Cover			
Location: Col 26		Contact:	
Plot Number: 2,000.00	Feature Id - Location: To Boundary Xba	Feature Type: Street Section	
Job Number: 2701800			
Enquiry No.: 86956	Logged by: [REDACTED]	on: 24/03/2020 09:38	Office
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: Overgrown veg works			
Location: Entire		Contact:	
Enquiry No.: 86179	Logged by: [REDACTED]	on: 24/02/2020 13:43	Office
Service: Trees/Verges	Subject:	Classification: Report or Observation	
Desc.: A lot of vegetation has been cut back on Woodhouse Way. I have been asked whether there is going to be any replanting.			
Location: Entire		Contact:	

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Customer Services

Enquiry No.: 85807 Logged by: [REDACTED] on: 11/02/2020 10:33 Officer: [REDACTED]
 Service: Trees/Verges Subject: Overhanging Vegetation/Trees Classification: Report or Observation
 Desc.: Information request for ongoing tree works
 Location: Entire Contact:

Enquiry No.: 85408 Logged by: [REDACTED] on: 28/01/2020 10:42 Officer: [REDACTED]
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: [REDACTED]

Can this stretch of road please be inspected.
 From: james garrigan
 Sent: Saturday 25 January, 21:42
 Subject: Road surfacing program
 To: Councillor Philip Owen

Dear [REDACTED]
 Do you remember me, I told you about Cloverlands Drive back in October November time I think, anyway I know of another road which needs maintenance, but I don't know which council it comes under, so the road is the A6002 from Mornington close all the way to the island where the new Aldi store is. By the way it needs line painting for the whole stretch.
 Thank you
 [REDACTED]

Location: Entire Contact:

Enquiry No.: 85364 Logged by: [REDACTED] on: 27/01/2020 09:46 Officer: [REDACTED]
 Service: Carriageway/Footway Subject: Line Marking/Stud Renewal Classification: Report or Observation
 Desc.: Refresh carriageway markings
 Location: From Nuthall island to City Boundary adjacent Hotel Contact:

Enquiry No.: 71903 Logged by: [REDACTED] on: 22/05/2018 16:25 Officer: [REDACTED]
 Service: Licences/Permits Subject: Scaffold Licence Request Classification: Service Request
 Desc.: HIAB 12/06/18
 Location: Near Old Moor Lodge Contact:

Plot Number: 2,000.00 Feature Id - Location: To Boundary Xba Feature Type: Street Section

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: To Boundary Xba			Feature Type: Street Section		Area: Broxtowe	
2675573	Cway potholes (CW Repairs-Bituminous)	Lamp columns 46, 55, 59 & 60	Robin Perkins	Category 2	Job Completed	26/03/2018	12/04/2018	Act. BRO-AS/5203415
2675786	Carriageway Potholes (CW Repairs-Bituminous)	lamp column 8	Robin Perkins	Category 2	Job Completed	27/03/2018	12/04/2018	Act. BRO-AS/5203424
2677108	Carriageway Potholes (CW Repairs-Bituminous)	Lamp columns 37 & 39	Robin Perkins	Category 2	Job Completed	09/04/2018	12/04/2018	Act. BRO-AS/5203482

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: To Boundary Xba			Feature Type: Street Section		Area: Broxtowe	
2680347	Carriageway Patches (CW Repairs-Bituminous)	Lamp columns 46 & 50 at the traffic lights Sunday working advised		Category 3	Job Completed	03/05/2018	08/08/2018	Act. BROX/3304816
2683428	Carriageway Potholes filled when found (CW Repairs-Bituminous)	Lamp column 46		Filled when found (Cat 2)	Job Completed	30/05/2018	30/05/2018	Act.
2683820	Cway pothole filled when found (CW Repairs-Bituminous)	Lamp column 35		Filled when found (Cat 1)	Job Completed	04/06/2018	04/06/2018	Act.
2688476	Cway potholes filled when found (CW Repairs-Bituminous)	LC 19, 55, 59 & in the junction with Mornington Crescent		Filled when found (Cat 2)	Job Completed	25/07/2018	25/07/2018	Act.
2701793	Replace missing gully cover (CW Ironwork)	Lamp column 26: Made safe by Inspector with Cones 14/01/19: Please replace ASAP as a priority		Category 2	Job Completed	14/01/2019	07/02/2019	Act. BROX/3305584
2701794	Gully cover missing, I have made safe with cones and issued works for repair (Other)	Lamp column 26		Made Safe (Cat 1)	Job Completed	14/01/2019	14/01/2019	Act.
2701800	Manholes/Gullies - Missing Cover (Enquiry 3207451)	Col 26		Category 1	Job Completed	14/01/2019	15/01/2019	Act. BRO-AS/5204365
2703513	Cway pothole (CW Repairs-Bituminous)	Lamp column 51		Category 2	Job Completed	31/01/2019	01/02/2019	Act. BRO-AS/5204416
2708594	Carriageway Potholes (CW Repairs-Bituminous)	Lamp columns 51, 55, 57 & 59		Category 2	Job Completed	22/03/2019	28/03/2019	Act. BRO-AS/5204659
2730013	Carriageway Potholes (CW Repairs-Bituminous)	Lamp columns 32, 33, 51 & 55		Category 2	Repair Completed	02/12/2019	10/12/2019	Act.
2735057	Cway potholes (CW Repairs-Bituminous)	Lamp columns 8, 12, 31, 50, 51, 55 & 59		Category 2	Repair Completed	23/01/2020	05/02/2020	Act.
2739779	Carriageway Potholes (CW Repairs-Bituminous)	Lamp columns 34,35 & 55		Category 2	Repair Completed	09/03/2020	27/03/2020	Act.

Street Works Inspections

Organisation: O2 (NSN) (7182016)

Works Ref: 45274/STM/KG/POLE

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 31/05/2019 13:37:59
Category: Category B	Outcome: Passed	Defect No: N/A	Sampled: Yes
Defect Notif. No: N/A	Tel: 07507 878490	Site Informed: Yes	Sign/Light/Guard. Inadequacy: No
Officer: [REDACTED]		Site Location: Woodhouse Way approx 70m NE of Mornington Crescent	Sampled Site No: 1
Insp. Notes: [REDACTED]		Position: Footway	Site Post Code:
Defect Notes:			
Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 27/06/2018 14:59:06
Category: Category B	Outcome: Failed (Lower Risk/Non Dangerous)	Defect No: 11301000	Sampled: Yes
Defect Notif. No: 11301000	Tel: 07507 878490	Site Informed: Yes	Sign/Light/Guard. Inadequacy: No
Officer: [REDACTED]		Site Location: Woodhouse Way approx 70m NE of Mornington Crescent	Sampled Site No: 1
Insp. Notes: [REDACTED]		Position: Footway	Site Post Code:
Defect Notes:			

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Street Works Notices**Organisation:** NCC - BROXTOWE (3055006) (VIA Bilsthorpe)**Works Ref:** 30302758**Version:** 3**Work Desc:** Via East Midlands Carrying Out Tree Cutting Works on Behalf of Nottinghamshire County Council**Notice Type:** Confirmation of Minor**Start:** 20/01/2020 00:00:00**Work Status:** Proposed Works**Issued:** 31/01/2020 14:34:10**Work Type:** EToN 4: Minor**Est. End:** 04/02/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Junction with Mornington Crescent	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	20/01/2020			04/02/2020

Works Ref: CHRISMASON**Version:** 3**Work Desc:** Via East Midlands Carrying Out Cut Back of Overhanging Trees Works on Behalf of Nottinghamshire County Council**Notice Type:** Actual Start Date**Start:** 20/01/2020 00:00:00**Work Status:** In Progress**Issued:** 29/01/2020 09:11:55**Work Type:** EToN 4: Standard**Est. End:** 31/01/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From its Southern most junction with Mornington Crescent to its junction with Nuthall Roundabout	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	20/01/2020			31/01/2020

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** /GCWOODHOUSEWAY**Version:** 1**Work Desc:** Gully Cleansing**Notice Type:** 10 Day Initial Notice**Start:** 20/08/2018 00:00:00**Work Status:** Proposed Works**Issued:** 01/08/2018 10:55:46**Work Type:** EToN 4: Standard**Est. End:** 31/08/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	USRN: 4911713, Woodhouse Way, Gully Cleansing, Nuthall	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	20/08/2018			31/08/2018

Works Ref: /WOODHOUSEWAY1**Version:** 1**Work Desc:** Refresh lining**Notice Type:** Immediate Initial Notice**Start:** 15/10/2018 09:00:00**Work Status:** In Progress**Issued:** 11/10/2018 11:10:59**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 19/10/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	In Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	15/10/2018 09:00:00			19/10/2018

Works Ref: /WOODHOUSEWAY2**Version:** 1**Work Desc:** Refresh lining**Notice Type:** Immediate Initial Notice**Start:** 15/10/2018 09:00:00**Work Status:** In Progress**Issued:** 11/10/2018 11:12:48**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 19/10/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	In Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	15/10/2018 09:00:00			19/10/2018

Effective: 23/03/2018 to 06/04/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: Yes

Street: Woodhouse Way (4911713)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** WOODHOUSEWAYA**Version:** 3**Work Desc:** resurfacing**Notice Type:** Works Stop**Start:** 08/08/2018 00:00:00**Work Status:** Works Stopped**Issued:** 13/08/2018 09:19:06**Work Type:** EToN 4: Minor**Est. End:** 08/08/2018**Completion:** 09/08/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Woodhouse Way	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	09/08/2018			08/08/2018

Organisation: O2 (Cintel Structural Consultants Ltd) (7182067)**Works Ref:** 45274-COBRA-JC**Version:** 3**Work Desc:** Cherry Picker to access a telecoms pole for essential repairs. Traffic to be managed with a Lane Narrows with a Walkway going onto the road for people to pass.**Notice Type:** Works Stop**Start:** 02/08/2018 00:00:00**Work Status:** Works Stopped**Issued:** 02/08/2018 16:59:28**Work Type:** EToN 4: Minor**Est. End:** 02/08/2018**Completion:** 02/08/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	jnc Mornington Crescent	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	02/08/2018			02/08/2018

Organisation: O2 (Lifting Power Ltd) (7182056)**Works Ref:** 45274**Version:** 3**Work Desc:** Working on existing telecoms cabinet on footway. No excavation, no carriageway incursion. Component installation and testing only. 1.2 metres will be maintained for pedestrians. No weekend working.**Notice Type:** Works Stop**Start:** 22/06/2018 00:00:00**Work Status:** Works Stopped**Issued:** 23/06/2018 10:05:34**Work Type:** EToN 4: Minor**Est. End:** 26/06/2018**Completion:** 22/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On footway Woodhouse Way close to junction with Mornington Crescent.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	22/06/2018			26/06/2018

Organisation: O2 (NSN) (7182016)**Works Ref:** 45274/STM/KG/POLE**Version:** 11**Work Desc:** Excavation works - signing and guarding to be installed including relevant signage for telecoms works - Repair defect**Notice Type:** Registration of Reinstatement - Full**Start:** 08/01/2019 00:00:00**Work Status:** Works Stopped**Issued:** 16/01/2019 15:19:22**Work Type:** EToN 4: Minor**Est. End:** 08/01/2019**Completion:** 08/01/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Woodhouse Way approx 70m NE of Mornington Crescent	Footway	Up to 1.5 Metres of Cover	3.00	1.00	A Permanent Reinstatement	08/01/2019		08/01/2019	08/01/2019

Works Ref: 45274/STM/SC/EMERG**Version:** 2**Work Desc:** Emergency, non excavation works. Telecoms site has gone down and is experiencing complete outage which is having an effect on all surrounding businesses, residents and emergency services. Pedestrian management so that the issue can be rectified**Notice Type:** Works Stop**Start:** 09/07/2018 12:30:00**Work Status:** Works Stopped**Issued:** 12/07/2018 08:35:02**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 11/07/2018**Completion:** 11/07/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Woodhouse Way approx 70m NE of Mornington Crescent	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	11/07/2018			11/07/2018