

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

Street: Albert Road (2203480)

Locality: Retford, Nottinghamshire

Area: Bassetlaw

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b>		<b>Feature Type:</b>	Street Section		<b>Area:</b>	Bassetlaw
<b>Batch:</b>	20357113 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Oct Enh CW/FV		<b>Date:</b>	03/10/2019
3621368	2 no fw ph's	02/10/2019	entrance to clinton carpets	FW Repairs-Bituminous	Internal		Uncommitted	2725076
3621387	raise gully frame, see attached photo.	03/10/2019	car park entrance to Goodbodys gym	CW Ironwork	Internal		Committed	2725095
<b>Batch:</b>	20355588 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Sep Saf CW		<b>Date:</b>	19/09/2019
3620522	1 no cw ph	19/09/2019	os no 75	CW Repairs-Bituminous	Internal		Uncommitted	2724226
3620525	p80 - 4.0 x 1.8 - due to continually potholing	19/09/2019	os no 75, photo attached	CW Repairs-Bituminous	Internal		Committed	2724229
3620523	1 no cw ph	19/09/2019	os no 73	CW Repairs-Bituminous	Internal		Uncommitted	2724227
<b>Batch:</b>	20351616 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Aug Saf CW		<b>Date:</b>	23/08/2019
	No actionable defects found							
<b>Batch:</b>	20344615 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Jul Saf CW/FW		<b>Date:</b>	03/07/2019
	No actionable defects found							
<b>Batch:</b>	20343607 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Jun Saf CW		<b>Date:</b>	26/06/2019
3614197	1 no cw ph	26/06/2019	os no 75	CW Repairs-Bituminous	Internal		Committed	2717869
<b>Batch:</b>	20336377 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 May Saf CW		<b>Date:</b>	17/05/2019
	No actionable defects found							
<b>Batch:</b>	20331290 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Apr Saf CW/FV		<b>Date:</b>	11/04/2019
3606758	replace 1 no 6x5 kerb	11/04/2019	os no 83	Kerbing/Edging	Internal		Committed	2710395
3606757	replace 3 no 6x5 kerbs	11/04/2019	car park entrance to goodbodys gym	Kerbing/Edging	Internal		Committed	2710394
<b>Batch:</b>	20330168 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Mar Saf CW		<b>Date:</b>	04/04/2019
	No actionable defects found							
<b>Batch:</b>	20324203 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Feb Saf CW		<b>Date:</b>	21/02/2019
	No actionable defects found							
<b>Batch:</b>	20320717 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Jan Saf CW/FV		<b>Date:</b>	29/01/2019
3599670	2 no cw ph's	29/01/2019	junc with london rd, photo's attached	CW Repairs-Bituminous	Internal		Committed	2703205
3599686	2 no cw ph's	29/01/2019	junc with victoria rd	CW Repairs-Bituminous	Internal		Committed	2703221
3599685	seal patch around cover 2.5x0.3	29/01/2019	os no 55, photo attached	FW Repairs-Bituminous	Internal		Committed	2703220
<b>Batch:</b>	20315419 - Inspection Batch			<b>Route:</b>	Adhoc Inspection		<b>Date:</b>	13/12/2018
3596301	1 no cw ph	13/12/2018	os no 1, just as you turn onto albert rd off london rd	CW Repairs-Bituminous	Internal		Committed	2699743
<b>Batch:</b>	20312559 - Inspection Batch			<b>Route:</b>	Bassetlaw Area 3 Dec Saf CW		<b>Date:</b>	26/11/2018
	No actionable defects found							

Effective: 17/11/2018 to 18/11/2019  
Display Action Officer: No

Feature No.: 2000.00 to 2000.00  
Street: Albert Road (2203480)

**Customer Services**

**Enquiry No.:** 6145051      **Logged by:** External to Confirm      **on:** 08/11/2019 09:57  
**Service:** Carriageway/Footway      **Subject:** Flooding      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-155804994  
**Desc.:** Street flooding - Hello there we have massive problem with the flooding still at the front of the property the drain you have put in is working yo a certain degree but the soak away is flooding our path , it is next to the land we were asking for but didn't get the builder says that the roots from all that vegetation which over growing into our property have damaged the soak away it is coming from your piece of land and my place is suffering from it [REDACTED] Albert road rexford

On 31 Oct 2019 5:18 pm [REDACTED]

On 28 Oct 2019 10:10 am, Customer Service Centre &lt;enquiries@nottscc.gov.uk&gt; wrote:  
Dear [REDACTED],

Thank you for your e-mail.  
As advised by Highways the issue will be resolved in a future improvement scheme. If you are not happy with their response, please use the link below to submit a corporate complaint.

<https://www.nottinghamshire.gov.uk/contact-and-complaints/complaints/complaint-comment-compliment>  
We hope you find this helpful but if you have any further queries, please email us at: enquiries@nottscc.gov.uk.  
For further information and advice on all County Council services please visit our website at <http://www.nottinghamshire.gov.uk>  
Yours sincerely,

Customer Services  
Nottinghamshire County Council

Original email:

[REDACTED]

FS 152719091

We have been to our property [REDACTED] and our path in front of the property and our side path is 6 inches under water . This is not good enough do you think we can wait until the council are doing some scheme in the future, this needs tending to now not some time down the line. The foundation's are suffering from the con . Submitted by Advisor: [REDACTED] iCustomer title is [REDACTED]s.

**Location:** [REDACTED] Albert road - path way in front of property      **Contact:**

**Enquiry No.:** 6142107      **Logged by:** External to Confirm      **on:** 14/10/2019 13:09  
**Service:** Carriageway/Footway      **Subject:** Flooding      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-150217242  
**Desc.:** Street flooding - customer complaining of water flooding into her property and wants the issue resolved as she thinks its causing damage to her house.. Submitted by Advisor: [REDACTED] iCustomer title is [REDACTED]  
**Location:** [REDACTED] albert road      **Contact:**

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Customer Services**

<b>Enquiry No.:</b> 6140453	<b>Logged by:</b> External to Confirm	<b>on:</b> 29/09/2019 15:06	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Line Marking/Stud Renewal	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-146830558
<b>Desc.:</b> Road marking renewal - Road markings change, left lane has always been for left onto albert rd and straight on for Carolgate this has now changed to the right hand lane for straight on to carolgate and turn right to A638, I've seen a lot of people not noticing the new road markings and nearly causing accidents and there are no signs up warning of new layout. Please can someone come look at this ASAP REGARDS [REDACTED]. . Online report Customer title is [REDACTED]			
<b>Location:</b> London Rd traffic lights junction	<b>Contact:</b>		
<b>Enquiry No.:</b> 6140429	<b>Logged by:</b> External to Confirm	<b>on:</b> 28/09/2019 19:57	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Surface Dressing	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-146713722
<b>Desc.:</b> Issue with newly laid roads - I wish to query the change in road markings of the two lanes at the traffic lights. Left lane used to be left and straight on and the right lane was right. It has been repainted as left lane left and right lane straight on and right. This will cause major issues during rush hour traffic and will result in gridlocking the road. Please consider revising. . Online report Customer title is [REDACTED]			
<b>Location:</b> Crossroads at the bottom on London Road, Retford. Current roadworks.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6137618	<b>Logged by:</b> External to Confirm	<b>on:</b> 29/08/2019 12:12	
<b>Service:</b> Trees/Verges	<b>Subject:</b> Overhanging Vegetation/Trees	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-140272419
<b>Desc.:</b> Overgrown hedges and vegetation - Overgrown hedges making it very difficult for motorists to see clearly when they pull out of Duke Street. Also for pedestrians walking on Albert Road . Submitted by Advisor: [REDACTED].			
<b>Location:</b> outside number 77 Albert Road	<b>Contact:</b>		
<b>Enquiry No.:</b> 6137613	<b>Logged by:</b> External to Confirm	<b>on:</b> 29/08/2019 11:30	
<b>Service:</b> Bridges/Structures	<b>Subject:</b> Bridges/Structures Damage	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-140260085
<b>Desc.:</b> Bridges/structure damage - Customer is calling from Bassetlaw District Council on behalf of a local councillor who has reported this issue to them.  There is a large amount of graffiti on the bridge on the roadside which needs to be cleaned up.  Can we please get someone out to have a look at this issue? . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]			
<b>Location:</b> Bridge over the river on Albert Road, Retford.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6123304	<b>Logged by:</b> External to Confirm	<b>on:</b> 20/03/2019 12:04	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Spillage/Debris on Carriageway	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-110237372
<b>Desc.:</b> Spillage/debris in road - Car has been towed off the road onto the drive, diesel has leaked onto the road and running into the drains. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]			
<b>Location:</b> Outside number [REDACTED] Albert Road.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6113567	<b>Logged by:</b> External to Confirm	<b>on:</b> 03/12/2018 11:57	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Dropped Kerb (Vehicle) Request	<b>Classification:</b> Service Request	<b>Enquiry Ref:</b> FS-CASE-98220668
<b>Desc.:</b> Dropped kerb - Cars & other vehicles - Would like to apply for a dropped kerb outside the property . Submitted by Advisor: [REDACTED] - Quote required 5 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - The full length of the house to be able to get 2 cars on there Streetlight - No Customer title is [REDACTED]			
<b>Location:</b> Outside [REDACTED] Albert Rd Retford DN22 7AW	<b>Contact:</b>		

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Customer Services**

**Enquiry No.:** 6112410 **Logged by:** External to Confirm **on:** 19/11/2018 15:48  
**Service:** Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-96340901  
**Desc.:** Dropped kerb - Cars & other vehicles - Enough kerb stone for access to driveway however preferably the full length of the property.  
 . Submitted by Advisor: [REDACTED] - Quote required 4 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - Straight at the front of the property. Customer title is [REDACTED]  
**Location:** Outside property number [REDACTED] Albert Road, Retford, DN22 7AW **Contact:**

Customer doesn't live at this property yet so could all communication be done via email.

**Enquiry No.:** 3208400 **Logged by:** [REDACTED] **on:** 03/10/2019 10:18  
**Service:** Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation  
**Desc.:** stats required for ops to raise gully. job no 2725095  
**Location:** car park entrance to Goodbodys Gym **Contact:**

**Plot Number:** 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section  
**Job Number:** 2725095 **Defect Number:** 3621387

**Enquiry No.:** 80666 **Logged by:** [REDACTED] **on:** 20/06/2019 09:16  
**Service:** Traffic Management **Subject:** Parking General **Classification:** Report or Observation  
**Desc.:** See attached letter regarding a parking complaint  
**Location:** Albert Road **Contact:**

**Enquiry No.:** 80197 **Logged by:** [REDACTED] **on:** 28/05/2019 14:42  
**Service:** Highway Searches **Subject:** Searches - Other Enquiries **Classification:** Report or Observation  
**Desc.:** status enquiry - no charge as member of public enquiry. 28.5.19  
**Location:** path marked pink on plan - fruns from Albert Road to Whitehall Road **Contact:**

**Enquiry No.:** 79947 **Logged by:** [REDACTED] **on:** 15/05/2019 12:50  
**Service:** Highway Searches **Subject:** Adoption Extents **Classification:** Report or Observation  
**Desc.:** extent plan - [REDACTED]  
**Location:** [REDACTED] Albert Road Retford DN22 6JD **Contact:**

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b>		<b>Feature Type:</b> Street Section		<b>Area:</b> Bassetlaw	
2699743	1 no cw ph (CW Repairs-Bituminous)	os no 1, just as you turn onto albert rd off london rd	Category 2	Job Completed	13/12/2018	14/12/2018	Act. BAS-AS/5105797
2703205	2 no cw ph's (CW Repairs-Bituminous)	junc with london rd, photo's attached	Category 2	Job Completed	29/01/2019	30/01/2019	Act. BAS-AS/5106171
2703220	seal patch around cover 2.5x0.3 (FW Repairs-Bituminous)	os no 55, photo attached	Category 2	Job Completed	29/01/2019	05/03/2019	Act. BASS/3903063
2703221	2 no cw ph's (CW Repairs-Bituminous)	junc with victoria rd	Category 2	Job Completed	29/01/2019	30/01/2019	Act. BAS-AS/5106179
2710394	replace 3 no 6x5 kerbs (Kerbing/Edging)	car park entrance to goodbodys gym	Category 2	Job Completed	11/04/2019	18/04/2019	Act. BASS/3903476
2710395	replace 1 no 6x5 kerb (Kerbing/Edging)	os no 83	Category 2	Job Completed	11/04/2019	18/04/2019	Act. BASS/3903475
2717869	1 no cw ph (CW Repairs-Bituminous)	os no 75	Category 2	Job Completed	26/06/2019	04/07/2019	Act. BAS-AS/5107881

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>		<b>Feature Type:</b> Street Section		<b>Area:</b> Bassetlaw	
2724226	1 no cw ph (CW Repairs-Bituminous)	os no 75	Category 2	Repair Completed	19/09/2019	25/09/2019	Act.
2724227	1 no cw ph (CW Repairs-Bituminous)	os no 73	Category 2	Repair Completed	19/09/2019	25/09/2019	Act.
2724229	p80 - 4.0 x 1.8 - due to continually potholing (CW Repairs-Bituminous)	os no 75, photo attached	Category 2	Job Completed	19/09/2019	04/10/2019	Act. BASS/3904606
2725076	2 no fw ph's (FW Repairs-Bituminous)	entrance to clinton carpets	Category 2	Repair Completed	02/10/2019	03/10/2019	Act.
2725095	raise gully frame, see attached photo. (CW Ironwork)	car park entrance to Goodbodys gym	Category 3	Job Completed	03/10/2019	28/11/2019	Act. BASS/3904714

**Street Works Inspections**

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 2724229JG

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 04/10/2019 13:35:46
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> No
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> [REDACTED]	<b>Site Location:</b> OS Nr 75
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>

Organisation: WPD 5136 Retford (7011536)

Works Ref: M51362087153

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 06/12/2018 08:55:51
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> [REDACTED]	<b>Site Location:</b> OUTSIDE NUMBER 62
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

**Street Works Notices**

Organisation: Anglian Water - Clancy Water Maint&amp; Repair (9100032)

Works Ref: 56596395

Version: 4

Work Desc: Stoptap Replacements

Notice Type: Registration of Reinstatement - Full

Start: 23/08/2019 00:00:00

Work Status: Works Stopped

Issued: 29/08/2019 10:42:23

Work Type: EToN 4: Minor

Est. End: 28/08/2019

Completion: 28/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	104	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	28/08/2019		28/08/2019	28/08/2019

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Street Works Notices****Organisation:** Anglian Water - Clancy Water Maint& Repair (9100032)**Works Ref:** 56707275**Version:** 4**Work Desc:** Communication Pipe Repair**Notice Type:** Registration of Reinstatement - Full**Start:** 24/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 27/09/2019 11:01:01**Work Type:** EToN 4: Minor**Est. End:** 26/09/2019**Completion:** 26/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	21A	Footway	Up to 1.5 Metres of Cover	0.70	0.70	A Permanent Reinstatement	26/09/2019		26/09/2019	26/09/2019

**Works Ref:** 56735121**Version:** 4**Work Desc:** Leaking ferrule**Notice Type:** Registration of Reinstatement - Full**Start:** 08/10/2019 10:46:00**Work Status:** Works Stopped**Issued:** 11/10/2019 09:43:27**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 14/10/2019**Completion:** 10/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	21a	Carriageway	Up to 1.5 Metres of Cover	1.50	1.00	A Permanent Reinstatement	10/10/2019		10/10/2019	14/10/2019

**Organisation:** Anglian Water - Clancy Metering & Dev Services (9100029)**Works Ref:** 10543900/1**Version:** 7**Work Desc:** New connection in conjunction with AD029 - 10543900**Notice Type:** Works Stop**Start:** 12/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 18/11/2019 12:49:50**Work Type:** EToN 4: Standard**Est. End:** 15/11/2019**Completion:** 15/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Side of 57	Carriageway	Up to 1.5 Metres of Cover	2.00	1.10	A Permanent Reinstatement	07/01/2020		07/01/2020	08/01/2020

**Organisation:** BT (0030005)**Works Ref:** CN1W00AUG04SL6UKD43**Version:** 2**Work Desc:** SAFE Access to carriageway boxes to restore customer service**Notice Type:** Works Stop**Start:** 04/08/2019 08:00:00**Work Status:** Works Stopped**Issued:** 05/08/2019 07:42:09**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 04/08/2019**Completion:** 04/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	JCN ALBERT ROAD AND THRUMPTON LANE RETFORD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	04/08/2019			04/08/2019

**Works Ref:** CN789WOCT08SL6VEE75**Version:** 2**Work Desc:** SAFE Access to joint box to restore customer service.**Notice Type:** Works Stop**Start:** 08/10/2019 10:30:00**Work Status:** Works Stopped**Issued:** 08/10/2019 15:58:35**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 08/10/2019**Completion:** 08/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE ALBERT ROAD, RETFORD, DN22 6JB.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	08/10/2019			08/10/2019

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Street Works Notices****Organisation:** Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000875996**Version:** 3**Work Desc:** LAY 3X NEW DOMESTIC 32MM PE SERVICES 5M FROM MAIN IN CARRIAGEWAY**Notice Type:** Revert Actual Start**Start:** 29/10/2019 00:00:00**Work Status:** Proposed Works**Issued:** 29/10/2019 09:46:52**Work Type:** EToN 4: Standard**Est. End:** 01/11/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	DIG IN CARRIAGEWAY ADJACENT TO 57 COBWELL ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	29/10/2019			01/11/2019

**Works Ref:** 179209EM**Version:** 4**Work Desc:** SECTION 81- To reset surface box in Carriageway**Notice Type:** Cancellation**Start:** 12/05/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 13/05/2019 08:13:35**Work Type:** EToN 4: Minor**Est. End:** 12/05/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 89	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	12/05/2019			12/05/2019

**Works Ref:** 179209EM/01**Version:** 3**Work Desc:** SECTION 81- To reset surface box in Carriageway**Notice Type:** Cancellation**Start:** 15/09/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 16/09/2019 10:10:39**Work Type:** EToN 4: Major**Est. End:** 15/09/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 89	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	15/09/2019			15/09/2019

**Organisation:** NCC - BASSETLAW (3055002) (VIA Bilsthorpe)**Works Ref:** 30204498**Version:** 1**Work Desc:** Installation of a finger post**Notice Type:** 10 Day Initial Notice**Start:** 11/03/2019 00:00:00**Work Status:** Proposed Works**Issued:** 14/03/2019 13:17:31**Work Type:** EToN 4: Standard**Est. End:** 18/03/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Eastern end of Albert Road B6044 opposite Beehive Street.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/03/2019			18/03/2019

**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /HW30064/AR**Version:** 4**Work Desc:** Carriageway Resurfacing**Notice Type:** Works Stop**Start:** 16/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 02/10/2019 16:50:27**Work Type:** EToN 4: Major**Est. End:** 01/10/2019**Completion:** 02/10/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From Junction with Arlington Way to Beehive Street	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	02/10/2019			01/10/2019

Effective: 17/11/2018 to 18/11/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Albert Road (2203480)

**Street Works Notices****Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 2703220**Version:** 4**Work Desc:** Footpath repairs**Notice Type:** Works Stop**Start:** 31/01/2019 00:00:00**Work Status:** Works Stopped**Issued:** 06/03/2019 09:18:17**Work Type:** EToN 4: Standard**Est. End:** 15/02/2019**Completion:** 05/03/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside number 55	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/03/2019			08/02/2019

**Works Ref:** 2710395**Version:** 3**Work Desc:** Replace damaged / missing kerbs**Notice Type:** Works Stop**Start:** 16/04/2019 00:00:00**Work Status:** Works Stopped**Issued:** 18/04/2019 15:34:57**Work Type:** EToN 4: Standard**Est. End:** 26/04/2019**Completion:** 18/04/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OS Goodbody Gym & Nr 83	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	18/04/2019			26/04/2019

**Works Ref:** 2724229JG**Version:** 3**Work Desc:** Carriageway Patching**Notice Type:** Works Stop**Start:** 02/10/2019 00:00:00**Work Status:** Works Stopped**Issued:** 09/10/2019 09:23:35**Work Type:** EToN 4: Minor**Est. End:** 04/10/2019**Completion:** 04/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OS Nr 75	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	04/10/2019			04/10/2019

**Works Ref:** ALBERTROADJG**Version:** 3**Work Desc:** Ducting works**Notice Type:** Works Stop**Start:** 29/10/2019 00:00:00**Work Status:** Works Stopped**Issued:** 01/11/2019 14:38:18**Work Type:** EToN 4: Standard**Est. End:** 01/11/2019**Completion:** 01/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OS Nr 7	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	01/11/2019			01/11/2019

**Organisation:** WPD 5136 Retford (7011536)**Works Ref:** M51362087153**Version:** 4**Work Desc:** 1 joint hole in tarmac footway and install 43m of ducting and cable for new supply**Notice Type:** Registration of Reinstatement - Full**Start:** 29/11/2018 00:00:00**Work Status:** Works Stopped**Issued:** 11/12/2018 16:02:30**Work Type:** EToN 4: Standard**Est. End:** 07/12/2018**Completion:** 07/12/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE NUMBER 62	Footway	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	07/12/2018		07/12/2018	07/12/2018
2	OUTSIDE NUMBER 62	Footway	Up to 1.5 Metres of Cover	43.00	0.30	A Permanent Reinstatement	07/12/2018		07/12/2018	