

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Street: Southwell Road (26805346)

Locality: Oxtou, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	C42 - Oxtou	Feature Type: Street Section			Area: Newark	
Batch: 20283894 - Inspection Batch		Route: Newark Area 2 May Saf CW			Date: 17/05/2018			
No actionable defects found								
Batch: 20279148 - Inspection Batch		Route: Newark Area 2 Apr Enh CW/FW			Date: 23/04/2018			
3575810	pothole	23/04/2018	at bottom of hill going to oxtou all marked	CW Repairs-Bituminous	Internal		Committed	2678903
Batch: 20271793 - Inspection Batch		Route: Newark Area 2 Mar Saf CW			Date: 08/03/2018			
3570382	potholes	08/03/2018	on bends in shell grip near sandy lane marked	CW Repairs-Bituminous	Internal		Committed	2673364
3570380	pothole	08/03/2018	inbetween old hall nurseries and sandy lane marked	CW Repairs-Bituminous	Internal		Committed	2673365
3570381	potholes	08/03/2018	on bends just befor old hall near please slow singe marked	CW Repairs-Bituminous	Internal		Committed	2673366
Batch: 20268303 - Inspection Batch		Route: Newark Area 2 Feb Saf CW			Date: 14/02/2018			
3568022	potholes	14/02/2018	200mpassed oxtou turn off, before bend, marked	CW Repairs-Bituminous	Internal		Committed	2670978
Batch: 20261392 - Inspection Batch		Route: Newark Area 2 Jan Saf CW			Date: 04/01/2018			
3562966	potholes	04/01/2018	from sand lane to tractor sign marked	CW Repairs-Bituminous	Internal		Committed	2665859
3562965	pothole	04/01/2018	opps old hall next to culvert to sand lane marked	CW Repairs-Bituminous	Internal		Committed	2665858
3562968	potholes	04/01/2018	on straight befor oxtou turn off marked	CW Repairs-Bituminous	Internal		Committed	2665857
3562967	pothole	04/01/2018	os park farm marked	CW Repairs-Bituminous	Internal		Committed	2665860
Batch: 20259809 - Inspection Batch		Route: Newark Area 2 Dec Saf CW			Date: 19/12/2017			
No actionable defects found								
Batch: 20253598 - Inspection Batch		Route: Newark Area 2 Nov Saf CW			Date: 07/11/2017			
3559029	pothole	07/11/2017	near give way sign marked	CW Repairs-Bituminous	Internal		Committed	2661775
3559030	pothole	07/11/2017	next to bend sign epperstone road end marked	CW Repairs-Bituminous	Internal		Committed	2661774
Batch: 20250914 - Inspection Batch		Route: Newark Area 2 Oct Saf CW			Date: 19/10/2017			
No actionable defects found								
Batch: 20247138 - Inspection Batch		Route: Newark Area 2 Sep Saf CW			Date: 22/09/2017			
3555881	pothole	22/09/2017	from sandy ln to epperstone rd marked	CW Repairs-Bituminous	Internal		Committed	2658397
Batch: 20243422 - Inspection Batch		Route: Newark Area 2 Jun Saf CW			Date: 29/08/2017			
No actionable defects found								
Batch: 20242801 - Inspection Batch		Route: Newark Area 2 Aug Saf CW			Date: 23/08/2017			
3553978	potholes	23/08/2017	os deer leep house marked	CW Repairs-Bituminous	Internal		Committed	2656428
3553977	potholes	23/08/2017	on junction with epperstone rd marked	CW Repairs-Bituminous	Internal		Committed	2656427
3553979	potholes	23/08/2017	in middle of road near old hall nurseries marked	CW Repairs-Bituminous	Internal		Committed	2656426

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C42 - Oxtou			Feature Type: Street Section			Area: Newark	
Batch: 20240163 - Inspection Batch				Route: Newark Area 2 Jul Saf CW				Date: 01/08/2017
3552741	potholes	01/08/2017	outside old hall nurseries 100 m from sandy lane , marked	CW Repairs-Bituminous	Internal		Committed	2655089
3552742	cat 2 high pothole	01/08/2017	as mapped. filled during inspection	CW Repairs-Bituminous	Internal		Uncommitted	2655090
3552743	pothole	01/08/2017	just before sandy lane marked in orange spray	CW Repairs-Bituminous	Internal		Committed	2655088
Batch: 20229804 - Inspection Batch				Route: Newark Area 2 May Saf CW				Date: 12/05/2017
No actionable defects found								
Batch: 20226656 - Inspection Batch				Route: Newark Area 2 Apr Enh CW/FW				Date: 25/04/2017
No actionable defects found								
Batch: 20221259 - Inspection Batch				Route: Adhoc Inspection				Date: 17/03/2017
3544796	Carriageway potholes	17/03/2017	between junc with sandy lane and blind lane, marked yellow, all are nearer to sandy lane	CW Repairs-Bituminous	Internal		Committed	2646566
Batch: 20220038 - Inspection Batch				Route: Newark Area 2 Mar Saf CW				Date: 07/03/2017
No actionable defects found								
Batch: 20215854 - Inspection Batch				Route: Newark Area 2 Feb Saf CW				Date: 08/02/2017
No actionable defects found								
Batch: 20211892 - Inspection Batch				Route: Newark Area 2 Jan Saf CW				Date: 10/01/2017
No actionable defects found								
Batch: 20209558 - Inspection Batch				Route: Newark Area 2 Dec Saf CW				Date: 19/12/2016
No actionable defects found								
Batch: 20203871 - Inspection Batch				Route: Newark Area 2 Nov Saf CW				Date: 04/11/2016
No actionable defects found								
Batch: 20200600 - Inspection Batch				Route: Newark Area 2 Oct Saf CW				Date: 13/10/2016
No actionable defects found								
Batch: 20195643 - Inspection Batch				Route: Newark Area 2 Sep Saf CW				Date: 06/09/2016
3534213	potholes	06/09/2016	in between sand lane and old hall nursery marked	CW Repairs-Bituminous	Internal		Committed	2635512
Batch: 20192627 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 09/08/2016
No actionable defects found								
Batch: 20189392 - Inspection Batch				Route: Newark Area 2 Jul Saf CW				Date: 18/07/2016
No actionable defects found								
Batch: 20184055 - Inspection Batch				Route: Newark Area 2 Jun Saf CW				Date: 07/06/2016
No actionable defects found								
Batch: 20179332 - Inspection Batch				Route: Newark Area 2 May Saf CW				Date: 09/05/2016
3528656	potholes	09/05/2016	In between sandy lane and blind lane in middle of carriageway marked will need stop and go due to location	CW Repairs-Bituminous	Internal		Committed	2629635

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C42 - Oxtou			Feature Type: Street Section			Area: Newark	
Batch: 20179332 - Inspection Batch				Route: Newark Area 2 May Saf CW				Date: 09/05/2016
3528655	pothole	09/05/2016	Just before sandy lane marked	CW Repairs-Bituminous	Internal		Committed	2629634
3528657	potholes	09/05/2016	On bend just before sandy lane on bend In middle of carriageway marked may need traffic management due to location	CW Repairs-Bituminous	Internal		Committed	2629633
Batch: 20174463 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Apr Enh CW/FW				Date: 06/04/2016
Batch: 20170660 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Mar Saf CW				Date: 07/03/2016
Batch: 20169673 - Inspection Batch				Route: Adhoc Inspection				Date: 02/03/2016
3524645	pothole	02/03/2016	Nr entrance to old hall nurseries opposite side to f road marked	HW CW Pothole Z1	Internal		Committed	2625595
Batch: 20164636 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Feb Saf CW				Date: 02/02/2016
Batch: 20161829 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jan Saf CW				Date: 14/01/2016
Batch: 20156900 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Dec Saf CW				Date: 03/12/2015
Batch: 20151691 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Nov Saf CW				Date: 02/11/2015
Batch: 20147913 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Oct Saf CW				Date: 06/10/2015
Batch: 20144656 - Inspection Batch				Route: Adhoc Inspection				Date: 16/09/2015
3515440	pothole	16/09/2015	Just before the old hall in middle of road	HW CW Pothole Z1	Internal		Uncommitted	2616091
Batch: 20143481 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Sep Saf CW				Date: 08/09/2015
Batch: 20140726 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Aug Saf CW				Date: 14/08/2015
Batch: 20135901 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jul Saf CW				Date: 07/07/2015
Batch: 20131831 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jun Saf CW				Date: 09/06/2015

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Customer Services

Enquiry No.: 6077601	Logged by: External to Confirm	on: 22/01/2018 15:42	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-66386697
Desc.: Road Pothole - On southbound side on approach to junction . Online report			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6074807	Logged by: External to Confirm	on: 03/01/2018 10:30	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-64902392
Desc.: Road Pothole - Potholes on left when travelling west . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C42 - Oxton	Feature Type: Street Section	
Job Number: 2665858	Defect Number: 3562965		
Enquiry No.: 6063784	Logged by: External to Confirm	on: 11/09/2017 14:34	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: FS-CASE-58557761
Desc.: Damaged/dangerous/fallen tree - Fallen oak tree branch on junction of Southwell Road and Epperstone Road B6386 parallel with Oxton Bypass. covering carriageway on one side. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6046936	Logged by: External to Confirm	on: 15/03/2017 14:17	
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-14134317
Desc.: Street/road sign damage - The 'Oxton Village' sign post on the B6383 near the Blind Lane junction has been turned around (perhaps by being hit by a vehicle?) and it is now pointing in the wrong direction. It should be pointing to go down down Blind Lane. This sign is on a pole with two other direction road signs and the Oxton Village sign should be at right angles to the other two. . Online report			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6046935	Logged by: External to Confirm	on: 15/03/2017 14:16	
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-14134317
Desc.: Street/road sign damage - The 'Oxton Village' sign post on the B6383 near the Blind Lane junction has been turned around (perhaps by being hit by a vehicle?) and it is now pointing in the wrong direction. It should be pointing to go down down Blind Lane. This sign is on a pole with two other direction road signs and the Oxton Village sign should be at right angles to the other two. . Online report			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6046785	Logged by: External to Confirm	on: 14/03/2017 13:46	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-14073083
Desc.: Road Pothole - Customer Email: This unlit road has a serious pothole that damaged a bike last night. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C42 - Oxton	Feature Type: Street Section	
Job Number: 2646566	Defect Number: 3544796		
Enquiry No.: 6038776	Logged by: External to Confirm	on: 10/01/2017 15:42	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-11460227
Desc.: Spillage/debris in road - farmer /workman cutting the hedge with a tractor and lots of debris flying about and has made 5 chips in the windscreen . when get home will inspect the car more we not sure if council workers or local farmer. . Submitted by Advisor: [REDACTED]			
Location: The pin has been placed near Main Street, Southwell, United Kingdom, NG25 0SD		Contact:	

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Customer Services

Enquiry No.: 6027835 **Logged by:** External to Confirm **on:** 19/09/2016 09:38
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-6745032
Desc.: Spillage/debris in road - RTC on Southwell Road Oxtou, between Epperstone road and old hall nurseries. Diesel and Oil is on the road, emergency services are currently out there. The fire services have tried to deal with the spillage but need more to deal with it. Incident no 194/19092016 . Sherwood Lodge , Sherwood Park Drive, , NG5 8PP. Submitted by Advisor: [REDACTED]
Location: The pin has been placed near Epperstone Road, Southwell, United Kingdom, NG25 **Contact:** OSQ

Enquiry No.: 6015416 **Logged by:** External to Confirm **on:** 18/05/2016 08:56
Service: Traffic Management **Subject:** Speed Limits/Issues **Classification:** Report or Observation
Desc.: Speed limits - Please see email below:

I have had a resident inform me that within the Road works between Southwell and Oxtou on the B6386 there are 2 different speed limit signs.

The resident has asked that this be rectified as soon as possible so that the speed limit is clear.

Location: The pin has been placed near Southwell Road, Southwell, United Kingdom, NG25 **Contact:** ORJ -

Enquiry No.: 6007617 **Logged by:** External to Confirm **on:** 01/03/2016 16:00
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103879570
Desc.: Pothole on south travelling side of Oxtou Road
Location: 385 meters from 2 Holly Lodge Cottage Southwell Road **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C42 - Oxtou **Feature Type:** Street Section
Job Number: 2625595 **Defect Number:** 3524645

Enquiry No.: 6001177 **Logged by:** External to Confirm **on:** 14/01/2016 12:49
Service: Trees/Verges **Subject:** Fallen Tree **Classification:** Report or Observation **Enquiry Ref:** 103846170
Desc.: Officer is reporting a fallen tree on Southell road between Southwell and Oxtou. Officer that gave information didnt tell them any near by houses. It is totally blocking the road as it is a large tree They are trying to move the tree but having some difficulty.
 Logged by CSC operator: [REDACTED]
Location: 206 meters from Deer Leap Oxtou Hill **Contact:**

Enquiry No.: 3177082 **Logged by:** External to Confirm **on:** 06/07/2015 15:12
Service: Carriageway/Footway **Subject:** St Furn/Non Illum Sign Damage **Classification:** Report or Observation **Enquiry Ref:** 103631666
Desc.: There is no direction confirmation sign for Southwell at this junction. The B6386 requires traffic to turn at this junction which could easily be missed without the direction sign.
Location: 450 meters from Meadow View Nottingham Road **Contact:**

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Customer Services

Enquiry No.: 68580

Logged by: [REDACTED]

on: 18/01/2018 09:18

Service: Carriageway/Footway

Subject: Carriageway Damage

Classification: Report or Observation

Desc.: From [REDACTED]

Sent: 18 January 2018 08:37

To: [REDACTED]

Subject: Patching Work required - Southwell Road, Oxton

Hi [REDACTED]

As discussed yesterday please find attached plan showing proposed works on Southwell Road, Oxton, between its junctions with Sandy Lane and Blind Lane. The section of road is to have the centre line renewed and new edge of carriageway lines added. At the moment parts of the centre of the road and the edge of the road are potholed and unsuitable for lining. The works are due to take place on the 25th February 2018.

[REDACTED]
Senior Improvements Officer
Via East Midlands Ltd

Location: Southwell Road

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C42 - Oxton		Feature Type: Street Section		Area: Newark	
2616091	pothole (HW CW Pothole Z1)	Just before the old hall in middle of road	Filled when found (Cat 2)	Job Completed	16/09/2015	16/09/2015	Act.
2625595	pothole (HW CW Pothole Z1)	Nr entrance to old hall nurseries opposite side to f road marked	Category 1	Job Completed	02/03/2016	03/03/2016	Act. NEW-AS/5500837
2629633	potholes (CW Repairs-Bituminous)	On bend just before sandy lane on bend In middle of carriageway marked may need traffic management due to location	Category 2	Job Completed	09/05/2016	10/05/2016	Act. NEW-AS/5501105
2629634	pothole (CW Repairs-Bituminous)	Just before sandy lane marked	Category 2	Job Completed	09/05/2016	10/05/2016	Act. NEW-AS/5501106
2629635	potholes (CW Repairs-Bituminous)	In between sandy lane and blind lane in middle of carriageway marked will need stop and go due to location	Category 2	Job Completed	09/05/2016	10/05/2016	Act. NEW-AS/5501107
2635512	potholes (CW Repairs-Bituminous)	in between sand lane and old hall nursery marked	Category 2	Job Completed	06/09/2016	07/09/2016	Act. NEW-AS/5501722
2646566	Carriageway potholes (CW Repairs-Bituminous)	between junc with sandy lane and blind lane, marked yellow, all are nearer to sandy lane	Category 2	Job Completed	17/03/2017	21/03/2017	Act. NEW-AS/5502723
2655088	pothole (CW Repairs-Bituminous)	just before sandy lane marked in orange spray	Category 2	Job Completed	01/08/2017	03/08/2017	Act. NEW-AS/5503376
2655089	potholes (CW Repairs-Bituminous)	outside old hall nurseries 100 m from sandy lane , marked	Category 2	Job Completed	01/08/2017	03/08/2017	Act. NEW-AS/5503377

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	C42 - Oxtou	Feature Type:	Street Section	Area:	Newark
2655090	cat 2 high pothole (CW Repairs-Bituminous)	as mapped. filled during inspection		Filled when found (Cat 2) Job Completed	01/08/2017	01/08/2017	Act.
2656426	potholes (CW Repairs-Bituminous)	in middle of road near old hall nurseries marked	Category 2	Job Completed	23/08/2017	01/09/2017	Act. NEW/3605473
2656427	potholes (CW Repairs-Bituminous)	on junction with epperstone rd marked	Category 3	Job Completed	23/08/2017	01/09/2017	Act. NEW/3605470
2656428	potholes (CW Repairs-Bituminous)	os deer leep house marked	Category 2	Job Completed	23/08/2017	01/09/2017	Act. NEW/3605474
2658397	pothole (CW Repairs-Bituminous)	from sandy ln to epperstone rd marked	Category 3	Job Completed	22/09/2017	11/10/2017	Act. NEW/3605878
2661774	pothole (CW Repairs-Bituminous)	next to bend sign epperstone road end marked	Category 3	Job Completed	07/11/2017	30/11/2017	Act. NEW/3606477
2661775	pothole (CW Repairs-Bituminous)	near give way sign marked	Category 3	Job Completed	07/11/2017	30/11/2017	Act. NEW/3606478
2665857	potholes (CW Repairs-Bituminous)	on straight befor oxtou turn off marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607155
2665858	pothole (CW Repairs-Bituminous)	opps old hall next to culvert to sand lane marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607156
2665859	potholes (CW Repairs-Bituminous)	from sand lane to tractor sign marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607157
2665860	pothole (CW Repairs-Bituminous)	os park farm marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607158
2670978	potholes (CW Repairs-Bituminous)	200mpassed oxtou turn off, before bend, marked	Category 3	Job Completed	14/02/2018	03/04/2018	Act. NEW/3608014
2673364	potholes (CW Repairs-Bituminous)	on bends in shell grip near sandy lane marked	Category 3	Job Completed	08/03/2018	03/04/2018	Act. NEW/3608512
2673365	pothole (CW Repairs-Bituminous)	inbetween old hall nurseries and sandy lane marked	Category 2	Job Completed	08/03/2018	12/03/2018	Act. NEW-AS/5505308
2673366	potholes (CW Repairs-Bituminous)	on bends just befor old hall near please slow singe marked	Category 3	Job Completed	08/03/2018	03/04/2018	Act. NEW/3608513
2678903	pothole (CW Repairs-Bituminous)	at bottom of hill going to oxtou all marked	Category 2	Job Completed	23/04/2018	24/04/2018	Act. NEW/3609294

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011392429

Group No: 1	Site No: 1	Street Authority: NCC - NEWARK	Inspected: 21/06/2016 15:00:00
Category: Category A		Outcome: Failed (Higher Risk/Dangerous)	Sampled: Yes
Defect Notif. No: 699		Defect No: 699	Site Informed: Yes
		Tel: 0115 977 3502	Site Location: CRIFTIN MILL COTTAGE, SOUTHWELL ROAD, OXTON, NG14 6AT
Insp. Notes: Temporary Traffic Lights had failed. HA attended site to remove the lights the allow traffic to move. Trifix attended site as we were leaving and the site was handed back to Severn Trent TM Team			Position: Carriageway
Defect Notes: Temporary Traffic Lights had failed. HA attended site to remove the lights the allow traffic to move. Trifix attended site as we were leaving and the site was handed back to Severn Trent TM Team			Sampled Site No: 1
			Sign/Light/Guard. Inadequacy: No
			Site Post Code:

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Street Works Notices**Organisation:** Events in Nottinghamshire (3055365)**Works Ref:** NK178-15A**Version:** 1**Work Desc:** Southwell Ploughing Match**Notice Type:** 3 Day Initial Notice**Start:** 26/09/2015 00:00:00**Work Status:** Proposed Works**Issued:** 08/09/2015 15:05:50**Work Type:** EToN 4: Minor**Est. End:** 26/09/2015**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	26/09/2015			26/09/2015

Organisation: NCC - NEWARK (3055004)**Works Ref:** 30603190**Version:** 3**Work Desc:** Gully Emptying**Notice Type:** Works Stop**Start:** 04/05/2016 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2016 12:34:15**Work Type:** EToN 4: Minor**Est. End:** 06/05/2016**Completion:** 06/05/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	06/05/2016			06/05/2016

Works Ref: 30603792**Version:** 1**Work Desc:** Pot Hole Repairs**Notice Type:** 10 Day Initial Notice**Start:** 31/08/2017 00:00:00**Work Status:** Proposed Works**Issued:** 30/08/2017 13:50:17**Work Type:** EToN 4: Standard**Est. End:** 02/09/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	B6386	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	31/08/2017			02/09/2017

Works Ref: NK16-18**Version:** 2**Work Desc:** Lining Works**Notice Type:** Confirmation of Major**Start:** 24/02/2018 00:00:00**Work Status:** Proposed Works**Issued:** 14/02/2018 17:04:04**Work Type:** EToN 4: Major**Est. End:** 25/02/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Blind Lane & Sandy Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	24/02/2018			25/02/2018

Works Ref: NK16-18A**Version:** 4**Work Desc:** Lining Works**Notice Type:** Works Stop**Start:** 04/03/2018 00:00:00**Work Status:** Works Stopped**Issued:** 05/03/2018 11:52:42**Work Type:** EToN 4: Major**Est. End:** 04/03/2018**Completion:** 04/03/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Blind Lane & Sandy Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	04/03/2018			04/03/2018

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Southwell Road (26805346)

Street Works Notices**Organisation:** NCC - NEWARK (3055004)**Works Ref:** OP1700344**Version:** 1**Work Desc:** Installing new signs for the reduction of the speed limit**Notice Type:** 10 Day Initial Notice**Start:** 16/01/2018 00:00:00**Work Status:** Proposed Works**Issued:** 16/01/2018 13:39:25**Work Type:** EToN 4: Standard**Est. End:** 19/01/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Southwell & Oxtou	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	16/01/2018			19/01/2018

Organisation: NRSWA - BT (0030005)**Works Ref:** CC1W0013MAREM9PCU08**Version:** 4**Work Desc:** Access required to overhead BT structure to repair service - No structural changes. Work being carried out on existing BT Plant**Notice Type:** Temporary Traffic Signal Response**Start:** 13/03/2017 09:30:00**Work Status:** Works Stopped**Issued:** 16/03/2017 09:06:21**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 13/03/2017**Completion:** 13/03/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	south of Middlehay school on Southwell Rd Southwell NG25 0RB	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	13/03/2017			13/03/2017

Works Ref: CC1W00EM0BLK94APR11**Version:** 3**Work Desc:** Access required to overhead BT structure to repair service - No structural changes. Work being carried out on existing BT Plant**Notice Type:** Works Stop**Start:** 11/04/2018 09:30:00**Work Status:** Works Stopped**Issued:** 11/04/2018 16:27:09**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 11/04/2018**Completion:** 11/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	ENTRANCE TO OLD HALL NURSERIES ON SOUTHWELL ROAD OXTON NG25 0RJ	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	11/04/2018			11/04/2018

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000011392429**Version:** 4**Work Desc:** Sluice Valve Rebuild chamber Job in Carriageway (Hot Rolled Asphalt)**Notice Type:** Registration of Reinstatement - Full**Start:** 20/06/2016 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2016 12:59:35**Work Type:** EToN 4: Minor**Est. End:** 22/06/2016**Completion:** 22/06/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	CRIFTIN MILL COTTAGE, SOUTHWELL ROAD, OXTON, NG14 6AT	Carriageway	Up to 1.5 Metres of Cover	2.00	2.00 A Permanent Reinstatement	22/06/2016		22/06/2016	22/06/2016