

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Devonshire Road (33000866)

Street: Devonshire Road (33000866)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area: Rushcliffe	
Batch: 20407934	- Inspection Batch No actionable defects found			Route: Rush Area 2 Sep Saf CW				Date: 03/09/2020
Batch: 20404101	- Inspection Batch No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 06/08/2020
Batch: 20398707	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 02/07/2020
Batch: 20393738	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jun Saf CW				Date: 01/06/2020
Batch: 20389445	- Inspection Batch No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 01/05/2020
Batch: 20388185	- Inspection Batch No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 17/04/2020
Batch: 20384708	- Inspection Batch No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 27/03/2020
Batch: 20381280	- Inspection Batch No actionable defects found			Route: Rush Area 2 Feb Saf CW				Date: 05/03/2020
Batch: 20379999	- Inspection Batch			Route: Adhoc Inspection				Date: 27/02/2020
3634940	Carriageway defects has been made safe	27/02/2020	On the T junction	Musters Rd	CW Repairs-Bituminous	Internal	Uncommitted	2738691
Batch: 20371386	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jan Enh CW/FW				Date: 07/01/2020
Batch: 20368427	- Inspection Batch No actionable defects found			Route: Rush Area 2 Dec Saf CW				Date: 12/12/2019
Batch: 20364856	- Inspection Batch No actionable defects found			Route: Rush Area 2 Nov Saf CW				Date: 26/11/2019
Batch: 20359561	- Inspection Batch No actionable defects found			Route: Rush Area 2 Oct Saf CW				Date: 17/10/2019
Batch: 20355535	- Inspection Batch No actionable defects found			Route: Rush Area 2 Sep Saf CW				Date: 19/09/2019

Customer Services

Enquiry No.: 6172974

Logged by: External to Confirm

on: 24/07/2020 10:54

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Enquiry Ref: FS-CASE-231444329

Desc.: Other tree issues - Young trees were planted, but these were taken down in the night, The caller is unhappy that we have just dug the roots out and tarmacked over it as he believes this means the vandals have won. . Submitted by Advisor: **PERSONAL DATA**

Location: 2 trees near the Melton Road end od Devonshire

Contact:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Devonshire Road (33000866)

Customer Services

Enquiry No.: 6167957	Logged by: External to Confirm	on: 01/06/2020 13:33	Enquiry Ref: FS-CASE-212710505
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	
Desc.: Damaged/dangerous/fallen tree - There is a young tree which has been planted in the pavement. It is currently staked with, and secure to, two wooden posts. In the high winds last weeks the tree was swaying dangerously and one of the wooden stakes has worked loose. Cars parked in the vicinity had to be moved as we were concerned that it could blow down. The tree looks very healthy but it needs re-staking/securing in case we have high winds again. . Online report PERSONAL .			
Location: On the pavement outside 10 Devonshire Road, West Bridgford, Nottingham, NG2 6EU		Contact:	
Enquiry No.: 6166268	Logged by: External to Confirm	on: 28/04/2020 12:27	Enquiry Ref: FS-CASE-201353653
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - A felled tree that has been left with jagged spikes - dangerous should someone fall on it . Online report PERSONAL			
Location: Outside 20 Devonshire Road, West Bridgford		Contact:	
Enquiry No.: 6165991	Logged by: External to Confirm	on: 20/04/2020 17:36	Enquiry Ref: FS-CASE-198359644
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - The tree has been cut down at about the one metre line from pavement level.A small tree as trees go in West Bridgford. . Online report PERSONAL			
Location: On the pavement out side (whats left of the tree in front of 28 Devonshire Road (loughborough rd end) West Bridgford NG2. Just 20 m from the old railway bridge which spans the disused railway Bridge.		Contact:	
Enquiry No.: 6165132	Logged by: External to Confirm	on: 20/03/2020 14:03	Enquiry Ref: FS-CASE-185653784
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - There is a tree that has been cut down at the trunk and placed on the pavement, this is now the second tree to be chopped down at this location within the last few days. Customer believes someone is deliberate doing this to the trees and then they are placed in the pavement, customer believes they are placed there strategically. . Submitted by Advisor: PERS			
Location: Just before the railway bridge on Devonshire road (coming from musters road)		Contact:	
Enquiry No.: 6164709	Logged by: External to Confirm	on: 16/03/2020 12:30	Enquiry Ref: FS-CASE-184142153
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - For the second time in as many weeks a roadside tree has been deliberately cut down with a saw. This is not just mindless vandalism, it is criminal damage. I hope you can do something to catch the villain . Submitted by Advisor: Candy Cooper PERSONAL .			
Location: Devonshire Road West Bridgford NG2 6EU		Contact:	
Enquiry No.: 6164557	Logged by: External to Confirm	on: 16/03/2020 07:58	Enquiry Ref: FS-CASE-183621877
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	
Desc.: Damaged/dangerous/fallen tree - It looks like someone has chopped the tree down...it's been sawn through about 3 feet from the ground. The same thing seems to have happened to a different tree on the same road last week - this is not the same one. At 13:00 on Sat 14th March there was a man who was cutting the tree up with Secateurs - I don't think he was the person who chopped it down though, I think he was just making it safe and less of an obstruction to pedestrians. . Online report PERSONAL .			
Location: Devonshire Road in West Bridgford, it's on the north side of the road very close to the road tunnel under the Green Line. It's on the opposite side of the road from the Scott's Wood Day Nursery.		Contact:	

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Devonshire Road (33000866)

Customer Services

Enquiry No.: 6161147 **Logged by:** External to Confirm **on:** 25/02/2020 15:59
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-177809591
Desc.: Road Pothole - Pothole forming . Online report PERSONAL
Location: On the join of Devonshire as it meets Musters Rd **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section
Job Number: 2738691 **Defect Number:** 3634940

Enquiry No.: 6144722 **Logged by:** External to Confirm **on:** 07/11/2019 10:18
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-155565604
Desc.: Other enquiry - Ref; 83383 regarding illegal access to number 20 Devonshire Road, WB. Dr Eastwood lives at number 17 so does not know why she has received this letter. Has requested a call back.
07815057127 . Submitted by Advisor: PERSONAL
Location: 20 Devonshire Road, West Bridgford **Contact:**

Enquiry No.: 86691 **Logged by:** PERSONAL **on:** 10/03/2020 12:16
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request
Desc.: PERS,

Your Ref.: Instructions to prosecute for installation of a substandard and unauthorised vehicle crossing
Our Ref.: SJE/23523 (20191217 SJE3 Devonshire Rd, West Bridgford - Unauthorised VA - Enforcement)

Thank you for your e-mail. Please accept my apologies for the delay in replying.

I have been considering this and, while I note the reference to actions such as prosecuting for the installation of the unauthorised vehicle crossing, I also note that our direct course (and the indications we have given to the property owner) are one of taking action under S.184. As such, I would recommend that we pursue the specific actions under S.184 rather than the more general one of prosecution in this instance.

Additionally, I have no information as to whether planning permission was obtained for the vehicle crossing (or whether it is required) S.184 is a licensing section authorising the taking of action only where the conditions imposed as a result of us using S.184 are not complied with. As such, it is likely strictly incorrect to state that the unauthorised vehicle crossing, as a vehicle crossing, is illegal – what may be unlawful is the disturbance to the metalled carriageway &c.

Accordingly, I would recommend that you / Via now serve an appropriate Notice in accordance with S.184(1) stating that NCC will do such works as a required to make the crossing 'proper' and imposing conditions on its use in the meantime (and perhaps lesser conditions for thereafter) having regard to S.184(5). Should such conditions of making 'proper' not be complied with, we may then move to doing it ourselves under S.184, invoicing them, and reminding them as to contraventions under S.184(17).

I hope this is helpful.

Atb,

PER

Location: O/S No 20

Contact:

Enquiry No.: 83383 **Logged by:** PERSONAL **on:** 28/10/2019 16:05
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation
Desc.: Illegal opening of the highway. Mud / illegal stored materials. PERSONAL would like feedback. Possibly related to Selby Rd mud/materials - logged separately
Location: By the railway bridge **Contact:**

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Devonshire Road (33000866)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Rushcliffe	
2738691	Carriageway defects has been made safe (CW Repairs-Bituminous)	On the T junction Musters Rd	Filled when found (Cat 2)	Job Completed	28/02/2020	27/02/2020	Act.

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** T1001MW500297657000**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 11/05/2020 00:00:00**Work Status:** Works Stopped**Issued:** 21/05/2020 08:35:02**Work Type:** EToN 4: Minor**Est. End:** 13/05/2020**Completion:** 13/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	WORKS BETWEEN OPP NO. 20 TO OPP NO. 26 ON, DEVONSHIRE ROAD	Footway	Up to 1.5 Metres of Cover	1.20	0.50 A Permanent Reinstatement	13/05/2020		13/05/2020	13/05/2020
2	WORKS BETWEEN OPP NO. 20 TO OPP NO. 26 ON, DEVONSHIRE ROAD	Footway	Up to 1.5 Metres of Cover	1.60	0.60 A Permanent Reinstatement	13/05/2020		13/05/2020	

Works Ref: T1003MW500295618101**Version:** 4**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 26/03/2020 00:00:00**Work Status:** Works Stopped**Issued:** 15/04/2020 14:21:05**Work Type:** EToN 4: Minor**Est. End:** 30/03/2020**Completion:** 30/03/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW OPP 20, DEVONSHIRE ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	30/03/2020		30/03/2020	27/03/2020

Organisation: BT -MTS - ONSA (0030411)**Works Ref:** WBKNVF4T001**Version:** 6**Work Desc:** TRENTSIDE 760878 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.**Notice Type:** Registration of Reinstatement - Full**Start:** 04/06/2020 00:00:00**Work Status:** Works Stopped**Issued:** 05/06/2020 08:33:07**Work Type:** EToN 4: Minor**Est. End:** 04/06/2020**Completion:** 04/06/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	APPRX 22M NE FROM OS 20 ON DEVONSHIRE ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	04/06/2020		04/06/2020	04/06/2020

Organisation: BT -Telent - NEMSA (0030210)**Works Ref:** MW00000500295618100**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 15/07/2020 08:26:00**Work Status:** Works Stopped**Issued:** 30/07/2020 16:13:01**Work Type:** EToN 4: Minor**Est. End:** 17/07/2020**Completion:** 17/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW OPP 20, DEVONSHIRE ROAD, Actual Depth: 0.4	Footway	Up to 1.5 Metres of Cover	1.00	0.40 An Interim Reinstatement	17/07/2020 01:00:00	17/07/2020 01:00:00		17/07/2020
2	FW OPP 20, DEVONSHIRE ROAD, Actual Depth: 0.4	Footway	Up to 1.5 Metres of Cover	1.00	0.40 An Interim Reinstatement	17/07/2020 01:00:00	17/07/2020 01:00:00		

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Devonshire Road (33000866)

Street Works Notices**Organisation:** BT: Amey - BDUK/SEP/Non NEMSA/Non ONSA (0030128)**Works Ref:** WAPR242P**Version:** 4**Work Desc:** BT POLE REPLACEMENT IN FOOTWAY**Notice Type:** Works Stop**Start:** 11/09/2020 11:51:00**Work Status:** Works Stopped**Issued:** 11/09/2020 13:58:38**Work Type:** EToN 4: Minor**Est. End:** 11/09/2020**Completion:** 11/09/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE 20 (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	11/09/2020 11:59:00			11/09/2020

Organisation: NRSWA - BT (0030005)**Works Ref:** AM1W000000WAPR242P**Version:** 2**Work Desc:** POLE REPLACEMENT IN FW**Notice Type:** Cancellation**Start:** 18/05/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 14/05/2020 14:30:50**Work Type:** EToN 4: Minor**Est. End:** 20/05/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 20 DEVONSHIRE ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	18/05/2020			20/05/2020

Works Ref: AM1W00000WAPR242P/1**Version:** 7**Work Desc:** Pole replacement in F/Way**Notice Type:** Cancellation**Start:** 18/05/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 19/05/2020 12:53:07**Work Type:** EToN 4: Minor**Est. End:** 18/05/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 20 DEVONSHIRE ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	18/05/2020			18/05/2020

Works Ref: AM1W00000WAPR242P/2**Version:** 3**Work Desc:** POLE REPLACEMENT IN FW**Notice Type:** Cancellation**Start:** 04/06/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 08/06/2020 09:31:47**Work Type:** EToN 4: Minor**Est. End:** 08/06/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 20 DEVONSHIRE ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	04/06/2020			08/06/2020

Organisation: WPD 5154 Keyworth (7011554)**Works Ref:** M51540485752**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 21/10/2019 16:45:00**Work Status:** Works Stopped**Issued:** 08/11/2019 11:52:50**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 25/10/2019**Completion:** 25/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Number 20	Verge	Up to 1.5 Metres of Cover	1.50	0.80	A Permanent Reinstatement	25/10/2019		25/10/2019	25/10/2019
2	Outside Number 20	Footway	Up to 1.5 Metres of Cover	1.10	1.10	A Permanent Reinstatement	25/10/2019		25/10/2019	