

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Street: Pinxton Lane (1216088)

Locality: Fulwood, Sutton in Ashfield, Nottinghamshire

Area: Ashfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feature No.:	2,000.00	Feature Id - Locn.:	C151 - A38 To Adc Boundary	Feature Type:	Street Section		Area: Ashfield	
Batch:	20412144 - Inspection Batch			Route:	Review Outcome-David Freer			Date: 02/10/2020
	No actionable defects found							
Batch:	20410450 - Inspection Batch			Route:	Ashfield Sut Sep Saf CW			Date: 16/09/2020
	No actionable defects found							
Batch:	20403182 - Inspection Batch			Route:	Ashfield Sut Aug Saf CW			Date: 04/08/2020
	No actionable defects found							
Batch:	20400486 - Inspection Batch			Route:	Ashfield Sut Jul Saf CW			Date: 14/07/2020
	No actionable defects found							
Batch:	20395042 - Inspection Batch			Route:	Ashfield Sut Jun Saf CW			Date: 04/06/2020
	No actionable defects found							
Batch:	20390678 - Inspection Batch			Route:	Ashfield Sut May Saf CW			Date: 11/05/2020
	No actionable defects found							
Batch:	20386219 - Inspection Batch			Route:	Ashfield Sut Apr Saf CW			Date: 03/04/2020
	No actionable defects found							
Batch:	20383543 - Inspection Batch			Route:	Ashfield Sut Mar Saf CW			Date: 18/03/2020
	No actionable defects found							
Batch:	20380008 - Inspection Batch			Route:	Ashfield Sutton Feb Enh CW/FW			Date: 28/02/2020
	No actionable defects found							
3634952	10 potholes	28/02/2020	Entrance to roundabout and down lane to electricity substation	CW Repairs-Bituminous	Internal		Uncommitted	2738703
Batch:	20379793 - Inspection Batch			Route:	Adhoc Inspection			Date: 27/02/2020
3634806	Carriageway Pothole	27/02/2020	Coming from A38 the pot hole is just before the farm on the left hand side.	CW Repairs-Bituminous	Internal		Uncommitted	2738557
Batch:	20375436 - Inspection Batch			Route:	Ashfield Sut Jan Saf CW			Date: 30/01/2020
3632154	2 potholes	30/01/2020	Near Farm entrance and side of big warehouse	CW Repairs-Bituminous	Internal		Uncommitted	2735895
Batch:	20370020 - Inspection Batch			Route:	Ashfield Sut Dec Saf CW			Date: 23/12/2019
	No actionable defects found							
Batch:	20366449 - Inspection Batch			Route:	Ashfield Sut Nov Saf CW			Date: 03/12/2019
	No actionable defects found							
Batch:	20363714 - Inspection Batch			Route:	Adhoc Inspection			Date: 19/11/2019
3624971	4 patches	19/11/2019	Various locations see map	CW Repairs-Bituminous	Internal		Committed	2728695
Batch:	20363713 - Inspection Batch			Route:	Adhoc Inspection			Date: 19/11/2019
3624970	3 patches	19/11/2019	Various locations see map	CW Repairs-Bituminous	Internal		Committed	2728694
Batch:	20363673 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/11/2019
3624942	10 potholes	18/11/2019	From roundabout to Farm bothsides of road and 170metres past farm	CW Repairs-Bituminous	Internal		Uncommitted	2728666

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C151 - A38 To Adc Boundary			Feature Type: Street Section			Area: Ashfield	
Batch: 20361982 - Inspection Batch				Route: Adhoc Inspection				Date: 05/11/2019
3623919	7 pothole on edge of carriageway	05/11/2019	Just before entrance to Farm and about 100metre past Farm	CW Repairs-Bituminous	Internal		Uncommitted	2727639
Batch: 20359161 - Inspection Batch				Route: Ashfield Sut Oct Saf CW				Date: 15/10/2019
	No actionable defects found							
Batch: 20358187 - Inspection Batch				Route: Adhoc Inspection				Date: 08/10/2019
3621810	9 potholes	08/10/2019	From roundabout down to Farm both sides of road and side of the newly built warehouse	CW Repairs-Bituminous	Internal		Uncommitted	2725518
Batch: 20355933 - Inspection Batch				Route: Ashfield Sut Sep Saf CW				Date: 23/09/2019
3620752	4 potholes	23/09/2019	60 metres past farm	CW Repairs-Bituminous	Internal		Uncommitted	2724456
Batch: 20352571 - Inspection Batch				Route: Ashfield Sut Aug Saf CW				Date: 30/08/2019
	No actionable defects found							
Batch: 20348343 - Inspection Batch				Route: Ashfield Sut Jul Saf CW				Date: 30/07/2019
	No actionable defects found							
Batch: 20342947 - Inspection Batch				Route: Ashfield Sut Jun Saf CW				Date: 21/06/2019
	No actionable defects found							
Batch: 20341837 - Inspection Batch				Route: Adhoc Inspection				Date: 18/06/2019
3613423	11 potholes	18/06/2019	From roundabout to sub station both sides of road	CW Repairs-Bituminous	Internal		Committed	2717094
Batch: 20338809 - Inspection Batch				Route: Ashfield Sut May Saf CW				Date: 30/05/2019
3611512	pothole	30/05/2019	60 metres from roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2715174
Batch: 20333025 - Inspection Batch				Route: Ashfield Sut Apr Saf CW				Date: 24/04/2019
3607922	2 potholes	24/04/2019	Near Farm and Electric Substation	CW Repairs-Bituminous	Internal		Uncommitted	2711571
Batch: 20328563 - Inspection Batch				Route: Ashfield Sut Mar Saf CW				Date: 22/03/2019
3605069	3 potholes	22/03/2019	30metre from entrance farm	CW Repairs-Bituminous	Internal		Uncommitted	2708691
Batch: 20326891 - Inspection Batch				Route: Adhoc Inspection				Date: 12/03/2019
3603867	3 potholes	12/03/2019	Opposite Farm	CW Repairs-Bituminous	Internal		Uncommitted	2707479
Batch: 20325027 - Inspection Batch				Route: Ashfield Sutton Feb Enh CW/FW				Date: 27/02/2019
3602556	3 potholes	27/02/2019	Near Farm	CW Repairs-Bituminous	Internal		Uncommitted	2706148
3602554	5no patches	27/02/2019	From roundabout to Elecitic sub station	CW Repairs-Bituminous	Internal		Uncommitted	2706146
Batch: 20320827 - Inspection Batch				Route: Ashfield Sut Jan Saf CW				Date: 29/01/2019
3599734	5 potholes	29/01/2019	Near Farm and Electricity Sub Station	CW Repairs-Bituminous	Internal		Uncommitted	2703269
Batch: 20316347 - Inspection Batch				Route: Ashfield Sut Dec Saf CW				Date: 20/12/2018
3596860	8 potholes	20/12/2018	Near farm	CW Repairs-Bituminous	Internal		Uncommitted	2700316
Batch: 20312947 - Inspection Batch				Route: Ashfield Sut Nov Saf CW				Date: 27/11/2018
3594795	11 potholes	27/11/2018	Between roundabout and Farm	CW Repairs-Bituminous	Internal		Uncommitted	2698195

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C151 - A38 To Adc Boundary			Feature Type: Street Section			Area: Ashfield	
Batch: 20308756 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Oct Saf CW				Date: 26/10/2018
Batch: 20304494 - Inspection Batch				Route: Ashfield Sut Sep Saf CW				Date: 27/09/2018
3589797	3 potholes	27/09/2018	Nr Farm	CW Repairs-Bituminous	Internal		Uncommitted	2693129
Batch: 20299308 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Aug Saf CW				Date: 22/08/2018
Batch: 20299256 - Inspection Batch				Route: Ashfield Sut Aug Saf CW				Date: 22/08/2018
3587364	4 potholes	22/08/2018	Opposite Crow Tree Farm	CW Repairs-Bituminous	Internal		Uncommitted	2690655
Batch: 20295634 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Jul Saf CW				Date: 31/07/2018
Batch: 20292570 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Jun Saf CW				Date: 06/07/2018
Batch: 20288066 - Inspection Batch	No actionable defects found			Route: Ashfield Sut May Saf CW				Date: 08/06/2018
Batch: 20283437 - Inspection Batch				Route: Ashfield Sut Apr Saf CW				Date: 15/05/2018
3578545	3 patches	15/05/2018	Roundabout	CW Repairs-Bituminous	Internal		Committed	2681678
Batch: 20275526 - Inspection Batch				Route: Ashfield Sut Mar Saf CW				Date: 03/04/2018
3573189	8 potholes	03/04/2018	From roundabout to 150metres past Farm, both sides of road	CW Repairs-Bituminous	Internal		Committed	2676216
Batch: 20272484 - Inspection Batch				Route: Ashfield Sutton Feb Enh CW/FW				Date: 14/03/2018
3571032	Tack coat overlay scabby areas of c/way	14/03/2018	about 50metres before electricity sub station	CW Repairs-Bituminous	Internal		Committed	2674023
Batch: 20272481 - Inspection Batch				Route: Adhoc Inspection				Date: 14/03/2018
3571029	7 potholes	14/03/2018	From roundabout down to farm entrance both sides of road	CW Repairs-Bituminous	Internal		Committed	2674020
Batch: 20268941 - Inspection Batch				Route: Adhoc Inspection				Date: 19/02/2018
3568532	10 potholes, both sides of carriageway	19/02/2018	From roundabout to Farm	CW Repairs-Bituminous	Internal		Committed	2671489
Batch: 20265323 - Inspection Batch				Route: Ashfield Sut Jan Saf CW				Date: 29/01/2018
3565942	5 potholes	29/01/2018	Near roundabout near middle Farm	CW Repairs-Bituminous	Internal		Uncommitted	2668883
Batch: 20265036 - Inspection Batch				Route: Adhoc Inspection				Date: 26/01/2018
3565715	2 potholes filled at time of inspection	26/01/2018	Near farm	CW Repairs-Bituminous	Internal		Uncommitted	2668654
Batch: 20262098 - Inspection Batch				Route: Adhoc Inspection				Date: 09/01/2018
3563473	Carriageway Damage - potholes (Enquiry 3205664) 4 potholes	09/01/2018	Near field with Solar Panels	CW Repairs-Bituminous	Internal		Uncommitted	2666369
Batch: 20260581 - Inspection Batch				Route: Ashfield Sut Dec Saf CW				Date: 29/12/2017
3562556	pothole	29/12/2017	Carriageway edge near electric sub station	CW Repairs-Bituminous	Internal		Uncommitted	2665440

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C151 - A38 To Adc Boundary			Feature Type: Street Section			Area: Ashfield	
Batch: 20257156 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Nov Saf CW				Date: 30/11/2017
Batch: 20251914 - Inspection Batch				Route: Ashfield Sut Oct Saf CW				Date: 26/10/2017
3558247	5 potholes	26/10/2017	Roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2660936

Customer Services

Enquiry No.: 6178587	Logged by: External to Confirm	on: 23/09/2020 16:12					Enquiry Ref: FS-CASE-253051267
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation					
Desc.: Road Damage - Inside lane of the roundabout surface and the structure of the roundabout is damaged. Due to the large amount of HGV traffic Negotiating the tight roundabout . Online report Customer title is Mr.							
Location: The whole roundabout and most of the road are badly damaged and is causing vehicles to cross lanes to avoid the area of damage, which I causing near miss incidents	Contact:						
Enquiry No.: 6174857	Logged by: External to Confirm	on: 17/08/2020 07:32					Enquiry Ref: FS-CASE-238950159
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation					
Desc.: Road Damage - potholes . Online report Customer title is Mr.							
Location: roundabout	Contact:						
Enquiry No.: 6172020	Logged by: External to Confirm	on: 13/07/2020 16:24					Enquiry Ref: FS-CASE-227613869
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - On the roundabout there is loads of potholes all the round the roundabout and turn right . Online report Customer title is Mr.							
Location: Pinxton lane	Contact:						
Enquiry No.: 6172016	Logged by: External to Confirm	on: 13/07/2020 16:12					Enquiry Ref: FS-CASE-227607887
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - Email from Customer on Fix my street -----							
Turning right to Castlewood there is loads of potholes and damage roads surface. Which can damage my and other cars . Submitted by [redact] Customer title is Mr.							
Location: Pinxton Roundabout off the A38	Contact:						
Enquiry No.: 6167878	Logged by: External to Confirm	on: 30/05/2020 14:42					Enquiry Ref: FS-CASE-212176125
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation					
Desc.: Road Damage - Terrible road surface full of deep potholes and crumbling surface. . Online report Customer title is							
Location: Roundabout off the A38 by the new Shell garage.	Contact:						
Enquiry No.: 6164929	Logged by: External to Confirm	on: 18/03/2020 06:00					Enquiry Ref: FS-CASE-184756974
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation					
Desc.: Road Damage - The roundabout has loads of potholes and its very bumper going right on the roundabout. . Online report Customer title is Mr.							
Location: The roundabout has loads of potholes and its very bumper going right on the roundabout.	Contact:						

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6164383 **Logged by:** External to Confirm **on:** 12/03/2020 16:27
Service: Other **Subject:** Other Request (Highways) **Classification:** Service Request **Enquiry Ref:** FS-CASE-183064155
Desc.: Other requests - Customer is wanting to meet with a member of the team for an on site discussion in relation to ongoing problems with local roads.

. Submitted by Advisor: redact - Customer title is Mr.

Location: A38 Castlewood industrial estate Western Boundary.**Contact:**

Enquiry No.: 6162004 **Logged by:** External to Confirm **on:** 02/03/2020 07:49
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-179108278
Desc.: Road Damage - Turning right on the outer side of the road . Online report Customer title is Mr.

Location: roundabout**Contact:**

Enquiry No.: 6161914 **Logged by:** External to Confirm **on:** 28/02/2020 15:33
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178883777
Desc.: Road Pothole - Line of potholes approx 6 . Online report Customer title is

Location: Going towards sutton near top**Contact:****Plot Number:** 2,000.00**Feature Id - Location:** C151 - A38 To Adc Boundary**Feature Type:** Street Section**Job Number:** 2738703

Enquiry No.: 6161821 **Logged by:** External to Confirm **on:** 28/02/2020 11:15
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS178780549
Desc.: Insurance claim - related to Confirm defect reference: 6161350

Date/Time: 26/02/2020 15:00:00

Direction of travel: Heading southbound towards Pinxton.

Account of what happened: redact was driving down Pinxton Lane in Sutton in Ashfield. She hit a pothole which caused a loud bang and the tire to burst and the alloy to buckle.

Location: Coming from A38 the pot hole is just before the farm on the left hand side. It's very deep and not always visible , and is unavoidable if traffic is coming the other way. Will cause wheel damage. The road surface condition on this stretch of road and on the round about prior to this turn off are really poor and with the adverse weather conditions we have had recently it has made them a a lot worse.

Contact:

Enquiry No.: 6161594 **Logged by:** External to Confirm **on:** 27/02/2020 09:30
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178400744
Desc.: Road Pothole - VERY deep and VERY dangerous. Hard to dodge if there's oncoming traffic and seems to get worse and worse every day. . Online report Customer title is Miss.

Location: 3 or 4 telegraph poles from the roundabout. Left hand side of the road if driving from the A38 into Pinxton.

Contact:**Plot Number:** 2,000.00**Feature Id - Location:** C151 - A38 To Adc Boundary**Feature Type:** Street Section**Job Number:** 2738557

Enquiry No.: 6161350 **Logged by:** External to Confirm **on:** 26/02/2020 09:21
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178064823
Desc.: Road Pothole - Large pot hole . Online report Customer title is Ms.

Location: Coming from A38 the pot hole is just before the farm on the left hand side. It's very deep and not always visible , and is unavoidable if traffic is coming the other way. Will cause wheel damage. The road surface condition on this stretch of road and on the round about prior to this turn off are really poor and with the adverse weather conditions we have had recently it has made them a a lot worse.

Contact:**Plot Number:** 2,000.00**Feature Id - Location:** C151 - A38 To Adc Boundary**Feature Type:** Street Section**Job Number:** 2738557**Defect Number:** 3634806

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6161066	Logged by: External to Confirm	on: 25/02/2020 15:58	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-177717061
Desc.: Road Pothole - Pothole is at the edge of the carriageway and it is approx 500x500mm in size and 75mm deep. . Online report Customer title is Mr.			
Location: At the edge of the carriageway approx 100 metres from the roundabout on the right hand side of the road when travelling from the A38 towards Pinxton.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2738557			
Enquiry No.: 6158971	Logged by: External to Confirm	on: 14/02/2020 22:33	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-175054678
Desc.: Road Pothole - Pothole . Online report Customer title is Mr.			
Location: Approaching from A38 in between the two lanes of the roundabout when joining the round about		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2738703			
Enquiry No.: 6157818	Logged by: External to Confirm	on: 10/02/2020 09:54	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS173645517
Desc.: Insurance claim - related to Confirm defect reference: 6157091 Date/Time: 29/01/2020 17:55:00 Direction of travel: From the A38 onto the Roundabout. Account of what happened: Damaged wheels on pothole. They are the nearside wheels.			
Location: Road surrounding the roundabout and adjoining roads		Contact:	
Enquiry No.: 6157091	Logged by: External to Confirm	on: 04/02/2020 22:33	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-172482750
Desc.: Road Damage - The road is in a very poor state, especially around the roundabout due not the increased volume of traffic . Online report Customer title is			
Location: Road surrounding the roundabout and adjoining roads		Contact:	
Enquiry No.: 6156116	Logged by: External to Confirm	on: 29/01/2020 07:57	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS170933713
Desc.: Road Pothole - Ive damaged my wheels on this road. They are my nearside wheels. I went to the car wash and did it then. How do i claim? . Online report Customer title is Mr. - Previous Confirm Case: 6154608			
Location: Pinxton lane roundabout		Contact:	
Enquiry No.: 6154608	Logged by: External to Confirm	on: 20/01/2020 08:18	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-168741790
Desc.: Road Damage - The road is severly rough to drive over needs resurfacing . Online report Customer title is			
Location: Roundabout inside lane		Contact:	
Enquiry No.: 6149752	Logged by: External to Confirm	on: 12/12/2019 08:48	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-161907811
Desc.: Road Pothole - pot hole . Online report Customer title is			
Location: Junction of pinxton Lane		Contact:	
Enquiry No.: 6149736	Logged by: External to Confirm	on: 11/12/2019 20:30	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-161864210
Desc.: Road Damage - Very poor repair of damaged road surface. Still just as poor as it was previously, with extra loose chippings. Causes people to drive in the incorrect position for going around the roundabout. . Online report Customer title is			
Location: Roundabout near Shell garage off the A38 headin- to Pinxton.		Contact:	

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6149355	Logged by: External to Confirm	on: 09/12/2019 11:21	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS159904586
Desc.: Insurance claim - related to Confirm defect reference: 6148310 Date/Time: 15/11/2019 22:10:00 Direction of travel: Coming from Castlewood Buisness Park, down Pinxton Lane towards Pinxton. Account of what happened: redact (the Co-op warehouse on castlewood business park) at just after 10pm, a car was coming in the other direction and with it being dark and a national speed limit road, he didn't see it until it was too late.			
Location: Pinxton Lane, behind Castlewood Business Park (Sutton).		Contact:	
Enquiry No.: 6148310	Logged by: External to Confirm	on: 29/11/2019 16:50	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-159904586
Desc.: Insurance claim form requested - Road Pothole - Large pot hole. On edge of the road. (It has now been fixed) - there is still a cone where the pot hole was. . Submitted by Advisor: reda redact Customer title is Mrs.			
Location: Pinxton Lane, behind Castlewood Business Park (Sutton).		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2728666			
Enquiry No.: 6146657	Logged by: External to Confirm	on: 18/11/2019 12:42	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-157467646
Desc.: Road Pothole - Deep pot hole sufficient to cause heavy wheel damage identified this morning 18th Nov. . Online report Customer title is Mr.			
Location: Pinxton Lane - travelling toward Pinxton		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2728666			
Defect Number: 3624942			
Enquiry No.: 6145821	Logged by: External to Confirm	on: 13/11/2019 12:24	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS156746624
Desc.: Insurance claim - related to Confirm defect reference: 6145820 Date/Time: 04/11/2019 19:30:00 Direction of travel: Southbound from A38 - going down Pinxton Lane Account of what happened: The incident occurred on November 4th on my way home from work at 19:30 on Pinxton Lane leading from the A38. The incident occurred when I hit the pothole on the left hand side of the road and due to it being unlit it was impossible to see which is rather dangerous.			
Location: Pinxton Lane leading to Brook Hill Lane		Contact:	
Enquiry No.: 6145820	Logged by: External to Confirm	on: 13/11/2019 12:23	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-156746624
Desc.: Insurance claim form requested - Road Pothole - On Monday the 4th of November at the top of Pinxton Lane leading to Brookhill Lane, I hit an extremely large pothole at that near side of the road. This is a 60mph road and is also unlit, therefore the pothole was not visible until it was too late. As a direct result of this I burst my tyre. The next morning I had to get a new tyre and have the tracking aligned redact lact redact . I attach a photograph of the pothole and the damage to the tyre redact . As this is a direct result of the road condition under your care, I would like recompense for my expenses. . Submitted by Advisor: redact Customer title is			
Location: Pinxton Lane leading to Brook Hill Lane		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2727639			
Enquiry No.: 6144705	Logged by: External to Confirm	on: 07/11/2019 10:00	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS155559296
Desc.: Road Damage - The road is becoming hazardous to drive on due to the poor condition of the right hand lane towards the estate. People are using the left hand lane to turn right. . Online report Customer title is Mr. - Previous Confirm Case: 6141788			
Location: Roundabout at NG17 1BX		Contact:	

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6144304 **Logged by:** External to Confirm **on:** 04/11/2019 20:06
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-154939080
Desc.: Road Pothole - Extremely deep pothole which I hit with my car. This is a 60 mph road and could easily cause a serious accident . Online report Customer title is Mrs.
Location: Coming from roundabout down the road on the left hand side of the road **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C151 - A38 To Adc Boundary **Feature Type:** Street Section
Job Number: 2727639 **Defect Number:** 3623919

Enquiry No.: 6144072 **Logged by:** External to Confirm **on:** 02/11/2019 16:51
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-154472552
Desc.: Road Pothole - Pot hole/ damage to the edge of the road . Online report Customer title is
Location: Approx 100m from the mini roundabout, on the left outside farm entrance. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C151 - A38 To Adc Boundary **Feature Type:** Street Section
Job Number: 2727639

Enquiry No.: 6141788 **Logged by:** External to Confirm **on:** 10/10/2019 17:03
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-149467986
Desc.: Road Damage - Poor road surface around the roundabout . Online report Customer title is Mr.
Location: The roundabout that accesses A38, Costa Coffee, Parker Knoll & other businesses on the Castlewood Industrial Park. **Contact:**

Enquiry No.: 6136906 **Logged by:** External to Confirm **on:** 20/08/2019 13:06
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-138513881
Desc.: Road Damage - Email enquiry:
The whole surface around the roundabout is potholed and broken. As you turn around at any speed it causes you to bump and skid around over the craters. . Submitted by Advisor: **redact**
Customer title is Mr.
Location: Roundabout coming off of Pinxton Lane/Farmwell Lane near Castlewood Business Park. **Contact:**

Enquiry No.: 6133694 **Logged by:** External to Confirm **on:** 17/07/2019 13:36
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-131545728
Desc.: Road Pothole - Various pot holes and kerb damage due to the large amount of vehicles /lorries using the roundabout . Online report Customer title is Mrs.
Location: When coming from Mansfield off the A38 to go to the Castlewood Business Park and Shell garage turn right at the roundabout **Contact:**

Enquiry No.: 6130828 **Logged by:** External to Confirm **on:** 17/06/2019 18:21
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-125220790
Desc.: Road Pothole - Large pothole 200 ti 300 yards from roundabout toward pinxton left side of the car . Online report Customer title is Mrs.
Location: Left hand lane heading into pinxton large pothole ni way of missing due to oncoming traffic **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C151 - A38 To Adc Boundary **Feature Type:** Street Section
Job Number: 2717094 **Defect Number:** 3613423

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services**Enquiry No.:** 6130500**Logged by:** External to Confirm**on:** 14/06/2019 11:30**Service:** Carriageway/Footway**Subject:** Carriageway Pothole**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-124667878**Desc.:** Road Pothole - pot holes - deep ones form the junction of a38, all the road is breaking away from the island and making the road extremely uneven for driving

the pot holes have damaged my car massively and now i have an unexpected garage bill to pay, not what you expect when driving around a corner under 25mph but it is that deep . Online report
Customer title is Mrs.

Location: potholes on the junction from a38 onto pinxton lane**Contact:**

road damage / pot holes all around the island on pixton lane going on to the
industrial estate

Enquiry No.: 6129185**Logged by:** External to Confirm**on:** 03/06/2019 19:36**Service:** Carriageway/Footway**Subject:** Traffic Signal Damage**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-122508887**Desc.:** Traffic light damage - Filter lights for turning from A38 north bound into Pinxton lane have been spun and are now facing Pinxton lane giving vehicles emerging from pinxton lane conflicting signals .
Online report Customer title is**Location:** Traffic lights at the junction of the A38 and Pinxton lane NG17 1JF**Contact:**

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6125635

Logged by: External to Confirm

on: 15/04/2019 15:06

Service: Carriageway/Footway

Subject: Carriageway Pothole

Classification: Report or Observation

Enquiry Ref: FS113692886

Desc.: Road Pothole - We have received the following email from a customer following an auto response from Highways:

Re: Pothole, road or pavement damage - FS112571294 update

Can you please confirm you have assessed the correct road? (The road leading into Castlewood business park with a mini roundabout).

This road is far from safe due to the many people diverting around the damage in the road and heading into the other lane. It is also damaging cars. I am an employee in the petrol station on site and have numerous reports daily from customers complaining about this road.

Please reassess this road.

Kind Regards

----- Original Message -----

Subject: Pothole, road or pavement damage - FS112571294 update

From: Nottinghamshire County Council

To: redact

CC:

Following your report of a pothole :

The location you have raised concerns with has now been inspected and no hazardous defects have been identified. As such, no action is warranted at this time to keep the road in a safe condition.

Please be assured we have a very dedicated team of Highway Inspectors who carry out regular inspections in this area. Should conditions deteriorate, we will then arrange for the necessary works to be undertaken.

You can find out more about our approach to highway repairs at <http://www.nottinghamshire.gov.uk/transport/roads/potholes>

Nottinghamshire County Council are also investing an additional £20m in highways across the next four years, including improvements to road surfaces on residential roads. To find out more about improvements in your area visit www.nottinghamshire.gov.uk

If you spot any other problems on Nottinghamshire roads, please let us know online or give us a call.

Thanks for helping to keep Nottinghamshire roads safe.

Kind regards,

Nottinghamshire County Council

T: 0300 500 80 80 Submitted by Advisor: redact Customer title is Miss. - Previous Confirm Case: 6124816

Location: All the way around the roundabout

Contact:

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6124816	Logged by: External to Confirm	on: 04/04/2019 14:57	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-112571294
Desc.: Road Pothole - Around 4 very large potholes around the roundabout . Online report Customer title is Miss.			
Location: All the way round the roundabout		Contact:	
Enquiry No.: 6122341	Logged by: External to Confirm	on: 11/03/2019 21:36	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-109066304
Desc.: Road Damage - Heavy road damage to the extent that I almost had a head on collision with the van travelling toward me who came onto my side of the road to avoid the pot hole! . Online report Customer title is Mr.			
Location: Pinxton Lane on the side of the road travelling toward the A38 from Pinxton. Precise location can't be provided but was within the extent of the adjacent field containing solar panels.		Contact:	
Enquiry No.: 6122311	Logged by: External to Confirm	on: 11/03/2019 16:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-109033652
Desc.: Road Pothole - Very large, deep pothole. . Online report Customer title is			
Location: There are a series of deep potholes on both sides of the road. Notably, there is a huge one just after the large tree on the left side of the road, if you're standing looking up the road towards the roundabout. It has always been rather large, but just recently has gotten severely deep and very dangerous.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2707479	Defect Number: 3603867		
Enquiry No.: 6121474	Logged by: External to Confirm	on: 01/03/2019 21:42	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-107792829
Desc.: Road Damage - Heavy use of articulated lorries have dug up the tarmac. Very hazardous to us motorcyclist. As your leaning right and going around you have little option but to hit it. First time was a surprise and causes bike to become unstable.			
I that it has been actioned for repair in future and thats all fine and well for vehicles with 4 wheels.			
What about us two wheels that rely upon smooth level ground?? . Online report Customer title is Mr.			
Location: On the roundabout inner lane		Contact:	
Enquiry No.: 6116156	Logged by: External to Confirm	on: 06/01/2019 23:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-101576565
Desc.: Road Pothole - there is a total breakdown of the road surface the 'pot hole' is very wide as access to the coop depot and the new garage/ drive thru costa. Caused buy traffic levels and at that the industrial estate is not full . Online report Customer title is Mrs.			
Location: As you go round the roundabout on the inside lane to go onto the industrial estate level with the turn to pinxton. It's huge you can't miss it		Contact:	
Enquiry No.: 6114895	Logged by: External to Confirm	on: 18/12/2018 07:45	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-99977807
Desc.: Road Pothole - deep pothole in the driving lane . Online report Customer title is Mrs.			
Location: just after the roundabout heading towards Pinxton on the left hand side before the farm		Contact:	
Enquiry No.: 6113656	Logged by: External to Confirm	on: 04/12/2018 07:00	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-98341829
Desc.: Road Damage - large parts of the road surface has broken away due to large volumes of HGV's using the roundabout. . Online report Customer title is Mr.			
Location: roundabout on pinxton lane that leads to farmwell lane in Pinxton.		Contact:	

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6113505	Logged by: External to Confirm	on: 03/12/2018 05:30	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-98168239
Desc.: Road Damage - Un even road, on a bend of the round about, that bag it nearly brought me off my motorcycle. If the conditions was on a straight road it would be as bad, but being on a round about it caused my wheels to come from underneath me. . Online report Customer title is Mr.			
Location: Round about on Pinxton lane NG17 1JF	Contact:		
Enquiry No.: 6113475	Logged by: External to Confirm	on: 01/12/2018 10:51	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-97995312
Desc.: Road Damage - pothole on entry to the island is big enough to deflect front wheels of my medium sized car. road surface deterioration is perhaps six feet wide+ on the inside portion of the island and has a raised middle section that also deflects the front tyres. . Online report Customer title is Mr.			
Location: coming from direction of A38 onto the island, right hand lane turning onto Farmwell Lane there is a pot hole that is in the line of my travel. two thirds round the island the surface has deteriorated also.	Contact:		
Enquiry No.: 6113471	Logged by: External to Confirm	on: 30/11/2018 23:11	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-97954784
Desc.: Road Pothole - Damage to road surface on the roundabout beside the new Shell petrol station . Online report Customer title is Mr.			
Location: Farnwell Lane off the A38	Contact:		
Enquiry No.: 6112693	Logged by: External to Confirm	on: 22/11/2018 11:12	
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-96756961
Desc.: Traffic sign request - On A38 there is a new garage. People going towards the motorway are using the traffic lights at top of common road to do a U turn.			
Customer thinks that they need to have a no U turn sign at the traffic lights near the shell garage. A sign to advise that there is a 7.5 tonne weight limit as lorries are using the farm turning to turn			
Green road sign board, outside the Snipe indicating Pinxton and Castlewood Estate, also needs to have the service station noted on this sign			
30mph sign from Pinxton lane towards the mini roundabout, customer would like to see this moved 300 meters southwest on pinxton lane towards crows Farm. . Submitted by Advisor: redact Customer title is Mr.			
Location: on Pinxton Lane off the A38	Contact:		
Enquiry No.: 6112565	Logged by: External to Confirm	on: 21/11/2018 10:27	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-96587218
Desc.: Road Pothole - Heavy road damage around a large area of the roundabout. This is becoming a danger to vehicles and the public! . Online report Customer title is Mr.			
Location: On the roadabout coming into the Castlewood Business Park	Contact:		
Enquiry No.: 6112321	Logged by: External to Confirm	on: 19/11/2018 08:36	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-96256851
Desc.: Road Damage - There is damage to both the road and the roundabout . Online report Customer title is Mr.			
Location: The roundabout just off the A38 before Pinxton Lane and Castlewood industrial estate	Contact:		
Enquiry No.: 6112320	Logged by: External to Confirm	on: 19/11/2018 08:33	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-96256869
Desc.: Road Pothole - Pot holes and road surface breaking up. . Online report Customer title is Mr.			
Location: On the roundabout	Contact:		

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6112319	Logged by: External to Confirm	on: 19/11/2018 08:33	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-96256682
Desc.: Road Pothole - various size potholes causing vehicle damage . Online report Customer title is Mr.			
Location: On the Roundabout	Contact:		
Enquiry No.: 6112318	Logged by: External to Confirm	on: 19/11/2018 08:12	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-96254409
Desc.: Road Pothole - Poor road surface on the road and roundabout . Online report Customer title is Mr.			
Location: On the roundabout	Contact:		
Enquiry No.: 6112316	Logged by: External to Confirm	on: 19/11/2018 06:49	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-96247959
Desc.: Road Damage - Severe damage to the road surface on the roundabout. . Online report Customer title is Mr.			
Location: Roundabout at the junction of Pinxton Lane and Farmwell Lane (Castlewood Business Park)	Contact:		
Enquiry No.: 6112303	Logged by: External to Confirm	on: 18/11/2018 07:00	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-96158276
Desc.: Road Damage - the roundabout has uneven surfaces and pot holes . Online report Customer title is Mr.			
Location: at the roundabout the road is severely damaged, causing potential damage to in excess of 1000 vehicles that access the business park	Contact:		
Enquiry No.: 6112253	Logged by: External to Confirm	on: 16/11/2018 16:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-95949643
Desc.: Road Pothole - Potholes on the roundabout at various points . Online report Customer title is Mr.			
Location: Roadabout at the entrance to the Castlewood business park	Contact:		
Enquiry No.: 6112251	Logged by: External to Confirm	on: 16/11/2018 16:15	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-95949643
Desc.: Road Pothole - Potholes on the roundabout at various points . Online report Customer title is Mr.			
Location: Roadabout at the entrance to the Castlewood business park	Contact:		
Enquiry No.: 6112193	Logged by: External to Confirm	on: 16/11/2018 10:29	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-95949643
Desc.: Road Pothole - Potholes on the roundabout at various points . Online report Customer title is Mr.			
Location: Roadabout at the entrance to the Castlewood business park	Contact:		
Enquiry No.: 6112153	Logged by: External to Confirm	on: 15/11/2018 18:06	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95882615
Desc.: Road Damage - The roundabout has severe damage from last winter, and has been left uneven with different layers of tarmac showing through and a few pot holes to avoid. . Online report Customer title is Mr.			
Location: The roundabout on Pinxton lane leading to the Castlewood business park,	Contact:		
Enquiry No.: 6112152	Logged by: External to Confirm	on: 15/11/2018 18:03	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95882615
Desc.: Road Damage - The roundabout has severe damage from last winter, and has been left uneven with different layers of tarmac showing through and a few pot holes to avoid. . Online report Customer title is Mr.			
Location: The roundabout on Pinxton lane leading to the Castlewood business park,	Contact:		

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6112137	Logged by: External to Confirm	on: 15/11/2018 14:30	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95850083
Desc.: Road Damage - Pitted and roughed up road as you go round the roundabout. I ride a bicycle every morning around the roundabout and have to ensure I ride within the undamaged pieces for fear of coming off/damaging my wheels. Often with lorries behind me!! . Online report Customer title is Mr.			
Location: Roundabout at the top of Farmwell Lane/Pinxton Lane	Contact:		
Enquiry No.: 6112135	Logged by: External to Confirm	on: 15/11/2018 14:24	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95849303
Desc.: Road Damage - There's massive pot holes all around the roundabout! . Online report Customer title is Mrs.			
Location: The roundabout at that joins Farmwell lane and A38	Contact:		
Enquiry No.: 6112125	Logged by: External to Confirm	on: 15/11/2018 13:06	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95823985
Desc.: Road Damage - damages to the road.. big holes and uneven surfaces . Online report Customer title is Miss.			
Location: On the round about	Contact:		
Enquiry No.: 6112118	Logged by: External to Confirm	on: 15/11/2018 12:39	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95826182
Desc.: Road Damage - The road is worn, the pavement is damaged. . Online report Customer title is Mr.			
Location: Castlewood Industrial Park access roundabout	Contact:		
Enquiry No.: 6112116	Logged by: External to Confirm	on: 15/11/2018 12:36	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95826182
Desc.: Road Damage - The road is worn, the pavement is damaged. . Online report Customer title is Mr.			
Location: Castlewood Industrial Park access roundabout	Contact:		
Enquiry No.: 6112114	Logged by: External to Confirm	on: 15/11/2018 12:00	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95805293
Desc.: Road Damage - Road in desperate need of repair . Online report Customer title is Mr.			
Location: Road breaking up surrounding the roundabout prior to entering Castlewood Business Park.	Contact:		
Enquiry No.: 6111713	Logged by: External to Confirm	on: 12/11/2018 10:48	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-95335293
Desc.: Road Pothole - There are many potholes, damaged road and damaged side of roundabout. - Lorries pass through here to the Business Park and struggle to turn around the size of the roundabout. . Online report Customer title is Miss.			
Location: On the roundabout coming off the A38 to Farmwell Lane (to the Castlewood Business Park)	Contact:		
Enquiry No.: 6111474	Logged by: External to Confirm	on: 08/11/2018 13:12	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94894900
Desc.: Road Damage - 3 large craters in the road surface which is not only is causing damage to vehicles but also causing drivers to cut each other up trying to drive around them. . Online report Customer title is Mr.			
Location: There are 3 large areas of concern, as you enter the round about from the A38, then about another 2metres, and again just after the exit that leads to Pinxton.	Contact:		
Enquiry No.: 6111465	Logged by: External to Confirm	on: 08/11/2018 11:42	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94880338
Desc.: Road Damage - Badly damaged Road Surface . Online report Customer title is Mr.			
Location: Roundabout	Contact:		

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6111462	Logged by: External to Confirm	on: 08/11/2018 11:36	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94878025
Desc.: Road Damage - Uneven road surface and deep potholes . Online report Customer title is Mrs.			
Location: Roundabout leading to Castlewood Business Park		Contact:	
Enquiry No.: 6111460	Logged by: External to Confirm	on: 08/11/2018 11:30	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94877330
Desc.: Road Damage - Road very uneven . Online report Customer title is Miss.			
Location: Roundabout		Contact:	
Enquiry No.: 6111458	Logged by: External to Confirm	on: 08/11/2018 11:27	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-94876901
Desc.: Road Pothole - THE ROQAD SURFACE ON THIS ROUNDABOUT IS IN A VERY POOR STATE . Online report Customer title is			
Location: ROUNDABOUT OFF THE A38 LEADING TO CASTLEWOOD IND ESTATE		Contact:	
Enquiry No.: 6111455	Logged by: External to Confirm	on: 08/11/2018 11:18	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94874786
Desc.: Road Damage - Each day I try to drive between this road damage in order to avoid any possible damage to my tyres and suspension. This has been here since I started working on this estate in 2016. . Online report Customer title is Mrs.			
Location: 2 x elongated potholes/road damage.		Contact:	
Enquiry No.: 6111454	Logged by: External to Confirm	on: 08/11/2018 11:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-94874579
Desc.: Road Pothole - Pothole which you have to swerve around . Online report Customer title is Miss.			
Location: On the roundabout to Pinxton Lane		Contact:	
Enquiry No.: 6111453	Logged by: External to Confirm	on: 08/11/2018 11:15	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94865401
Desc.: Road Damage - Road surface badly damaged and needs resurfacing . Online report Customer title is Mr.			
Location: On Roundabout		Contact:	
Enquiry No.: 6111452	Logged by: External to Confirm	on: 08/11/2018 11:03	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94871770
Desc.: Road Damage - Road is damaged . Online report Customer title is Mr.			
Location: Roundabout		Contact:	
Enquiry No.: 6111447	Logged by: External to Confirm	on: 08/11/2018 10:42	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-94867329
Desc.: Road Damage - Roundabout at the beginning of the Castlewood estate . Online report Customer title is Mr.			
Location: Roundabout, dangerous as most of pavement around has been damaged road is now is a very poor state of repair. dangerous for drives		Contact:	
Enquiry No.: 6110447	Logged by: External to Confirm	on: 29/10/2018 11:45	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-93550723
Desc.: Road Damage - Missing Top surface x 2 dimnension of each hole 1m x 0.75m . Online report Customer title is Mr.			
Location: Roundabout at the top of Farmwell Lane		Contact:	

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6110301 **Logged by:** External to Confirm **on:** 26/10/2018 11:57
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-93281409
Desc.: Road work issue - Road is severely damaged all around the roundabout. it could potentially damage vehicles and cause accidents. Is likely to get worse with the increased volume of traffic due to the new petrol station and costa opening and with winter coming up and bad weather.
The above map only allows me to put one pin in to indicate where the damage is but it is in fact all around the roundabout including the curb structure of the roundabout is collapsed.
. Online report Customer title is Miss.
Location: On the roundabout **Contact:**

Enquiry No.: 6110276 **Logged by:** External to Confirm **on:** 26/10/2018 10:03
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-93259280
Desc.: Road Damage - Due to the increased amount of traffic and large lorries the roundabout is getting worse, the tarmac and kerb needs fixing. This will cause damage to peoples vehicles and I also notice a lot of cyclists going to and from work.... which could cause great injury and potentially an accident not just to them selves but to whom ever is around them at the time. . Online report Customer title is Mrs.
Location: All the way around the roundabout **Contact:**

Enquiry No.: 6110275 **Logged by:** External to Confirm **on:** 26/10/2018 10:00
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-93258413
Desc.: Road Damage - The road is badly damaged as you go around the island, also the kerb stones have been damaged to the point of collapse. These issues mean as you go round the island your car is pulled into the large rut in the road & there is a risk that the tyres could be damaged, or once the weather gets worse it could cause an accident. . Online report Customer title is Mrs.
Location: The road around the island & the kerb around the actual island. **Contact:**

Enquiry No.: 6110269 **Logged by:** External to Confirm **on:** 26/10/2018 09:43
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-93253641
Desc.: Road Damage - Road is severely damaged all around the roundabout. it could potentially damage vehicles and cause accidents. Is likely to get worse with the increased volume of traffic due to the new petrol station and costa opening and with winter coming up and bad weather.
The above map only allows me to put one pin in to indicate where the damage is but it is in fact all around the roundabout including the curb structure of the roundabout is collapsed. . Online report Customer title is Mrs.
Location: Road around the roundabout **Contact:**

Enquiry No.: 6094027 **Logged by:** External to Confirm **on:** 03/05/2018 12:57
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-74611284
Desc.: Road Damage - Roundabout has potholes all the way round road is ripped up half way round plus all pavement slabs are broken on the inside of roundabout. . Online report Customer title is
Location: Whole way round the roundabout **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C151 - A38 To Adc Boundary **Feature Type:** Street Section
Job Number: 2681678

Enquiry No.: 6090143 **Logged by:** External to Confirm **on:** 06/04/2018 11:12
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS72206339
Desc.: Insurance claim - related to Confirm defect reference: 6085947
Date/Time: 02/04/2018 18:00:00
Direction of travel: south west
Account of what happened: hit pothole, cracked windscreen on car
Location: The pot holes are deep and superficial on both sides of Pinxton Lane right up to the Derbyshire border. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C151 - A38 To Adc Boundary **Feature Type:** Street Section

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6089144	Logged by: External to Confirm	on: 03/04/2018 09:42	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-71845203
Desc.: Road Pothole - LARGE DEEP POTHOLE ON NEARSIDE, WHICH I KNOW BECAUSE I HIT IT THIS MORNING (03/04/2018).... . Online report			
Location: GOING FROM PINXTON TO SUTTON ON PINXTON LANE EXTREMELY LARGE DEEP POTHOLE ON NEARSIDE.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2676216			
Enquiry No.: 6086152	Logged by: External to Confirm	on: 14/03/2018 14:57	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-70323292
Desc.: Road Damage - The road edges here aren't kerbside because its only a lane, the edges are breaking up very badly to the point where people are driving on the wrong side of the road or swerving in front of on coming traffic, this is for the first quarter or half mile after the Island. It's not just potholes, it's dangerous because of the traffic having to avoid the holes. . Submitted by Advisor: redact			
Location: Pinxton Lane coming off the A38 and just after the roandabout		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2674020			
Enquiry No.: 6085947	Logged by: External to Confirm	on: 13/03/2018 18:12	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70238881
Desc.: Road Pothole - The pot holes are deep and superficial on both sides of Pinxton Lane right up to the Derbyshire border, following the adverse weather conditions it has deteriorated greatly in places. The worst damage being around the farm entrance and it is on both sides of the road, and could cause potential damage to vehicles or even an accident as cars are trying to avoid them. . Online report			
Location: The pot holes are deep and superficial on both sides of Pinxton Lane right up to the Derbyshire border.		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2674020			
Defect Number: 3571029			
Enquiry No.: 6078445	Logged by: External to Confirm	on: 26/01/2018 08:39	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-66673429
Desc.: Road Pothole - large deep pothole . Online report			
Location: from Sutton on Pinxton, on left hand side just before middle farm		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section	
Job Number: 2668654			
Defect Number: 3565715			
Enquiry No.: 6074336	Logged by: External to Confirm	on: 27/12/2017 16:59	
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-64551313
Desc.: Street flooding - redact from Derbyshire Police has called to report standing water on the junction of Pinxton Lane and the A38. Police feels that this may not be an urgent but concerned it may freeze.			
Please could this be looked into . . Submitted by Advisor: redact			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6073984	Logged by: External to Confirm	on: 20/12/2017 07:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-64208034
Desc.: Road Pothole - Road deterioration on roundabout, nearly causing me to crash my motorcycle because of condition of surface , requires attention ASAP . Online report			
Location: See map coordinates and description details		Contact:	

Effective: 01/10/2017 to 04/10/2020

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 6066366

Logged by: External to Confirm

on: 05/10/2017 14:26

Service: Traffic Management

Subject: Road Adoption Enquiry

Classification: Report or Observation

Enquiry Ref: FS-CASE-59748836

Desc.: Adopted road enquiries - Received the following email from the customer:

From: TM Property Searches Commercial Helpdesk

Sent: 03 October 2017 16:55

To: redact

Subject: Case Reference OGJ/85811/19 - SearchID 17099203

SearchID 17099203

Case Reference

OGJ/85811/19

Request Type

TMGCon29, TMGLLC1

Data Provider

Ashfield District Council/Com

Property Address

Unit 9A, Castlewood Business Park, South Normanton, NG17 1BX

Good afternoon

Further to the client receiving the results of the above search, they have raised the following query:

"Please can you ask the local authority to confirm whether Pinxton Lane (adjoining the site) is a highway maintainable at public expense."

Please can you investigate and provide a response?

Thank you in advance for your assistance.

Kind regards

red

1200 Delta Business Park | Swindon | Wiltshire | SN5 7XZ

. Submitted by Advisor redact -

Location: See map coordinates and description details

Contact:

Enquiry No.: 3207655

Logged by: redact

on: 04/03/2019 13:20

Service: Carriageway/Footway

Subject: Carriageway Pothole

Classification: Report or Observation

Desc.: Carriageway pothole

Location: At roundabout (where kerbs have been removed)

Contact:

Plot Number: 2,000.00

Feature Id - Location: C151 - A38 To Adc Boundary

Feature Type: Street Section

Job Number: 2706562

Enquiry No.: 3207325

Logged by: redact

on: 11/12/2018 08:19

Service: Carriageway/Footway

Subject: Carriageway Pothole

Classification: Report or Observation

Desc.: Carriageway potholes developing

Location: Approach to Island

Contact:

Plot Number: 2,000.00

Feature Id - Location: C151 - A38 To Adc Boundary

Feature Type: Street Section

Job Number: 2699336

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 3207323	Logged by: redact	on: 10/12/2018 13:30
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation
Desc.: Address vehicle damage caused by LGV overide		
Location: Around Island -	Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section
Job Number: 2699332		
Enquiry No.: 3205664	Logged by: redact	on: 09/01/2018 15:33
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation
Desc.: potholes		
Location: Near field with Solar Panels	Contact:	
Plot Number: 2,000.00	Feature Id - Location: C151 - A38 To Adc Boundary	Feature Type: Street Section
Job Number: 2666369	Defect Number: 3563473	
Enquiry No.: 88103	Logged by: redact	on: 08/06/2020 16:33
Service: Highway Searches	Subject: Extents and CON29	Classification: Report or Observation
Desc.: extent plan and con29		
Location: UNIT 11A, PLOT 11A, CASTLEWOOD BUSINESS PARK, PINXTON LANE, SUTTON-IN-ASHFIELD, NG17 1JF	Contact:	
Enquiry No.: 84274	Logged by: redact	on: 02/12/2019 16:36
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation
Desc.: Incident date 15/11/2019 Car went int a pothole causing damage to vehicle. (onreceipt of a claim form an insurance claim has been raised)		
Location: Pinxton Lane (driving fromm the roundaboutentrance to the business park)	Contact:	
Enquiry No.: 84134	Logged by: redact	on: 26/11/2019 15:28
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation
Desc.: Incident date 04/11/2019 Car went into a large pothole causing damage to vehicle (on receipt of claim form an insurance claim has been raised)_		
Location: Brookhill Lane (pinxtonLane Fulwood)	Contact:	
Enquiry No.: 79816	Logged by: redact	on: 09/05/2019 11:27
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation
Desc.: Carriageway Damage		
Location: At island	Contact:	
Enquiry No.: 77622	Logged by: redact	on: 31/01/2019 11:54
Service: Highway Searches	Subject: Adoption Extents	Classification: Report or Observation
Desc.: extent plan - paid via CC 31/1/19		
Location: Highway Extents Request - Land at Pinxton Lane, Sutton-in-Ashfield, Nottinghamshire, NG17 1JF	Contact:	
Enquiry No.: 76154	Logged by: redact	on: 15/11/2018 11:23
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation
Desc.: See Letter in Links raising concerns with the condition of this island (carriageway surface, kerbstones etc). Plan and photos are with the scanned copy of the letter		
Location: Island off the A38 leading to Castlewood Industrial Estate	Contact:	
Enquiry No.: 75830	Logged by: redact	on: 02/11/2018 14:51
Service: Highway Searches	Subject: Extents and CON29	Classification: Report or Observation
Desc.: extent & CON29 - cheque rec'd - 2/11/18		
Location: Unit 5, Plots 2&3 Castlewood Busniess Park, Pinxton Lane. NG16 6JU	Contact:	

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Customer Services

Enquiry No.: 70597

Logged by: redact

on: 04/04/2018 10:23

Service: Highway Searches

Subject: Extents and CON29

Classification: Report or Observation

Desc.: received chq 16.4.18

Location: Plots 2 & 3, Castlewood Business Park

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C151 - A38 To Adc Boundary		Feature Type: Street Section		Area: Ashfield	
2660936	5 potholes (CW Repairs-Bituminous)	Roundabout	Filled when found (Cat 2)	Job Completed	26/10/2017	26/10/2017	Act.
2665440	pothole (CW Repairs-Bituminous)	Carriageway edge near electric sub station	Filled when found (Cat 1)	Job Completed	29/12/2017	29/12/2017	Act.
2666369	Carriageway Damage - potholes (Enquiry 3205664) 4 potholes (CW Repairs-Bituminous)	Near field with Solar Panels	Filled when found (Cat 1)	Job Completed	09/01/2018	09/01/2018	Act.
2668654	2 potholes filled at time of inspection (CW Repairs-Bituminous)	Near farm	Filled when found (Cat 1)	Job Completed	26/01/2018	26/01/2018	Act.
2668883	5 potholes (CW Repairs-Bituminous)	Near roundabout near middle Farm	Filled when found (Cat 1)	Job Completed	29/01/2018	29/01/2018	Act.
2671489	10 potholes, both sides of carriageway (CW Repairs-Bituminous)	From roundabout to Farm	Category 1	Job Completed	19/02/2018	20/02/2018	Act. ASH-AS/5003320
2674020	7 potholes (CW Repairs-Bituminous)	From roundabout down to farm entrance both sides of road	Category 1	Job Completed	14/03/2018	15/03/2018	Act. ASH-AS/5003480
2674023	Tack coat overlay scabby areas of c/way (CW Repairs-Bituminous)	about 50metres before electricity sub station	Category 2	Job Completed	14/03/2018	21/03/2018	Act. ASH/3802442
2676216	8 potholes (CW Repairs-Bituminous)	From roundabout to 150metres past Farm, both sides of road	Category 1	Job Completed	03/04/2018	04/04/2018	Act. ASH-AS/5003675
2681678	3 patches (CW Repairs-Bituminous)	Roundabout	Category 3	Job Completed	15/05/2018	25/06/2018	Act. ASH/3802665
2690655	4 potholes (CW Repairs-Bituminous)	Opposite Crow Tree Farm	Filled when found (Cat 2)	Job Completed	22/08/2018	22/08/2018	Act.
2693129	3 potholes (CW Repairs-Bituminous)	Nr Farm	Filled when found (Cat 2)	Job Completed	27/09/2018	27/09/2018	Act.
2698195	11 potholes (CW Repairs-Bituminous)	Between roundabout and Farm	Filled when found (Cat 2)	Job Completed	27/11/2018	27/11/2018	Act.
2699332	Carriageway Damage - Address vehicle damage caused by LGV override (Enquiry 3207323)	Around Island - Remove badly damaged / dislodged kerbs. Install 2 x drop kerbs. Install timber edging as a retainer / provide RC35 concrete (15M2) to replace dislodged kerbs as a temporary measure.	Category 2	Job Completed	11/12/2018	07/01/2019	Act. ASH/3803189
2699336	Carriageway Pothole - Carriageway potholes developing (Enquiry 3207325)	Approach to Island	Category 2	Job Completed	11/12/2018	13/12/2018	Act. ASH-AS/5005205

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	C151 - A38 To Adc Boundary	Feature Type:	Street Section	Area:	Ashfield
2700316	8 potholes (CW Repairs-Bituminous)	Near farm	Filled when found (Cat 2)	Job Completed	21/12/2018	20/12/2018	Act.
2703269	5 potholes (CW Repairs-Bituminous)	Near Farm and Electricity Sub Station	Filled when found (Cat 2)	Job Completed	29/01/2019	29/01/2019	Act.
2706146	5no patches (CW Repairs-Bituminous)	From roundabout to Elecitic sub station	Category 3	Job Cancelled	27/02/2019	28/05/2019	Est. ASH/3803722
2706148	3 potholes (CW Repairs-Bituminous)	Near Farm	Filled when found (Cat 1)	Job Completed	27/02/2019	27/02/2019	Act.
2706562	Carriageway Pothole - Carriageway pothole (Enquiry 3207655)	At roundabout (where kerbs have been removed)	Filled when found (Cat 2)	Job Completed	04/03/2019	04/03/2019	Act.
2707479	3 potholes (CW Repairs-Bituminous)	Opposite Farm	Filled when found (Cat 1)	Job Completed	12/03/2019	12/03/2019	Act.
2708691	3 potholes (CW Repairs-Bituminous)	30metre from entrance farm	Filled when found (Cat 2)	Job Completed	22/03/2019	22/03/2019	Act.
2711571	2 potholes (CW Repairs-Bituminous)	Near Farm and Electric Substation	Filled when found (Cat 2)	Job Completed	24/04/2019	24/04/2019	Act.
2715174	pothole (CW Repairs-Bituminous)	60 metres from roundabout	Filled when found (Cat 2)	Job Completed	30/05/2019	30/05/2019	Act.
2717094	11 potholes (CW Repairs-Bituminous)	From roundabout to sub station both sides of road	Category 1	Job Completed	18/06/2019	19/06/2019	Act. ASH-AS/5006285
2724456	4 potholes (CW Repairs-Bituminous)	60 metres past farm	Filled when found (Cat 2)	Job Completed	23/09/2019	23/09/2019	Act.
2725518	9 potholes (CW Repairs-Bituminous)	From roundabout down to Farm both sides of road and side of the newly built warehose	Category 2	Repair Completed	08/10/2019	09/10/2019	Act.
2727639	7 pothole on edge of carriageway (CW Repairs-Bituminous)	Just before entrance to Farm and about 100metre past Farm	Category 1	Repair Completed	05/11/2019	06/11/2019	Act.
2728666	10 potholes (CW Repairs-Bituminous)	From roundabout to Farm bothsides of road and 170metres past farm	Category 1	Repair Completed	18/11/2019	19/11/2019	Act.
2728694	3 patches (CW Repairs-Bituminous)	Various locations see map	Category 2	Job Completed	19/11/2019	28/11/2019	Act. ASH/3804131
2728695	4 patches (CW Repairs-Bituminous)	Various locations see map	Category 2	Job Completed	19/11/2019	18/12/2019	Act. ASH/3804132
2735895	2 potholes (CW Repairs-Bituminous)	Near Farm entrance and side of big warehouse	Filled when found (Cat 2)	Job Completed	30/01/2020	30/01/2020	Act.
2738557	Carriageway Pothole (CW Repairs-Bituminous)	Coming from A38 the pot hole is just before the farm on the left hand side.	Filled when found (Cat 1)	Job Completed	27/02/2020	27/02/2020	Act.
2738703	10 potholes (CW Repairs-Bituminous)	Entrance to roundabout and down lane to electricity substation	Category 2	Repair Completed	28/02/2020	02/03/2020	Act.

Effective: 01/10/2017 to 04/10/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216088)

Street Works Notices**Organisation:** NCC - ASHFIELD (3055005)**Works Ref:** AVERY3971**Version:** 6**Work Desc:** Installtion of Sign for New petrol station**Notice Type:** Works Stop**Start:** 10/06/2018 00:00:00**Work Status:** Works Stopped**Issued:** 13/06/2018 15:01:23**Work Type:** EToN 4: Minor**Est. End:** 10/06/2018**Completion:** 10/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Adjacent to New Petrol Station approx 25 metres from A38 Alfreton Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	10/06/2018			10/06/2018

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** A18**Version:** 3**Work Desc:** Replace damaged poles & columns**Notice Type:** Works Stop**Start:** 16/06/2020 08:00:00**Work Status:** Works Stopped**Issued:** 19/06/2020 14:00:02**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 19/06/2020**Completion:** 19/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction with A38	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	19/06/2020			19/06/2020

Works Ref: PINX**Version:** 3**Work Desc:** HW repairs**Notice Type:** Works Stop**Start:** 22/03/2018 00:00:00**Work Status:** Works Stopped**Issued:** 27/03/2018 11:41:51**Work Type:** EToN 4: Minor**Est. End:** 22/03/2018**Completion:** 23/03/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	23/03/2018			22/03/2018

Works Ref: PINXTONLANE**Version:** 3**Work Desc:** Carriageway works**Notice Type:** Revert Actual Start**Start:** 01/06/2018 00:00:00**Work Status:** Proposed Works**Issued:** 30/05/2018 11:55:45**Work Type:** EToN 4: Minor**Est. End:** 01/06/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	01/06/2018		01/06/2018	01/06/2018

Works Ref: PINXTONLANESWCLW**Version:** 3**Work Desc:** Carriageway repairs**Notice Type:** Works Stop**Start:** 18/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 19/12/2019 08:32:02**Work Type:** EToN 4: Minor**Est. End:** 19/12/2019**Completion:** 18/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane, Fulwood	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	18/12/2019			19/12/2019

Works Ref: PINXTONLANETA**Version:** 3**Work Desc:** CW patching**Notice Type:** Works Stop**Start:** 28/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 29/11/2019 08:20:40**Work Type:** EToN 4: Minor**Est. End:** 29/11/2019**Completion:** 28/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane Sutton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	28/11/2019			29/11/2019

Effective: 01/10/2017 to 04/10/2020
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Pinxton Lane (1216088)
