

Effective: 31/03/2018 to 31/03/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Barlow Drive South (4913700)

Street: Barlow Drive South (4913700)

Locality: Awsworth, Nottinghamshire

Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	Inc Service Road & Estate Fps	Feature Type:	Street Section		Area: Broxtowe	
Batch:	20440170 - Inspection Batch			Route:	Broxtowe North Feb Enh CW/FW		Date:	30/03/2021
3668444		30/03/2021	jn tulip rd to no 56	CW Repairs-Bituminous	Internal		Uncommitted	2772252
3668443		30/03/2021	lc 3	FW Repairs-Bituminous	Internal		Uncommitted	2772254
3668442		30/03/2021	96/106	FW Repairs-Bituminous	Internal		Uncommitted	2772253
Batch:	20377947 - Inspection Batch			Route:	Broxtowe North Feb Enh CW/FW		Date:	14/02/2020
3633697	Cway potholes	14/02/2020	Lamp columns 2, 3 & 4	CW Repairs-Bituminous	Internal		Committed	2737444
Batch:	20322696 - Inspection Batch			Route:	Broxtowe North Feb Enh CW/FW		Date:	12/02/2019
3601024	Fway pothole	12/02/2019	Outside 91	FW Repairs-Bituminous	Internal		Committed	2704583
3601023	Reset two loose bullnose kerbs and raise radius kerb back to level	12/02/2019	Outside and opposite 99	Kerbing/Edging	Internal		Committed	2704584