

Effective: 31/03/2018 to 31/03/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Lawrence Avenue (4913929)

Street: Lawrence Avenue (4913929)

Locality: Awsworth, Nottinghamshire

Area: Broxtowe

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b>		<b>Feature Type:</b>	Street Section		<b>Area:</b>	Broxtowe	
<b>Batch:</b>	20440173 - Inspection Batch			<b>Route:</b>	Broxtowe North Feb Enh CW/FW			<b>Date:</b>	30/03/2021
3668447		30/03/2021	18/35 os shop	CW Repairs-Bituminous	Internal		Uncommitted	2772256	
3668446		30/03/2021	28/33	FW Repairs-Bituminous	Internal		Uncommitted	2772257	
<b>Batch:</b>	20434329 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	02/03/2021
3664122	overhead power cables present next to catv box	02/03/2021	os mamma mia pizza shop. existing kerb	relay Kerbing/Edging	Internal		Committed	2767926	
<b>Batch:</b>	20434318 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	02/03/2021
3664116		02/03/2021	os no: 1-2 2 -2 4 -1 6-1 8-3 12-3 16-2 20-3 22-1 37-1 os the garages 5 os londis 2 os mamma mia pizza 2 opp 33-1	CW Repairs-Bituminous	Internal		Committed	2767920	
<b>Batch:</b>	20430947 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	11/02/2021
3661335		11/02/2021	8(2) 14(2) 18(1)	CW Repairs-Bituminous	Internal		Committed	2765141	
<b>Batch:</b>	20430028 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	04/02/2021
3660488	x6 ph's	04/02/2021	from no.4 to no16	CW Repairs-Bituminous	Internal		Uncommitted	2764287	
3660487	x1 cat 1 ph	04/02/2021	outside no.8	CW Repairs-Bituminous	Internal		Uncommitted	2764288	
<b>Batch:</b>	20428463 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	26/01/2021
3659237	Carriageway Potholes	26/01/2021	Lamp columns 2 & 3	CW Repairs-Bituminous	Internal		Uncommitted	2763035	
<b>Batch:</b>	20422271 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	08/12/2020
3655085	Carriageway potholes	08/12/2020	Lamp columns 3 & 4	CW Repairs-Bituminous	Internal		Uncommitted	2758874	
<b>Batch:</b>	20422264 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	08/12/2020
3655084	Footway potholes	08/12/2020	Lamp column 1	FW Repairs-Bituminous	Internal		Uncommitted	2758873	
<b>Batch:</b>	20418530 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	11/11/2020
3653291	Carriageway Potholes	11/11/2020	Lamp column 2	CW Repairs-Bituminous	Internal		Uncommitted	2757078	
<b>Batch:</b>	20413399 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	09/10/2020
3650344	Cway potholes	09/10/2020	From Sycamore to Wordsworth	CW Repairs-Bituminous	Internal		Committed	2754127	
<b>Batch:</b>	20404573 - Inspection Batch			<b>Route:</b>	Broxtowe North Aug Saf FW			<b>Date:</b>	10/08/2020
3645904	Cway potholes	10/08/2020	Lamp column 3 in the kerb edge	CW Repairs-Bituminous	Internal		Committed	2749685	

Effective: 31/03/2018 to 31/03/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Lawrence Avenue (4913929)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section			<b>Area:</b> Broxtowe	
<b>Batch:</b> 20384869 - Inspection Batch	No actionable defects found			<b>Route:</b> Review Outcome-David Freer				<b>Date:</b> 30/03/2020
<b>Batch:</b> 20377946 - Inspection Batch				<b>Route:</b> Broxtowe North Feb Enh CW/FW				<b>Date:</b> 14/02/2020
3633696	Cway potholes	14/02/2020	Lamp columns 4, 3A, 3 & 2	CW Repairs-Bituminous	Internal		Committed	2737443
<b>Batch:</b> 20372025 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 10/01/2020
3629914	Carriageway Potholes	10/01/2020	Lamp column 1	CW Repairs-Bituminous	Internal		Uncommitted	2733652
<b>Batch:</b> 20372024 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 10/01/2020
3629913	Carriageway Potholes	10/01/2020	Lamp column 3A	CW Repairs-Bituminous	Internal		Uncommitted	2733651
<b>Batch:</b> 20371362 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 07/01/2020
3629505	Carriageway Potholes	07/01/2020	Around the junction with Wordsworth rd	CW Repairs-Bituminous	Internal		Uncommitted	2733243
<b>Batch:</b> 20351625 - Inspection Batch				<b>Route:</b> Broxtowe North Aug Saf FW				<b>Date:</b> 23/08/2019
3618723	Cway potholes	23/08/2019	Lamp columns 2, 3, 3A & 4	CW Repairs-Bituminous	Internal		Committed	2722422
<b>Batch:</b> 20322637 - Inspection Batch				<b>Route:</b> Broxtowe North Feb Enh CW/FW				<b>Date:</b> 12/02/2019
3600989	Reset loose bullnose kerb	12/02/2019	Opposite the junction with Tennyson square	Kerbing/Edging	Internal		Committed	2704550
3600991	Cway potholes	12/02/2019	Lamp columns 2, 3, 4 & 5	CW Repairs-Bituminous	Internal		Committed	2704549
3600990	Fway patches	12/02/2019	Outside 26 & adjacent to lamp column 3A	FW Repairs-Bituminous	Internal		Committed	2704551
<b>Batch:</b> 20295698 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 01/08/2018
3585552	Cway pothole	01/08/2018	Near lamp column 6	CW Repairs-Bituminous	Internal		Committed	2688811
<b>Batch:</b> 20295695 - Inspection Batch	No actionable defects found			<b>Route:</b> Broxtowe North Aug Saf FW				<b>Date:</b> 01/08/2018
<b>Batch:</b> 20281730 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 03/05/2018
3577354	Reset loose bullnose kerb	03/05/2018	Opposite the junction with Tennyson square in front of the garages	Kerbing/Edging	Internal		Committed	2680474
<b>Batch:</b> 20281721 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 03/05/2018
3577349	Cway potholes	03/05/2018	Lamp column 3, 4 & 5	CW Repairs-Bituminous	Internal		Committed	2680469
<b>Batch:</b> 20281720 - Inspection Batch	No actionable defects found			<b>Route:</b> Broxtowe North May Saf FW				<b>Date:</b> 03/05/2018
<b>Batch:</b> 20275983 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 04/04/2018
3573471	Carriageway Potholes	04/04/2018	Lamp column 4	CW Repairs-Bituminous	Internal		Committed	2676503