

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Street: Stapleford Lane (4910456)

Locality: Toton, Nottinghamshire

Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	From boundary s/o #273 to Chetwynd Road junc exc service roa		Feature Type:	Street Section	Area:	Broxtowe
Batch:	20435405 - Inspection Batch		Route: Broxtowe South Mar Saf CW			Date: 05/03/2021		
No actionable defects found								
Batch:	20435404 - Inspection Batch		Route: Broxtowe South Jan Enh CW/FW			Date: 05/03/2021		
3664718		05/03/2021	jct st gerge's drive (4) jct blackrod close (3) 15(2)	CW Repairs-Bituminous	Internal		Committed	2768523
3664716	replace 3 number 2m staggered infill with sight gap barriers RTA damage, traffic management required lane closure or four way lights	05/03/2021	junction banks Road	Guardrail Repairs	Internal		Committed	2768518
3664719		05/03/2021	31(1) 28(1)	FW Repairs-Bituminous	Internal		Uncommitted	2768524
3664715		05/03/2021	opp 238	CW Repairs-Bituminous	Internal		Committed	2768520
3664720	two patches	05/03/2021	30/32	FW Repairs-Bituminous	Internal		Committed	2768525
3664714	stop and go	05/03/2021	lamp 46	FW Repairs-Bituminous	Internal		Committed	2768519
3664713		05/03/2021	opp 238	CW Repairs-Bituminous	Internal		Committed	2768521
3664721	tree root uplift	05/03/2021		FW Repairs-Bituminous	Internal		Committed	2768526
3664717		05/03/2021	opp 208	FW Repairs-Bituminous	Internal		Uncommitted	2768522
Batch:	20431134 - Inspection Batch		Route: Adhoc Inspection			Date: 12/02/2021		
3661508		12/02/2021	198(4) 204(5) 208(2)	CW Repairs-Bituminous	Internal		Committed	2765313
3661507		12/02/2021	204	CW Repairs-Bituminous	Internal		Committed	2765314
Batch:	20430415 - Inspection Batch		Route: Broxtowe South Feb Saf CW			Date: 08/02/2021		
3660785	500*300*50mm	08/02/2021	lamp 356	CW Repairs-Bituminous	Internal		Uncommitted	2764588
3660790		08/02/2021	entrance to stw works	CW Repairs-Bituminous	Internal		Committed	2764587
3660789	two cat 1 defects 800*250*80mm and 500x300*70mm	08/02/2021	95	CW Repairs-Bituminous	Internal		Uncommitted	2764592
3660788	500*200*40	08/02/2021	lamp 356	CW Repairs-Bituminous	Internal		Uncommitted	2764591
3660787	defect 500*300*50mm	08/02/2021	lamp 356	CW Repairs-Bituminous	Internal		Uncommitted	2764590
3660786	defect 400*300*50mm	08/02/2021	lamp 356	CW Repairs-Bituminous	Internal		Uncommitted	2764589
Batch:	20429254 - Inspection Batch		Route: Adhoc Inspection			Date: 02/02/2021		
3660011		02/02/2021	toton methodist church	CW Repairs-Bituminous	Internal		Committed	2763809
3660010	Carriageway Pothole - Road Pothole - Several potholes going down hill towards toton needs addressing as wheel damage and unsafe road surface . Online report Customer title is (Enquiry 6193352)	02/02/2021	jct swiney way (1) 95(2)	CW Repairs-Bituminous	Internal		Committed	2763810
Batch:	20429232 - Inspection Batch		Route: Adhoc Inspection			Date: 02/02/2021		
3659999		02/02/2021	210(4) 202(2)	CW Repairs-Bituminous	Internal		Committed	2763799
3659998		02/02/2021	238(6) lamp 46(4)	CW Repairs-Bituminous	Internal		Committed	2763798
3659997		02/02/2021	lamp 356(5) opp 239(3)	CW Repairs-Bituminous	Internal		Committed	2763797
3659996		02/02/2021	200	CW Repairs-Bituminous	Internal		Committed	2763796
3659995		02/02/2021	200	CW Repairs-Bituminous	Internal		Committed	2763795

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From boundary s/o ##### to Chetwynd Road junc exc service roa			Feature Type: Street Section			Area: Broxtowe	
Batch: 20429232 - Inspection Batch				Route: Adhoc Inspection				Date: 02/02/2021
3660000		02/02/2021	opp 239	CW Repairs-Bituminous	Internal		Committed	2763794
Batch: 20427883 - Inspection Batch				Route: Adhoc Inspection				Date: 21/01/2021
3658632	Carriageway Pothole x 3	21/01/2021	Stapleford Lane lamp posts 44--45	CW Repairs-Bituminous	Internal		Uncommitted	2762430
Batch: 20427878 - Inspection Batch				Route: Adhoc Inspection				Date: 21/01/2021
3658630	Carriageway Pothole x 3	21/01/2021	Lamp post 57	CW Repairs-Bituminous	Internal		Uncommitted	2762428
Batch: 20423124 - Inspection Batch				Route: Adhoc Inspection				Date: 11/12/2020
3655424	replace x3 sight gap guardrails pics attached possibly stop and go or left turn lane closure to allow works pics attached of lane	11/12/2020	Crossroad of Swiney way and Stapleford Lane	Guardrail Repairs	Internal		Committed	2759214
Batch: 20422405 - Inspection Batch				Route: Broxtowe South Dec Saf CW				Date: 08/12/2020
No actionable defects found								
Batch: 20418146 - Inspection Batch				Route: Adhoc Inspection				Date: 09/11/2020
3653082	Works required to replace Gully Pot (Enquiry 6169673) also linked to enquiry (89074) not entered contract as wont allow me to put Other repair then select Broxtowe Drainage Repair, please advise.	09/11/2020	Gully outside No138	Other	Internal		Committed	2756869
Batch: 20418100 - Inspection Batch				Route: Broxtowe South Nov Saf CW				Date: 09/11/2020
3653063	Fill 1 X Pothole around utility.	09/11/2020	Opposite Library & No 54	CW Repairs-Bituminous	Internal		Uncommitted	2756850
Batch: 20413458 - Inspection Batch				Route: Broxtowe South Oct Saf CW				Date: 12/10/2020
No actionable defects found								
Batch: 20412716 - Inspection Batch				Route: Adhoc Inspection				Date: 06/10/2020
3650111	Fill 1 X PH	06/10/2020	Junc with Katherine Opposite LC 51.	CW Repairs-Bituminous	Internal		Committed	2753894
Batch: 20410334 - Inspection Batch				Route: Broxtowe South Sep Saf CW				Date: 15/09/2020
No actionable defects found								
Batch: 20406810 - Inspection Batch				Route: Adhoc Inspection				Date: 26/08/2020
3647325	Fill 5 X PH (Enquiry 6175762)	26/08/2020	No 31 to Junc of Blackrod Close	CW Repairs-Bituminous	Internal		Committed	2751105
Batch: 20406218 - Inspection Batch				Route: Broxtowe South Aug Saf CW				Date: 21/08/2020
No actionable defects found								
Batch: 20401984 - Inspection Batch				Route: Adhoc Inspection				Date: 24/07/2020
3644706	Blocked Gully please ref to photo (Enquiry 3208547)	24/07/2020	LC 47 +10mtr	Drainage-Blocked Asset	Internal		Committed	2748486
Batch: 20401407 - Inspection Batch				Route: Broxtowe South Jul Saf CW/FW				Date: 20/07/2020
No actionable defects found								

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From boundary s/o ##### to Chetwynd Road junc exc service roe			Feature Type: Street Section			Area: Broxtowe	
Batch: 20399538 - Inspection Batch				Route: Adhoc Inspection				Date: 07/07/2020
3643029	Blocked Gully .Please ref to photo (Enquiry 6147659)	07/07/2020	LC 20	Drainage-Blocked Asset	Internal		Committed	2746808
Batch: 20398791 - Inspection Batch				Route: Adhoc Inspection				Date: 02/07/2020
3642670	Fill potholes at following locations LC 48 to LC 50 X 4 & LC 43 to LC44 X 5 (Enquiry 6169234)	02/07/2020	LC 48 to LC 50.& LC 43 to LC44	CW Repairs-Bituminous	Internal		Committed	2746447
Batch: 20398373 - Inspection Batch				Route: Adhoc Inspection				Date: 29/06/2020
3642461	Blocked Gully - Please ref to photo's	29/06/2020	No 126	Drainage-Blocked Asset	Internal		Committed	2746238
Batch: 20398260 - Inspection Batch				Route: Broxtowe South Jun Saf CW				Date: 26/06/2020
	No actionable defects found							
Batch: 20394456 - Inspection Batch				Route: Adhoc Inspection				Date: 02/06/2020
3640130	Loose gravel from Resurfacing in February, Sweeper required ASAP. Please ref to photo's	02/06/2020	From LC 14 to LC 19	Other	Internal		Committed	2743906
Batch: 20389672 - Inspection Batch				Route: Broxtowe South May Saf CW				Date: 01/05/2020
	No actionable defects found							
Batch: 20389300 - Inspection Batch				Route: Adhoc Inspection				Date: 30/04/2020
3638381	Fill 6 X Potholes	30/04/2020	Junc Katherine Ave to LC 51	CW Repairs-Bituminous	Internal		Uncommitted	2742157
Batch: 20388453 - Inspection Batch				Route: Broxtowe South Apr Saf CW				Date: 21/04/2020
	No actionable defects found							

Customer Services

Enquiry No.: 6202021	Logged by: External to Confirm	on: 18/03/2021 14:03	
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS-CASE-317446066
Desc.: Overgrown grass and verges - The hedges along this road have grown a lot and are obstructing pedestrians and making it very difficult to look onto the main road. . Submitted by Advisor: #####			
Location: Between Carfield Avenue and Banks Road (on Stapleford Lane itself)			
Contact:			
Enquiry No.: 6196363	Logged by: External to Confirm	on: 13/02/2021 10:15	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-307538916
Desc.: Road Pothole - Lots of pot holes running down the hill . Online report Customer #####			
Location: Near the speedometer			
Contact:			
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ##### to Chetwynd Road junc exc service roe	Feature Type: Street Section	
Job Number: 2765313			
Enquiry No.: 6196146	Logged by: External to Confirm	on: 11/02/2021 18:03	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-307116552
Desc.: Road Damage - Road surface sinking, pot holes forming rapidly . Online report Customer #####			
Location: By access to barracks footpath			
Contact:			
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ##### to Chetwynd Road junc exc service roe	Feature Type: Street Section	
Job Number: 2764587			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6195965	Logged by: External to Confirm	on: 10/02/2021 22:03	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-306752064
Desc.: Road Damage - Road damage and with various pot holes causing damage to cars when driving . Online report Customer title is Mr.			
Location: Stapleford Lane Road Damage		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Enquiry No.: 6195964	Logged by: External to Confirm	on: 10/02/2021 22:00	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306751545
Desc.: Road Pothole - Big pothole causing car damage . Online report Customer title is Mr.			
Location: Near ### Stapleford Lane Service Road		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Enquiry No.: 6195928	Logged by: External to Confirm	on: 10/02/2021 18:06	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-306695131
Desc.: Road Damage - The whole road heading up and down Toton Lane and Stapleford Lane, Toton, Nottingham is completely useless. Damaging vehicle tyres and suspension. This need some serious repairs asap. . Online report Customer title is Mr.			
Location: Stapleford Lane NG96FZ		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Enquiry No.: 6195703	Logged by: External to Confirm	on: 09/02/2021 20:39	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306307120
Desc.: Road Pothole - Multiple large pot holes . Online report Customer title is Ms.			
Location: Loads of pot holes		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Enquiry No.: 6195684	Logged by: External to Confirm	on: 09/02/2021 19:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306282918
Desc.: Road Pothole - Potholes appearing and reappearing. . Online report Customer title is Mrs.			
Location: Left side of road, coming down the hill. Too many potholes shoddily repaired!		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Enquiry No.: 6195628	Logged by: External to Confirm	on: 09/02/2021 16:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306228931
Desc.: Road Pothole - Pot holes all the way down from tram stop to Tesco lights in toton Category: Potholes			
Potholes been there, repaired and reappeared over 6 months + Very dangerous when going down hil. . Submitted by Advisor: ##### Customer title is			
Location: Stapleford Lane, Beeston, NG9 6JB		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2765313			
Defect Number: 3661508			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6195571	Logged by: External to Confirm	on: 09/02/2021 14:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306166769
Desc.: Road Pothole - Several potholes on this section of the road . Submitted by Advisor: ##### Customer title is			
Location: ## Stapleford Lane, Beeston, NG9 6GB	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2763799			
Enquiry No.: 6195561	Logged by: External to Confirm	on: 09/02/2021 14:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306153924
Desc.: Road Pothole - Multiple potholes along the road. Excerpt from customers email - Whole road needs resurfacing ASAP this road is dangerous . Submitted by Advisor: ##### Customer title is			
Location: ## Stapleford Lane, Beeston, NG9 6JG	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2763797			
Enquiry No.: 6195535	Logged by: External to Confirm	on: 09/02/2021 13:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-306133818
Desc.: Road Pothole - For over a year we have been waiting a suitable solution to resolving the series of potholes on this road You only ever patch one hole, if any when you visit - this is pointless. The road needs resurfacing, or a heavy amount of tarmac for at least well over a 100 holes. . Online report Customer title is			
Location: B6003	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2763798			
Enquiry No.: 6195533	Logged by: External to Confirm	on: 09/02/2021 13:12	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-306132335
Desc.: Road Damage - Yet more pothole to repair please complete the series of holes not just another one . Online report Customer title is			
Location: Close to Blackrod Close	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2763799			
Enquiry No.: 6195344	Logged by: External to Confirm	on: 08/02/2021 22:45	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS305899424
Desc.: Road Pothole - Three large potholes. Car now going into garage. . Online report Customer title is Miss. - Previous Confirm Case: 6190657			
Location: Stapleford lane, top of the hill	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2764588			
Enquiry No.: 6195304	Logged by: External to Confirm	on: 08/02/2021 17:36	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-305826070
Desc.: Road Pothole - Pot holes and very uneven road, NEEDS RESURFACING . Online report Customer title is Mrs.			
Location: Location from sub station to all the way down Stapleford Lane, upto Woodstock	Contact:		
Road various potholes, uneven road			
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ## to Chetwynd Road junc exc service roe		Feature Type: Street Section
Job Number: 2764589			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6195167	Logged by: External to Confirm	on: 08/02/2021 13:39	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-305710270
Desc.: Road Damage - The whole of the stretch of road is full of potholes some potholes are very deep and the whole road needs resurfacing, is there any plans for this to be done? . Submitted by Advisor: ##### Customer title is Mr.			
Location: the whole of stapleton lane from the tram station to #####		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763798			
Enquiry No.: 6195164	Logged by: External to Confirm	on: 08/02/2021 13:39	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-305708549
Desc.: Road Damage - as received by email. Hi i regularly commute to and from my work place and use the B6003 Stapleford Lane road. Due to the weather i have noticed the condition of this road has deteriorated over months there are now massive potholes some very deep scatter across this road. I have seen one tiny patch be resurfaced by the council once the rest hasn't been touched its becoming dangerous now as you have to swerve out of the way of them all. I would like to hear your response thanks. . Submitted by Advisor: ##### Customer title is Unknown			
Location: B6003 Stapleford Lane		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763798			
Enquiry No.: 6194692	Logged by: External to Confirm	on: 05/02/2021 20:54	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-304931602
Desc.: Road Pothole - Two areas of tarman missing . Online report Customer title is			
Location: On Stapleford Lane as you come out Katherine drive,		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763797			
Enquiry No.: 6194691	Logged by: External to Confirm	on: 05/02/2021 20:51	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-304931043
Desc.: Road Damage - Various pieces of road missing, it is terrible to drive on. . Online report Customer title is			
Location: All the way down the hill from Katherine drive to Woodstock road,		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o #273 to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763798			
Enquiry No.: 6194668	Logged by: External to Confirm	on: 05/02/2021 19:21	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-304911995
Desc.: Road Damage - Road surface is terrible with potholes . Online report Customer title is Miss.			
Location: All the way down Toton hill, from top to bottom		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763799			
Enquiry No.: 6194602	Logged by: External to Confirm	on: 05/02/2021 15:21	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-304832619
Desc.: Road Pothole - pothole on the junction - just under a foot wide . Submitted by Advisor: ##### Customer title is Ms.			
Location: junction of stapleford lane and swiney way		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ	Feature Type: Street Section	
Job Number: 2763810			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6194326 **Logged by:** External to Confirm **on:** 04/02/2021 15:33
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304414407
Desc.: Road Pothole - Recent pothole repair has failed already at one end of the recently introduced patch ? (Assume by Bodged and Scarppered ...). Could your workforce please visit the contractors work and assess the quality of repair (this one falls way short) wasting tax payers money. Please recover the charge for this inferior repair. . Online report Customer title is
Location: B6003 Stapleford Lane **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763798

Enquiry No.: 6194323 **Logged by:** External to Confirm **on:** 04/02/2021 15:27
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304412135
Desc.: Road Damage - Shocking road surface - too numerous potholes to mention. The road present a significant danger to all road users . Online report Customer title is
Location: Stapleford lane **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763799

Enquiry No.: 6194117 **Logged by:** External to Confirm **on:** 03/02/2021 22:18
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304100473
Desc.: Road Damage - Large potholes and surface damage across carriage way . Online report Customer title is Dr.
Location: Width of road on main down hill **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763796 **Defect Number:** 3659996

Enquiry No.: 6193491 **Logged by:** External to Confirm **on:** 01/02/2021 15:48
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-303058023
Desc.: Road Pothole - Uneven surface, manhole cover dropping from level of road surface . Online report Customer title is Miss.
Location: Several deep holes developing around large manhole cover in Stapleford Lane, opposite Toton Library **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763810

Enquiry No.: 6193488 **Logged by:** External to Confirm **on:** 01/02/2021 15:42
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-303051832
Desc.: Road Pothole - Pothole dangerous to cyclists . Online report Customer title is Miss.
Location: Near kerb at entrance to Toton Methodist Church, opposite Blackrod Close **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763809

Enquiry No.: 6193486 **Logged by:** External to Confirm **on:** 01/02/2021 15:39
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-303051559
Desc.: Road Pothole - Some repairs done a few days ago, but only down the centre of the Rd There are more to the sides which fill with water and splashes pedestrians . Submitted by Advisor: #####
Customer title is Mrs. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ##### to Chetwynd Road junc exc service roa **Feature Type:** Street Section
Job Number: 2763797

Effective: 01/04/2020 to 01/04/2021

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6193357	Logged by: External to Confirm	on: 01/02/2021 12:09	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-302922398
Desc.: Road Pothole - Pothole on junction of swiney way catching wheels as it's in turning circle . Online report Customer title is			
Location: Traffic lights corner of swiney way		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ		Feature Type: Street Section
Job Number: 2763810			
Enquiry No.: 6193352	Logged by: External to Confirm	on: 01/02/2021 12:00	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-302917518
Desc.: Road Pothole - Several potholes going down hill towards toton needs addressing as wheel damage and unsafe road surface . Online report Customer title is			
Location: From the top of stapleford lane going towards toton		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ		Feature Type: Street Section
Job Number: 2763809			
Defect Number: 3660011			
Enquiry No.: 6192954	Logged by: External to Confirm	on: 29/01/2021 15:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-302039259
Desc.: All other cycling issues - Many numerous requests have been made to the highways team to fill the potholes on the B6003 to no avail. Reported last year - these potholes were the cause of an injury - someone being thrown from their bike. So when will we see an absolutley disgusting road surface being repaired/releid so it is safe for cyclists to use. Its currently condition will KILL someone Online report Customer title is			
Location: B6003 Stapleford Lane		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ		Feature Type: Street Section
Job Number: 2763798			
Enquiry No.: 6192952	Logged by: External to Confirm	on: 29/01/2021 14:57	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-302037862
Desc.: Road Pothole - A recent repair in the vacinity has missed numerous holes in the road. Ask them to revisit and correct what they should have done in the first instance. (The whole lane needs attention - as we have had yellow lines marked around holes and nothing has been done during the last year with regards to fixing any of the other issues). . Online report Customer title is			
Location: Stapleford Lane Toton		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ		Feature Type: Street Section
Job Number: 2763794			
Defect Number: 3660000			
Enquiry No.: 6192183	Logged by: External to Confirm	on: 26/01/2021 17:12	
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-300728063
Desc.: Road work issue - Red man light not working			
Location: post 12 at crossing of Stapleford Lane, Swiney Way & Banks Rd		Contact:	
Enquiry No.: 6190873	Logged by: External to Confirm	on: 20/01/2021 10:57	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-298219949
Desc.: Road Pothole - Road surface inadequate after winter . Online report Customer title is			
Location: Stapleford Lane		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roæ		Feature Type: Street Section
Job Number: 2762430			
Defect Number: 3658632			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6190868 **Logged by:** External to Confirm **on:** 20/01/2021 10:48
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-298214347
Desc.: Road Pothole - Pot holes are horrendous on this road - Years of fixes have failed - Failure to repair the road may cost lives as it is not safe for cyclists to use this road due to the number of issues along the lane. . Online report Customer title is
Location: B6003 **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ### to Chetwynd Road junc exc service ro **Feature Type:** Street Section
Job Number: 2762428 **Defect Number:** 3658630

Enquiry No.: 6189750 **Logged by:** External to Confirm **on:** 14/01/2021 16:06
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS296100268
Desc.: Insurance claim - related to Confirm defect reference: 6189749
Date/Time: 14/01/2021 08:30:00
Direction of travel: Southbound to Toton.
Account of what happened: Drove into a pothole which has caused The front near side tire to burst and wheel damage. Car is now in the garage being assessed for other damages.
Location: Stapleford Lane, Toton, Near Darley avenue and Cleve Avenue. **Contact:**

Enquiry No.: 6189749 **Logged by:** External to Confirm **on:** 14/01/2021 16:05
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-296100268
Desc.: Insurance claim form requested - Road Pothole - Customer's wife drove over a pot hole which has caused damage to the car. . Submitted by Advisor: ##### Customer title is Mr.
Location: Stapleford Lane, Toton, Near Darley avenue and Cleve Avenue. **Contact:**

Enquiry No.: 6189331 **Logged by:** External to Confirm **on:** 12/01/2021 13:45
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-294911944
Desc.: Blocked drains - Customer details
: #####
: #####
: ## Stapleford Lane Toton & Chilwell Meadows Toton NG9 6GB

Enquiry details

: 12/01/2021 13:00:51 (this time will be one hour behind during british summer time)

We have recently had contractors on the service road, Stapleford Lane, Toton, to repair drains - think it was at ## Whilst walking on Sunday we noticed that one of the repaired drains is completely full of sand and the contractors have left sand all over one of the driveways and in the gutter, which, when it rains, will also wash into the drain and cause further problems. The drain is so full of sand that I think it will need someone to come and scoop it out. Further up the road, closer to us at ## there are two drains which are completely blocked. One has been filled with tarmac and one is blocked with debris. My husband did take photos which we will happily upload for you if you can tell us who to send these to. Let me know if you require further information.. Submitted by Advisor: ##### Customer title is Mrs.

Location: ## Stapleford Lane Toton & Chilwell Meadows Toton NG9 6GB**Contact:**

Enquiry No.: 6186704 **Logged by:** External to Confirm **on:** 17/12/2020 11:12
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS284936072
Desc.: Insurance claim - related to Confirm defect reference: 6186703
Date/Time: 05/12/2020 21:00:00
Direction of travel: Traveling in my car to Toton tesco from Stapleford in my car
Account of what happened: When traveling in my car to Toton tesco from stapleford in my car, at the speed limit of the road, I hit a very dangerous, very unavoidable pothole that caused serious damage to my front passenger wheel and tyre and also my rear passenger wheel and tyre, causing my car to be undriveable as it had bent both wheels, deflating both tyres and even tearing one open. Which now means I need to buy two new wheels and tyres to fix the damage of my car caused by a pothole that, according to a resident that kindly came over to assist whilst waiting for the AA, had also caused damage to three other road users that day?
Location: Stapleford Lane B6003 near the NET tram park and ride stop **Contact:**

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6186703	Logged by: External to Confirm	on: 17/12/2020 11:10	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-284936072
Desc.: Insurance claim form requested - Road Pothole - A large unavoidable pothole #####. Submitted by Advisor: ##### Customer title is Unknown			
Location: Stapleford Lane B6003 near the NET tram park and ride stop	Contact:		
Enquiry No.: 6186016	Logged by: External to Confirm	on: 11/12/2020 11:09	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS282716511
Desc.: Insurance claim - related to Confirm defect reference: 6186014 Date/Time: 07/12/2020 07:00:00 Direction of travel: ##### was travelling towards Boots Head office from Belper Account of what happened: Hit the pothole and this has ripped her tyre and bent the wheel. The nearside front wheel.			
Location: Stapleford Lane B6003 near to Kathryn Drive	Contact:		
Enquiry No.: 6186014	Logged by: External to Confirm	on: 11/12/2020 11:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-282716511
Desc.: Insurance claim form requested - Road Pothole - ##### rang as not received an insurance claim form for his wife who hit a pothole and damaged her tyre and bent her wheel. #####			
##### says this pothole has been repaired. . Submitted by Advisor: ##### Customer title is			
Location: Stapleford Lane B6003 near to Kathryn Drive	Contact:		
Enquiry No.: 6185234	Logged by: External to Confirm	on: 03/12/2020 14:51	
Service: Carriageway/Footway	Subject: Guard Rail Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-279694087
Desc.: Guard rail damage - Guard rails on the junction of Swiney way, 4 rails in total and one is damaged. Customer has advised there is a lot of big lorries using the road and it is unsafe for people using the crossing. . Submitted by Advisor: ##### Customer title is Mr.			
Location: Crossroad of Swiney way and Stapleford Lane. Near ### Stapleford Lane NG9 6GA	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ##### to Chetwynd Road junc exc service roa	Feature Type: Street Section	
Job Number: 2759214	Defect Number: 3655424		
Enquiry No.: 6184365	Logged by: External to Confirm	on: 24/11/2020 10:24	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS275931385
Desc.: Road Damage - Customer has re raised the problem case number FS244651565 said she reported the damage to Stapleford Lane outside ### & # in August It has been assessed twice and sprayed yellow. Can you please let me know if a date for fixing this damage has been set, as the damage is getting worse . Submitted by Advisor: ##### Customer title is ### - Previous Confirm Case: 6176446			
Location: damage to Stapleford Lane outside ### & #	Contact: Na		
Enquiry No.: 6181373	Logged by: External to Confirm	on: 22/10/2020 18:18	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-264024485
Desc.: Road Damage - Road dangerous to cyclists due to road surface being in an unacceptable state . Online report Customer title is			
Location: Stapleford Lane Nottinghamshire	Contact:		
Enquiry No.: 6180022	Logged by: External to Confirm	on: 09/10/2020 11:39	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-259032604
Desc.: Road Damage - Tarmac has fallen away - exposing grate cover . Online report Customer title is			
Location: Around a drainage grate	Contact:		

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6179448	Logged by: External to Confirm	on: 05/10/2020 07:32	Enquiry Ref: FS-CASE-256765895
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - awful road - needs resurfacing before an accident occurs . Online report Customer title is			
Location: hill of indicated road	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2753894	Defect Number: 3650111		
Enquiry No.: 6179178	Logged by: External to Confirm	on: 30/09/2020 14:03	Enquiry Ref: FS-CASE-255579788
Service: Trees/Verges	Subject: Weeds	Classification: Report or Observation	
Desc.: Overgrown weeds - Over a years worth of weeds have now amassed on the central reservation - Can we pleas have the area concreted if you are not maintaining the landscape. . Online report Customer title is			
Location: Central reservation Stapleford Lane	Contact:		
Enquiry No.: 6179174	Logged by: External to Confirm	on: 30/09/2020 13:54	Enquiry Ref: FS-CASE-255577010
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: Road Pothole - Uneven surface due to pot holes and in effective repairs . Online report Customer title is			
Location: Nottingham Road not alright	Contact:		
Enquiry No.: 6177644	Logged by: External to Confirm	on: 14/09/2020 22:03	Enquiry Ref: FS-CASE-249688504
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Problematic road surface - too many patches with collapsed area leaving further divits in the road surface. . Online report Customer title is			
Location: High Road	Contact:		
Enquiry No.: 6177639	Logged by: External to Confirm	on: 14/09/2020 21:24	Enquiry Ref: FS-CASE-249681100
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - nasty gash in road surface - exceptionally dangerous to cyclists and motorcyclists. . Online report Customer title is			
Location: B6003	Contact:		
Enquiry No.: 6177352	Logged by: External to Confirm	on: 10/09/2020 16:48	Enquiry Ref: FS-CASE-248247087
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	
Desc.: Parking issues - Obstructing line of sight for traffic exiting Hillview Road and causing traffic and pedestrian obstructions . Online report Customer title is Mr.			
Location: Vehicles parking on the roadside, on both sides of the road using the line of sight clear ways as parking	Contact:		
Enquiry No.: 6176446	Logged by: External to Confirm	on: 02/09/2020 07:46	Enquiry Ref: FS-CASE-244651565
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Damage to the main road, pothole, next to previous electric works re tarmac. HUGE noise issue when lorries go over the damaged area. Shaking of the houses!!, It's a Nightmare and has been getting worse over time. Please please please can this be fixed.....please. I have previously called to report this. It might not look too bad but please observe the impact that it has when the lorries go over it. Thank you . Online report Customer title is Mrs.			
Location: On the main road outside no. ### Stapleford Lane and opposite ### Stapleford Lane, Toton	Contact:		
Enquiry No.: 6175762	Logged by: External to Confirm	on: 25/08/2020 12:51	Enquiry Ref: FS-CASE-241997923
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Road surface dismal full of holes and patches) - bounced all over the place into on coming traffic. Saftey risk. . Online report Customer title is			
Location: 6003 Stapleford Lane	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2751105	Defect Number: 3647325		

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6174834	Logged by: External to Confirm	on: 17/08/2020 07:32	
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-238673831
Desc.: Road marking renewal - Markings on this junction are completely worn away and present issues with cars turning across two lanes instead of staying in lane. . Online report Customer title is Mrs.			
Location: 4 way junction of stapleford lane, by tescos petrol station. Particularly southbound left turn, stapleford lane.		Contact:	
Enquiry No.: 6173746	Logged by: External to Confirm	on: 03/08/2020 08:00	
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-234299758
Desc.: Traffic light fault - Myself and another local have noticed the traffic light phasing has changed or is wrong. The main Stapleford Land direction stays on green a lot longer now and even when traffic appears from the other directions = Banks rd Swiney Way it does not change even when nothing happens to be travelling down Stapleford Lane direction. . Online report Customer title is Mr.			
Location: Main 4 way traffic lights at Banks rd to Swiney Way etc.		Contact:	
Enquiry No.: 6172856	Logged by: External to Confirm	on: 23/07/2020 09:54	
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-231059878
Desc.: Other requests - Waste crew denied access to ##### in Toton - team at Broxtowe used to get up to date lists of works being carried out, however this is no longer the case. Could this be done again? . Submitted by Advisor: ##### - Customer title is Mr.			
Location: Cleve Ave		Contact:	
Enquiry No.: 6172640	Logged by: External to Confirm	on: 21/07/2020 00:06	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-230181213
Desc.: Road Damage - disgraceful road surface - riddled with holes . Online report Customer title is			
Location: on the hill		Contact:	
Enquiry No.: 6172639	Logged by: External to Confirm	on: 21/07/2020 00:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-230181177
Desc.: Road Pothole - Holes ! . Online report Customer title is			
Location: B6003		Contact:	
Enquiry No.: 6171858	Logged by: External to Confirm	on: 10/07/2020 22:33	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-226805762
Desc.: Road Damage - road surface has become separated - terrible surface conditions with plenty of potholes which are dangerous to cyclists . Online report Customer title is			
Location: on the slope of the hill		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2746447	Defect Number: 3642670		
Enquiry No.: 6171569	Logged by: External to Confirm	on: 08/07/2020 08:39	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-225668833
Desc.: Road Damage - Totally uneven road with patchy repairs - needs totally resurfacing . Online report Customer title is			
Location: Top of stapleford lane		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa		Feature Type: Street Section
Job Number: 2746447	Defect Number: 3642670		

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6170906	Logged by: External to Confirm	on: 01/07/2020 11:12	
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-223174041
Desc.: I am writing for urgent assistance needed to stop the flooding of my property. I have lived at the above property for 30 years which on many occasions has incurred damage from flooding caused by heavy rains storms. The house is situated at the bottom of the service road with approximately 2ft deep, 30 ft sunken garden which overflows with water causing it to enter the air bricks and on a few occasions is so close to going in the house. To stop this happening the side gate has to be opened to let the water run into the back garden and into the shed causing damage. Extra gulleys were added to the entrance of the property approximately 10 years ago but the problem is getting worse. The house has recently gone up for sale but this problem is likely to affect that as you have to declare all flooding issues. Please see the attached video's and photographs from the storm on 17th June and as you can see from them the amount of water coming down the street and the speed of it, something needs to be done urgently to resolve this issue.			
Look forward to hearing from you			
Location: ### Stapleford Lane, Toton	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roe	Feature Type: Street Section	
Job Number: 2748486	Defect Number: 3644706		
Enquiry No.: 6170653	Logged by: External to Confirm	on: 29/06/2020 12:27	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-222359141
Desc.: Road Damage - Large area of unsatisfactory road that is in need of dire repair. It is physically unsafe for road users with samller transport solutions . Online report Customer title is			
Location: B6003 - a big stretch from bottom of the hill over the top of the hill	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roe	Feature Type: Street Section	
Job Number: 2746447	Defect Number: 3642670		
Enquiry No.: 6170633	Logged by: External to Confirm	on: 29/06/2020 10:39	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS222282707
Desc.: Insurance claim - related to Confirm defect reference: 6170629 Date/Time: 17/06/2020 18:20:00 Direction of travel: driving down the hill coming from Stapleford and travelling towards Toton Account of what happened: as I drove over the manhole cover it came out of its location and flicked up damaging my front and rear tyres and the alloys on the left side of my vehicle.			
Location: Stapleford lane, Toton, directly opposite the junction of Woodstock Road	Contact:		
Enquiry No.: 6170629	Logged by: External to Confirm	on: 29/06/2020 10:35	
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-222282707
Desc.: Insurance claim form requested - Missing and damaged manhole/drain covers - I am contacting regarding a metal manhole cover on Stapleford lane, Toton, directly opposite the junction of Woodstock Road. At 18:20 on Wednesday 17th June I drove over the manhole cover which flicked out of its location as I drove over it. At no fault of my own have incurred severe damage to my tyre and wheel alloys on my front left wheel. I have attached picture evidence of my wheel and the manhole cover as well as front and rear-view dash cam footage which you can view via this link: https://we.tl/-BhMpz9B1Je . Submitted by Advisor: ##### Customer title is			
Location: Stapleford lane, Toton, directly opposite the junction of Woodstock Road	Contact:		
Enquiry No.: 6170230	Logged by: External to Confirm	on: 24/06/2020 10:53	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-220646404
Desc.: Insurance claim form requested - Road Pothole - I hit a pothole which damaged my tyre so badly it had to be replaced the same day. I was travelling in fairly heavy traffic and hit a pothole. There was a loud bang. I was speaking to a person on handsfree on my phone in the car and even they heard it. . Submitted by Advisor: ##### Customer title is Miss.			
Location: B6003 the city side of your Toton Lane park and ride. The road condition is appalling	Contact:		
all the way as far as around 196 Stapleford Lane which runs parallel. City bound.			

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6170155	Logged by: External to Confirm	on: 23/06/2020 13:21	Enquiry Ref: FS220358484
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	
Desc.: Insurance claim - related to Confirm defect reference: 6170154 Date/Time: 17/06/2020 17:45:00 Direction of travel: south on Stapleford Lane Account of what happened: drain cover was sticking up and not visible as covered by water as raining and he hit this and blew out 2 tyres front and back			
Location: Stapleford Lane opposite Woodstock Road	Contact:		
Enquiry No.: 6170154	Logged by: External to Confirm	on: 23/06/2020 13:19	Enquiry Ref: FS-CASE-220358484
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Insurance claim form requested - Road Damage - ran over drain cover and this was sticking up out of the road, covered in water. . Submitted by Advisor: ##### Customer title is Ms.			
Location: Stapleford Lane opposite Woodstock Road	Contact:		
Enquiry No.: 6169673	Logged by: External to Confirm	on: 19/06/2020 08:42	Enquiry Ref: FS-CASE-218727619
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	
Desc.: Blocked drains - Outside 120 to 138 the street drain on the side nearest the houses is completely blocked with soil and roots, I have dug it out as much as possible but cannot unblock the pipe to the sewer. Outside 126 it was blocked with pebbles/stones, this has cleared by using a pole to allow water to disperse but remains full of stone to level of the sewer connection. This caused flooding to properties at bottom of the slip road, no.120 & 118. Online report Customer title is Mr.			
Location: Stapleford Lane service road, blocked street drains outside no.120 to 138 & #	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o # to Chetwynd Road junc exc service ro		Feature Type: Street Section
Job Number: 2756869	Defect Number: 3653082		
Enquiry No.: 6169551	Logged by: External to Confirm	on: 18/06/2020 09:36	Enquiry Ref: FS218556574
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	
Desc.: Insurance claim - related to Confirm defect reference: 6169550 Date/Time: 17/06/2020 18:20:00 Direction of travel: driving down the b6003 in the left hand lane, driving towards tesco Account of what happened: The grate was raised and couldn't avoid the cover as traffic was driving towards the car and heard a loud bang that popped front near side of passenger wheel and cust drove towards Tesco as couldn't stop on the road as cars was behind			
Location: Stapleford Lane Lat52.9116 long 1.2608 Opposite juct of Woodstock road the man hole cover next to the railing in the road on B6003	Contact:		
Enquiry No.: 6169550	Logged by: External to Confirm	on: 18/06/2020 09:34	Enquiry Ref: FS-CASE-218556574
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	
Desc.: Insurance claim form requested - Missing and damaged manhole/drain covers - A Manhole cover has lifted in the road in the middle and is really close to the kerb and with on coming traffic cant miss the cover , Iron grate two triangle and is raised up from the middle of the drain . Submitted by Advisor: ##### iCustomer title is Mr.			
Location: Opposite juct of Woodstock road the man hole cover next to the railing in the road on B6003	Contact:		
Enquiry No.: 6169478	Logged by: External to Confirm	on: 17/06/2020 19:12	Enquiry Ref: FS-CASE-218418654
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Square drain cover has been pushed up and is split down the middle and elevated above the hole, causing a very dangerous sharp edge. It has punctured both my tyres on the left-hand side of my car. . Online report Customer title is Mr.			
Location: On the left hand side of the road coming down the hill- in the road, but to the left near to the curb.	Contact:		
Enquiry No.: 6169319	Logged by: External to Confirm	on: 17/06/2020 09:06	Enquiry Ref: FS-CASE-218146524
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Sink holes in the road surface at the narrowest point - Cars try to avoid dips and nearly knock cyclist off thier bike. Area need relaying . Online report Customer title is			
Location: by the Church	Contact:		

Effective: 01/04/2020 to 01/04/2021

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6169234	Logged by: External to Confirm	on: 16/06/2020 12:48	Enquiry Ref: FS-CASE-217875686
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Riddled with gaps and holes . Online report Customer title is			
Location: B6003	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa	Feature Type: Street Section	
Job Number: 2746447	Defect Number: 3642670		
Enquiry No.: 6167872	Logged by: External to Confirm	on: 30/05/2020 11:09	Enquiry Ref: FS-CASE-212134746
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Clumps of loose gravel from antiskid surfacing. Nearly came skidding of my bike. Could or will cause a serious accident for cyclists. The loose gravel is along the whole stretch of the antiskid surface. . Online report Customer title is Mrs.			
Location: Junctions of B6003, Chetwynd Road, Hill view Road	Contact:		
Plot Number: 2,000.00	Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roa	Feature Type: Street Section	
Job Number: 2743906	Defect Number: 3640130		
Enquiry No.: 6167365	Logged by: External to Confirm	on: 22/05/2020 13:38	Enquiry Ref: FS-CASE-209822144
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	
Desc.: Damaged/dangerous/fallen tree - There is a tree outside my house which has branches hanging off the tree because they have broken in the wind,They are about 5/6 foot long and about 3 inch in diameter and about 5 foot from the ground .The branches are still in the trees but have broke off from the tree. . Submitted by Advisor: ##### Customer title is Mr.			
Location: # Stapleford Lane, Toton, Nottinghamshire, NG9 6GA,	Contact:		
Enquiry No.: 6166478	Logged by: External to Confirm	on: 04/05/2020 11:48	Enquiry Ref: FS-CASE-203519822
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: From: ##### Sent: 15 May 2020 14:08 To: ##### Cc: ##### > Subject: RE: Fallen tree at Stapleford Lane, Toton (Hams 6166478)			
Hi ##			
I hope all is well with you? This one came through and I think its land maintained by Broxtowe. Please can you let me know?			
Both tree and hedge looks to be the issue.			
Many thanks,			
Location: Stapleford Lane, Toton (next to junction of Broadstairs Road / Spinney Crescent)	Contact:		
Enquiry No.: 6166303	Logged by: External to Confirm	on: 29/04/2020 11:15	Enquiry Ref: FS-CASE-201705120
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: Road Pothole - Sink hole / pot hole requires a patch . Online report Customer title is			
Location: Opposite slip road entrance	Contact:		

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 6165645 **Logged by:** External to Confirm **on:** 06/04/2020 20:18
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-192904084
Desc.: Road Pothole - The pothole still remains as a pothole - who ever dumped a lump of tarmac on the road as ran over it needs removing from the scene. Shoddy workmanship which will not last the summer, let alone the winter months . Online report Customer title is
Location: As indicated **Contact:**

Enquiry No.: 6165639 **Logged by:** External to Confirm **on:** 06/04/2020 19:57
Service: Trees/Verges **Subject:** Fallen Tree **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-192897956
Desc.: Damaged/dangerous/fallen tree - Tree split in two - other branches may be liable to dropping ? Needs attention . Online report Customer title is
Location: Stapleford Lane Toton **Contact:**

Enquiry No.: 6165638 **Logged by:** External to Confirm **on:** 06/04/2020 19:54
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-192897280
Desc.: Road Pothole - Repaired pothole has failed - obviously not value for money from the contractor, as you now need to revisit . Online report Customer title is
Location: Existing pothole repair failure **Contact:**

Enquiry No.: 6165633 **Logged by:** External to Confirm **on:** 06/04/2020 18:27
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-192868671
Desc.: Road Damage - road in really poor state of repair - so much i am sure it is damaging my cars suspension . Online report Customer title is
Location: on the hill of Stapleford lane **Contact:**

Enquiry No.: 3209743 **Logged by:** ##### **on:** 12/03/2021 14:16
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation
Desc.: section 81 raised by email ref 2005114993
Location: 267 **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ### to Chetwynd Road junc exc service roæ **Feature Type:** Street Section

Enquiry No.: 3209541 **Logged by:** ##### **on:** 05/01/2021 09:58
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation
Desc.: Please check the gullies are functioning correctly, if they are blocked with leaves etc. If so raise a cleansing job giving the locations and how many.
Location: Gullies between house no's ### to ### on the main road and service road. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ### to Chetwynd Road junc exc service roæ **Feature Type:** Street Section

Enquiry No.: 3209456 **Logged by:** ##### **on:** 30/11/2020 16:59
Service: Other **Subject:** Utility STATS requested **Classification:** Service Request
Desc.: Stats required to enable replacement of gully pot
Location: Outside No. ### on service road **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ### to Chetwynd Road junc exc service roæ **Feature Type:** Street Section

Job Number: 2756869**Defect Number:** 3653082

Enquiry No.: 3209283 **Logged by:** ##### **on:** 06/10/2020 11:27
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation
Desc.: Tree has sprouted secondary bush encroaching & blocking part of Fway, Cut back required.please ref to photo's
Location: Opposite No ### on service Rd Next to LC # **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From boundary s/o ### to Chetwynd Road junc exc service roæ **Feature Type:** Street Section

Enquiry No.: 96781 **Logged by:** ##### **on:** 29/03/2021 14:57
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation
Desc.: see attached letter with photos
Location: # stapleford lane **Contact:**

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 95668 Logged by: ##### on: 24/02/2021 16:19
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway Condition
 Location: Entire Contact:

Enquiry No.: 95231 Logged by: ##### on: 11/02/2021 15:47
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway Conditions
 Location: Entire Contact:

Enquiry No.: 94644 Logged by: ##### on: 28/01/2021 08:24
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Carriageway Condition
 Location: Entire Contact:

Enquiry No.: 94406 Logged by: ##### on: 21/01/2021 16:45
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Carriageway Condition
 Location: Entire Contact:

Enquiry No.: 93610 Logged by: Dave Walker on: 21/12/2020 13:33
 Service: Carriageway/Footway Subject: Blocked Drain Classification: Report or Observation
 Desc.: Hi #####
 Is it possible to have the service road swept now all the leaves have fallen off and keep it maintained on a regular basis especially in summer when the grass has been cut as it falls into the gulleys which makes the situation worse when the garden floods and takes longer to clean the mess.
 Could you pass this on to the correct department please.

Regards
#####

Contact:

Enquiry No.: 93375 Logged by: ##### on: 11/12/2020 14:47
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Hi #####

There is a pothole on Stapleford Lane at Toton near to the tram terminus, it has been repaired a number of times but the repair has failed again, can we look at you look at a permanent repair at this very busy site

#####

Location: Near the Tram Terminus

Contact:

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 92124 **Logged by:** ##### **on:** 03/11/2020 15:13
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation

Desc.: From #####

Hello.

I've been advised by Darren Henry's constituency office to contact you regarding the condition of the surface on Stapleford Lane.

I have noticed that a couple of streets have been completely resurfaced instead of having stone chips thrown onto wet tar, so when is Stapleford Lane going to get the resurfacing from the tram stop to Woodstock Road it is so badly needed? It is a danger to motorcyclists, and the damage to vehicles can turn out to be expensive.

Regards

#####

Location: Stapleford Lane

Contact:

Enquiry No.: 92006 **Logged by:** ##### **on:** 29/10/2020 15:39
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation

Desc.: Carriageway potholes and sunken manhole near lamp #

Location: Carriageway between lamps #####

Contact:

Enquiry No.: 91275 **Logged by:** ##### **on:** 06/10/2020 14:05
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation

Desc.: Traffic Issues

Location: O/s #

Contact:

Enquiry No.: 90488 **Logged by:** ##### **on:** 08/09/2020 17:01
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation

Desc.: ----- Original message -----

From: ##### >

Date: 10/08/2020 15:40 (GMT+00:00)

To: #####

Subject: RE: ## Stapleford Lane, Toton

Hi,

Is it possible the council can provide sand bags to put across our double drive and next doors to stop the water coming in with the storms lasting a few days.

I am worried the water will not soak away in time for the next flash flood as it is going to last a few days which doesn't normally happen .

Regards

#####

Location: O/s ##

Contact:

Enquiry No.: 89584 **Logged by:** ##### **on:** 04/08/2020 11:38
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation

Desc.: after the junction with Cleve Avenue, from the last house on Stapleford Lane the path becomes extremely narrow. I reported last year and the farmer who has the first field on the left between the last house on stapleford lane (##) and the sub station did cut their bushes which were overhanging the pathway. This again is a problem but from looking at it more closely, the main problem is the width of the path. At least 600 school children walk this route twice a day and the path safely does not allow for children to comfortably walk 2 a breast. It is an accident waiting to happen as there is a constant flow of traffic all day, including many hgv's that use Stapleford Lane and also many vehicles do not adhere to the 30mph due the poor signage. I think this need to be addressed urgently, before a child is badly injured or killed.

Location: As you leave Toton at the top of the hill just after the last house at ## Stapleford Lane, the foot path becomes far too narrow

Contact:

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Customer Services

Enquiry No.: 89074

Logged by: #####

on: 16/07/2020 10:24

Service: Carriageway/Footway

Subject: Flooding

Classification: Report or Observation

Desc.: Flooding see Video

Location: O/s 120

Contact:

Plot Number: 2,000.00

Feature Id - Location: From boundary s/o ### to Chetwynd Road junc exc service roe

Feature Type: Street Section

Job Number: 2756869

Defect Number: 3653082

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From boundary s/o ### to Chetwynd Road junc exc service roe		Feature Type: Street Section		Area: Broxtowe	
2735920	Remove 2 X Damaged VRS Single rail (Inspection required before ordering and works as 1 X VRS may not need replacing but re-positioning) Replace 1 Or 2 X for New and Footings. Please see attached photo's for spec. (Guardrail Repairs)	Stapleford Rd Junction Swiney way	Category 3	Job Cancelled	31/01/2020	30/04/2020	Est.
2742157	Fill 6 X Potholes (CW Repairs-Bituminous)	Junc Katherine Ave to LC 51	Category 2	Repair Completed	30/04/2020	04/05/2020	Act.
2743906	Loose gravel from Resurfacing in February, Sweeper required ASAP. Please ref to photo's (Other)	From LC 14 to LC 19	Category 2	Job Completed	02/06/2020	09/06/2020	Act. BROX/3307108
2746238	Blocked Gully - Please ref to photo's (Drainage-Blocked Asset)	No 126	DRAINAGE Score 4 - PRIORITY 2	Further Drainage Work Required	29/06/2020	15/07/2021	Est. DC-BRO/900045
2746447	Fill potholes at following locations LC 48 to LC 50 X 4 & LC 43 to LC44 X 5 (Enquiry 6169234) (CW Repairs-Bituminous)	LC 48 to LC 50.& LC 43 to LC44	Category 2	Job Completed	02/07/2020	13/07/2020	Act. BROX/3307173
2746808	Blocked Gully .Please ref to photo (Enquiry 6147659) (Drainage-Blocked Asset)	LC 20	Drainage - Matrix	Works Order Committed	07/07/2020	14/07/2020	Est. DC-BRO/900018
2748486	Blocked Gully please ref to photo (Enquiry 3208547) (Drainage-Blocked Asset)	LC 47 +10mtr	DRAINAGE Score 2 - PRIORITY 4	Works Order Committed	24/07/2020	24/07/2021	Est. DC-BRO/900017
2751105	Fill 5 X PH (Enquiry 6175762) (CW Repairs-Bituminous)	No 31 to Junc of Blackrod Close	Category 2	Job Completed	26/08/2020	10/09/2020	Act. BROX/3307340
2753894	Fill 1 X PH (CW Repairs-Bituminous)	Junc with Katherine Opposite LC 51.	Category 2	Job Completed	06/10/2020	12/10/2020	Act. BROX/3307517
2756850	Fill 1 X Pothole around utility. (CW Repairs-Bituminous)	Opposite Library & No 54	Category 2	Repair Completed	09/11/2020	10/11/2020	Act.

Effective: 01/04/2020 to 01/04/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Stapleford Lane (4910456)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From boundary s/o ##### to Chetwynd Road junc exc service roæ		Feature Type: Street Section		Area: Broxtowe	
2756869	Works required to replace Gully Pot (Enquiry 6169673) also linked to enquiry (89074) not entered contract as wont allow me to put Other repair then select Broxtowe Drainage Repair, please advise. (Other)	Gully outside No138	DRAINAGE Score 5 - PRIORITY 1	Job Completed	09/11/2020	04/01/2021	Act. DR-BRO/200010
2759214	replace x3 sight gap guardrails pics attached possibly stop and go or left turn lane closure to allow works pics attached of lane (Guardrail Repairs)	Crossroad of Swiney way and Stapleford Lane	Category 3	Job Completed	11/12/2020	17/01/2021	Act. BROX/3307766
2762428	Carriageway Pothole x 3 (CW Repairs-Bituminous)	Lamp post 57	Filled when found (Cat 2)	Job Completed	21/01/2021	21/01/2021	Act.
2762430	Carriageway Pothole x 3 (CW Repairs-Bituminous)	Stapleford Lane lamp posts 44--45	Filled when found (Cat 2)	Job Completed	21/01/2021	21/01/2021	Act.
2763794	CW Repairs-Bituminous	opp 239	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307920
2763795	CW Repairs-Bituminous	200	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307904
2763796	CW Repairs-Bituminous	200	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307905
2763797	CW Repairs-Bituminous	lamp 356(5) opp 239(3)	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307906
2763798	CW Repairs-Bituminous	238(6) lamp 46(4)	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307907
2763799	CW Repairs-Bituminous	210(4) 202(2)	Category 2	Job Completed	02/02/2021	09/02/2021	Act. BROX/3307908
2763809	CW Repairs-Bituminous	toton methodist church	Category 1	Job Completed	02/02/2021	04/02/2021	Act. BROX/3307903
2763810	Carriageway Pothole - Road Pothole - Several potholes going down hill towards toton needs addressing as wheel damage and unsafe road surface . Online report Customer title is (Enquiry 6193352) (CW Repairs-Bituminous)	jct swiney way (1) 95(2)	Category 2	Job Completed	02/02/2021	04/02/2021	Act. BROX/3307909
2764587	CW Repairs-Bituminous	entrance to stw works	Category 2	Job Completed	08/02/2021	19/02/2021	Act. BROX/3307930
2764588	500*300*50mm (CW Repairs-Bituminous)	lamp 356	Category 1	Repair Completed	08/02/2021	09/02/2021	Act.
2764589	defect 400*300*50mm (CW Repairs-Bituminous)	lamp 356	Category 1	Repair Completed	08/02/2021	09/02/2021	Act.
2764590	defect 500*300*50mm (CW Repairs-Bituminous)	lamp 356	Category 1	Repair Completed	08/02/2021	09/02/2021	Act.
2764591	500*200*40 (CW Repairs-Bituminous)	lamp 356	Category 1	Repair Completed	08/02/2021	09/02/2021	Act.
2764592	two cat 1 defects 800*250*80mm 95 and 500x300*70mm (CW Repairs-Bituminous)		Filled when found (Cat 1)	Job Completed	08/02/2021	08/02/2021	Act.
2765313	CW Repairs-Bituminous	198(4) 204(5) 208(2)	Category 2	Job Completed	12/02/2021	03/03/2021	Act. BROX/3307994
2765314	CW Repairs-Bituminous	204	Category 2	Job Completed	12/02/2021	03/03/2021	Act. BROX/3307993

Effective: 01/04/2020 to 01/04/2021
 Display Action Officer: No

Feature No.: 2000.00 to 2000.00
 Street: Stapleford Lane (4910456)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From boundary s/o ##### to Chetwynd Road junc exc service roa		Feature Type: Street Section		Area: Broxtowe	
2768518	replace 3 number 2m staggered infill with sight gap barriers RTA damage, traffic management required lane closure or four way lights (Guardrail Repairs)	junction banks Road	Category 3	Works Order Printed	05/03/2021	03/06/2021	Est. BROX/3308361
2768519	stop and go (FW Repairs-Bituminous)	lamp 46	Category 3	Works Order Printed	05/03/2021	03/06/2021	Est. BROX/3308362
2768520	CW Repairs-Bituminous	opp 238	Category 2	Job Completed	05/03/2021	26/03/2021	Act. BROX/3308346
2768521	CW Repairs-Bituminous	opp 238	Category 2	Job Completed	05/03/2021	26/03/2021	Act. BROX/3308347
2768522	FW Repairs-Bituminous	opp 208	Category 2	Repair Completed	05/03/2021	10/03/2021	Act.
2768523	CW Repairs-Bituminous	jct st geroge's drive (4) jct blackrod close (3) 15(2)	Category 2	Job Completed	05/03/2021	26/03/2021	Act. BROX/3308348
2768524	FW Repairs-Bituminous	31(1) 28(1)	Category 2	Repair Completed	05/03/2021	10/03/2021	Act.
2768525	two patches (FW Repairs-Bituminous)	30/32	Category 3	Works Order Printed	05/03/2021	03/06/2021	Est. BROX/3308363
2768526	tree root uplift (FW Repairs-Bituminous)		Category 3	Works Order Printed	05/03/2021	03/06/2021	Est. BROX/3308377