

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Street: Mansfield Road (15003276)

Locality: Ravenshead, Nottinghamshire

Area: Gedling

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	South Lodge to Blidworth Waye. Ravenshead	Feature Type:	Street Section		Area: Gedling	
Batch:	20430169 - Inspection Batch		Route:	Adhoc Inspection			Date:	05/02/2021
3660599	repaired cat 1 pothole with via fix length 1000mm x width 1000mm x 90mm depth	05/02/2021	mansfield road papplewick between lamp col 61/61 pothole	CW Repairs-Bituminous	Internal		Uncommitted	2764399
Batch:	20429194 - Inspection Batch		Route:	Gedling Area 1 Feb Saf CW			Date:	01/02/2021
	No actionable defects found							
Batch:	20428791 - Inspection Batch		Route:	Adhoc Inspection			Date:	28/01/2021
3659576	Carriageway Pothole length 1000mm x 800mm width x 70mm depth cat 1 repaired on site with via fix	28/01/2021	Just before junction with burnt stump heading towards Nottingham next to entrance to house 25 called RANI	CW Repairs-Bituminous	Internal		Uncommitted	2763374
Batch:	20427841 - Inspection Batch		Route:	Adhoc Inspection			Date:	21/01/2021
3658586	Carriageway Potholes	21/01/2021	just before the dairy farm all way to miller and carter traffic lights	CW Repairs-Bituminous	Internal		Committed	2762384
Batch:	20427196 - Inspection Batch		Route:	Adhoc Inspection			Date:	18/01/2021
3657985	Carriageway Pothole	18/01/2021	heading southbound just before lc 50	CW Repairs-Bituminous	Internal		Uncommitted	2761783
3657986	Carriageway Pothole	18/01/2021	between lc nos 50 and 51 marked near police head quartes sign	CW Repairs-Bituminous	Internal		Uncommitted	2761782
Batch:	20427017 - Inspection Batch		Route:	Adhoc Inspection			Date:	15/01/2021
3657824	Carriageway Pothole	15/01/2021	on A60 just after lc 16 heading to nottingham before traffic lights.	CW Repairs-Bituminous	Internal		Uncommitted	2761622
3657826	Carriageway Pothole	15/01/2021	on A60 after lc16 heading to trafic lights towards Nottingham	CW Repairs-Bituminous	Internal		Uncommitted	2761621
3657825	Carriageway Pothole	15/01/2021	On the A60 just before Lc 61 heading to nottingham before the t lights	CW Repairs-Bituminous	Internal		Uncommitted	2761623
Batch:	20426853 - Inspection Batch		Route:	Adhoc Inspection			Date:	13/01/2021
3657721	pothole marked in white	13/01/2021	Outside 99/101 Mansfield Road - Northbound	CW Repairs-Bituminous	Internal		Uncommitted	2761518
Batch:	20423460 - Inspection Batch		Route:	Gedling Area 1 Dec Saf CW			Date:	15/12/2020
3655678	potholes	15/12/2020	as marked outside sherwood lodge opp miller and carter steak house	CW Repairs-Bituminous	Internal		Committed	2759470

Customer Services

Enquiry No.: 6194513

Logged by: External to Confirm

on: 05/02/2021 12:33

Service: Claims

Subject: Highway Insurance Claim

Classification: Report or Observation

Enquiry Ref: FS304751419

Desc.: Insurance claim - related to Confirm defect reference: 6194512

Date/Time: 05/02/2021 06:30:00

Direction of travel: Heding south into nottingham on A60 Mansfield Road near Miller and Carter

Account of what happened: The caller's wife hit a pothole in the road which has pictured both nearside tyres. he is wanting to claim for recovery costs. The

Location: A60 Mansfield Road not far north of junction with Burntstump Hill, near Miller and Carter restaurant

Contact:

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6194512 **Logged by:** External to Confirm **on:** 05/02/2021 12:32
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304751419
Desc.: Insurance claim form requested - Road Pothole - Caller is making a claim on pothole, already being fixed/inspector has put cones around it. Caller's wife has had to take a day off from work in the Covid ward because of this. . Submitted by Advisor: Jakub Gan Customer title is Mr.
Location: A60 Mansfield Road not far north of junction with Burntstump Hill, near Miller and Carter restaurant **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399

Enquiry No.: 6194486 **Logged by:** External to Confirm **on:** 05/02/2021 11:06
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304703489
Desc.: Road Pothole - Large pothole in nearside lane, passenger side wheel track. . Online report Customer title is Mr.
Location: Large and deep pothole on north A60 approach to traffic signalled junction with Burnt Stump Hill **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399

Enquiry No.: 6194421 **Logged by:** External to Confirm **on:** 05/02/2021 08:30
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304627351
Desc.: Road Pothole - there is a huge pot hole, it nearly took my wheel off this morning and urgently needs repair, this is a danger to road users as it causes traffic to swerve into the other lane. it looks like this is previously reported but should be treated as urgent. . Online report Customer title is Mrs.
Location: Heading towards Nottingham, just before the traffic lights and the turning to Burnt Stump Hill **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399 **Defect Number:** 3660599

Enquiry No.: 6194416 **Logged by:** External to Confirm **on:** 05/02/2021 07:03
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS304601588
Desc.: Road Pothole - Tyre splitting pot hole in a fast road . I had to cut over traffic to get to safety . Online report Customer title is Mr. - Previous Confirm Case: 6192582
Location: 40m up from traffic lights .this council is a disgrace ,reported 1 then got a damaged wheel and split tyre on this one . People along the road changing tyres . There is enough people dying a.t.m and this council will be adding to our problems . **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399

Enquiry No.: 6194364 **Logged by:** External to Confirm **on:** 04/02/2021 17:12
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-304460576
Desc.: Road Pothole - Very deep pothole! With different layers. Very surprised tyre wasn't damaged with depth . Online report Customer title is Miss.
Location: Just before where the road becomes 2 lanes before the traffic lights. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399

Enquiry No.: 6193979 **Logged by:** External to Confirm **on:** 03/02/2021 13:30
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-303909308
Desc.: Road Pothole - Large pot hole . Online report Customer title is Mrs.
Location: Large pot hole between forest lane & burnt stump hill **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2764399

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6193620	Logged by: External to Confirm	on: 02/02/2021 10:36	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS303328631
Desc.: Insurance claim - related to Confirm defect reference: 6193619			
Date/Time: 28/01/2021 08:00:00			
Direction of travel: Forest Lane (B6011) on to the A60 to turn left a little further on at the next traffic lights for Burntstump Hill			
Account of what happened: On Thursday, 28th January I hit a pot hole on my way to work. I had turned right at the traffics lights at the end of Forest Lane (B6011) on to the A60 to turn left a little further on at the next traffic lights for Burntstump Hill. Somewhere between these 2 sets of lights my offside wheel hit a pot hole which damaged the wheel. I had to replace it with the spare. My local tyre garage has now repaired the wheel which cost £20. They have also booked me in for re-tracking on 9th February which will cost £30. Could you please compensate me for this loss. I would be happy to forward copies of the invoices. I would have supplied you a picture of the pot hole but this was not practical as the A60 is very busy			
Location: Mansfield Road (A60) between Forest Lane junction and Burntstump Hill junction		Contact:	
Enquiry No.: 6193619	Logged by: External to Confirm	on: 02/02/2021 10:35	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-303328631
Desc.: Insurance claim form requested - Road Pothole - hit a pot hole which damaged the wheel . Submitted by Advisor: Kerry Carby Customer title is			
Location: Mansfield Road (A60) between Forest Lane junction and Burntstump Hill junction		Contact:	
Enquiry No.: 6192651	Logged by: External to Confirm	on: 28/01/2021 14:54	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS301563202
Desc.: Insurance claim - related to Confirm defect reference: 6192650			
Date/Time: 28/01/2021 13:15:00			
Direction of travel: From the a60 going towards nottingham			
Account of what happened: Cust has hit a pothole going towards arnold, the passenger side tyre has been damaged and needed to replace the pothole was deep and impacted me straight away and needs to put the spare tyre on			
Location: Mansfield Rd, Nottingham NG5 8PJ		Contact:	
At the junction with Bruntstump hill and mansfield road			
Enquiry No.: 6192650	Logged by: External to Confirm	on: 28/01/2021 14:52	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-301563202
Desc.: Insurance claim form requested - Road Damage - Cust has hit a pothole going towards arnold, the passenger side tyre has been damaged and needed to replace the pothole was deep and impacted me straight away and needs to put the spare tyre on . Submitted by Advisor: Ricky Gandhi Customer title is Miss.			
Location: Mansfield Rd, Nottingham NG5 8PJ		Contact:	
At the junction with Bruntstump hill and mansfield road			
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section
Job Number: 2763374			
Enquiry No.: 6192585	Logged by: External to Confirm	on: 28/01/2021 12:27	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS301481949
Desc.: Insurance claim - related to Confirm defect reference: 6192582			
Date/Time: 28/01/2021 09:35:00			
Direction of travel: going into Nottingham			
Account of what happened: Gone over the pothole and his burst two his tyres			
Location: Road pothole near the burnstump hill		Contact:	
Enquiry No.: 6192582	Logged by: External to Confirm	on: 28/01/2021 12:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-301481949
Desc.: Insurance claim form requested - Road Pothole - Gone over a pot hole and has punctured two of his tyres . Submitted by Advisor: Claudia Beastall Customer title is Mr.			
Location: Road pothole near the burnstump hill		Contact:	
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section
Job Number: 2763374			

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6192534	Logged by: External to Confirm	on: 28/01/2021 10:34	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-301409163
Desc.: Road Pothole - Large pot hole could severely injure a motorcyclist			
17827012021 . Submitted by Advisor: James Fraser-Miller Customer title is			
Location: Large pothole south bound carriage way A60 with Burnt Stump Hill aprox 15 meters before traffic lights Contact:			
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead	Feature Type: Street Section	
Job Number: 2763374			
Enquiry No.: 6192304	Logged by: External to Confirm	on: 27/01/2021 12:51	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-301032197
Desc.: Road Pothole - Large pothole . Online report Customer title is Mrs.			
Location: Just before junction with burnt stump heading towards Nottingham Contact:			
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead	Feature Type: Street Section	
Job Number: 2763374 Defect Number: 3659576			
Enquiry No.: 6191467	Logged by: External to Confirm	on: 22/01/2021 13:15	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS299198879
Desc.: Insurance claim - related to Confirm defect reference: 6191466			
Date/Time: 14/01/2021 17:20:00			
Direction of travel: Heading North along the A60 on Mansfield Road, near the miller and carter			
Account of what happened: The caller hit the pothole which damaged the driver's side front tyre, resulting in them needing to have a mobile tyre van replace it at extra expense. The caller is wanting to ask for the cost of the tyre to be reimbursed.			
Location: On the A60 Norringham Road, near the Miller and Carter/junction for Burntstump Hill Contact:			
Enquiry No.: 6191466	Logged by: External to Confirm	on: 22/01/2021 13:13	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-299198879
Desc.: Insurance claim form requested - Road Damage - The caller his a pothole on the road and it has damaged their wheel, are claiming. . Submitted by Advisor: Jakub Gan Customer title is			
Location: On the A60 Norringham Road, near the Miller and Carter/junction for Burntstump Hill Contact:			
Enquiry No.: 6191047	Logged by: External to Confirm	on: 20/01/2021 20:09	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-298476927
Desc.: Road Pothole - A60 Arnold bound after burnt sump is covered in potholes. Dangerous on motorbike . Online report Customer title is			
Location: A60 Arnold bound after burnt sump is covered in potholes. Dangerous on motorbike Contact:			
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead	Feature Type: Street Section	
Job Number: 2762384 Defect Number: 3658586			
Enquiry No.: 6190718	Logged by: External to Confirm	on: 19/01/2021 15:45	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS297935811
Desc.: Insurance claim - related to Confirm defect reference: 6190716			
Date/Time: 14/01/2021 16:35:00			
Direction of travel: Towards Arnold on Mansfield Road.			
Account of what happened: Good afternoon I would like to report and complain regarding damage to my car caused by a reported pot hole. On Thursday 14th Jan 2021 evening 16:35pm I was driving along the A60 ahead of the Burnt stump traffic lights toward Arnold and hit an unmarked pot hole. This caused my front right wheel to burst and need to stop at Miller and Carter car park. Another gentleman had also had the exact same thing occur to him moments before. I went on to your website to report the pot hole and it had already been reported. The issue was I was stranded by the side of the road for 2 hours on my own and then charged 60GBP for a tow to a garage and 124GBP for a new tyre and wheel alignment. My issue is this pot hole had already been reported but no sign or caution around it leading to damage on my car and a situation in which I was left vulnerable. I have attached a picture of the pothole. I look forward to your response. Eve Byrne			
Location: A60 ahead of the Burnt stump traffic lights toward Arnold. Next to the Miller and Carter. Contact:			

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6190716 **Logged by:** External to Confirm **on:** 19/01/2021 15:44
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-297935811
Desc.: Insurance claim form requested - Road Pothole - Email from customer:

Good afternoon I would like to report and complain regarding damage to my car caused by a reported pot hole. On Thursday 14th Jan 2021 evening 16:35pm I was driving along the A60 ahead of the Burnt stump traffic lights toward Arnold and hit an unmarked pot hole. This caused my front right wheel to burst and need to stop at Miller and Carter car park. Another gentleman had also had the exact same thing occur to him moments before. I went on to your website to report the pot hole and it had already been reported. The issue was I was stranded by the side of the road for 2 hours on my own and then charged 60GBP for a tow to a garage and 124GBP for a new tyre and wheel alignment. My issue is this pot hole had already been reported but no sign or caution around it leading to damage on my car and a situation in which I was left vulnerable. I have attached a picture of the pothole. I look forward to your response. Eve Byrne . Submitted by Advisor: Nathan Lavery Customer title is

Location: A60 ahead of the Burnt stump traffic lights toward Arnold. Next to the Miller and Carter. **Contact:**

Enquiry No.: 6189972 **Logged by:** External to Confirm **on:** 15/01/2021 13:24
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS296459902
Desc.: Insurance claim - related to Confirm defect reference: 6189970
Date/Time: 15/01/2021 07:30:00
Direction of travel: Southbound from Mansfield.
Account of what happened: Drove into a pot hole which has caused the driver side front tire to burst and the AA were called out, the vehicle currently in the garage being assessed for further damage.

Location: A60 just before the junction to Burntstump Hill heading south. **Contact:**

Enquiry No.: 6189970 **Logged by:** External to Confirm **on:** 15/01/2021 13:21
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-296459902
Desc.: Insurance claim form requested - Road Damage - Pot hole in the road in the middle of the lane, southbound. . Submitted by Advisor: Matthew Jackson2 Customer title is Mr.
Location: A60 just before the junction to Burntstump Hill heading south. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2761622

Enquiry No.: 6189887 **Logged by:** External to Confirm **on:** 15/01/2021 10:09
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS296344788
Desc.: Insurance claim - related to Confirm defect reference: 6189881
Date/Time: 15/01/2021 07:15:00
Direction of travel: Southbound
Account of what happened: Pothole has burst tyre
Location: previously reported **Contact:**

Enquiry No.: 6189881 **Logged by:** External to Confirm **on:** 15/01/2021 10:06
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-296344788
Desc.: Insurance claim form requested - Road Pothole - previously reported . Submitted by Advisor: James Fraser-Miller Customer title is Ms.
Location: previously reported **Contact:**

Enquiry No.: 6189879 **Logged by:** External to Confirm **on:** 15/01/2021 10:03
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS296341360
Desc.: Insurance claim - related to Confirm defect reference: 6189878
Date/Time: 15/01/2021 07:15:00
Direction of travel: Southbound
Account of what happened: Vehicle has struck pothole and has caused right front tyre to bulge and deflate.
Location: A60 junction Burnt Stump Hill **Contact:**

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6189878	Logged by: External to Confirm	on: 15/01/2021 10:02	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-296341360
Desc.: Insurance claim form requested - Road Pothole - Pothole previously reported . Submitted by Advisor: James Fraser-Miller Customer title is Ms.			
Location: A60 junction Burnt Stump Hill	Contact:		
Enquiry No.: 6189852	Logged by: External to Confirm	on: 15/01/2021 09:13	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS296308871
Desc.: Insurance claim - related to Confirm defect reference: 6189850 Date/Time: 14/01/2021 18:10:00 Direction of travel: Heading south on the A60 Mansfield Road, 200-300 yards north of the junction with Burntstump Hill/Miller and Carter Account of what happened: The caller drove over the pothole and it has burst the driver's front side tyre. He isn't sure of the rear tyre had any damage either. He is wanting to claim to replace the tyre.			
Location: 200-300 Yards north of the junction with Burnstump Hill on the A60, Mansfield Road	Contact:		
Enquiry No.: 6189850	Logged by: External to Confirm	on: 15/01/2021 09:06	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-296308871
Desc.: Insurance claim form requested - Road Pothole - The caller drove over a pothole that burst his tyre at the centre of the road. . Submitted by Advisor: Jakub Gan Customer title is Mrs.			
Location: 200-300 Yards north of the junction with Burnstump Hill on the A60, Mansfield Road	Contact:		
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section
Job Number: 2761621			
Enquiry No.: 6189849	Logged by: External to Confirm	on: 15/01/2021 09:02	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-296307698
Desc.: Road Pothole - Pothole, southbound carriageway has given a few vehicles punctures. . Submitted by Advisor: James Fraser-Miller Customer title is Mr.			
Location: Junction of Burnt Stump Hill with A60	Contact:		
Enquiry No.: 6189842	Logged by: External to Confirm	on: 15/01/2021 08:27	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-296293213
Desc.: Insurance claim form requested - Road Pothole - Pothole has caused tyre to burst and then 3 more vehicles have done the same thing straight after. When she called the police after the police officer knew the exact location and said she had done the same . Submitted by Advisor: Ricky Fusco Customer title is Mrs.			
Location: A60 coming from Mansfield to Notts (Burnstump Hill on left) it is 100-200 yards before traffic lights	Contact:		
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section
Job Number: 2761621	Defect Number: 3657826		
Enquiry No.: 6189777	Logged by: External to Confirm	on: 14/01/2021 16:51	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-296117779
Desc.: Road Pothole - i believe it is at least 4 inches deep about a foot wide and two feet long. it is bad enough to damage vehicles as i have just driven through it and it had broken one of my alloys and i am currently waiting for my car to be recovered. . Online report Customer title is Mr.			
Location: heading southbound on the A60 before the traffic lights near the pinpoint on the map (miller and carter restaurant) there is a sign for the traffic lights, the hole is just before this.	Contact:		
Plot Number: 2,000.00	Feature Id - Location: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section
Job Number: 2761782	Defect Number: 3657986		

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Customer Services

Enquiry No.: 6188993 **Logged by:** External to Confirm **on:** 11/01/2021 08:01
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-293577537
Desc.: Road Pothole - Large pothole that has been reported before and temporarily back filled before. Backfill has all come out again and pothole now seems deeper - every time a lorry goes over it the house vibrates. . Online report Customer title is Mr.
Location: Outside 99/101 Mansfield Road - Northbound **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** South Lodge to Blidworth Waye. Ravenshead **Feature Type:** Street Section
Job Number: 2761518 **Defect Number:** 3657721

Enquiry No.: 6186725 **Logged by:** External to Confirm **on:** 17/12/2020 13:39
Service: Other **Subject:** Other Request (Highways) **Classification:** Service Request **Enquiry Ref:** FS-CASE-285013068
Desc.: Other requests - Dear Sirs, Our Ref: UKA20-1139 We are all-uk Adjusters and are acting on behalf of PSV Claims (on behalf of Stagecoach) and have been instructed to assess the damage caused by a Stagecoach bus to a grass verge outside The Bungalow Sherwood Lodge, Arnold, NG5 8PN. We understand from the owner of the property, Mr Carver, that the land belongs to you. He would like the damage repaired, which we are prepared to do at no cost to the council or Mr Carver, however as the land owner, we require your permission to do so. We have carried out a site visit to assess the damage, which is minimal, and would be grateful if you could contact me, either via phone or email, to confirm if we are able to repair the damage caused. Yours Faithfully Peter Barber Loss Adjuster all-uk . Submitted by Advisor: Adele Morris - Customer title is Mr.
Location: Mansfield Road (A60) Arnold **Contact:**

Enquiry No.: 94366 **Logged by:** Denise Bennett **on:** 21/01/2021 09:33
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation
Desc.: Incident 15/01/21: I was driving along the A60 travelling from Mansfield to Sherwood Lodge, when approximately 50 yards from the traffic lights my car hit a pothole. The Pothole was not marked in any way and was not visible. I was physically moved in my seat at how deep it was. (enquiry raised on receipt of claim form)
Location: A60 Mansfield Road near the turning for Burntstump Hill **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: South Lodge to Blidworth Waye. Ravenshead		Feature Type: Street Section		Area: Gedling	
230957	HW DR Blocked Gully Z3	o/s 189, 191,	Category 2	Job Cancelled	26/07/2012	22/08/2012	Est. GED/79103
2604756	Please investigate standing water not draining away in Entrance, there is an offset kerb to the r/h/s and a gully which sits high on the l/h/s grass verge. I'am not sure, but they be a carrier drain in the verge here. Jet out and clean through system please. (HW DR Standing water Z3)	In entrance to North Lodge Mansfield Road.	Category 2	Job Cancelled	10/02/2015	10/03/2015	Est. GED/3400600
2741278	clear out blocked gullies. Submitted by Advisor: Cheryl EvansCustomer title is Mr. (Enquiry 6135958) (Drainage-Blocked Asset)	47 to 63	DRAINAGE Score 5 - PRIORITY 1	Further Drainage Work Required	01/04/2020	01/04/2021	Est. DC-GED/1000005

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	South Lodge to Blidworth Waye. Ravenshead	Feature Type:	Street Section	Area:	Gedling
2744395	Please replace 9no steel / 1no concrete offlet kerbs with water fall grates and install gully pots to suit. (Drainage Repair)	Outside the following property's - SHIRLEYS NURSERIES L/C NO69 DOWN FROM L/C NO69 167 RUSSETWAYS 151 PAPPLEWICK RDA 95 GALABANK CATTERY 81 77 HEBDEN ROYD 75	DRAINAGE Score 5 - PRIORITY 1	Job Raised	09/06/2020	09/06/2021	Est.
2759470	potholes (CW Repairs-Bituminous)	as marked outside sherwood lodge opp miller and carter steak house	Category 2	Job Completed	15/12/2020	24/12/2020	Act. GED/3409700
2761518	pothole marked in white (CW Repairs-Bituminous)	Outside 99/101 Mansfield Road - Northbound	Category 1	Repair Completed	13/01/2021	14/01/2021	Act.
2761621	Carriageway Pothole (CW Repairs-Bituminous)	on A60 after lc16 heading to traffic lights towards Nottingham	Filled when found (Cat 1)	Job Completed	15/01/2021	15/01/2021	Act.
2761622	Carriageway Pothole (CW Repairs-Bituminous)	on A60 just after lc 16 heading to nottingham before traffic lights.	Filled when found (Cat 1)	Job Completed	15/01/2021	15/01/2021	Act.
2761623	Carriageway Pothole (CW Repairs-Bituminous)	On the A60 just before Lc 61 heading to nottingham before the t lights	Filled when found (Cat 2)	Job Completed	15/01/2021	15/01/2021	Act.
2761782	Carriageway Pothole (CW Repairs-Bituminous)	between lc nos 50 and 51 marked near police head quartes sign	Category 2	Repair Completed	18/01/2021	21/01/2021	Act.
2761783	Carriageway Pothole (CW Repairs-Bituminous)	heading southbound just before lc 50	Filled when found (Cat 1)	Job Completed	18/01/2021	18/01/2021	Act.
2762384	Carriageway Potholes (CW Repairs-Bituminous)	just before the dairy farm all way to miller and carter traffic lights	Category 2	Job Completed	21/01/2021	06/02/2021	Act. GED/3409894
2763374	Carriageway Pothole length 1000mm x 800mm width x 70mm depth cat 1 repaired on site with via fix (CW Repairs-Bituminous)	Just before junction with burnt stump heading towards Nottingham next to entrance to house 25 called RANI	Filled when found (Cat 1)	Job Completed	28/01/2021	28/01/2021	Act.
2764399	repaired cat 1 pothole with via fix length 1000mm x width 1000mm x 90mm depth (CW Repairs-Bituminous)	mansfield road papplewick between lamp col 61/61 pothole	Filled when found (Cat 1)	Job Completed	05/02/2021	05/02/2021	Act.

Effective: 07/12/2020 to 06/02/2021

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (15003276)

Street Works Notices**Organisation:** BT: Amey - BDUK/SEP/Non NEMSA/Non ONSA (0030128)**Works Ref:** WAPR717E-A**Version:** 5**Work Desc:** POLE REPLACEMENT**Notice Type:** Cancellation**Start:** 29/01/2021 08:00:00**Work Status:** Abandoned Works**Issued:** 29/01/2021 10:39:55**Work Type:** EToN 4: Minor**Est. End:** 30/01/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	HEAD ONLY - MANSFIELD ROAD (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	21/01/2021 08:00:00			30/01/2021

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** 3671717**Version:** 3**Work Desc:** SL- Street Light out**Notice Type:** Cancellation**Start:** 16/01/2021 00:00:00**Work Status:** Abandoned Works**Issued:** 14/01/2021 08:53:35**Work Type:** EToN 4: Minor**Est. End:** 16/01/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	mansfield road ravenshead	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	16/01/2021			16/01/2021

Works Ref: 3672297**Version:** 3**Work Desc:** SL- Illuminated Sign Knockdown**Notice Type:** Cancellation**Start:** 16/01/2021 00:00:00**Work Status:** Abandoned Works**Issued:** 14/01/2021 08:55:28**Work Type:** EToN 4: Minor**Est. End:** 16/01/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	mansfield road ravenshead.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	16/01/2021			16/01/2021

Works Ref: 3672297A**Version:** 2**Work Desc:** SL- Illuminated Sign Knockdown**Notice Type:** Grant Permit**Start:** 06/02/2021 00:00:00**Work Status:** Proposed Works**Issued:** 29/01/2021 08:26:01**Work Type:** EToN 4: Minor**Est. End:** 06/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	mansfield road ravenshead.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	06/02/2021			06/02/2021